Appendix E

HTRW Assessment Report Fourth Avenue



HTRW Assessment Report Fourth Avenue

Mouse River Enhanced Flood Protection Project Minot, North Dakota

Prepared for Souris River Joint Board

July 2015

234 West Century Avenue Bismarck, ND 58503 Phone: 701.255.5460 Fax: 701.222.6371

HTRW Assessment Report Fourth Avenue

July 2015

Contents

Backgro	ound	1
1.0	Assessment Area Setting	2
2.0	Land-Use History and Current Conditions	4
2.1	Assessment Area History	4
2.2	Current Conditions	5
3.0	Regulatory History	6
4.0	Previous Environmental Investigations	7
5.0	Findings	8
6.0	Conclusions	10

List of Figures

Figure 1	Project Overview
Figure 2	Assessment Area Location Map
Figure 3	Assessment Area Layout Map
Figure 4	Investigation Locations
Figure 5	Historic Layout Map

List of Appendices

HTRW Documentation
Historical Documentation
Regulatory Reports
Site Visit Photographs
Information Resources
Braun Intertec Boring Logs
Limitations and Qualifications
Contingency Plan

Background

Barr Engineering Co. completed a Hazardous, Toxic, and Radioactive Waste Assessment (HTRW Assessment) for the Fourth Avenue segment of the Mouse River Enhanced Flood Protection Project (Project) in Minot, Ward County, North Dakota. The Project consists of multiple flood protection features from Burlington to south of Minot (Figure 1). This HTRW Assessment focuses on the flood control features to be constructed in the Fourth Avenue segment, where construction of a new floodwall, levee, road realignments, and related utility relocations are planned as part of the Project. The Initial Assessment Area was originally established around planned Project features and a buffer of approximately 50 feet to account for temporary construction areas (the Initial Assessment Area Figure 2). In May, 2015, additional areas were added to the Initial Assessment Area, including east of Third Street NE and west of Broadway Street (Assessment Area; Figure 2). The following resources were used to obtain information on the Assessment Area: site reconnaissance, historical maps, reverse city directories, historical aerial photographs, a regulatory database report, and select interviews with Minot staff. The majority of those resources were able to provide full coverage of the Assessment Area as it was expanded beyond the Initial Assessment Area, with the exception of incomplete historical fire insurance maps west of Broadway Street. Barr conducted a second site reconnaissance in May to account for the additional areas; however, we did not contact Minot staff again as their responses were not site-specific.

Barr performed this HTRW Assessment in general conformance with ER 1156-2-132 U.S. Army Corps of Engineers Water Resources Policies and Authorities, Hazardous, Toxic and Radioactive Waste Guidance for Civil Works Projects (Ref. 16). This narrative briefly summarizes the results of the HTRW Assessment. The Assessment Area's setting, land-use history, regulatory history, and features, as well as information related to interviews and information resources, are presented in the HTRW Assessment documentation in Appendix A. Historical documentation is in Appendix B. Regulatory Reports are in Appendix C. Site visit photographs are in Appendix D. Reference numbers cited throughout this report and in Appendix A correlate to the numbers listed with the information resources in Appendix E.

1.0 Assessment Area Setting

The Fourth Avenue segment is north of the Mouse River and extends from west of Broadway Street to east of the Third Street SE (Figure 2). The proposed improvements within the Assessment Area include construction of a floodwall, levees, and road realignments.

There are 107 parcels within the Assessment Area; 34 are owned by Minot, 1 by the ND state highway department and 72 are privately owned. A comparison between aerial photographs and site inspection observations indicate that approximately six buildings have been demolished on parcels owned by Minot. As of May 17, 2015, there are approximately 56 buildings within the Assessment Area; including a vacant church, 41 residences or business, 8 buildings marked "No Trespassing – City of Minot" and 6 buildings associated with Helm's & Mork Storage (Figure 3).

The Assessment Area is in the floodplains of the Mouse River Basin at a surface elevation of approximately 1,550 feet above mean sea level (Refs. 1, 12). This basin was carved into late Wisconsin age glacial drift during the draining of Glacial Lake Regina, in Saskatchewan, Canada. Floodplain alluvial deposits, generally mapped across the extent of the Souris River Valley Floodplain, consist of fluvial channel and overbank sands, gravels, silts, and clays (Refs. 21, 22). The floodplain alluvial deposits varying in thickness from approximately 50 to 200 feet thick (Ref. 20). At the margins of the floodplain, colluvial fan deposits of sandy and silty clay originate from the mouths of coulees and ravines (Ref. 22). Based on a recent geotechnical investigation, fill is present from 0 to 15 feet below ground surface (bgs) throughout the Assessment Area.

Bedrock underlying the Assessment Area is the Cannonball Formation, consisting of alternating sand, shale, poorly consolidated sandstone and mudstone (Refs. 5, 20). The Cannonball Formation is within the lower part of the Fort Union Group which is regionally present in the vicinity of the Assessment Area (Ref. 5). The depth to bedrock underling the Assessment area is approximately 144 to 206 feet below ground surface, ranging from approximately 1,406 to 1,344 feet above mean sea level (Ref. 19).

In January 2015, a geotechnical investigation was conducted in the Assessment Area (Ref. 12; Figure 4). Fill was observed in all investigation locations, ranging in depth from 0 feet bgs to 15 feet bgs (Ref. 12). Environmental field screening for potential contaminants was not conducted as part of the geotechnical investigation; however, borings ST-4 and ST-7 contained bituminous fragments, test pit TP-1001 contained 8 inches of bituminous pavement between 2.0 and 2.8 feet bgs and pieces of concrete and wood between 2.8 and 7.5 feet bgs, and test pit TP-1006 contained brick fragments, glass, and concrete between 3 and 7 feet bgs (Ref. 12). Groundwater was observed at depths ranging from 12 to 19 feet bgs; however, the boring logs indicate that groundwater levels fluctuate in the area (Ref. 12). Alluvium generally consisting of silt, silty sand, or clay was present directly beneath the fill (Ref. 12). Boring logs are in Appendix F.

Minot provides potable water to residents in the Assessment Area from wells within and east of Minot, screened in the Minot aquifer and Sundre Aquifer (Refs. 10, 17). Prior to connecting to Minot's water

supply, private wells were used within the Assessment Area (Ref. 10). The City now requires all residents within the city limits to be connected to Minot's water supply system (Ref. 10).

The Assessment Area is within the Hudson Bay Drainage (Ref. 19). The nearest surface water body is the Mouse River, located south of the Fourth Avenue segment. The Mouse River originates in Canada; it flows southeasterly though North Dakota before bending northwards back into Canada (Ref. 6). Drainage ditches and storm water outlets are present throughout the Assessment Area.

The Minot aquifer is comprised of very coarse sand and gravels containing numerous of boulders. The depth varies from approximately 100 to 150 feet below ground surface (bgs) throughout the vicinity (Ref. 20). Historical groundwater flow direction within the Assessment Area is anticipated to be south towards the Mouse River (Refs. 1, 8); however, due to pumping from public water supply wells, groundwater flow reverses direction away from the river and towards the public water supply wells in the area (Ref. 8). The public water supply wells in the Mouse River valley obtain water from the Minot aquifer (Refs. 10, 17) and Sundre Aquifer (Ref 17). Therefore, the groundwater flow direction varies and for the purposes of this HTRW Assessment it is assumed that all sites listed in the regulatory database report that are located between the Mouse River and the public water supply wells are potentially upgradient.

2.0 Land-Use History and Current Conditions

In 1886, the Great Northern Railroad ended its development in the state of North Dakota for the winter, after having difficulty constructing a trestle across Gassman Coulee (Ref. 15). A tent town sprung up overnight and the town was named after Henry Davis Minot, a railroad investor (Ref. 15). The city was incorporated on June 28, 1887 (Ref. 15). The town started out as a western town, and additional development occurred in the 1950s, census data records a population of 22,032 (Ref. 15). In 1969, a severe flood on the Mouse River devastated Minot and the U.S. Army Corps of Engineers straightened the river through the city and built several flood control structures (Ref. 15). The 2010 census data records a population of 40,888 people (Ref. 15). The Assessment Area has a variety of zoning including: R1, single family; R3B, multifamily; C1, limited commercial; C2, general commercial; and M2, light industrial, (Ref. 17).

2.1 Assessment Area History

Fire insurance maps indicate that the Assessment Area was used for residential purposes by at least 1913 (Ref. 2). Other uses indicated in the 1913 map include: the Minot Flour Mill that was at the intersection of Third Street NE and Fourth Avenue (Ref. 2); a Feed and Stable building that was at the intersection of Fourth Avenue and Third Street NE; and a bakery that was at the intersection of Fifth Avenue NE and Third Street NE. A vacant parcel north and east of the Minot Flour Mill was indicated as the former Great Northern Lumber Co. in the 1913 map (Ref. 2). A historical layout map is provided in Figure 5.

Additional development was apparent in the 1918 fire insurance maps (Ref. 2). The Minot Flour Mill was still present and Standard Oil Co. constructed a building northeast of the flour mill which included an oil warehouse, a lubricating tank house, a building for filling wagon tanks, a barrel-filling shed, oil pump house, and gasoline and kerosene tanks within the Assessment Area (Ref. 2). A dry cleaner was present north of the intersection of Third Street NE and Fifth Avenue NE (Ref. 2). A garage was also present at the intersection of Fourth Avenue and Second Street NW; however, no additional information is available on this garage (Ref. 2). A pump house was also present at the intersection of Fifth Avenue NW and Walders Street NW (Ref. 2). The Feed and Stable building was converted to Cox-Emerson Lumber Company (Ref. 2). North of the Assessment Area, a creamery was present (Ref. 2), and northwest of the Assessment area a Water Treatment Plant was present (Ref. 2).

By 1926, more residential development is apparent north of Fourth Avenue (Ref. 2). The Minot Flour Mill, Standard Oil Co., dry cleaner, and the garage were still present (Ref. 2). The Cox-Emerson Lumber Company had been converted to the Bond Lumber Company and included a filling station (Ref. 2). The Minot Bakery had been converted to Purity Ice Cream and Dairy Co. (Ref. 2). The Minot Water Treatment Plant was still present, and the creamery had been converted to a filling station.

Based on a review of the historical aerial photos, the Assessment Area was largely developed by 1938 (Ref. 3). Between 1969 and 1979, the Mouse River was realigned west of the Assessment Area and the Broadway Street Bridge, and a number of buildings were demolished in the process (Ref. 3). Demolition material was removed from the Assessment Area (Ref. 10). Based on the aerial photos, portions of the Assessment Area have been developed for industrial purposes since at least 1938 (Ref. 3).

Reverse city directories indicate that a heating and air conditioning shop was located at 400 Fifth Avenue NE in 2004 (Ref. 7). From 1978 to 1988, this same parcel was occupied by Werner Oil, and from 1963 to 1973, this parcel was occupied by Standard Oil Division of American Oil Company, which was also identified in the 1918 fire insurance map (wholesale) (Ref. 7).

2.2 Current Conditions

Current land use in the Assessment Area is a mix of vacant land, residential, commercial, and industrial. There were approximately 56 buildings present as of May 17, 2015, with 8 marked as "No Trespassing – City of Minot". Industrial and commercial uses include Home Sweet Home gift shop, Giscon concrete pumping service, Souris Valley Feed and Seed grain elevator, Souris River Design, Taxi 9000, and Helm's & Mork's Storage which is used as a furniture store, a small used car sale lot, and portable heater storage; all of these uses are contained within a large fenced-in area. There is also a large vacant church and the bridges for Broadway Street and Third Street SE.

Rivers and railroads are south of the area. The surrounding area to the north consists of residential property, churches, McKinley Elementary School, and several businesses, including Sammy's Pizza, Lowe's Printing, Watne Real Estate office, All Washed Up Laundromat, B&D Market, E-cig electric cigarette shop, Body Brite massage parlor, Philotechnics Ltd building, and leased commercial garages. A small city park is also present.

Site inspections were completed for the Initial Assessment Area on March 17, 2015, and the Assessment Area on May 17, 2015, from public rights-of-way (Figure 3). No buildings were entered and inspected. Notable items observed within the Initial Assessment Area during the site inspection visits were a vent pipe east of the Broadway Street bridge and one pole-mounted transformer, both in good condition. No concrete washout, barrels, or stained ground were observed in the vicinity of Giscon concrete pumping service.

Notable items observed in the site visit for the expanded Assessment Area include seven pole-mounted transformers and one pad-mounted electrical box, all in good condition. A private car repair shop with car repair materials and presumably welding tanks were observed at a residence. No stained ground or stressed vegetation were observed. Approximately 20 trailer-mounted portable heaters and some heavy equipment were observed in the fenced-in area at Helm's & Mork's Storage, along with a small used car sale lot. No barrels or stained ground were observed.

Notable items in the surrounding area to the north were a generator in Lowe's Printing yard, two padmounted electrical boxes in good condition in the city park, three pole-mounted transformers in good condition, and a 55-gallon drum, large plastic liquids container, lawn mowing equipment, and heavy equipment near a shop behind Philotechnics Ltd. No stained ground was observed.

The following were not observed within the Assessment Area during the site inspection visits: septic systems; visible evidence of filling, excavation, or burned areas; pits, ponds, or lagoons; stained pavement; pipelines; vegetative stress; rail lines; and non-stormwater discharges into drains, ditches, streams or adjacent properties.

3.0 Regulatory History

A search of regulatory records for the Initial Assessment Area was obtained from Historical Information Gatherers, Inc. (HIG) on March 10, 2015, and for the rest of the Assessment Area on May 7, 2015. The HIG regulatory database reports (HIG Report) are in Appendix C. No sites with a regulatory listing were within the Initial Assessment Area identified in the HIG Report (Ref. 9). Three listed sites were identified in the expanded Assessment Area, including the Werner Oil Company, North Dakota Concrete Products, and Porter Brothers Salvage Yard. Werner Oil Company and Porter Brothers have registered storage tanks, and North Dakota Concrete Products as listed as a leaking storage tank site, with site cleanup complete in 1989.

Several regulated sites were identified in the HIG report as potentially adjacent to or upgradient of the Assessment Area (Ref. 9). More than 75 unmappable sites (i.e., sites that could not be definitively located by HIG) were listed in the HIG Report. None of the unmappable sites with documented releases were determined to be adjacent to or up-gradient of the Assessment Area (Ref. 9). Additional details regarding the regulatory history of surrounding properties are included in Appendix A and Appendix C.

4.0 Previous Environmental Investigations

Minot conducted environmental investigations from 2013 to 2015 at nearby sites under an Environmental Protection Agency (EPA) Brownfield Program Area Wide Assessment Grant. Within the Area Wide Planning Project Boundary, two sites, the Porter Brother Salvage Yard and Standard Oil, are identified as catalyst sites, and they are located within the Assessment Area and west of the Assessment Area (Ref. 14). Catalyst sites are brownfield sites that were selected as key redevelopment sites in the grant application. In spring 2015, Minot received approval from the EPA to allow for further investigations at the Porter Brothers Salvage Yard and Standard Oil. A Phase I Environmental Site Assessment is planned in 2015 and a Limited Phase II Investigation will be completed as necessary.

5.0 Findings

The following is a list of notable observations and findings that may present an environmental risk as part of the Project implementation:

- A PVC vent pipe was observed on the northern side of the river near the Broadway Street bridge.
 No stressed vegetation was observed.
- Several pole-mounted and pad-mounted transformers were observed throughout the Assessment Area. No leaks, spills, rust spots, or dents were observed.
- Home Sweet Home Gift Shop (103 Fourth Avenue) is on the south side of Fourth Avenue No barrels or stressed vegetation was observed.
- A vacant church is on Fourth Avenue. No signs of stressed vegetation or evidence of trespassers was observed.
- Historically, a dry cleaner and a garage were located upgradient of the Assessment Area.
- Portions of the Assessment Area have been used for commercial and industrial purposes since at least 1918. Industrial uses have included a lumber yard, salvage yard, flour mill, and petroleum product storage and distribution facility. Some of the commercial properties likely represent a lower risk for encountering potentially contaminated sites including a bakery, former church, gift shop, furniture store, and bakery. Additional details for select commercial properties that have greater potential for encountering contaminated sites are listed below:
 - A private car repair shop is north-adjacent to the Assessment Area. A fence was present, so current chemical use was not readily ascertainable. Additionally, vegetative stress or leaking containers were not readily observable.
 - A garage with vehicle repair materials and fluids (including one rusty 55-gallon drum) stored near the alley was noted at one residence immediately north of the Assessment Area at 414 First Street NE. No staining or distressed vegetation was observed from the public right-of-way.
 - A concrete pumping service (Giscon) is on Third Street NW. Heavy equipment was observed, no staining, concrete washouts, or stressed vegetation were observed.
 - o Approximately 20 trailer-mounted portable heaters, some heavy equipment, and a small used car lot, were observed in the fenced in area at Helm's & Mork's Storage. No barrels, leaks, or stained ground were observed.
 - o No car repairs were apparent at Taxi 9000, as no barrels, oil pans, or car repair parts were observed in the parking lot.

- An existing railroad is present east of the Third Street NE Bridge, and south of Fourth Avenue. Railroad ties are typically treated with creosote which can leach into soil and groundwater. Additionally, rail spurs are typically sprayed with herbicides to prevent significant vegetation growth.
- In nearby areas, potentially contaminated sites include:
 - o North of the Assessment Area, a 55-gallon metal drum and large plastic container were observed outside of a shop behind Philotechnics Ltd. Lawn mowing equipment and heavy equipment were also observed in the parking lot. No evidence of staining or leaking was observed. The containers appeared to be in good condition.
 - A commercial building resembling leased garages was observed north adjacent to the Assessment Area. No barrels or evidence of stained concrete were observed from the exterior.
 - About 200 feet north of the Assessment Area, a generator located to the west of Lowe's Printing was observed. No leaks or staining were observed in the vicinity.
 - The Assessment Area is north adjacent to existing rail lines that have been used since at least 1913.
 - Based on the geotechnical investigation, fill is present along the proposed location for the flood wall and levee near Fourth Avenue and debris was observed in some of the borings.

6.0 Conclusions

Barr performed this HTRW Assessment in conformance with the HTRW guidelines. Company qualifications, special terms, conditions, limitations, and exceptions that apply to the Assessment are described in Appendix G.

The following environmental risks were identified as having the potential to impact the Project:


- Due to the age of the buildings present in the Assessment Area, it is possible that hazardous building materials (such as asbestos-containing material (ACM) and lead-based paint) could have been used during construction. Also, older buildings could have had heating oil storage, wells, septic systems, or other concerns. Although the HTRW did not involve building walkthroughs or interviews with owners, an inventory of such items should be conducted in the future at buildings to be demolished and any identified environmental concerns should be addressed/abated/sealed/etc. prior to demolition in accordance with applicable local, state, and federal requirements.
- Debris is present in some areas in the shallow fill soil, including glass, brick, and asphalt fragments. If the Project involves excavation into these areas, then the excavated materials may require further evaluation to determine whether the extent of the debris represents a concern for reuse of the soil within the Project area, and/or for potential export to off-site locations. If areas of the excavation encounter significant concentration of debris, then it may be necessary to segregate the excavated debris materials from these areas for transport to a landfill. Excavation of debris areas should be monitored by an environmental professional to verify that the debris are consistent with the type of materials observed in the geotechnical investigations (glass, brick, asphalt).
- Some of the parcels east of Third Street NE have been used for industrial purposes since at least 1918, including a lumber yard, oil company, and flour mill. In addition, this area was listed in the regulatory report due to registered storage tanks and leaking storage tanks associated with Werner Oil Company, North Dakota Concrete Products, and Porter Brothers Salvage Yard, and a leaking storage tank associated with North Dakota Concrete Products.


The long-term industrial nature of the properties east of Third Street NE should be further assessed and investigated prior to finalizing the design for the Project or initiating construction. This will include site walkthroughs, interviews with the property owners, and subsurface environmental investigations. The assessment should target specific locations of historical environmental concerns (e.g., former tank locations) as well as areas planned for excavation as part of the Project.

If further assessment identifies contamination at these sites, then it is also recommended that a corrective action plan for managing contaminated soils during the Project be developed prior to finalizing the design for the Project or initiating construction.

In addition to the above risks, it is recommended that work crews implementing the Project always be alert to the possibility that unexpected hazardous substances or petroleum products may be encountered which were not identified by the HTRW Assessment, especially given the urban setting and long land-use history in the Assessment Area. Appendix H provides a Contingency Plan that can be used to guide actions in the event that unanticipated environmental conditions are encountered during the Project.

Figures







Mouse River Project

560



Initial Assessment Area
Assessment Area
Geotechnical Boring Locations

- SPT Boring
- SPT Boring (with Debris)

Test Pit Location (Houston)

- Test Pit Location
- Test Pit Location (with Debris)





Figure 4

INVESTIGATION LOCATIONS Mouse River Project



Appendices

Appendix A HTRW Documentation

Appendix A

HTRW Assessment Documentation

Fourth Avenue

Mouse River Enhanced Flood Protection Project Minot, North Dakota

Area Information

Township/range/section:	T155N, R83W, Sections 13, 23, 24
Area Use:	The Assessment Area is currently used for residences, industrial purposes, commercial buildings, and a city park The primary land use is permanent residences and commercial properties. Several homes were marked as "no trespassing by the City of Minot," and a large building that may have been a church was in the process of being vacated.
Approximate Levee Length:	Levee centerline 485 feet
	Floodwall centerline 2,380 feet
Zoning: The Assessment Area is zoned R1, single family, R3B, multifamily C1, limited commercial, and C2, general commercial, and M2, light industrial (Ref. 17)	

The properties included in the HTRW Assessment are shown on Figure 3. The Initial Assessment Area was originally established around planned Project features and a buffer of approximately 50 feet to account for temporary construction areas. In May, 2015, additional areas were added to the Initial Assessment Area, including east of Third Street NE and west of Broadway Street. These are collectively referred to as the "Assessment Area" throughout this appendix and report.

Utility Service

Municipal water supply:	City water comes from wells located in Minot that are screened in the Minot aquifer. Additional water comes from wells located 6 miles southeast of Minot		
	that are screened in the Sundre aquifer (Ref. 10).		
Property potable/process	Residences within the Assessment Area receive their water from the Minot		
water supply:	municipal water supply (Ref. 10). No wells are located in the Assessment Area		
	(Ref.13), nearby wells are shown on Figure 4.		
Historical water supplies:	Prior to connecting to Minot's water supply, residences within the Assessment		
	Area used private wells (Ref. 10). The City now requires all residents within the city		
	limits to be connected to Minot's water supply system (Ref. 10).		
Type of sanitary service:	Sanitary service is provided by Minot; however, private septic systems may be		
	hooked up to Minot's system (Ref. 10). No septic systems were encountered		
	during demolition of residences within the Assessment Area (Ref. 10).		
Onsite septic system or drainfields:	None reported (Ref. 10) or observed.		

Regulatory Data

Two regulatory database reports were obtained by Historical Information Gathers (HIG Report).

The HIG Report did not identify any sites with a regulatory listing within the Initial Assessment Area (Ref. 9). Three sites, the Werner Oil Company, North Dakota Concrete Products, and Porter Brothers Salvage Yard were identified in the regulatory report. Werner Oil Company and Porter Brothers have registered

storage tanks, and North Dakota Concrete Products is listed as having a leaking storage tank, with site cleanup complete in 1989.

All of the other listings, located within the Assessment Area or potentially upgradient of the Assessment Area were listed in the Facility Registry System (FRSND).

Assessment Area Land-Use History

The Assessment Area has mainly been used for residential housing since at least 1913 (Refs. 2, 3). The nonresidential uses identified in the Assessment Area include a gift shop and a vacant church. Historically, nonresidential uses included a lumber company, flour mill, and an oil company as shown on Figure 4 (Ref. 3). No demolition debris was evident in the Assessment Area during the site inspection visit performed as part of this HTRW Assessment (Ref. 11). The area has not changed significantly since 1913, with the exception of additional residential housing development over time, some of which has been demolished since the flood in 2011 (Ref. 3).

A portion of the Assessment Area has been used for industrial purposes since at least 1938. The nonresidential portion of the Assessment Area is currently used by a concrete pumping service (Giscon), Souris Valley Feed and Seed, Souris River Design, Helm's & Mork's Storage, a furniture store, and Taxi 9000.

The surrounding area includes residences, an electric cigarette shop (E-cig), a massage parlor (Body Brite), a hazardous materials and waste contractor business (Philotechnics Ltd), Sammy's Pizza, a realty company, churches, Lowe's Printing, McKinley Elementary, All Washed Up Laundromat, B&D Market, and leased commercial garages.

Nearby Area Land Use

Direction	Historical	Current
North	Undeveloped, residential, McKinley Public	Residential, McKinley Elementary School,
	School, dry cleaner (Refs. 1, 2, 3)	churches, commercial
South	Mouse River (Refs. 1, 2, 3)	Mouse River
East	Residential (Refs. 1, 2, 3, 9)	Residential
West Minot Water Works Station, Ice Cream		Commercial and Mouse River
	Company, church, Mouse River (Ref. 3)	

Assessment Area (Current and Historical)

Approximate Number	Types of Area		
of Structures	Structures	Issues Associated with Levee Construction	Notes
Residences and associated garages/sheds are apparent in the current aerial photograph and were observed onsite during the site inspection visit (Ref. 11). As of May 17, 2015 there are approximately 56 residential and commercial buildings present within the Assessment Area.	Residential and commercial	Any septic tanks, fuel tanks, transformers, hazardous building materials, wells, or remaining debris present at lots that are currently occupied and slated for demolition as part of the levee construction will need to be removed prior to floodwall and levee construction.	Some residential properties appear to have been recently demolished (Ref. 3)

Exterior Observations – Initial Assessment Area

Site inspection visits were performed within the Initial Assessment Area on March 17, 2015, and May 17, 2015; associated observations and methods are described in the following table. Photographs taken during the site inspection visits are in Appendix D. Building interiors were not inspected.

Observation Method	The inspector walked transects along the Mouse River from the Broadway Street		
	bridge to approximately the Home Sweet Home gift shop parking lot. The inspector		
	also drove along all public streets and alleys intersecting the Assessment Area.		
Access to the Assessment Area	Access was only available from public rights-of-way.		
Periphery of the Assessment	The Assessment Area is located north-adjacent to the Mouse River between		
Area	Broadway Street to the west and 3rd Street SNE to the east. Surrounding parcels		
	are owned by public and private entities.		
Ground surface cover:	Mixture of parking lots, residential lots, and paved or gravel driving/parking		
	surfaces. Vegetation immediately adjacent to river is not mowed.		
Filling, excavation, vegetative	None observed.		
stress, burned areas:			
Pits, ponds, and lagoons:	None observed.		
Stained soil or pavement: None observed.			
Wastewater, other liquid	None observed.		
discharge into a drain, ditch,			
stream or adjacent property:			
Wells:	None observed.		
Pipelines:	A 4-inch diameter PVC vent pipe in good condition was observed north of the		
	Mouse River near the Broadway Street bridge.		
Rail lines:	Burlington Northern Santa Fe Railroad is located south of the Mouse River and		
	Assessment Area. This railroad crosses the river near the east end of the		
	Assessment Area.		
Transformers:	One pole-mounted transformer was observed in the Assessment Area. No spills,		
	leaks, dents, or staining were observed.		
Other:	None observed.		

Exterior Observations – Assessment Area

A site inspection visit was performed within the Assessment Area on May 17, 2015; associated observations and methods are described in the following table. Photographs taken during the site inspection visit are in Appendix D. Building interiors were not inspected.

Observation Method	The inspector drove all public streets and alleys intersecting the Assessment Area.		
Access to the Assessment Area	Access was only available from public rights-of-way.		
Periphery of the Assessment Area	The Assessment Area is located north-adjacent to the Mouse River and Burlington Northern Santa Fe Railroad between 3 rd Avenue NE to the west and 6 th Street NE		
Ground surface cover:	to the east. Surrounding parcels are owned by public and private entities. Mixture of parking lots, residential lots, and paved or gravel driving/parking surfaces. Vegetation immediately adjacent to river is not mowed.		
Filling, excavation, vegetative None observed. stress, burned areas:			
Pits, ponds, and lagoons:	None observed.		
Stained soil or pavement:	None observed.		
Wastewater, other liquid	None observed.		
discharge into a drain, ditch,			
stream or adjacent property:			
Wells:	None observed.		
Pipelines:	None observed.		
Rail lines:	Burlington Northern Santa Fe Railroad was observed immediately south of the Mouse River and Assessment Area.		
Transformers:	Seven pole-mounted transformers and one electrical box were observed in the Assessment Area. Two additional electrical boxes and two pole-mounted transformer were observed adjacent to the Assessment Area. No spills, leaks, dents, or staining were observed.		
Other:	Car repair parts, including liquids and welding tanks, were observed in the alley of a derby car enthusiast's garage area (414 1st Street NE). The garage door was closed, so additional observations were not possible. No vegetative stress or staining of paved areas was observed.		
	Approximately 20 portable heaters (trailer units) and vehicles for sale were observed in the fenced in area near Helm's & Mork's Storage building. No vegetative stress or staining of paved areas was observed.		

USTs/ASTs/Outdoor Chemical Storage Areas

Type (AST,	Location, Size, Age, Condition,	Containment Devices/	Runoff Management/	Materials Currently
UST, Drums)	Registration	Structures	Sumps/Drains	Stored
AST	None observed.			
UST	None observed.			
Drums	Within the Initial Assessment Area, one rusty 55-gallon drum was observed at a derby car enthusiast's residential property. No obvious staining or distressed vegetation was observed from the right-of-way. (Ref. 11). North of the Assessment Area, one red metal 55-gallon drum, and one large plastic bin holding liquids were observed along with some lawn mowing equipment and heavy machinery at a shop behind Philotechnics Ltd. No staining of the nearby soil was observed. The containers were in good condition.	Unknown	Unknown	Unknown
Barrels	None observed.			
Cylinders	Two cylinders, one missing a cap, were observed at a derby car enthusiast's residential property. (Ref. 11)	Unknown	Unknown	Unknown; presumably welding gases.

Appendix B


Historical Documentation





2014








2009







2003







1995








1991








1979








1969







1961







1953








1946








1938





Map Type: Fire Insurance
Publisher: Sanborn Map Co.

Map Date: October 1926


Revised Date:
Republished:
Sheet Number: 2

1926

Minot, ND

HIG Project No.1513281






Map Type: Fire Insurance
Publisher: Sanborn Map Co.

Map Date: October 1926
Revised Date:
Republished:
Republished:
Sheet Number: 3

Minot, ND

HIG Project No. 1513281

HISTORICAL INFORMATION GATHERES.INC.



Map Type: Fire Insurance Publisher: Sanborn Map Co.

Map Date: October 1926 Revised Date: Republished:


Sheet Number: 9

1926

Minot, ND

HIG Project No.1513281





Map Type: Fire Insurance
Publisher: Sanborn Map Co.


Map Date: October 1926

Revised Date:
Republished:
Republished:
Sheet Number: 10

Minot, ND

HIG Project No. 1513281

HISTORICAL INFORMATION GATHERERS, INC.



Map Type: Fire Insurance Publisher: Sanborn Map Co.

Map Date: October 1926 Revised Date: Republished:


Sheet Number: 11

1926

Minot, ND

HIG Project No. 1513281





Map Type: Fire Insurance Publisher: Sanborn Map Co.


Map Date: October 1926

Revised Date: Republished: Sheet Number: 16 1926

Minot, ND

HIG Project No. 1513281






Map Type: Fire Insurance
Publisher: Sanborn Map Co.

Map Date: October 1926
Revised Date:
Republished:
Sheet Number: 17

Minot, ND

HIG Project No.1513281

HISTORICAL
INFORMATION
GATHERESS,INC.



Map Type: Fire Insurance Publisher: Sanborn Map Co.

Map Date: September 1918 Revised Date: Republished:


Sheet Number: 3

1918

Minot, ND

HIG Project No. 1513281






Map Type: Fire Insurance
Publisher: Sanborn Map Co.

Map Date: September 1918
Revised Date:
Republished:
Sheet Number: 4

Minot, ND

HIG Project No. 1513281

HISTORICAL INFORMATION GATHERES, INC.



Map Type: Fire Insurance
Publisher: Sanborn Map Co.

Map Date: September 1918


Revised Date:
Republished:
Sheet Number: 5

1918

Minot, ND

HIG Project No. 1513281





Map Type: Fire Insurance
Publisher: Sanborn Map Co.

Map Date: September 1918

Revised Date:


Revised Date:
Republished:
Sheet Number: 7

1918

Minot, ND

HIG Project No.1513281





Map Type: Fire Insurance
Publisher: Sanborn Map Co.

Map Date: September 1918


Revised Date:
Republished:
Sheet Number: 8

1918

Minot, ND

HIG Project No. 1513281






Map Type: Fire Insurance
Publisher: Sanborn Map Co.

Map Date: September 1918
Revised Date:
Republished:
Republished:
Sheet Number: 9

Minot, ND

HIG Project No. 1513281

HISTORICAL INFORMATION GATHERERS, INC.



Map Type: Fire Insurance Publisher: Sanborn Map Co.

Map Date: September 1918 Revised Date: Republished:


Sheet Number: 10

1918

Minot, ND

HIG Project No.1513281





Map Type: Fire Insurance Publisher: Sanborn Map Co.

Map Date: August 1913 Revised Date: Republished:


Sheet Number: 3

1913

Minot, ND

HIG Project No.1513281






Map Type: Fire Insurance
Publisher: Sanborn Map Co.

Map Date: August 1913 Revised Date: Republished: Sheet Number: 4 1913

Minot, ND

HIG Project No. 1513281





Map Type: Fire Insurance Publisher: Sanborn Map Co.

Map Date: August 1913 Revised Date: Republished:


Sheet Number: 5

1913

Minot, ND

HIG Project No.1513281





Map Type: Fire Insurance Publisher: Sanborn Map Co.

Map Date: August 1913 Revised Date: Republished:


Sheet Number: 6

1913

Minot, ND

HIG Project No. 1513281





Map Type: Fire Insurance Publisher: Sanborn Map Co.


Map Date: August 1913

Revised Date: Republished: Sheet Number: 7 1913

Minot, ND

HIG Project No.1513281





Map Type: Fire Insurance Publisher: Sanborn Map Co.

Map Date: August 1913 Revised Date: Republished:


Sheet Number: 8

1913

Minot, ND

HIG Project No. 1513281





Map Type: Fire Insurance Publisher: Sanborn Map Co.

Map Date: October 1907 Revised Date:

Republished:


Sheet Number: 1

1907

Minot, ND

HIG Project No.1513281





Map Type: Fire Insurance Publisher: Sanborn Map Co.


Map Date: October 1907

Revised Date: Republished: Sheet Number: 3 1907

Minot, ND

HIG Project No. 1513281





Map Type: Fire Insurance
Publisher: Sanborn Map Co.

Map Date: October 1907


Revised Date:
Republished:
Sheet Number: 6

1907

Minot, ND

HIG Project No.1513281





Map Type: Fire Insurance Publisher: Sanborn Map Co.

Map Date: September 1904 Revised Date:

Republished:

Sheet Number: 1

1904

Minot, ND

HIG Project No.1513281



Polk City Directories Now on the Internet @ www.citydirectory.com

® NEW NEIGHBOR	13	3RD ST SE - 4TH AVE NW
3RD ST SE Cont'd 1	47H AVE NE Cont'd 26 Caroline Patricia L ✓ 2	4TH AVE NW Cont'd 114 De Vries Carol L ✓ 4
2 Mehl Connie I ✓ 8	28 Edwards Cody 5	+ WALDERS ST BEGINS
4 Soine Rita R ✓ ② ④	31 Benson Karen M ✓ ⑦	+ N BROADWAY INTERSECTS + 3RD ST NW ENDS
BUSINESSES 79 HOUSEHOLDS 77	35 Sather Gary	+ 4TH ST NW CONTINUES
3RD ST SE (SURREY)	36 Rasmusson Gerald A ✓ ③	• ZIP CODE 58703 CAR-RT C009 400 Wood Reginald L & Betty L ✓ 20 🖨 (1939)
• ZIP CODE 58785 CAR-RT R001 201 Lukenbach Wayne & Roberta R ✓ 36 ♠ (1974)701-839-5468	37 Dionne Julius S 🗸 🔯701-385-4266	413 - 414 No Current Listing (2 Hses) 417 Pedersen Ronda ✓ (1939)
202 Siewert Gary & Linda L ✓ 🗇 📤 (1974)701-852-0859	38 Voigt Joyce M	419 Chernoff Suzanne K ✓ 20 📤 (1939)
207 Storkson Wayde A & Sarah ✓ @ ⑨ ♠ (1974) HOUSEHOLDS 3	207 Nelson Cody F & Jennifer ✔ @ ② ▲ (1952)701-385-4705 208 Livingston Sandra K ⑨ ▲ (1952)	422 Engleson Roderic F & Peggy M ✓ 20 ≜ (1900)701-839-5821 423 Koland Gerald R & Judith M ✓ 18 ≜ (1939)701-852-4610
	215 Michel Tory J ✓ 6 4 (1952)701-385-3457	426 Runyan Thomas A & Donna A ✓ 17 🖨 (1904)701-839-0024
3RD ST SW (MINOT) + 2ND AVE SW CONTINUES	220 Grosser Darcy L & Tammy J √ 7 ♠ (1952)701-385-3850 301 Bruner Jason A √ 🛭 ♠ (1952)	429 © Magandy Mona ≜ (1939) + 5TH ST NW INTERSECTS
• ZIP CODE 58701 CAR-RT C023 200 FIRST BAPTIST CHURCH churches ✓ @701-852-4533	BRUNER'S FENCING fence contractors ✓701-400-5054	504 Green Brad ✓
Holt Shirley ✓ 3	304 Brekhus Boyd ② ▲ (1952) 521 Westby Arlow & Marcella M 🗸 @ 20 ▲ (1948)701-385-4754	505 Garbe Robert K ✓ ⑨ ♠ (1939) 510 Carr James E & Carol I ✓ ⑤ ♠ (1905)701-838-3548
+ SUMMIT DR INTERSECTS + SUMMIT DR INTERSECTS	BUSINESSES 1 HOUSEHOLDS 19	DAKOTAH ROSE BED & BREAKFAST bed & breakfast accommodations ✓ @
+ WESTERN AVE INTERSECTS + 3RD AVE SW CONTINUES	4TH AVE NE (MINOT)-FROM 399 6TH ST NE	Jelleberg Robert ✓ 16
+ SUMMIT DR INTERSECTS	+ 4TH AVE NW CONTINUES + MAIN ST N INTERSECTS	+ 6TH ST NW INTERSECTS 600 4 Ofsthun Steve D [27]
• ZIP CODE 58701 CAR-RT C035 412 ☑ Rylander Dean A ✓ ▲ (1939)	• ZIP CODE 58703 CAR-RT C007 11 No Current Listing	608 Yester James R ✓ 28 ▲ (1948)
420 REHAB SERVICES alcoholism info/treatment ctrs ✓ @	+ 1ST ST NE INTERSECTS	610 Staniger Aaron T ✓ 10 ≜ (1930)
701-839-9679 TRINITY HEALTH MENTAL HEALTH mental health serv ✓ @	• ZIP CODE 58703 CAR-RT C006 109 - 117 No Current Listing (3 Hses)	618 Bechtold Margery M ✓ 22
	+ 2ND ST NE INTERSECTS	+ 7TH ST NW INTERSECTS
+ SUMMIT DR BEGINS	203 ⑤ Bagwell Jessica ✓ ⑥ Martin Thomas ✓	700 Ofsthun Josh ✓ 2 702 Cain Jeremy ✓ 4
800 Anderson Edward A & Myrtle E ✓ 43 ≜ (1952)701-839-7053 803 Kee Malena A ✓ 5	207 - 209 No Current Listing (2 Hses) 211 Mattson Michael H & Holly B ✓ @ [15] ♠ (1922)	706 Cooper Robert J & Barbara J ✓ 38 ♠ (1938)701-838-8580 708 Bolinger Noel A ✓ 51 ♠ (1939)
Kinard Eugene ✓ 5	400 MINOT WELDING CO welding ✓ @701-838-0513	Bolinger Hannah
Stevens Troy D ✓ ⑤ ≜ (1948) Stevens Malena	404 Feather Evangeline E ✓ 13 405 SOURIS RIVER DESIGNS & HOME home improvements ✓ @	712 Nicholes Nicole M 6 716 Frickson Derek ✓
804 Walter Edwin J ✓ 19	701-852-7605	720 Burandt Thomas (1939)
805 Prissel Chelsey J ✓	612 TARGET ROOFING INC roofing contractors ✓ @701-838-4482 614 TAMARACK NORTHLAND dry wall contrs equip/supl @	COMPLEAT MOTHER MAGAZINE publishers-magazine ✓ @701-852-2822
	701-509-3356 701 Jensen Larry D 9	+8TH ST NW INTERSECTS 800 Bradwisch Edwin L & Annette P ✓ 13 ≜ (1939)
Poole Dillon + A AVE SW INTERSECTS	Jensen Monique M	806 Prater Joseph R 16 ≜ (1939)
812 Rubbelke Nancy R & Robert J ✓ 24 ▲ (1946)701-838-3454	STEAM BRO PRO CLEAN RESTORATN carpet & rug cleaners ✓ @	809 Sullivan Wanda ③ 812 No Current Listing
820 ♥ Proudfit Heidi ✓ 825 ♥ Anderson Melissa ✓	706 No Current Listing + 8TH ST NE INTERSECTS	813 Coody Beverly A 🖺 🛦 (1936)
Duchsherer Matthew D ✓ @ 2	+ 9TH ST NE INTERSECTS	814 Fogarty Ryan L ✓ ⓑ 🖨 (1935) Fogarty Mike P
Duchsherer Samantha 830 A Ganje Daniel R ✓ 21	+ 10TH ST NE INTERSECTS + 3RD ST NE INTERSECTS	818 - 822 No Current Listing (2 Hses) 826 Schmalz Joseph B ✓ 21 ♠ (1965)
B May Priscilla J ✓ 22701-838-2334	1620 No Current Listing	Schmalz Loren M701-838-4836
C Houge Clyde H & Janell K 🗸 🗓	1640 LOWE'S FLORAL garden centers ✓701-838-2868 • ZIP CODE 58703 CAR-RT R008	+ 9TH ST NW INTERSECTS 900 Otis Dayna M ✓ 12 ≜ (1939)
831 Nettleton Gene E & Lori J ✔ @ 14 ≜ (1950)701-852-2479 840 No Current Listing ✔	8300 Dailey Joseph M & Paulette D ✓ @ IB ♠(1961)701-838-6822 + 27TH ST SE INTERSECTS	901 No Current Listing
+ 9TH AVE SW INTERSECTS	9200 LAFARGE NORTH AMERICA cement-whol ✓@701-852-8163	902 @ Fauque Eddy 905 - 906 No Current Listing (2 Hses)
901 Hoevenm Marcela ✓ 3 902 Muus Steven P 26 ♠ (1928)	9460 Burckhard Blaine A & Sonda M ✓ @ ⑥ ♠ (1976)701-838-4358 9690 Myers Raymond E ✓ Ⅰ ♠ (1966)701-838-7637	910 Lillis Matthew C & Cathy J ✓ ⑥ ♠ (1927) 915 Joyner Richard A & Lori ✓ @ 11 ♠ (1921)
906 ② Breitling Joel ✓ Woodard Kara M ✓ ②	BUSINESSES 7 HOUSEHOLDS 16	916 Blong Phillip L ✓ 4
912 Lucy Michael A & Nancy A ✓ 23 📤 (2000)	4TH AVE NW (BURLINGTON)	917 Cartier Brian M ✓ 33 📤 (1918) Cartier Steven B
+ 11TH AVE SW CONTINUES + 13TH AVE SW CONTINUES	• ZIP CODE 58722 CAR-RT R001 15815 Groninger Delwyn E & Karen M ✓ 19 ≜ (1975)701-725-4654	920 Sipma Shaun R ✓ 🗵 📤 (1936) Sipma Keri J
• ZIP CODE 58701 CAR-RT C017 1305 Weltikol Christoph B & Mandy M ✓ @ 111 ♠ (1950)	+ 156TH ST NW INTERSECTS HOUSEHOLDS 1	1000 No Current Listing
1316 Kolobakken Kelly ✓ ③ ▲ (1971)		1001 Hanson Jerry D √ 6 ♠ (1945)
Salgado David C ✓ 5 ♠ (1971) 1317 Brabandt Roger L & Juell K ✓ 40 ♠ (1956)701-839-6577	4TH AVE NW (DES LACS) • ZIP CODE 58733 CAR-RT R001	1004 Hartman Sashá ✓ ④
1318 Andrade Clyde M ✓ 5 ≜ (1971)701-858-9342	15501 Schaefer Gregg A ✓ 🛭 ੈ (1973) Schaefer Kari	1005 No Current Listing • ZIP CODE 58703 CAR-RT C019
1320 Rust Jason T & Teina M ✓ (1984)	+ 156TH ST NW INTERSECTS	1212 OAK PARK SHOPPING CTR shopping centers & malls C Mettler Carla 4
Burckhard Michelle M	16910 Schaefer Jeffery M ✓ @ 20 角 (1975) Schaefer Kacie L	1224 ADVANTAGE APPLIANCE & ELECT appliances-hshld- major-
Vinje Michaela	21515 SCHAEFER FARM nonclassified establishments ✓ @	dlrs ✓ @
1327 Peterson Amber E ✓ @ 4 1330 Henderson Stanton L & Barbara W ✓ @ 30 🖨 (1929)	Schaefer Sharon A & Richard R ✓ 20 4 (1972)701-725-4321	ALLEN REALTY CO REALTORS real estate ✓ @701-838-8400 1506 Collins Audrey O ✓ [到 ♠ (1927)701-838-4714
701-839-5058	+ 268TH ST NW INTERSECTS 23315 Kleven Peter A & Janice D ✓ 20 ▲ (1974)701-725-4380	1512 LOAF 'N JUG convenience stores ✓ @701-852-5331
1334 Orne Daniel J ✓ @ 15 ▲ (1950) 1335 Heinze Robert J ✓ 37 ▲ (1939)701-839-2919	BUSINESSES 1 HOUSEHOLDS 4	+ 16TH ST NW INTERSECTS 1602 B FRANCIS LAW OFFICE attorneys ✓ @701-837-8500
Heinze Douglas A	4TH AVE NW (KENMARE)-FROM 399 5TH ST NW	1609 ADULT LEARNING CTR schools ✓ @701-857-4488
BUSINESSES 3 HOUSEHOLDS 37	• ZIP CODE 58746 CAR-RT R002 402 Neubauer Randy R & Arlene M @ 16	MINOT ADULT LITERACY VOLUNTEER reading improvement instructio ✓ @701-852-2614
3RD ST SW (SURREY)	419 Wiedner Greg A ✓ 11 ♣ (1966) Wiedner James J	1620 ® Braun Jesse + 17TH ST NW BEGINS
• ZIP CODE 58785 CAR-RT R001 130 Steppe Ashley M ✓ (1974)	509 Kling Clifford ✓ 10 ≜ (1966)	1705 Berdahl Linda 6
Schriock Carissa ✓ 5 春 (1974)	Kling Eddy M	CORNERSTONE ADDICTION SVC marriage & family counselors ✓ @
132 No Current Listing 140 Sasse Jarvis J & Marla ✓ 10 ≜ (1974)	517 Pausig Richard S & Alice F ✓ 12 € (1966)701-385-3355	EATON & ASSOC psychologists ✓@701-839-0474
231 Reichenberger Megan ✓ 13 ≜ (1974)	520 Helmers Arlene J ✓ ⑨ ♠ (1966)	EDWARDS KATHY T nurses- practitioners ✓ @701-839-0474 VEAZEY BRYCE L social workers ✓701-839-0474
233 Langley Megan ② 239 Staggs Ryan E & Alyssa ✓ ⑧ ▲ (1974)701-852-6653	617 Peterson Thomas R & Margaret H ✓ 13 📤 (1966)	1720 BIBLE FELLOWSHIP CHURCH churches ✓ @701-838-0916 + 18TH ST NW INTERSECTS
241 No Current Listing HOUSEHOLDS 8	620 Zorn Chad G & Jennifer E ✓ ④ ♠ (1966)701-385-4079 HOUSEHOLDS 8	1800 ATO SERVICE video equip- serv & rpr ✔@701-837-9773
	4TH AVE NW (MINOT)	FATHER TIME'S WATCH REPAIR watches-rpr ✓ @701-838-0960
4TH AVE E (MAKOTI) • ZIP CODE 58756 CAR-RT H002	• ZIP CODE 58703 CAR-RT C007	GELLER FLOORING floor laying refinishing/resur ✓ @
11 Johnson Darrell G ✓ ⑤ ♠(1961)	12 No Current Listing 14 Jensen Heidi J 3	
	+ 1ST ST NW CONTINUES 100 West Teresa N ✓ @ 2	1800 C Steele Jim ✓ ᆁ 1801 RASMUSON APPRAISAL CONSULTANT appraisers ✓ @
4TH AVE NE (BERTHOLD) • ZIP CODE 58718 CAR-RT R001	102 Carlson Krystal ✓ @	
400 Feickert Brian ✓ ③ 🌢 (1972) HOUSEHOLDS 1	Lord Troy ✓ 2 103 GIFTS DAKOTA STYLE gift shops ✓ @701-852-5604	1809 Moseanko Mary F ✓ 🛽 📤 (1956)
	HOME SWEET HOME gift shops ✓ @701-852-5604	1810 No Current Listing
4TH AVE NE (KENMARE) • ZIP CODE 58746 CAR-RT R002	Johnson Mark L & Linda F ✓ [5]	1813 Moya Lori ③ 1820 ALICE'S BEAUTY SALON beauty salons ✔@701-838-3068
111 Benson Melanie ✓	110 © Hanks Tiffany ✓ Mesa V 国	L S DRYWALL INC dry wall contractors ✓ @701-858-1830 Sedevie Darrell H [20] ♠ (1956)
Nilsen Tina ✓ 2	Mesa V 9 111 Struckness Dale E & Marion J ✓ @ 38 ≜ (1945)701-838-7398	Sedevie Darrell H <u>[20]</u> ≜ (1956) Sedevie Shirley M
		•

NEW NEIGHBOR	13	3RD ST SE - 4TH AVE NE
RD ST SE Cont'd	3RD ST SE Cont'd	3RD ST SW Cont'd 1324 O'Brien William J & Olga 25 701-858-8999
WARD COUNTY EMERGENCY MGMT county government	819 Ness Leo 823 Samuelson Reuben W & Stacy L 25 ■	1327 No Current Listing
WARD COUNTY EXTENSION SVC government	701-839-3257	1330 Henderson Stanton L & Barbara W 26 ≜
offices-county	825 McLeod Louis E Jr & Ernestine E 18 ♠701-852-4817	
offices-county701-857-6450	826 Fraley James A & Barbara K 36 ▲701-838-6843	1335 Heinze Robert J 33 ▲
WARD COUNTY FEDERAL & STATE government offices-county	• ZIP CODE 58701 CAR-RT C004 900 Lyon John M & Carolyn R ③ ▲701-852-2005	Heinze Douglas A701-839-2919 + 14TH AVE SW INTERSECTS
WARD COUNTY FLOOD PLAIN ZONING county	901 Carpenter Marshall 2	BUSINESSES 1 HOUSEHOLDS 30
government	905 Carpenter Sara J 5	3RD ST SW (SURREY)
WARD COUNTY JAIL county govt701-857-6530 WARD COUNTY JUVENILE COURT county	Knodel Kay	 ZIP CODE 58785 CAR-RT R001
government- courts701-857-6650	908 Williams Doris M 32701-838-1086	114 Volk Richard C 27 ▲
WARD COUNTY JUVENILE DETENTION government offices-county701-857-6518	909 Borgen Byron J 7	132 ® Baustad Corey ≜
WARD COUNTY LAND RECORDS government	913 No Current Listing	© Boucher Corey A701-852-7461
offices-county	916 ® Vernon Daniel & Amie701-837-8819 919 Thomason Patti L <u>⑨</u>	140 Sasse Jarvis J 🗟 🖍
offices-county701-857-6477	920 Haberman Donald S & Madonna S 23 ▲	231
WARD COUNTY NDSU EXTENSION government offices-county701-857-6444		239 Staggs Ryan E & Alyssa 🗐 📤
WARD COUNTY PASSPORTS government offices-	925 Roberts Dennis N & Elizabeth A 16 ≜701-839-1676	HOUSEHOLDS 8
county	926 Saltsman Mary 43 🛦701-839-5925	4TH AVE E (MAKOTI)
WARD COUNTY PERSONNEL government offices- county701-857-6499	1000 No Current Listing 1006 Tiller George R 24 ▲701-839-5941	• ZIP CODE 58756 CAR-RT H002
WARD COUNTY PROPERTY TAX county government	1008 Welder Paula A 8	81 Anderson Joel HOUSEHOLDS 1
	2 Seabolt Paula A 7 ▲	
county701-857-6404	1012 © Cree Matthew J ≜ 1016 © Tompkins Becky	4TH AVE NE (KENMARE)-FROM 399 4TH ST NE
WARD COUNTY REAL ESTATE RCRDNG	1020 Sande Jacky A & Jacqueline A 18 ♠	NORTH + 4TH AVE SE BEGINS
government offices-county701-857-6411 WARD COUNTY REAL ESTATE TAX county	1106 No Current Listing 1108 Schalesky Marty D & Carol J 24 ♠701-852-8710	+ E DIVISION ST CONTINUES
government701-857-6426	• ZIP CODE 58701 CAR-RT C029	• ZIP CODE 58746 CAR-RT R002 111 © Struck Gerhardt701-385-4376
WARD COUNTY RECORDER government offices- county701-857-6410	1704 Laqua Richard W & Cecilia M 3 ♠701-838-6727 1705 Ringdahl Edwin J 15 ♠701-839-5704	27 Stroklund April D701-385-3383
WARD COUNTY SHERIFF sheriff701-857-6500	1710 Haberlack Paul R & Elaine M 34701-838-7958	30 Garman Hildegarde 7701-385-4916 31 Benson Karen M 3701-385-3129
WARD COUNTY SHERIFFS DEPT sheriff701-857-6516	1711 Price Terry C & Sandy R 22701-838-4854	33 Chametzki Arvid L & Constance M 4
WARD COUNTY SUPERINTENDENT schools	1715 Nissen Ronald D & Amy M ☑ ▲701-852-8880 1716 Ressler Wilbert F & Barbara E 33 ▲701-839-4535	701-385-3406
	1721 Klimpel Vernon L & Ione L 26 ▲701-839-8244	36 Jorgenson Harriette B 39701-385-4429 37 Dionne Julius S 13701-385-4266
WARD COUNTY TREASURER county government701-857-6420	1722 Nitsch Paul F & Karen L 33701-838-7351	+ 2ND ST NE INTERSECTS
WARD COUNTY UNIFORM COMMERCIAL	1727 Eskelson Raymond H & Evelyn I 8 1728	204 ② Krueger M
government offices-county701-857-6412 WARD COUNTY VETERANS SVC government	1735 Belgard Vickie A 4	207 & Desjardins Chad & Donna
offices-county701-857-6492	BUSINESSES 69 HOUSEHOLDS 70	220 Grosser Darcy L 14
ZIP CODE 58701 CAR-RT C008 07 ANDERSON MARY drug abuse/addiction info/trea	3RD ST SE (SURREY)	+ 3RD AVE NE INTERSECTS 301 Bruner Jason A 4
701-857-2480	• ZIP CODE 58785 CAR-RT R001 201 Lukenbach Wayne & Roberta R 32 ▲701-839-5468	+ 4TH ST NE INTERSECTS
Duchsherer Jeanie	202 Lesmann Vernon E 5 ▲	521 Westby Arlow & Marcella M 1
Fischbach Arie 2 JEANOTTE FRANK drug abuse/addiction info/trea	Siewert Gary ③ ▲ 207 Storkson Wayde & Sarah ⑤ ▲701-858-9355	+ 6TH ST NE INTERSECTS + 7TH ST NE INTERSECTS
701-857-2480	HOUSEHOLDS 4	+ 8TH ST NE CONTINUES + 8TH ST NE CONTINUES
KIDNEY BRIETTA drug abuse/addiction info/trea701-857-2480	3RD ST SW (MINOT)-FROM 201 8TH AVE SW SOUTH	+ BROADWAY AVE N ENDS
KRAUSE SKIP drug abuse/addiction info/trea	+ 1ST AVE SW CONTINUES	HOUSEHOLDS 13
	+ 2ND AVE SW CONTINUES + 2ND AVE SW ENDS	4TH AVE NE (MINOT)-FROM 399 6TH ST NE
serv701-852-3799	+ 2ND AVE SW INTERSECTS	+ 4TH AVE NW CONTINUES + MAIN ST N INTERSECTS
SANDBO SHERMAN drug abuse/addiction info/trea701-857-2480	+ 2ND AVE SW CONTINUES	
	◆ ZID CODE 58701 CAR-RT C013	• ZIP CODE 58703 CAR-RT C007
THOMAS CHERYL drug abuse/addiction into/trea	ZIP CODE 58701 CAR-RT C013 200 FIRST BAPTIST CHURCH churches701-852-4533	11 Adkins Emily ■
THOMAS CHERYL drug abuse/addiction info/trea701-857-2480	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS	11 Adkins Emily Adkins Robert J
THOMAS CHERYL drug abuse/addiction info/trea701-857-2480 TRINITY ADDICTION TREATMENT alcoholism info/	200 FIRST BAPTIST CHURCH churches701-852-4533	11
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 58701 CAR-RT C035	11
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS ■ ZIP CODE 58701 CAR-RT C035 412 Haugen Jenifer S ③ ▲	11
THOMAS CHERYL drug abuse/addiction info/frea 701-857-2480 TRINITY ADDICTION TREATMENT alcoholism info/ treatment ctrs	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS ■ ZIP CODE 58701 CAR-RT C035 412 Haugen Jenifer S ③ ▲ Haugen Jacob T + BURDICK EXPY W INTERSECTS	11
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS ■ ZIP CODE 58701 CAR-RT C035 412 Haugen Jenifer S Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS	11
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS ● ZIP CODE 58701 CAR-RT C035 412 Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E 39 701-839-7053 803 Stevens Troy D & Malena 701-852-7240	11
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS ● ZIP CODE 58701 CAR-RT C035 412 Haugen Jenifer S ③ ▲ Haugen Jenifer S ④ Haugen Jenifer S ④ Haugen Jenifer S ④ S Ø Stevens Troy D & Malena ▲	11
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS ● ZIP CODE 58701 CAR-RT C035 412 Haugen Jenifer S ③ ▲ Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E ③ ▲701-839-7053 803 ⑤ Stevens Troy D & Malena ▲701-852-7240 804 No Current Listing 805 ⑤ St Croix Casey J ▲	11
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS ● ZIP CODE 58701 CAR-RT C035 412 Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E 39 701-839-7053 803 Stevens Troy D & Malena 701-852-7240 804 No Current Listing 805 St Croix Casey J 809 Poole Gloria M 13 Poole Michelle	11
THOMAS CHERYL drug abuse/addiction info/trea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS ● ZIP CODE 58701 CAR-RT C035 412 Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E 39 701-839-7053 803 Stevens Troy D & Malena701-852-7240 804 No Current Listing 805 St Croix Casey J 809 Poole Gloria M 13 Poole Michelle + A AVE SW INTERSECTS	11
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 58701 CAR-RT C035 412 Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E 39 ♠701-839-7053 803 ₺ Stevens Troy D & Malena ♠	11
THOMAS CHERYL drug abuse/addiction info/trea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 58701 CAR-RT C035 412 Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E 39 ♠701-839-7053 803 ⑤ Stevens Troy D & Malena ♠701-852-7240 804 No Current Listing 805 ⑥ St Croix Casey J ♠ 809 Poole Gloria M [13] Poole Michelle + A AVE SW INTERSECTS 812 Rubbelke Nancy R & Robert J 20 ♠701-838-3454 820 Hulm Ricky L [10] ♠	11
THOMAS CHERYL drug abuse/addiction info/trea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 55701 CAR-RT C035 412 Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E 39 ♠701-839-7053 803 ₺ Stevens Troy D & Malena ♠701-852-7240 804 No Current Listing 805 ₺ St Croix Casey J ♠ 809 Poole Gloria M 13 Poole Michelle + A AVE SW INTERSECTS 812 Rubbelke Nancy R & Robert J 20 ♠701-838-3454 820 Hulm Ricky L 10 ♠	11
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 58701 CAR-RT C035 412 Haugen Jenifer S ③ ▲ Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E ③ ▲701-839-7053 803 ⑤ Stevens Troy D & Malena ▲701-852-7240 804 No Current Listing 805 ⑥ St Croix Casey J ▲ 809 Poole Gloria M 113 Poole Michelle + A AVE SW INTERSECTS 812 Rubbelke Nancy R & Robert J ② ▲701-838-3454 820 Hulm Ricky L 10 ▲	11
THOMAS CHERYL drug abuse/addiction info/trea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 55701 CAR-RT C035 412 Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E 39 ♠701-839-7053 803 ₺ Stevens Troy D & Malena ♠701-852-7240 804 No Current Listing 805 ₺ St Croix Casey J ♠ 809 Poole Gloria M 13 Poole Michelle + A AVE SW INTERSECTS 812 Rubbelke Nancy R & Robert J 20 ♠701-838-3454 820 Hulm Ricky L 10 ♠	11
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 55701 CAR-RT C035 412 Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E 39 ♠701-839-7053 803 ₺ Stevens Troy D & Malena ♠701-852-7240 804 No Current Listing 805 ₺ St Croix Casey J ♠ 809 Poole Gloria M 13 Poole Michelle + A AVE SW INTERSECTS 812 Rubbelke Nancy R & Robert J 20 ♠701-838-3454 820 Hulm Ricky L 10 ♠	11
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 55701 CAR-RT C035 412 Haugen Jarifer S ③ ♠ Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E ③ ♠701-839-7053 803 ♠ Stevens Troy D & Malena ♠701-852-7240 804 No Current Listing 805 ♠ St Croix Casey J ♠ 809 Poole Gloria M 13 Poole Michelle + A AVE SW INTERSECTS 812 Rubbelke Nancy R & Robert J 20 ♠701-838-3454 820 Hulm Ricky L 10 ♠	11
THOMAS CHERYL drug abuse/addiction info/trea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 58701 CAR-RT C035 412 Haugen Jenifer S	11
THOMAS CHERYL drug abuse/addiction info/trea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 58701 CAR-RT C035 412 Haugen Jenifer S ③ ▲ Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E ③ ▲701-839-7053 803 ⑤ Stevens Troy D & Malena ▲701-852-7240 804 No Current Listing 805 ⑥ St Croix Casey J ▲ 809 Poole Gloria M 139 Poole Michelle + A AVE SW INTERSECTS 812 Rubbelke Nancy R & Robert J ② ▲701-838-3454 820 Hulm Ricky L 1 ⑥ ▲	11
THOMAS CHERYL drug abuse/addiction info/trea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 58701 CAR-RT C035 412 Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E 39 ♠701-839-7053 803 ጭ Stevens Troy D & Malena ♠701-852-7240 804 No Current Listing 805 ጭ St Croix Casey J ♠ 809 Poole Gloria M 13 Poole Michelle + A AVE SW INTERSECTS 812 Rubbelke Nancy R & Robert J 20 ♠701-838-3454 820 Hulm Ricky L 10 ♠	11
THOMAS CHERYL drug abuse/addiction info/trea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 58701 CAR-RT C035 412 Haugen Jenifer S	11
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 55701 CAR-RT C035 412 Haugen Jacob T	Adkins Robert J
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 58701 CAR-RT C035 412 Haugen Jenifer S ③ ▲ Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E ③ ▲701-839-7053 803 ⑤ Stevens Troy D & Malena ▲701-852-7240 804 No Current Listing	Adkins Robert J
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 55701 CAR-RT C035 412 Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E 39 ▲701-839-7053 803 ⑤ Stevens Troy D & Malena ▲701-852-7240 804 No Current Listing 805 ⑥ St Croix Casey J ▲	Adkins Emily ▲ Adkins Nobert J Bannister Sheryl A 15 J-N-T SECURITY SVC security guard & patrol serv 701-852-1562 199 Arndt Tammy L ③ 1701-838-6682 115 Wickman Joseph P 199 ▲ 701-838-4784 117 No Current Listing 209 Barton Wilson Sacha 701-839-5150 207 No Current Listing 209 Barton Willard E ② 701-858-0791 211 Mattson Michael H & Holly B 1 ■ 2IP CODE 58703 CAR-RT C006 308 CONNOLE & SOMERVILLE HEATING air conditioning contrs & sys 701-839-7944 400 MINOT WELDING CO welding 405 © Lebrum David R ▲ SOURIS RIVER DESIGNS & HOME home improvements 701-838-482 + 7TH ST NE INTERSECTS 701 A-1 STEAM BROTHERS carpet & rug cleaners 701-839-5466 TIP TOP MOBILITY wheel chair lifts & ramps 701-838-2181 + 8TH ST NE INTERSECTS + 10TH ST NE INTERSECTS + 10TH ST NE INTERSECTS + 10TH ST NE INTERSECTS + 3RD AVE NE INTERSECTS 1620 No Current Listing 1640 LOWE'S GARDEN CTR garden centers
THOMAS CHERYL drug abuse/addiction info/frea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 58701 CAR-RT C035 412 Haugen Jenifer S ③ ▲ Haugen Jacob T + BURDICK EXPY W INTERSECTS • ZIWMIT DR BEGINS 800 Anderson Edward A & Myrtle E ③ ▲701-839-7053 803 ⑤ Stevens Troy D & Malena ▲701-852-7240 804 No Current Listing 805 ⑥ St Croix Casey J ▲ 809 Poole Gloria M 13 Poole Michelle + A AVE SW INTERSECTS 812 Rubbelke Nancy R & Robert J ② ▲701-838-3454 820 Hulm Ricky L 10 ▲701-838-3454 825 Hanson Blake R & Melissa S ⑥ ▲701-838-5880 830 A Ganje Daniel R 177	Adkins Robert J
THOMAS CHERYL drug abuse/addiction info/trea	200 FIRST BAPTIST CHURCH churches701-852-4533 + WESTERN AVE INTERSECTS + WESTERN AVE CONTINUES + 3RD AVE SW INTERSECTS • ZIP CODE 58701 CAR-RT C035 412 Haugen Jaroifer S ③ ▲ Haugen Jacob T + BURDICK EXPY W INTERSECTS + SUMMIT DR BEGINS 800 Anderson Edward A & Myrtle E ③ ▲701-839-7053 803 ⑤ Stevens Troy D & Malena ▲701-852-7240 804 No Current Listing 805 ⑥ St Croix Casey J ▲ 809 Poole Gloria M 13 Poole Michelle + A AVE SW INTERSECTS 812 Rubbelke Nancy R & Robert J 20 ▲701-838-3454 820 Hulm Ricky L 10 ▲	Adkins Robert J

4TH AVE NE - 4TH AVE SW	14	▲ HOMEOWNER
4TH AVE NE Cont'd 9460 Burckhard Blaine A & Sonda M ② ▲701-838-4358	4TH AVE NW Cont'd Hildenbrand Dylan J	4TH AVE NW Cont'd
9470 No Current Listing	813 Coody Beverly A	1924 Beechie Rebecca DAIRY QUEEN ice cream parlors701-852-6067
9690 Bradwisch Wayne A & Vivian C 3701-839-5751 + 128TH ST NW BEGINS	814 © Fogarty Ryan L ≜	+ 20TH ST NW CONTINUES 2010 BODY WRAP STUDIO & MORE body wrap salons
BUSINESSES 8 HOUSEHOLDS 16	818 Linington Geneva H 24 ▲701-839-2477 822 Scheeler Robert J & Janeen 34 ▲701-838-6370	701-852-9009
4TH AVE NW (BURLINGTON) • ZIP CODE 58722 CAR-RT R001	826 Schmalz Joseph B 17 ▲701-852-7842	DIGITAL ALBUMS video production & taping serv701-833-5467
15815 Groninger Delwyn E & Karen M 🔟 📤	Schmalz Loren M701-852-7842 900 Otis Dayna M 📵	KONDOS INSURANCE insurance701-852-1673 NATIONWIDE INSURANCE insurance
+ 156TH ST NW INTERSECTS	901 No Current Listing	701-852-8002
HOUSEHOLDS 1	902 © Olson Casey R 905 © Buee Jessica M	NATIONWIDE PROVIDENT financial planning consultants701-852-8002
4TH AVE NW (DES LACS)-FROM 401 170TH ST NW + 156TH ST NW INTERSECTS	906 Latour Kristina A 3 910 Lillis Matthew C 2 ▲ 701-858-7576	Thorson Mark ▲ 101 ORVIK MICHAEL CPA accountants
 ZIP CODE 58733 CAR-RT R001 	Lillis Cathy J701-858-7576	701-852-8850
16910 Schaefer Jeffery M & Julie L 16 ▲701-725-4600 + 254TH ST NW INTERSECTS	915 Joyner Richard A ☑	 ZIP CODE 58703 CAR-RT C019 2021 AMERICAN RED CROSS social serv & welfare org
21515 Schaefer Sharon A & Richard R 16 ▲	916 © Lucas Geoffrey M ▲ 917 Cartier Rene A 29 ▲	701-852-2828
+ 268TH ST NW BEGINS	Cartier Steven B701-838-5269	• ZIP CODE 58703 CAR-RT C034 2022 Moore Billi B
+ 268TH ST NW BEGINS 23315 © Borud Bessie J	920 Sipma Shaun R ຟ ▲ Sipma Maren J	+ 21ST ST NW INTERSECTS + 21ST ST NW INTERSECTS
Kleven Peter A & Janice D 16701-725-4380	1000 Higgins Verlin L 31 ▲701-839-5887	2100 BUETTNER RENTALS washing mach dryers/ironers
HOUSEHOLDS 4	1001 ® Brandt Tammy 1004 No Current Listing	GRANITE SPRING WATER & ICE CO ice-mfrs
4TH AVE NW (KENMARE)-FROM 399 5TH ST NW ◆ ZIP CODE 58746 CAR-RT R099	1005 Williams Shanda M 6 ◆ ZIP CODE 58703 CAR-RT C019	
409 © Lucy John & Nicole	1122 KAFFEE KIOSK coffee shops701-838-2169	701-839-1293
509 Kling Clifford 6	1124 RIVIERA LOUNGE casinos701-839-2027 1212 INSTITUTE OF DANCE & BALLET dancing	2116 MARRIAGE CLINIC marriage & family counselors701-838-2442
Kling Eddy M	instruction	NORTH PRAIRIE PSYCHOLOGICAL psychologists701-838-2442
	B VIDEO MAGIC video tapes & discs701-838-4544	2120 Kelly Elizabeth A 3 ▲701-852-6196
520 Helmers Arlene J 🗟 📤701-385-4865	1224 ADVANTAGE APPLIANCE & ELECT appliances- hshld- major-dirs701-838-9400	+ 22ND ST NW INTERSECTS 2200 Price Dale L & Sharon D 20 ▲701-839-6610
+ 6TH ST NW INTERSECTS 620 ௵ Weigel Brian J ▲	1300 A A & A INVESTMENT real estate701-839-6600 ALLEN REALTY CO REALTORS real estate	PRICE UPHOLSTERY auto seatcovers tops/ upholster701-838-3192
+ 7TH ST NW INTERSECTS HOUSEHOLDS 6	BEST BROADWAY INVESTORS industrial	• ZIP CODE 58703 CAR-RT C019
4TH AVE NW (MINOT)	developments701-838-1592 OAK PARK SHOPPING CTR shopping centers &	2209 ST MARK'S LUTHERAN CHURCH churches701-839-4663
• ZIP CODE 58703 CAR-RT C007	malls 1400 No Current Listing	• ZIP CODE 58703 CAR-RT C034 2212 Mueller Kirby G [23] ▲
12 Guthrie Michael D & Trisha K A 1/2 No Current Listing	A SERVICE SHOE SHOP shoe & boot rpr	+ 23RD ST NW INTERSECTS
100 @ Lord Ronald H 102 No Current Listing	701-838-1722 1500 BOB TIMM REALTOR real estate701-720-8513	• ZIP CODE 58703 CAR-RT C019 2309 Peterson Dennis E & Mary A 37 ♠701-838-5536
103 GIFTS DAKOTA STYLE gift shops701-852-6732	Domsten Doug D701-839-0669 OAK PARK THEATER theatres-movie	+ 24TH ST NW INTERSECTS 2405 No Current Listing
HOME SWEET HOME gift shops701-852-5604 D Johnson Mark L & Linda F	701-852-7469	2409 Mackey Leroy B & Helen L 19 701-838-6065
105'HOUSE NEXT DOOR antiques-dirs701-852-5625 Wood Betty L [16]	1506 Collins Audrey O 15 ▲701-838-4714 1507 No Current Listing	+ 25TH ST NW INTERSECTS 2505 Seney Arnold R & Marilyn J ③ ▲701-839-1483
106 THAT'S IT antiques-dlrs701-858-1926	1508 Merck Cecilia M ဩ ▲701-839-3976 1509 Grosche Donald A & Sharon M ဩ ▲	2509 Rollings Steven M
110 B No Current Listing 111 Struckness Dale E & Marion J 34 701-838-7398	701-838-8058	+ 26TH ST NW CONTINUES
114 ® De Vries Carol L701-837-8860 304 ® Boyce Jeremy ≜	1516 LOAF N' JUG convenience stores701-852-5331 • ZIP CODE 58703 CAR-RT C034	 ZIP CODE 58703 CAR-RT R006 2705 DAVISON LARSON ARCHITECTS architects
RE/MAX real estate701-839-1999	1602 LOVE ON A LEASH pet washing & grooming701-837-5508	+ 28TH ST NW INTERSECTS
● ZIP CODE 58703 CAR-RT C009 400 ® Weed Betty	• ZIP CODE 58703 CAR-RT C019 1609 ADULT LEARNING CTR schools701-857-4488	3110 Hand David E ▲
Wood Reginald L & Lynn R 16 ▲701-838-8885 413 - 414 No Current Listing (2 Hses)	MINOT ADULT LITERACY VOLUNTEER reading	3120 Holter Glen A 32 ▲
417 Burtman Jerald L 18701-839-5039	improvement instructio701-852-2614 • ZIP CODE 58703 CAR-RT C034	3200 MINOT PÁVING CO INC road building contractors701-852-0558
419 Chernoff Harvey N & Suzanne K 6 ▲ 422 Engleson Roderic F & Peggy M 16 ♠701-839-5821	1620 MIDWEST TIRE & MUFFLER auto rpr & serv	3205 Alm David O 22 ▲
423 No Current Listing 426 Runyan Thomas A 13	• ZIP CODE 58703 CAR-RT C019	ORHEIM-ALM CONSTRUCTION geni contractors701-839-1413
429 No Current Listing	1705 Berdahl Linda 2 CORNERSTONE ADDICTION SVC marriage &	3305 GRAVEL PRODUCTS INC sand & gravel701-838-8888
504 Wallin Julianne M 27	family counselors701-839-0474 DARVEAUX-EATON & ASSOC psychologists	MINOT BUILDERS SUPPLY trucking701-838-5624
510 @ Carr James E & Carol I701-838-3548 DAKOTAH ROSE BED & BREAKFAST bed &	701-839-0474	NIESS ENTERPRISES tool & die makers701-857-6366
breakfast accommodations701-838-3548	Eaton Timothy T ② ◆ ZIP CODE 58703 CAR-RT C034	PUMPCO ENERGY SVC INC oil field serv701-838-1214
JIM'S PAINTING & PAPERHANGING painters701-833-7388	1720 BIBLE FELLOWSHIP CHURCH churches701-838-0916	3504 CONCRETE MOBILE LLC concrete- ready mixed
• ZIP CODE 58703 CAR-RT C003 600 1 @ Jesser Aidan S	MENNONITE BRETHREN CHURCH churches	+ COUNTY ROAD 15 W INTERSECTS
4 Ofsthun Steve D 23701-838-5827	701-838-0916 1800 ATO SVC video equip- serv & rpr701-837-9773	4101 Anderson Dennis W & Donna M 14 ▲701-852-5215
608 Yester James R 24	FATHER TIME'S WATCH REPAIR watches-rpr701-838-0960	4104 HISTORICAL PAINTING & HARDWOOD painters
618 Bechtold Randal R 1	• ZIP CODE 58703 CAR-RT C019	BUSINESSES 61 HOUSEHOLDS 89
620 Steeves Judy M [6] ▲ 700 ❷ Edwards John	1801 RASMUSON APPRAISAL CONSULTANT appraisers701-852-4861	4TH AVE SE (KENMARE)-FROM 399 E DIVISION ST
Edwards Rebecca	1809 Moseanko Mary F ③	SOUTH + 4TH AVE NE INTERSECTS
702 @ Cain Elizabeth Cain Jeremy	1810 KADRMAS LEE & JACKSON engineers- consulting	• ZIP CODE 58746 CAR-RT R099
Westerfield John R Jr	• ZIP CODE 58703 CAR-RT C019	203 NORRIE'S INC heating contractors701-385-4748 BUSINESSES 1
706 Cooper Robert J & Barbara J 34	1813 ③ Anderson William C ▲ • ZIP CODE 58703 CAR-RT C034	4TH AVE SE (MINOT)
712 Nicholes Brian 2 Nicholes Nicole	1820 ALICE'S BEAUTY SALON beauty salons	• ZIP CODE 58701 CAR-RT C011
716 Brevig Gary D & Lois E 16 ▲	RED'S CUSTOM LEATHER leather goods-rpr	2721 NORTH CENTRAL FEED & SEED INC feed-dirs701-838-1728
720 COMPLEAT MOTHER MAGAZINE publishers- magazine701-852-2822		3400 BEETER TRUCKING trucking701-839-1523 BUSINESSES 2
McLaughlin Timothy J & Jody 26 701-852-2822 800 Bradwisch Edwin L & Annette ⑨ 701-839-1494	Sedevie Darrell H 16 ▲	4TH AVE SW (MINOT)
806 Skar Travis 2 ▲	 ZIP CODE 58703 CAR-RT C019 	• ZIP CODE 58701 CAR-RT C023
Skar Cassandra 809 No Current Listing	1909 Westmeyer Todd R 5	1404 Marshall Craig L & Debora L 15 ♠701-838-1015 1405 Hankla Winifred A & Walfrid B 38 ♠701-852-4500
812 Hildenbrand Patty L	• ZIP CODE 58703 CAR-RT C034	1501 Messmore Dagny V 12 ▲

4TH AVE SE INTERSECTS

ZIP CODE 58746 CAR-RT R002 111 25 No Current Listing 31 Brekhus Hannah 15701-385-4776 31 Brekhus Ross D701-385-4776

+ RAILROAD CHOSSES
+ 100TH ST NW INTERSECTS
+ 100TH ST NW CONTINUES
+ 114TH ST NW INTERSECTS
+ 128TH ST NW INTERSECTS
+ 128TH ST NW CONTINUES
• ZIP CODE 58722 CAR-RT R001 15815 Groninger Delwyn E & Karen M 10 ▲ + 156TH ST NW BEGINS **HOUSEHOLDS 1**

4TH AVE NW (DES LACS)-FROM 401 170TH ST

+ 156TH ST NW BEGINS + 170TH ST NW INTERSECTS + 184TH ST NW INTERSECTS

511 No Current Listing 512 Hoffer Jamie J 3701-852-0668

701-837-1629

5TH AVE SE CONTINUES 510 @ Gasiewski Patryk

529 No Current Listing

2ND AVE SE BEGINS

+ 1ST AVE SW CONTINUES
• ZIP CODE 58701 CAR-RT C013

SOUTH

3RD ST SW (MINOT)-FROM 299 AVENUE A

© NEW NEIGHBOR

4TH AVE NW Cont'd + 184TH ST NW CONTINUES • ZIP CODE 58733 CAR-RT R001 16910 Schaefer Jeffery M & Julie L 11

+ 5TH ST NW INTERSECTS • ZIP CODE 58746 CAR-RT R002 517 Pausig Richard S & Alice F 3 •

620 No Current Listing + 7TH ST NW INTERSECTS + 8TH ST NW INTERSECTS + 9TH ST NW INTERSECTS

12 Guthrie Michael D & Trisha K 2 14 1/2 No Current Listing + 1ST ST NW INTERSECTS + 1ST ST NW CONTINUES 100 1/2 No Current Listing 102 @ Hutcheson Summe 103 HOME SWEET HOME gift shops

21515 Schaefer Richard R & Sharon A 8 .

4TH AVE NW (KENMARE)-FROM 425 5TH AVE NW NORTH

701-385-3355
520 No Current Listing
+ 6TH ST NW INTERSECTS

4TH AVE NW (MINOT)-FROM 6425 HIGHWAY 2 AND 52 W WEST + 4TH AVE NE CONTINUES + MAIN ST N INTERSECTS • ZIP CODE 58703 CAR-RT C007

701-852-5604

......701-838-8885

414 Charley Hattie C & Zachary J ® 701-838-0602 417 Burtman Jerald & 13701-839-5039 419 No Current Listing 422 Engleson Roderic F & Peggy M 12 a

+ 6TH ST NW INTERSECTS + 6TH ST NW CONTINUES

610 No Current Listing
618 Bechtold Margery M 13701-839-4169
Bechtold Randal R701-839-4169

....701-839-5341

B No Current Listing

111 Struckness Dale E & Marion J 20 a

+ WALDERS ST CONTINUES + 3RD ST NW ENDS + N BROADWAY INTERSECTS + 4TH ST NW INTERSECTS + 4TH ST NW CONTINUES • ZIP CODE 58703 CAR-RT C009 400 Wood Reginald L & Betty L 12 ▲

413 No Current Listing

504 Wallin Julianne M 20 ...

505 Germain David A & Violet A 20 ♠

• ZIP CODE 58703 CAR-RT C003 600 1 - 2 No Current Listing (2 Apts)

600 3 @ Dorner Christophe G

620 © Steeves Judy M + 7TH ST NW INTERSECTS + 7TH ST NW CONTINUES

HOUSEHOLDS 3

4TH AVE NW - 4TH ST NE

MORGAN PRINTING 307 3rd Ave. SE • MINO

YOUR ONE STOP PRINT SHOP Everything in Commercial & Quick Printing BUSINESS FORMS • LETTERHEADS • ENVELOPES

"Best Prices Around"

852-5250

-COLOR		1
-COLOR —	 020	000

SE • MINOI	
4TH AVE NW Cont'd	4TI
McLaughlin Timothy J & Joanna K 20 ♠701-852-2822	172
+ 8TH ST NW INTERSECTS + 8TH ST NW CONTINUES	+ 1: + 1:
800 Bradwisch Edwin L & Annette 4 701-839-1494	180
806 - 809 No Current Listing (2 Hses) 812 Stave Judy D 10 ▲	
Stave Annika M 813 - 814 No Current Listing (2 Hses)	
818 Linington Geneva H 19 701-839-2477	
822 Scheeler Robert J & Janeen 20 a	• Z I 180
826 Schmalz Joseph B 🔟 🛦701-838-4836 Schmalz Loren M701-838-4836	
+ 9TH ST NW INTERSECTS + 9TH ST NW CONTINUES	180
900 Strecker Neil R & Dayna 11701-838-3397	• ZI
901 No Current Listing 902 Lovszczyk Michael S [2]701-839-6685	181
902 Loyszczyk Michael S 2701-839-6685 905 Bergan Jamie D & Amy 3701-837-0618	• ZI
906 Middleton Miles T ②701-837-7914 910 Park Jonathan D & Jennifer L ⑦ ▲	181 • Zi
701-837-9296 915 ② Joyner Richard A & Lori701-838-9974	182
916 Fewster David A & Angela A 3	
917 Cartier Rene A & Barbara J 20 🛦701-838-5269	
920 @ Buller Debra J & Jeffery L 1000 Higgins Verlin L 20	
Higgins Beverly G701-839-5887	+ 15
1001 Darling Donald A & Patricia A 20 ♠701-839-3502	+ 15
1004 Horn Denise L 11 ▲ Kennedy Dustin F 2	190 • Z I
1005 Olson Shanda M 2701-858-9867	190
Olson Jesse L	191
• ZIP CODE 58703 CAR-RT C019 1122 KAFFE KIOSK coffee shops701-838-2169	
1124 RIVIERA LOUNGE cocktail lounges	• ZI 192
701-839-2027 1212 BODY TRENDS body piercing 701-839-1555	+ 20
DETANGLES HAIR STUDIO beauty salons	+ 20
	+ 20
instruction701-837-0239 VIDEO MAGIC video tapes & discs	201
701-838-4544 1224 BROWN & SAENGER office supl	
701-858-0808 1300 A A & A INVESTMENT real estate	
701-839-6600	
ALLEN REALTY CO REALTORS real estate BEST BROADWAY INVESTORS industrial	
developments701-838-1592 OAK PARK SHOPPING CTR shopping	
centers & malls	• ZI
1302 MICHAEL'S restaurants701-837-6133 1400 CROWD PLEASERS DJ & KARAOKE music	202
& live entertainment701-839-3006 D C ENTERTAINMENT entertainment	• ZI
bureaus701-839-3006	202: + 2 1
PROTRONICS musical instruments-dlrs701-839-3006	+ 21
SERVICE SHOE SHOP shoe & boot rpr701-838-1722	+ 21
B DISCOUNT SEW-VAC vacuum cleaners-	210
household-dirs701-852-8506 F HILLBILLY DAWG HOUSE pet supl &	2110
foods- retail	
1500 OAK PARK THEATER theatres-movie	2120
D SUPERIOR AUTO REPAIR auto rpr & serv	+ 22 + 22
	2200
1507 Lund Nathan A 3 Nicholson Stephanie D 2701-837-0406	
1508 Merck Cecilia M 20 ▲701-839-3976	• Z1
1509 Grosche Donald A & Sharon M 20	2209

701-852-5331 + 16TH ST NW INTERSECTS

Displaced Homemaker C 3701-857-4488

Displaced Homemaker C 3701-857-4488

MINOT ADULT LITERACY VOLUNTEER
reading improvement instructio 701-852-2614

• ZIP CODE 58703 CAR-RT C034

1620 MIDWEST TIRE & MUFFLER auto pr & serv

+ 17TH ST NW INTERSECTS + 17TH ST NW CONTINUES • ZIP CODE 55705 0-1

+ 16TH ST NW CONTINUES
1609 ADULT LEARNING CTR schools

BUSINESS CARDS • TYPESETTING • MULTI-COL
BROCHURES • INVITATIONS • FAX SERVICE
4TH AVE NW Cont'd
1720 BIBLE FELLOWSHIP CHURCH churches
701-838-0916 + 18TH ST NW INTERSECTS
+ 18TH ST NW CONTINUES
1800 FATHER TIME'S WATCH REPAIR watches- rpr701-838-0960
PRAIRIE DAKOTA INSURANCE INC
insurance
C BACKYARD BREWING SUPPLIES beer- homebrewing equip/supl701-858-9950
• ZIP CODE 58703 CAR-RT C019
1801 RASMUSON APPRAISAL CONSULTANT appraisers701-852-4861
1809 Marcy Vicki M (7
• ZIP CODE 58703 CAR-RT C034
1810 KADRMAS LEE & JACKSON engineers-
consulting701-839-3383 • ZIP CODE 58703 CAR-RT C019
1813 No Current Listing
ZIP CODE 58703 CAR-RT C034 1820 ALICE'S BEAUTY SALON beauty salons
701-838-3068
RED'S CUSTOM LEATHER leather goods-rpr
701-839-6593 RED'S STYLE SHOP barbers701-839-6593
Sedevie Darrell H 111701-839-6593
+ 19TH ST NW INTERSECTS + 19TH ST NW CONTINUES
+ 19TH ST NW INTERSECTS
+ 19TH ST NW CONTINUES 1900 GLADYS' PLACE restaurants701-852-8221
 ZIP CODE 58703 CAR-RT C019
1909 Devenere Joan 13
Devenere Betty J701-839-6764 1913 Sabo Wayne R & Alvera F 12 ▲
• ZIP CODE 58703 CAR-RT C034
1924 DAIRY QUEEN ice cream parlors
+ 20TH ST NW INTERSECTS + 20TH ST NW CONTINUES
+ 20TH ST NW CONTINUES + 20TH ST NW INTERSECTS
+ 20TH ST NW CONTINUES 2010 AMON INSURANCE insurance 701-852-3156
BERNI'S BODY WRAP STUDIO body wrap
salons701-852-9009 KONDOS INSURANCE insurance
701-852-1673
PROVIDENT MUTUAL INSURANCE
insurance701-852-8002 101 ORVIK MICHAEL CPA accountants
701-852-8850
103 TANDE PHOTOGRAPHY photographers- commercial701-852-8699
• ZIP CODE 58703 CAR-RT C019
2021 AMERICAN RED CROSS social serv & welfare org
• ZIP CODE 58703 CAR-RT C034
2022 No Current Listing + 21ST ST NW INTERSECTS
+ 21ST ST NW CONTINUES
+ 21ST ST NW INTERSECTS + 21ST ST NW CONTINUES
2100 GRANITE SPRING WATER & ICE CO ice-
mrs701-838-3910
2116 No Current Listing 100 MARRIAGE CLINIC psychologists
701-838-2442
2120 BALLANTYNE OIL oil/gas exploration/ developmen701-852-9235
+ 22ND ST NW INTERSECTS + 22ND ST NW CONTINUES
+ 22ND ST NW CONTINUES 2200 JACKETS BY PRICE coats-mfrs
701-838-3192
PRICE UPHOLSTERY upholsterers701-838-3192
 ZIP CODE 58703 CAR-RT C019
2209 Roth Carlyle (4
ST MARK'S LUTHERAN CHURCH churches701-839-4663
ZIP CODE 58703 CAR-RT C034 2212 Mueller Kirby G & Cynthia K 18 ▲
701-852-3641
2220 Price Dale R 14
+ 23RD ST NW CONTINUES
• ZIP CODE 58703 CAR-RT C019 2309 Peterson Dennis E & Douglas A 20 ▲
+ 24TH ST NW INTERSECTS
+ 24TH ST NW INTERSECTS 2405 Berg Douglas E & Karen L 16 ▲
701-852-8501
2409 Mackey Leroy B & Helen L 14 ▲
+ 25TH ST NW INTERSECTS
2505 Vix Lando D 8701-852-6760
Vix June M
701-852-1654
+ 26TH ST NW INTERSECTS

₹	Fax 838-2027
	4TH AVE NW Cont'd + 27TH ST NW INTERSECTS • ZIP CODE 58703 CAR-RT R006 2705 TORNO NESTER DAVISON architects 701-852-4178
	+ 28TH ST NW INTERSECTS + 30TH ST NW INTERSECTS + 30TH ST NW CONTINUES 3110 ABC MARKET-USED FURNITURE furniture- used
	Burgard Leo W & Alice B 20 ♠701-839-6874 3120 Holter Glen A 20 ♠
	contractors
	MINOT BUILDERS SUPPLY trucking701-838-5624 NIESS ENTERPRISES tool & die makers
	+ COUNTY ROAD 15 W BEGINS 3400 BEETER TRUCKING trucking701-839-1523 + 46TH ST NW INTERSECTS + 54TH AVE NW ENDS + 54TH ST NW BEGINS
	+ 62ND ST NW INTERSECTS + RAILROAD CROSSES + RAILROAD CROSSES + HIGHWAY 2 AND 52 W INTERSECTS 4101 Anderson Dennis W & Donna M 🗓 a
	4104 HISTORICAL PAINTING & HARDWOOD painters
	4TH AVE SE (KENMARE)-FROM 401 SOO ST SOUTH + 4TH AVE NE CONTINUES + E DIVISION ST INTERSECTS + LAKEVIEW ST INTERSECTS + LAKEVIEW ST CONTINUES + SOO ST INTERSECTS
	4TH AVE SE (MINOT)-FROM 401 31ST ST SE EAST - ZIP CODE 58701 CAR-RT C011 2721 N CENTRAL FEED & SEED INC feed-dirs
	BUSINESSES 1701-838-1728
	4TH AVE SW (MINOT)-FROM 399 15TH ST SW WEST • ZIP CODE 58701 CAR-RT C023 1404 Marshall Craig L & Debora L [10] a
	701-838-1015 1405 Hankla Walfrid B & Winifred A 20 ♠
	1501 Messmore Frank A Jr & Dagny V (1) ▲ 1505 Devilbiss Thomas E & Janice J (3)
	701-852-6788 1509 Burke Donald M & Jean M 15 a 701-852-8467
	2101 Wald Terry J Sr & Doreen L 3701-839-5983 + 24TH ST SW BEGINS BUSINESSES 1 HOUSEHOLDS 8

HOUSEHOLDS 8 4TH AVE SW (SURREY)-FROM 511 5TH ST SW

• ZIP CODE 58785 CAR-RT R001

502 Martin John R & Jane R 3 ▲701-838-0954

506 Wald Corey J & Christy (4)701-852-8776 508 Felber William S & Darla R (4) ...701-852-2233 + 6TH ST SW ENDS 510 Badke Charles D & Terrie L 111 ▲

4TH ST N (SURREY) 4TH ST NE ENDS 4TH ST NE INTERSECTS

4TH ST NE (KENMARE)-FROM 401 N CENTRAL AVE FAST

+ 4TH ST NW INTERSECTS + 1ST AVE NE INTERSECTS + 2ND AVE NE INTERSECTS + 3RD AVE NE INTERSECTS + 4TH AVE NE INTERSECTS * Free Continental Breakfast Close To Dakota Square Shopping Mall

DAYS INN

1-888-327-6466 852-3646



3RD ST SE to 4TH AV NW

102½ Bayert Eve K 858-0562

4TH AV NW



Pool - Sauna - Whirlpool Next To Perkins Restaurant 2100 4th St. SW 15 NEW NEIGHBOR cont'd 3D ST SW cont'd 3D ST SE Rubbelke Nancy R......838-3454 921 Not Verified 925 Roberts Dennis N & Elizabeth ③ ▲ + A AV INTERSECTS 820 Parge Robert E & Irene 9+ 4.838-0850 926 Not Verified 10TH AV SE INTERSECTS 1000@Marmon Michael M & Donna. 825-3993 Marmon Holly M......825-3993 838-2334 Marmon Mickael J Jr......825-3993 C Houge Clyde H & Janell 🖭+ ੇ Tiller George R & Marlene 19+ ▲ 1008 Not Verified 839-5941 1008 Upstairs Not Verified 901 Ross Lorayne B 191+ ♠852-1854 1012 Vacant 902 Muus Steve P 2 6852-4304 1305 Kleinsasser Virginia H [2] 839-6738 1316 Vacant 1317 Brabandt Roger L & Juell 191+ A852-8710 Warified 839-6577 + 12TH AV S E INTERSECTS 1318 Not Verified 1320 Schaefer Lorrie M & Kathy 19+ ▲ + 13TH AV S E INTERSECTS +SE ST PETER AV INTERSECTS +14TH AV S E INTERSECTS 852-6446 1321 Burckhard Mark P & Tara 3 🏚 +17TH AV INTERSECTS 1704 Laqua Richard W & Cecelia 19+ ▲ 1327 Heidt Theresa M 191+ 852-3548 1705 Ringdahl Edwin J & Tillie [2] 1330 Vacant ... 839-5704 1710 Haberlack Paul R & Elaine 회+ 🛦 1335 Heinze Robert J & Laura 19+ ▲ HOUSEHOLDS 29 1711 Price Terry C & Sandra 19+ BUSINESSES 6838-4854 4TH AV NE -FROM MAIN ST EAST, 1 1715 Savelkoul Bruce A & Anna Marie [2] NORTH OF MOUSE RIVER · ZIP CODE 58701 11 Ziesing Konrad & Saralee [2]...... 852-6442 + 1ST ST NE INTERSECTS 109 Vacant . 115 Wickman Joe [2] 838-4784852-2281 1728 Simmons Rev David & Florence 19+ 117 Not Verified +2D ST NE INTERSECTS838-3752 203 Vacant 207 Myers David T & Karla 4 852-5418 1735 SEVENTEEN THIRTY FIVE APARTMENTS 852-1765 209 Not Verified 1 Sharma Eva [2]......839-1575 211 Vacant + 3D ST NE INTERSECTS 308 CONNALE & SOMMERVILLE plmb & 3 Vacant839-7944 4@Estin L + 18TH AVE SE INTERSECTS
BUSINESSES 39 HOUSEHOLDS 56 3RD ST SW -FROM CENTRAL AV SOUTH, 404 Not Verified 436 Vacant 3 WEST OF MAIN ST +6TH ST NE INTERSECTS 600-601 Vacant (2 Hses) 605 AMERICAN LINEN SUPPLY 852-0351 + 1ST AV SW INTERSECTS
110 MINOT ELECTRIC INC contrs... 852-0551 · ZIP CODE 58701 612 TARGET ROOFING...... 838-4482 614 Vacant +2D AV SW INTERSECTS +7TH ST NE INTERSECTS 200 FIRST BAPTIST CHURCH 852-4533 + WESTERN AV INTERSECTS 706 Vacant + 8TH ST NE INTERSECTS 220 Vacant 826 Vacant 222 Not Verified +3D AV SW INTERSECTS +9TH ST NE INTERSECTS 306 INTERSTATE BRANDS CORP + 14TH ST INTERSECTS 852-2531 (GARAGE)..... 312 UNITED BLOOD SERVICES OF 1620 LOWE'S FLORAL AND GARDEN HOUSEHOLDS 4 BUSINESSES 5 4TH AV NW -FROM MAIN ST WEST, 4 NORTH OF CENTRAL + BTH AV SW INTERSECTS 800 Anderson Edward A & Myrtle ⑨+ 🌢 12 Hathaway Melissa [2]...... 852-8928

1	02½@Bayert Eve K858-0562 03 HOME SWEET HOME gift shop 852-5604 106 PICKET FENCE THE gift shop	
٠	107 Not Verified	
	A-B Vacant (2 Apts) 111 Struckness Dale E & Marion 団+	
	114 Christopherson Karla J 51	
ŀ	+ 2D NW INTERSECTS + 4TH ST NW INTERSECTS 413 Magazity Boods A [2] A	
ı	Zethren Josephine L	١
	419 Hernandez Joe W & Maria [2] 858-0956	۱
	422 Engleson Rod F & Peggy [2] ▲ 839-5821 423 Huizenga Thelma L (9)+ ▲	
	429 Panasuk Orrin L & Vicki 19+ 1 839-8795	
	504 Wallin Julianne M 191+ ■	
	510 Jelleberg Robert E & Cintria III = 838-3548	
	524 Vacant +6TH ST NW INTERSECTS 600 Apartments	
	1 Vacant 2 Braaten Tara D [2]838-9223 3-4 Vacant (2 Apts)	
2	608 Vacant	
2	618 Bechtold Margery M 4	
4	+ 7TH ST NW INTERSECTS 700 Vacant	
	702 Olson Wanda M [2]	
8	700 Asserted Alfred A & Nardine 19+	
4		
3	+ 8TH ST NW INTERSECTS	3
	806 Lovdahl Thomas H 图+	5
51 82	2 S13 Esterby Mike P	•
	814 Dahl Manuel & Elsie (9)+	7

822 Scheeler Robert J & Janeen 19+ 6

900 Belinskey Carol R 3 6

905 Vacant

121/2 DJohnson Annie May 852-8277

14 Not Verified

141/2 Apartments

100 Not Verified

838-3454 | 100½-102 Vacant (2 Hses)

A-B Vacant (2 Apts)

+ 1ST ST NW INTERSECTS

804 Norberg Dale L & Dorothy 191+ 🛦

812 Rubbelke Robert J & Nancy B &

809 Vacant

838-1012 805 Nathan Neil S & Sherry 19+ \$.852-3457

826 Schmalz Loren M 4838-7727

906 Beede James D & Venus 3 6 839-0422

916 Ryan P J & Michelle B 839-3765

852-6911

852-2401

838-5269

...... 839-0947

Cartier Aimee M......838-5269

Cartier Steven B...... 838-5269

910 Christensen John F & Joan 19+ A

915 Burckhard Dennis J & Sheila 191+ A

920 Mayer Robert M & De Ann 3 ≜

.....838-6370

...... 839-2379



cont'd

Furance, nce, Boiler & . Commercial (G Air Duct Cleaning Residential

 \mathbf{z}

IMPORTANT AS,

WHERE TO SELL

GOOD

THE KNOWLEDGE

9



LARSON ELECTRIC INC.

Residential - Commercial - Industrial

Master License 1267

Tel. 852-4188

15

3D ST SE-Contd 925 Waind David W & Charise L 9+ @ 839-6552

510 East Central

926 Saltsman Geo J & Mary 🗐 + 🐵 839-5925 • 10TH AV SE INTERSECTS 1000 Not Verified

1006 MARLENE'S MONOGRAMING 839-5941 Tiller Geo R & Marlene O 🖪 ⊚

839-5941 839-5941
1008-Upstairified Not Verified (2 Hses)
Bsmt Buettner Steve M 2 839-3015
1012 Paul Geo Jr & Margt V 5 © 838-6986
1016 Prescott Sheri 2

Bsmt Not Verified 1020 Sande Jackie & Jacqueline A 2 @

• 11TH AV S E INTERSECTS

1106 Brewer Donald 838-9206 1108 Schalesky Marty D & Carol J 3 @ 852-8710

**852-8710

**12TH AV S E INTERSECTS

**13TH AV S E INTERSECTS

**SE ST PETER AV INTERSECTS

**14TH AV S E INTERSECTS

1704 Laqua Richd W & Cecelia M 9+ ® 838-6727

1715 Mostad Chris & Marie L 9+ ⊚ 839-3792

839-3792

1716 Ressler Wilbert F & Barbara E 🖳 + ⊚
839-4535

1721 Klimpel Vernon L 📵 + ⊚ 839-8244

1722 ★Nitsch Paul & Karen L
1727 Kleingartner Marie A 📵 + ⊚ 852-2281

1728 Simmons David Rev & Florence 📵 +
939-2752

838-3752 1735 SEVENTEEN THIRTY FIVE APARTMENTS 852-1765

1 Bennett Kathleen 2 838-2281

1 Bennett Sharon N 838-2281

2 Mehl Connie 2 852-6188

3 Doure Angela R 852-6612

4 Not Verified 67 HOUSEHOLDS 37 BUSINESSES

3D ST SW -FROM CENTRAL AV SOUTH 3 WEST OF MAIN ST

• ZIP CODE 58701
• IST AV SW INTERSECTS
108 MINOT ELECTRIC INC (WHSE)
110 MINOT ELECTRIC INC contr 852-0551
• 2D AV SW INTERSECTS
200 FIRST BAPTIST CHURCH 852-4533
• WESTERN AV INTERSECTS

220 Vacant
222 Dhuybetter Chris T 2 838-4952
3D AV SW INTERSECTS
306 INTERSTATE BRANDS CORP
(GARAGE) 852-2531
312 UNITED BLOOD SERVICES OF
DAKOTAS-MINOT 852-2161
BURDICK EXPRESSWAY INTERSECTS
412 Landry John W 9+ 839-2057
420 COMMUNITY ACTION OPPORTUNITIES
INC Socl serv org 839-7221

INC socl serv org 839-7221
• 5TH AV SW INTERSECTS

8TH AV SW INTERSECTS 800 Anderson Edw A & Myrtle E 19 + © 839-7053

Currier Linda D Reyes-Flores Lena

812 Rubbelke Robt J & Nancy R 4 @ 838-3454

 A AV INTERSECTS 820 Parge Robt E & Irene 🗐 + ⊚ 838-0850 825★Heinze Marianne R ⊚

ocumenize Marianne R ⊚
830 HOUGE APARTMENTS 838-4922
A★Ganje Danl R 839-1514
B Schwartz Doug & Priscilla 2 838-2334
C Houge Clyde H & Janell K 9 + ⊚
838-4922

D Hanson Mark A 2

831 Rose Willard T & Inez F 7 839-7146 840 Waller Armida G 9 + @ 852-2324 • 9TH AV SW INTERSECTS 901 Ross Lorayne B 9 + @ 852-1854 902 Muus Steve P 4 852-4304

906★Stevenson Troy D & Tora L 838-1449 912★Mack Bruce Allen & Susie M

1305 Kleinsasser Virgine H 🗐 + ⊚ 839-6738 1316 Baros Patk A & Doreen K 🕄 ⊚ 852-9110

1317 Brabandt Roger L 🗐 + ⊚ 839-6577 1318★Goerndt J D 1320 Schaefer Lorrie M & Kathy L 📳 ⊚

852-6446
1321 Burkhard Mark P & Tara J 2 @
838-4543

1335 Heinze Robt J 🗐 🕇 🎯 839-2919 31 HOUSEHOLDS 5 BUSINESSES

4TH AV NE -FROM MAIN ST EAST 1 NORTH OF MOUSE RIVER

ZIP CODE 58701

• ZIP CODE 58701

11 Vacant
• 1ST ST NE INTERSECTS
109 Knutson Neal 2 839-0392
115 Not Verified
117★Jennings Sara E
• 2D ST NE INTERSECTS
203 Glock Katherine D 19 ★ 838-2429
207★Myers David & Karla
209 Kenyon Katherina D 9 ★ 838-4808
211★Auck Robt C & Dawn
• 3D ST NE INTERSECTS

308 Vacant 400 MINOT WELDING CO wldrs & brazers

838-0513 404 Faine John 9+ @ 838-8674 Faine Eddie 838-8674

11 436 Vacant

• 6TH ST NE INTERSECTS

• FER TAVERN

600 LIBERTY DEER TAVERN bar 852-5013 601 Vacant

605 AMERICAN LINEN SUPPLY 852-0351 614 Vacant

• 7TH ST NE INTERSECTS 706 Vacant
• 8TH ST NE INTERSECTS

826 J & S INSULATION 838-3759

• 9TH ST NE INTERSECTS
• 14TH ST INTERSECTS
1620 LOWE'S FLORAL greenhouse 838-2868
• 27TH SE INTERSECTS

HOUSEHOLDS 5 BUSINESSES

4TH AV NW -FROM MAIN ST WEST 4 NORTH OF CENTRAL

• ZIP CODE 58701 7 12 Downs Bessie M 🗐 + 852-6870 Downs Doris M 852-6870 12½ #Hank Gladys 838-5238

14½ Apartments

A★Sanders Marvin B & Amy 838-0866

B Vacant

1ST ST NW INTERSECTS

100 Schimke Yvette A 3 838-4904

100½ Vacant

102 Not Verified

1021/±walth Patti 839-8365 103 HOME SWEET HOME gift shop 852-5604 RUSSELL ENTERPRISES gift shop 852-5604

106 Gruenberg Richd J 2 @ 839-0206 107**★**Job Terry T

110 Apartments

A Carlson Paul W 2 852-2941 A Williams Thos J 852-2941 B Not Verified

111 Struckness Dale E 9+

838-7398

114 Christopherson Karla I 2

WALDERS ST INTERSECTS

· 2D NW INTERSECTS

• 4TH ST NW INTERSECTS 413 Not Verified

414★Hayes Gladys 417 Vedvig Marvin 2 839-5039

417 Vedvig Marvin tel 859-5039 419 Mulvaney Wm R & Julie A 2 852-8284 9-A 422★Radke Shannon D & Dori Jean ⊚

838-6560
423 Huizenga Thelma L 🔋 + 🔞 838-7953
426 Burnette David M & Cynde 🗵 🕲

852-4729 429 Panasuk Orrin L & Vicki J 9 + ⊚ 839-8795

Olson Derrick E Panasuk 839-8795
• 5TH ST NW INTERSECTS
504 Wallin Julianne M 🗐 + 🔞 839-5341
505 Germain David A & Violet A 🗐 + 🔞

839-2772
510 Jelleberg Robt & Cynthia 2 © 838-3548
Jelleberg Cynthia 838-3548
524 Mayer Darrin C & Shellie D 2 ©
838-8886

6TH ST NW INTERSECTS

600 Apartments
1 **Fox Lesa
2 **Houde Rich D
2 Rivard Paula K

★Swenson Dallene C 839-3449 4 Ofsthun Steve D 2 839-5094

608★Yester Jim 610 Stiefel Nora ᠑+ ⊚ 839-8632 618★Bechtold Margery ⊚ 839-4169

Samt Vacant
620★Tossett Andy R & Judith A 839-5360
• 7TH ST NW INTERSECTS
700 Stahl Sara J ② 852-6675
702 Kastner Allen J ② 838-1165
706 Not Verified

708 Aanestad Alf A & Naedine M 5 @ 839-1345

839-1345
712★Neard Wendell O & C Erlys 839-5794
716★Wood Wm & Lucinda © 839-1397
20 720 Mc Laughlin Tim J & Jody K 2 ©
852-2822

Mc Laughlin Riva L 852-2822 8TH ST NW INTERSECTS 800 Not Verified

822 Scheeler Noot J & Janeen E 1 838-6370 Scheeler Tom 838-6370 826#Schmalz Joseph B @ 838-4836 Schmalz Loren M 838-4836 • 9TH ST NW INTERSECTS

910 Christensen John F & Joan M 7 @ 852-6911

915 Burckhard Dennis J & Sheila A 9+ @ 852-2401

916 Ryan Pat J & Michelle 4 @ 839-3765 917 Cartier Rene A & Barbara J 9 + @

838-5269 No Return 838-5269

1 Keating Bruce H & Toni 2 852-3350 1000 Higgins Berlin L & Beverly G 9+ ⊚

839-5887
1001 Darling Donald A 19 + 889-3502
Floor Barnard Robt & Floy 2 ®
852-5419

Upstairs Tyson Amy 2 839-0510
Bsmnt Headrick Loren M 2 838-8574
1005 Bach Ollie M 99+ © 839-1244
1124 RIVIERA LOUNGE 838-4035
1212 ALLEN REALTY (WHSE)
MINOT MAGIC GYMNASTICS MINOT MAGIC GIMNASTICS instruction 838-3679 VOGUE II BEAUTY SALON 852-6003 G ANNES ALTERATIONS 852-1577 BRAY'S CLEANERS 852-4570

BUDGET MUSIC & VIDEO 852-4439 1224 O M F ofc sup 852-1412 1300 OAK PARK SHOPPING CENTER

838-8400

Darrel Hovde Agent Res. Tel. 838-5679 TEL. 852-2757 Mobile Tel. 240-1016 P.O. Box

1806

111 11th

Ave. S.W.

525

REAL Builders, inc. Residential - Commercial - Multiple 1715 12th AVE. S.W., P.O. BOX 3092 3D ST SE-Contd



TEL. 839-4328

2D AV SE INTERSECTS
311 County Court House 852-5420
Bsmt County Juvenile Court 852-2561
Bsmt County Superintendent Of Schools
857-6495
1st Fl Army Mothers
1st Fl County Ct Hse (Community
Room) 852-2012
1st Fl Daughters Of Union Veterans
The Civil War

1st	Fl	Disabled American Veterans
1st	Fl	Disabled American Veterans
		(Auxiliary)
1st	$\mathbf{F}\mathbf{l}$	Lincoln Abraham No 22
	T31	17-24-1 C2-1 117-0 37-4-0

1st Fl	Lincoln Abraham No 22
1st Fl	United Spanish War Veterans
	(Col E S Camp No 6)
ROOMS	

)MS	
101	State Crime Bureau 838-3272
101	County Coop Extension Serv
	852-6444

102	County	Veterans	Service	857-6490
103	County	Personnel	Admin	istration
	Services	857-R400		

104	County	States	Αt	torney	857-6480
201	County	Clerk	Of	Distric	t Court
	857-646	0			

857-646	0	
202 County	Commissioners	857-6420
203 County	Auditor 857-642	20

204 County	Treasurer	857-642	26
205 County	Tax Equa	lization	Director

	857-643	0
205	County	Bldg Insp 857-6430
206	County	Register Of Deeds 857-6410

206	С	ounty	Register	Of	Deeds	857-6410
OOR	S					
3d	Fl	Count	v Court	(Re	oms) (357-6470

3d	Fl	County	Court 8	57-6470)
3d	Fl	County	District	Court	Reporters

3d	Fl	County	District	Court	Reporters
		838-830	5		
	_	_		_	

³d Fl County District Court (Judge) 839-0305

Rear County Sheriff 857-6500 Rear County Jail 857-6500

3d Fl County Law Library 857-6409 STREET CONTINUED

3D AV SE INTERSECTS 4TH AV SE INTERSECTS 409 Saint Joseph's Hospital 857-2000 Saint Joseph's Hospital (Gift Shop)

416 Owner Direct Real Estate 852-2131

510★Thompson Paul D 839-1797
511 Johnson Roland W @ 839-6766
Johnson Raymond W 852-2969
512★Harvey Thelma
516 Lang June H 839-5455
525 Arneberg Cecelia J Mrs @ 838-8840
529★Beste Edythe A 839-3098
600 Seright Rebecca A 839-7446
601 Vacant
605 Mc Kay Timothy R @ 838-6775
611 Le Duc Charles H @ 838-8935
Bsmt Vacant

	26
	617 Veit Richd J 839-2536
	617½ Vacant
	625 Pringle Jean L Mrs @ 838-3476
6	629 Olson Burton G @ 839-4550
	7TH AV S E INTERSECTS
	700 Moe Steve W @ 839-6561
	707 Coffey Rex S @ 839-6450
	710 Barnes Dennis E @ 839-6397
	712 Vacant
	8TH AV SE INTERSECTS
	809 Vacant
	810 Larson Greg J @ 852-2331
Of	812 Scheid Ernie D @ 838-0038
	814 Smette Geo H @ 838-8904
	815 Vacant
	818 Maupin School Of Dance 852-5359
	Maupin Virginia L Mrs @ 838-3666
	819 Colton Edith M @ 838-2264
	823 Samuelson Reuben W 839-7725
	825 Rogness Rollin W Rev @ 852-1852
	826 Fraley James A @ 838-6843
	9TH AV SE INTERSECTS
	900 Lyon John M @ 852-2005
	901 Havelka Arnold J @ 838-4864
90	905 Ridl Gary A 838-0747
n	906 Bennett Billy R @ 852-3120
)	908 Williams Doris M @ 838-1086
,	909 Wald Mike 838-4402
	Williams Upholstry 852-6628
	★Williams Leslie K 838-2471
	912 Gruzensky Marie @ 839-3328
	913 Olson Edwin W @ 839-4007
or	916 Weishaar Donna J 838-8371
,,	919 Vacant
	920 Haberman Donald S @ 838-8619
410	921 Ringdahl Wm R @ 839-1069
	925 Waind David W @ 839-6552
70	926 Saltsman Geo J @ 839-5925
	10TH AV SE INTERSECTS
rs	1000★Gutbrod Robt B 852-3285
	1006 Tiller Geo R ◎ 839-5941
	Bsmt Marlene's Monogramming
	1008 ★ Kellogg John W 839-5777
	UpstairsnKing Darin 852-5619
	Bsmt #Openchain Bryan
4	1012 No Return
	★Paul Geo Jr © 838-6986
	1016★Bradwisch Marsha A 838-0920
	Downstairs Green Beth A

1106 Vacant
Bsmt Vacant
1201 Rosehill Cemetery 838-4310
12TH AV S E INTERSECTS
13TH AV S E INTERSECTS
SE ST PETER AV INTERSECTS
14TH AV S E INTERSECTS
1704 Laqua Richd W @ 838-6727
1705 Nelson David G @ 838-3945
1710 Haberlack Paul R @ 838-7958
1711★Price Terry C @ 838-4854
1715 Mostad Chris @ 839-3792
1716 Ressler Wilbert F @ 839-4535
1721 Klimpel Vernon L @ 839-8244
1722 Nitsch Paul F @ 838-7351
1727 Kleingartner Herbert A @ 852-2281
1728 Simmons David Rev 838-3752

1020 Sande Jacqueline A Mrs @ 838-7940

10

11TH AV S E INTERSECTS



3D ST SE-Contd

300 6th St., S.W. • P.O. Box 1927 • Minot, ND 58702

TEL. 852-3676

27

1735 Seventeen Thirty Five Apartments NORTH OF MOUSE RIVER 852-1765

1**★**Nair Ernie 839-5686 ZIP CODE 58701 2 No Return 11 Vacant 3±Joner David 839-5236 1ST ST NE INTERSECTS

11

3D ST SW -FROM CENTRAL AV SOUTH 3 WEST OF MAIN ST

4★Polzin Tim F 852-4633

ZIP CODE 58701 1ST AV SW INTERSECTS 108 Minot Electric Inc (Whse) 852-0551 110 Minot Electric Inc contr 852-0551 2D AV SW INTERSECTS WESTERN AV INTERSECTS

200 First Baptist Church 852-4533 220 Vacant

222 Seney Joyce Mrs 839-5979 3D AV SW INTERSECTS

306 Interstate Brands Corp (Garage) 852-2531

312 United Blood Services Of Dakotas-Minot 852-2161

4TH AV SW INTERSECTS 408 Vacant

412 Landry John W 839-2057

420 Community Action Opportunities Inc socl serv org 839-7221

5TH AV SW INTERSECTS

6TH AV SW INTERSECTS 8TH AV SW INTERSECTS 800 Anderson Edw A @ 839-7053 803 Martin Donald D @ 839-6881 804 Norberg Dale L @ 838-1012 805 Nathan Neil S @ 852-3457 809 ★Getzlaff David 839-8991 812 Bogner Nancy @ 838-3454 A AV INTERSECTS 820 Parge Robt E @ 838-0850

825 Opdahl Ruth H Mrs @ 838-0816 830 Houge Apartments 838-4922 A Lawler Marilyn A 838-2722

B Clark Cora I 838-2678 C Houge Clyde H @ 838-4922 D Effertz Verle S 838-7956

831 Rose Willard T @ 839-7146 840 Waller Armida G @ 852-2324

9TH AV SW INTERSECTS 901 Ross Leander F archt @ 852-1854

902 Vacant 906 Self Ida S Mrs @ 838-1449

912 No Return

1305 Kleinsasser Virgine H Mrs @ 839-6738

1316 Baros Patk A @ 1317 Brabandt Roger L @ 839-6577 1318**★**Joyce Lisa M 852-8364

1320 Schaefer Lorrie M @ 852-6446 1321 Killmer Joseph ● 852-5711

1324 O'Brien Wm J @ 838-5380 1327 Heidt Theresa M 852-3548

1330 No Return

1334 Bibow Bruce R @ 852-2759

1335 Heinze Robt J @ 839-2919

4TH AV NE -FROM MAIN ST EAST 1

109 Vacant

115 Vacant 117 Schmalz Mike A 838-3301 2D ST NE INTERSECTS

203 Glock Katherine D Mrs @ 838-2429

207 Mc Cauley Carolyn M

209 Kenyon Ellsworth L @ 838-4808

211 Fox Alice M Mrs 838-0585

308 Northern Machine mach shop 839-2344 Western Sheet Metal Co contrs 839-3020

400 Minot Welding Co wldrs & brazers 838-0513

404 Faine John @ 838-8674

436 Cenex Land-O-Lake Chemical Express Center distr 839-8905 6TH ST NE INTERSECTS

600 Liberty Tavern 852-5013

601 Sears Roebuck And Co (Serv Center) 857-1272

605 American Linen Supply 852-0351

614 American Freight 852-1368 Swenson Rube Warehouse 839-2630 Cavanaugh Trucking Inc 852-1358 7TH ST NE INTERSECTS

706 Vacant

8TH ST NE INTERSECTS

826 J & S Insulation 838-3759 1620 Lowe's Floral greenhouse 838-2868 9TH ST NE INTERSECTS

4TH AV NW -FROM MAIN ST WEST 4 NORTH OF CENTRAL

ZIP CODE 58701 12 Downs Bessie M 852-6870 Bsmt Hanke Gladys P 838-5238 141/2 Apartments

A Goldade Cathy S 852-8018 **B** Vacant

1ST ST NW INTERSECTS

100 Vacant 100½ Vacant

102 Abel Al A 839-0552 1021/2 Heinze Marianne R 838-9370

103 Home Sweet Home gift shop 852-5604 105 Vacant

106 Schimetz Mike 852-5628

110 Apartments A Vacant

B★Lommen Susan M 838-2545 111 Struckness Dale E @ 838-7398 114 Mac Lennan Mike J @ 839-7887

WALDERS ST INTERSECTS 2D NW INTERSECTS


4TH ST NW INTERSECTS

413 Vacant 414★Hines Jonathan J @ 838-8912

417 No Return

419 Vacant

422 Vacant 423 Huizenga Thelma L @ 838-7953



OFFICE EQUIPMENT INC.

P.O. Box 1745 17 East Central Avenue Minot, North Dakota 58702

.. 838-8624 838-4426

East Of Sai

15

³d Fl County District Court (Judge) 838-8305 311 County District Court (Judge) 838-9524

- READY MADE FRAMES

LIMITED EDITION PRINTS

PAULETTE THOMAS TIM GREENHECK

TEL. (701)852-1509

17 2d Av. S.E. (58701)

Northwest Building Improvement Company

Serving Your Needs Since 1948

STEEL & VINYL SIDING - ROOFING - INSULATING

LICENSED - BONDED - INSURED County Rd. 14 West

Tel. 852-2111

26

3D ST SE-Contd 1704 Laqua Richd W ⊚ 838-6727 1705 Nelson David @ 838-3945 1710 Haberlack Paul R ⊚ 838-7958 1711★Hanson Edw S ⊚ 1715 Mostad Chris @ 839-3792 1716 Ressler Wilbert F ⊚ 839-4535 1721★Klimpel Vernon L ⊚ 839-8244 1722 Nitsch Paul F ⊚ 838-7351 1727 Kleingartner Herbert A ⊚ 852-2281 1728 Simmons David Rev 838-3752

1735 Seventeen Thirty Five Apartments 852-1765 1★Lysne Scott A 838-0441 2 Lynch Ruth M 852-4528

3*Stults Chas L 839-7978 4 Olsen Vince H 852-0224

3D ST SW -FROM CENTRAL AV SOUTH 3 WEST OF MAIN ST

ZIP CODE 58701 1ST AV SW INTERSECTS 108 Minot Electric Inc (Whse) 110 Minot Electric Inc contr 852-0551 2D AV SW INTERSECTS WESTERN AV INTERSECTS 200 First Baptist Church 852-4533 220 Vacant 222 Seney Joyce Mrs 839-5979 3D AV SW INTERSECTS

306 Interstate Trans Co (Garage & Depot) 838-3428

Union Bus Depot 852-4671 312 United Blood Services Of Dakotas-Minot 852-2161

4TH AV SW INTERSECTS

408 Vacant 412 Landry John W 839-2057 420 Valker-Andrews Floral & Greenhouse 852-1328

5TH AV SW INTERSECTS

6TH AV SW INTERSECTS 8TH AV SW INTERSECTS 800 Anderson Edw A @ 839-7053

803 Martin Donald D @ 839-6881

804 Norberg Dale L @ 838-1012 805 Vacant

809 Vacant

812*Schalesky Alwood J 838-0173 A AV INTERSECTS

820 Parge Robt E @ 838-0850 825 Opdahl Ruth H Mrs @ 838-0816

830 Houge Apartments

A Chamberlain Joseph B 839-2254 B Clark Cora I 838-2678 C Houge Clyde H ⊚ 838-4922

THE PLACEMENT PEOPLE

D Effertz Verle 838-7956 831 Rose Willard T @ 839-7146

840 Waller Geo J @ 852-2324

9TH AV SW INTERSECTS

901 Ross Leander F archt @ 852-1854

902 Vacant 906 Self Ida Mrs @ 838-1449 912 Baker Colleen @ 838-3229

1305 Kleinsasser Virgine H Mrs ⊚ 839-6738 1316★Baros Patk A

1317 Brabandt Roger L @ 839-6577

1318★Austin Wm A 839-3869 1321 Killmer Joseph ⊚ 852-5711 1324 Vacant

1327★Alarcon Mary Lou T 839-2702 1330★Henderson Stanton L © 839-4502 1335 Heinze Robt J @ 839-2919

4TH AV NE -FROM MAIN ST EAST 1 NORTH OF MOUSE RIVER

ZIP CODE 58701

11 Vacant 1ST ST NE INTERSECTS

109 Healy James H @ 838-4243 115 No Return

117 Lovelace Joseph M 839-4788 2D ST NE INTERSECTS

203 Glock Katherina D Mrs @ 838-2429

207 Vacant 209 Kenyon Ellsworth L @ 838-4808

211 Fox Alice M Mrs 838-0585 MOUSE RIVER INTERSECTS

308 Northern Machine mach shop 839-2344 400 Minot Welding Co wldrs & brazers 838-0513

404 Faine John @ 838-8674

436 Cenex Chemical Fill-In Point chemical dealers 839-8905

6TH ST NE INTERSECTS 600 Liberty Tavern

601 Sears Roebuck And Co (Serv Center) 857-1272

605 Wilbur-Ellis Co 852-5199

614 American Freight 852-1368 Swenson Rube Warehouse 839-2630 7TH ST NE INTERSECTS

706 Vacant 8TH ST NE INTERSECTS 826 Arnie's Insulating Supplies 852-5690

1620 Lowe's Gardens Inc greenhouse 838-2868 9TH ST NE INTERSECTS


4TH AV NW -FROM MAIN ST WEST 4 NORTH OF CENTRAL

ZIP CODE 58701 12 Downs Bessie M ⊚ 852-6870 121/2 Hanke Gladys P 838-5238

141/2 Apartments A Kraft Terry 852-6670 B Leier Mark G 839-1907

401 S. Main St. Tel. 852-3601





1541 South Broadway

Tel. 852-3505

27

4TH AV NW-Contd 1ST ST NW INTERSECTS 100★Bush Alan R 852-8027 100½ ★Vinje Kevin 839-0067 102 Vacant

102½★Krout Penny

103 Garness Hardie J ⊚ 838-3691

105 Vacant

106 Happel Thos J 852-4659 110 Apartments

A★Nichols Ace C B★Pearson Josephine 852-0258 C Vacant

111 Struckness Dale E ⊚ 838-7398 114 Vacant

WALDERS ST INTERSECTS 2D NW INTERSECTS

304 Reorganized Church Of Jesus Christ-L D S 839-5197

4TH ST NW INTERSECTS 413 Grosz Gary D @ 838-4352 414★Ellis Michl © 838-1079

417 Burtman Gerald L @ 839-5039 419 Doerr Kurt M 838-8031

422 Knudson Sterling A 838-3714 423 Huizenga Thelma L ◎ 838-7953

426 Larson Rick D ⊚ 838-3528 Apartments

1 Slavens Shelly G 852-0669 429 Panasuk Orrin L @ 839-8795 5TH ST NW INTERSECTS

504 Wallin Julianne M Mrs @ 839-5341

505 Germain David A @ 839-2772 510 Vacant

524*Olsen Frank R 838-5729

600 Apartments 1 No Return

2 Abdalla Roberta 838-4301

3 Grooms Bruce 852-2709 4*Genao Juan 838-2525 608 Hargrave Robt. E @ 839-1422

610 Stiefel Nora Mrs © 839-8632 618 Riebe Mabel E @ 839-4016

620 Mc Kinzie Linda S @ 839-0102 7TH ST NW INTERSECTS

700 No Return 702 Byerly Margo J 852-3287 706★Barrett Bradley G @ 852-2366

708 Fredrickson Myrtle © 838-8607 712 Meinhardt Leroy D ⊚ 839-7842

716 Vacant 720★Mc Laughlin Tim J ◎ 852-2822 8TH ST NW INTERSECTS

800 ★Carhart Eric 806 Lovdahl Thos H ◎ 838-3503

809 Lovdahl Gerald R @ 838-2615 812 Lyon Wm R @ 852-0460

813 Rock Lucien A @ 839-3878 814 Dahl Elsie F © 838-2908

818 Linington Victor A @ 839-2477

822 Scheeler Robt J @ 838-6370

1800 S. Broadway

826**★**Gorden Zollie ⊚ 838-1582 9TH ST NW INTERSECTS 900 Momerak Andrew @ 838-1682 901 Ward Michl P 839-6705 902*Noa Butch 838-8706

905 Hanson Hannah A Mrs © 838-3937 906 Johnson Lillian O 838-4432

910 Christensen John F @ 852-6911 915 Burckhard Dennis J 852-2401

916 Wallace Gregory W K ⊚ 839-3715 917 Cartier Rene A @ 838-5269 920 Apartments

1 Madsen Marvin K @ 852-4317 2 Bond Jack R 838-5323

1000 Higgins Verlin L © 839-5887 1001 Darling Donald A @ 839-3502

1004 Carlson Hamphen C @ 838-1972 Tyson Amy Mrs 839-0510 1005 Bach Lloyd R @ 839-1244

1124 Riviera Lounge 839-9932 1200 Bray's Cleaners 852-4570

1212 Gym Dandy's Training Center 852-4585 Allen Realty (Whse) Vogue II Beauty Salon 852-6003

Klara Alteration 852-1577 1224 Vacant 1300 Oak Park Shopping Center 838-8400

Allen Realty Co 838-8400

1302 Arnie's Sewing Center 839-2503

1314 Service Shoe Shop 838-1722 1400 Oak Park Laundromat 839-9091

1400a No Return

1400b Vacant 1400c Burdick Grain Co 852-3607 1400d Four Paws Dog Grooming 852-5202

15TH ST NW INTERSECTS 1500 Minot Christian Center 852-2690 1500a Oak Park Book Gift & Sound ret

839-4740 1500b Christian Center (Annex) 1500c Christian Center (Annex) 1506 Frye Faye E Mrs © 838-0808

1507 Sjaastad Julie Lynn 1508 Merck Cecilia M Mrs © 839-3976 1509 Grosche Donald A 838-8058

1512 Mini Mart 852-5331 16TH ST NW INTERSECTS

1602 Beer Depot 852-1103 Oak Park News Arcade 839-4839 Soltis Business Forms 852-3676

1609 Meat Stop 1607 No Return 1620 Midwest Tire & Muffler 839-8046

17TH ST NW INTERSECTS 1705 J R's Texas Style Chicken & Catering Service 852-5358

1706 Vacant 1710 Mennonite Brethren Church 838-0916

18TH ST INTERSECTS

1800 Big John's Pizza restr 852-5770

JIM RYAN CHEVROLET, INC.

SALES - SERVICE

CHEVROLET Tel. (701) 852-357

23



1810 4th Av. N.W.,

T



852-2534

WHOLESALE

Box 699, 58701



40

3D ST SE-Contd 516 Weinand Fran C Mrs 839-1653 *Avitua Pedro 525 Arneberg Cecelia J Mrs ©

838-8840 529 Henjum Marion N Mrs ⊚ 838-2569

600 No Return

601 Gudmunson Sheldon L @ 852-4969

605 Dahlen Lester @ 838-0826 611 Le Duc Charles H @ 838-8935

617 No Return

Bsmt★Seright R F 839-6334 625 Pringle Kenneth G @ 838-3476

629 Olson Burton G @ 839-4550 7TH AV S E INTERSECTS 700 Westling Geo @ 839-6634

707 Vacant

710 Barnes Dennis E @ 838-9666

712 Krabbenhoft Lawrence E @ 838-5898

8TH AV SE INTERSECTS

809 Foss Bert @ 838-2064 810 Sys Joseph @ 838-2263

812 Vacant

814 Smette Geo H @ 838-8904

815 Chilson Michl D @ 838-4294

818 Maupin School Of Dance Maupin Leslie E ⊚ 838-3666

819 Colton Edith @ 838-2264

823 Samuelson Melford J @

852-4572 825 Tooley Gladys T Mrs ⊚ 838-9508

826 Fraley James A @ 838-6843 9TH AV SE INTERSECTS

900 Buggert Wm G @ 838-5219

901 Weber Del E @ 838-3291 905 Lyon John M @ 852-2005

906 Petrucci Manya Mrs © 838-0098

908 No Return

909 Gross Alma H Mrs © 838-2577

912 Gruzensky Matt @ 839-3328 Dovich Raelene 838-9393

913 Olson Edwin W @ 839-4007 916 Roen Agnes Mrs 838-5549

919 Eman Melvin R @ 839-4696

920 Haberman Donald S @ 838-8619

921 Ringdahl Wm R @ 839-1069

925 Vacant 925½ Vacant

926 Saltsman Geo J Jr @ 839-5925

10TH AV SE INTERSECTS 1000 Fink Deborah

1006 Reinke John L @ 839-6165

Bsmt Seranno Bruno 839-1517 1008 Braasch Elmer L @ 838-9632 Grondahl Karen M 839-1609

Bsmt★Zerettzke Susan 839-7289 1012 Lang Clifford A ⊚ 839-4173

1016 Rogers Kenneth R @ 852-2611

1020 Gobat Robt A @ 11TH AV S E INTERSECTS

1106 Berry Leslie L Jr 838-5065 1108 Furulie Clarence A @ 839-4592

1201 Rosehill Cemetery 12TH AV S E INTERSECTS 13TH AV S E INTERSECTS SE ST PETER AV

INTERSECTS

14TH AV S E INTERSECTS

3D ST SW -FROM CENTRAL AV SOUTH 3 WEST OF MAIN ST

ZIP CODE 58701 1ST AV SW INTERSECTS 108 Minot Electric Inc (Whse) 110 Minot Electric Inc contr 852-0551 2D AV SW INTERSECTS 213 Hennessy Tom M @ 838-5739 215 Barnett Richd D 839-6088

217 Ackerman Hannah S Mrs © 839-3991



"Everybody's" Credit Union

A CREDIT UNION FOR CITY AND RURAL RESIDENTS SAVINGS INSURED TO \$40,000 BY NOUA



TEL. 852-2018

ALL CABLE TY OF MINOT

TEL. 852-0376

1919 2d St. S.E.

P.O. Box 1606

41

3D ST SW-Contd WESTERN AV INTERSECTS 220 Vacant 222 Seney Joyce Mrs 839-5979 3D AV SW INTERSECTS

300 Interstate Trans Co (Garage) 838-3428

316 Vacant

4TH AV SW INTERSECTS 408 Peters Esther M Mrs 838-1467 412 Landry John W 839-2057

420 Valker Floral Inc & Greenhouse 852-1328 5TH AV SW INTERSECTS

6TH AV SW INTERSECTS 8TH AV SW INTERSECTS

800 Anderson Edw A @ 839-7053 803 Seel Jacob D @ 839-6046

804 Norberg Dale L @ 838-1012

805 Wengel Harold A @ 838-6735 809★Lorenzen Roger

A AV INTERSECTS

820 Parge Robt E @ 838-0850 825 Opdahl Halvor I @ 839-4649

830 Houge Apartments

A Chamberlain Joseph B 839-2254

B Clark Cora I 838-2678 C Houge Clyde H 838-4922

D*Shirley Alf C 839-1740 831 Rose Willard T @ 839-7146

840 Waller Specialty Co adv novelties 852-2324 Waller Geo J @ 852-2324

9TH AV SW INTERSECTS 901 Ross Leander F archt ⊚ 852-1854

902 Coad Ione A Mrs @ 838-9638 906 Self Ida Mrs @ 838-1449

912 No Return

1305 Kleinsasser Virgine H Mrs @ 839-6738 1316★Underdahl Ralph 839-2876

1541 South Broadway

1317 Brabandt Roger L @ 839-6577

1318 No Return

1321 Killmer Joe @ 838-4188 1324★Ensrude Eleanor M

839-3482 1327 Hayko John @ 839-5127

1332 No Return 1333★Erickson Eric P 839-4157

1335 Heinze Robt J @ 839-2919

4TH AV NE -FROM MAIN ST EAST 1 NORTH OF MOUSE RIVER

ZIP CODE 58701 11 Kinyon Willard R @ 839-2986 1ST ST NE INTERSECTS 109 Healy James H @ 838-4243

113 Vacant

117 Howell Wallace D 2D ST NE INTERSECTS

203 Bates Kathy @ 838-2429 207 Zodrow Anna E Mrs @ 838-0897

209 Kenyon Ellsworth L @ 838-4808

211 Fox Charles Jr 838-0585 MOUSE RIVER INTERSECTS

308 Northern Machine 838-1839 Western Sheet Metal Co. 839-3020

400 Minot Welding Co 838-0513 401 Cole Petroleum Co whol

838-9406 404 Faine John @ 838-8674 *Reed Leonard

415 Interstate Brands Inc (Whse) 436 Cenex Distribution Center oil

& auto parts 852-3588 6TH ST NE INTERSECTS

600 Liberty Tavern 838-9924 601 Sears (Serv Center) 852-1061 605 Vacant

614 Twin City Freight 838-2202 Swenson Rube Warehouse 839-2630

7TH ST NE INTERSECTS 706 Acme Moving & Storage Co 839-1422

Tel. 852-3505





Margaret Custom -Made Draperies

COMPLETE INTERIOR DECORATING AND INSTALLATION

 Custom Draperies

Bedspreads

Cloth Shades

Wallpaper

 Woven Wood Shades

 Carpet Cut Velvet

Valances

Custom Rods

Kirsch Hardware

 Residential Commercial

> First In Window Fashions

TEL. 839-826

> 1419-2nd Ave. S.W.



SUNDAY SCHOOL SUPPLIES
 SACRED RECORDINGS
 RELIGIOUS GIFTS

PROFESSIONAL BLDG 4th AVE AT S. MAIN BASEMENT IN REAR

BOX 757

4TH AV NE-Contd 8TH ST NE INTERSECTS 826 Robinson Insulation Co whol 852-5363 9TH ST NE INTERSECTS

17 4TH AV NW -FROM MAIN ST WEST 4 NORTH OF CENTRAL

ZIP CODE 58701 12 Downs Bessie N 852-6870 14½ Madison Berma R 838-8620 Bemt Vacant 29 No Return 1ST ST NW INTERSECTS 100 No Return 1001/2 Pulliam Kennith R 102 Vacant 1021/2 Flowers Alvie 838-5556 103 Garness Hardie J ⊚ 838-3691 105 Brown Joseph H 106 Durbin James M 107 Struksnes Harold C @ 838-4660 110 Hohmann Dean © 838-0078 111 Struckness Dale E @ 838-7398 114 Hansey Larry 838-7991 126 Sheep Shed Tavern 852-0734 WALDERS ST INTERSECTS 2D NW INTERSECTS

15 304 Reorganized Church Of Jesus Christ-L D S 839-5197 308 Vacant 312 No Return 316 Vacant 4TH ST NW INTERSECTS 406 Vacant 408 Vacant 410 ★ Drake Thos C © 852-6657 413★Copley Michl 838-2528

MOUSE RIVER CROSSES

417 Vacant 419 Phillips James E @ 839-8805

414 Donovan Mary 838-0139

422 Knudson Sterling A @ 838-3714

423 Huizenga Nick @ 838-7953 426★Ponder Richd B 838-5036 ★Halley Tick 839-1049

429 Olson Wm M 5TH ST NW INTERSECTS 504 Wallin Ralph C @ 839-5341 505 Germain David A @ 839-2772

510 Dobson Richd R @ 852-3897 524 Solberg Roger J @ 838-7367

600★Rahn Bambi D Mrs ★Molina Cindy L 839-4589 **★Lehmann Jeffrev R**

608 Watland Melvin O 839-3837 610★Stiefel Nora Mrs © 839-8632 618 Riebe Mabel E Mrs @

839-4016 620 Hovelka Arnold J 7TH ST NW INTERSECTS

700 Vacant 702±O'Brien Barry 839-2556

706 Palkovich Joseph B 839-6911 708 Fredrickson Arth C @ 838-8607

712 Vacant

716★Ziegler Barry @ 839-7681 720★Walker Hallie ◎

Roebke Cath A 839-8594 8TH ST NW INTERSECTS

800 Walsh James L @ 839-4848

806 Lovdahl Thos H @ 838-3503

809 Lovdahl Gerald R 838-2615

812 Lyon Wm R @ 852-0460

813 Harrison Evelyn G Mrs @ 839-1721

814 Dahl Manuel @ 838-2908

818 Linington Victor A @ 839-2477

822 Scheeler Robt J @ 838-6370

826 Gordon Zalman @ 838-1582 9TH ST NW INTERSECTS

900 Belinskey Carol Mrs 839-2379 Momerak Andrew © 838-1682

901 Vacant

902 Vacant 905 Hanson Hannah A Mrs @ 838-3937



Hwy. 2 East

Tel. 852-1634

Castle Construction Company

RESIDENTIAL - COMMERCIAL - BUILDING CONTRACTOR Tel. 722-3222. Tel. 839-8502 Rt. 2. Box 186

43		
4TH AV NW—Contd	1500a Burdick Grain Co grain	
906 Hanson Mae E Mrs ⊚	exch 852-3607	
838-9237	1500b Vacant	
910 Valor Lucille O Mrs ©	1500c Vacant	
852-3071	State Bd Of Registration	
915 Salo Arne A @ 838-1970	Prfssnl Engs Land Srvyrs	
916 Bergem Raymond M ⊚	852-1220	
838-3561	1506 Frye Jacob © 838-0808	
Bsmt Vacant	1507 Schmidt Stanley	
917 Bacon Grace V Mrs 🛛	1508 Merck Cecilia M Mrs 💿	
838-3070	839-3976	
Bsmt Vacant	1509 Grosche Donald A 838-8058	
920 Willoughby John D	1512 Northwest Banner Service	
1000★Higgins Verlin L ⊚	852-0756	
839-5877	Damberger Inc 838-1529	
1001 Darling Donald A ⊚ 839-3502	16TH ST NW INTERSECTS	
1004 Carlson Hamphen C ◎	23	
838-1972	1602 Oak Park Shopping Center	
Tyson Amy Mrs 839-0510	1601 Scotti Muffler Center	
1005 Bach Lloyd R @ 839-1244	839-8768	
MOUSE RIVER CROSSES	1602 Roy's Beer Depot 839-6625	
1124 Riviera Lounge 852-0932	Oak Park News Arcade	
1212 Allen Rity (Whse)	839-4839	
Clothes Rack 852-5316	1607 Vacant	
Paige's Figurama 53 colony pk 852-6720	1609 Community Development 852-3767	

1224 Oak Park White Drug 852-0388 White's One Hour Cleaners 838-0104

1300 Oak Park Shopping Center Allen Realty 838-8400

1302 Arnie's Pfaff Sewing Center 839-2503

1310 Piggly Wiggly (Br) gros 852-4458

1400 Hylander Center self serv ldnry 852-0091 Plant Factory The plantsflowers als ret 839-7927 1400a Service Shoe Shop shoe

reprs 838-1722 1400b Budget Tapes & Records

852-5321 1400d Naslund's TV Repair

839-7129

15TH ST NW INTERSECTS 1500 Oak Park Theatre 838-6008

852-3767 City Planning 852-4041 City Insp Dept 852-4041

City Engineer Dept 852-4041 1620 Garden Valley Mobil

852-0804

17TH ST NW INTERSECTS

1705 Kentucky Fried Chicken 852-4194

1706 Oak Park Tastee Freez frozen desserts dlrs 839-1565

1710 Mennonite Brethren Church 838-0916

18TH ST INTERSECTS

1800 Northwest Laundromat self serv 852-0741

1801 Marsland Realty Inc 852-3839

1809★Capaci Harold P ⊚

839-8495 1810 Wag In Tail dog groomers

838-7711 1813 Benson Kenneth @ 839-4473



HWY. 2 EAST

BECHTOLD EXCAVATING INC.

Excavating and Road Contractors

TEL. 852-4318



Midwestern Realtors.

Inc.



Jerry Harris 852-4392

Ted Schnaible 838 5673

Berny Schoenborn 839-6837

> Wayne Smith 838-5242

Lowell Strand 839-0549

> Joe Dillon 839-6357

EXCLUSIVE SALES

SOUTHDALE

852-3318

2028 South Broadway

REEVES REFRIGERATION & HEATING SUPPLY CO REFRIGERATION, HEATING & AIR CONDITIONING WHOLESALERS OF

838-0702

3D

901

905

906

908

909

912

912

913

916

919

920

921

925

925

926

Hwy. 2 and 52 W.

Who **Answered** by the Classified **Business** Lists

in this

Directory

MINOT INSURANCE AGENCY

MONTGOMERY'S OF MINOT

EVERYTHING IN INSURANCE

26 N. Main St.

Dial 838-2127

3D ST SE—Contd 901 Hicks Lula M Mrs ⊚ 905 Johnson Elmer B ⊚ 838-2677 906 Petrucci Arturo ⊚ 838-0098 908 Poss John F ⊚ 839-3463 909 Gross Alma H Mrs ⊚ 110 Minot Electric Inc contr 838-7551 2D AV SW INTERSECTS 204 Cruiser Cab Co 838-8228 ★ Amrein Raymond W ⓒ 208 ★ Miltonberger Clyde 838-	
905 Johnson Elmer B © 838-2677 906 Petrucci Arturo © 838-0098 908 Poss John F © 839-3463 2D AV SW INTERSECTS 204 Cruiser Cab Co 838-8228 **Amrein Raymond W ©	
906 Petrucci Arturo © 838-0098 204 Cruiser Cab Co 838-8228 908 Poss John F © 839-3463	
908 Poss John F @ 839-3463	
909 Gross Alma H Mrs ⊚ 208 ★ Miltonberger Clyde 838-	6517
838-2577 209 Vacant	
912 Gruzensky Matt ⊚ 839-3328 Bsmt Vacant	
912½ * Horton Larry 839-6509 210 Berg Agnes Mrs © 838-	1651
913 Olson Edwin W © 839-4007 213 * Hennessy Eileen L Mrs 916 Roen Agnes 838-5549 838-5739	
919 Eman Melvin R © 839-4696 215 Young Myrtle G Mrs © 920 Haberman Donald S © 838-2680	
838-8619 217 Ackerman Hannah S Mi 921 Ringdahl Wm R © 839-1069 839-3991	rs 🞯
925 Kingsnorth Esther A 839-5595 WESTERN AV INTERSEC	TS
925½ * Wagner Leigh 220 * Soland Margt L 838-95	
926 Saltsman Geo J Jr © 222 Seney Joyce Mrs 839-597	
839-5925 3D AV SW INTERSECTS	-
10TH AV SE INTERSECTS 300 Interstate Trans Co (Gar	rage)
1000 No Return 838-3428	•
1006 Reinke John L @ 839-6165 316 Vacant	
* Veiluva Michele 4TH AV SW INTERSECTS	3
1008 Braasch Elmer L @ 838-9632 408 Peters Esther M Mrs 83	8-1467
* Fox Ronald 838-6871 412 Landry John W 839-205	7
Bsmt * Saint Clair Lola 420 B & B Plumbing & Hea	iting
1012 Thompson Henry L @ Co contr 838-2822	
838-3638 5TH AV SW INTERSECTS	S
1016 Rogers Kenneth R ⊚ 838-9611	7
1016½ Ruud Edw W 838-9611 6TH AV SW INTERSECT	S
1019 Vacant 8TH AV SW INTERSECT	S
1020 Gange Albin P 838-2214 800 Anderson Edw A @ 839	-7053
11TH AV S E INTERSECTS 803 Seel Jacob D © 839-604	
804 Norberg Dale @ 838-101	12
10 805 Wengel Harold A ◎ 83	8-6735
1106 Esser Leo F ⊚ 839-1943 809 ★ Hoffman Thos 838-4331	L
1108 Furulie Clarence A A AV INTERSECTS	
839-4592 820 Parge Robt E @ 838-08	50
★ Everson Betty J 839-5905 825 Opdahl Halvor I ◎ 839	-464 9
1201 Rosehill Cemetery 830 Waller's Apartments	_
12TH AV S E INTERSECTS A Pearson John 838-3608	3
13TH AV S E INTERSECTS B Martinsen Leland F	

leating TS TS TS 39-7053 046 1012 838-6735 331 0850 39-4649 308 838-5902 C Houge Clyde H 838-4922 D * Mueller Allen 838-2590 831 ★ Rathbun Raymond A ◎ 838-2584 840 Waller Specialty Co adv novelties 839-1324 Waller Geo J @ 839-1324 9TH AV SW INTERSECTS 901 Ross Leander F archt @ 838-1854 902 Coad Melvin S @ 838-9638 906 Self Ida Mrs © 838-1449

Culligan WATER CONDITIONING

6TH ST NE INTERSECTS .

601 Sears Serv Center 838-7061

614 Twin City Freight 838-2202

Northwest Spraying Service

Swenson Rube Warehouse

7TH ST NE INTERSECTS

8TH ST NE INTERSECTS

9TH ST NE INTERSECTS

826 Robinson Insulation Co whol

605 Mobil Oil Co (Bulk Plant)

600 Liberty Tavern 838-9924

838-0012

839-2630

838-1991

Inc 839-5603

24 2d N.E.

Tel. 838-3305

37

3D ST SW-Contd 912 Vacant

10TH AV SW INTERSECTS 11TH AV SW INTERSECTS 1305 Kleinsasser Virgiene Mrs ⊚ 839-6738

1316 Underdahl Johanna Mrs @ 839-3223

1317 ★ Brabandt Roger © 839-6577 1318 Wright Bruce @ 838-6045

1321 * Beck Norman H 838-7877 1324 * Polnizak John 838-6618

1327 Hayko John ⊚ 839-5127

1332 Sorenson Larry D 839-4539 1333 Vacant

1335 Vacant

RIVER

7

ZIP CODE 58701

113 * Lamb Michl S

839-2986

117 No Return

11 Kinyon Adeline S Mrs

1ST ST NE INTERSECTS

2D ST NE INTERSECTS

207 Zodrow Anna E Mrs ©

4TH AV NE -FROM MAIN ST EAST 1 NORTH OF MOUSE

ZIP CODE 58701 12 Callies Rueben W @ 838-3695 141/2 Halstead Berma R Mrs 838-6681

25 * Doubek Wm J 839-6131 25½ ★ Jenkins James

106 Krefting Arth F @ 838-3675

110 Mc Diarmid Gloria Mrs Kessler Sally Mrs 838-3974 Rogers Lyle W 839-1554

111 Vacant

838-1998

126 Sheepshed Bar 838-9734 WALDERS ST INTERSECTS 2D NW INTERSECTS MOUSE RIVER CROSSES

839-7444

310 Vacant

311 * Akerlind Carol 839-4049

Bechtold **Excavating** Inc.



ALL **TYPES** OF **EXCAVATION**

TEL. 838-4318

HWY. 2 EAST

Classified than are Business any boug other Lists medium and 약 Plos ≠e 9 through Directory earth

4TH AV NW —FROM MAIN ST WEST 4 NORTH OF CENTRAL

Bsmt Larsen Connie 838-7845 29 * Martinson Myrna J 838-6474 1ST ST NW INTERSECTS 100 * Miller Wm D 838-5265 1001/2 Stach Balzer 838-0106 102 ★ Esser Darlene Mrs 838-8629 1021/2 No Return 103 Garness Hardie J ⊚ 838-3691 105 * Griffin David 838-7119

838-0897 209 Kenyon Ellsworth L @ 838-4808

211 Fox Charles Jr 838-0585

3D ST NE INTERSECTS 304 Balerud Ben @ 839-4682

308 Northern Machine 838-1839 Western Sheet Metal Co. 839-3020

315 Vacant

400 Minot Welding Co 838-0513

401 Cole Petroleum Co whol 838-9406

404 Faine John @ 838-8674 * Greenwell Joe 838-9384

436 Farmers Union Central Exchange oil & auto parts 839-7588

506 Alderman Leon 839-2413 5061/2 Bjorn Edw 839-6746

508 Sanderson Clarence J

510 Vacant

120 1 SE ST PETER AV

INTERSECTS 14TH AV S E INTERSECTS

11 3D ST SW -FROM CENTRAL AV SOUTH 3 WEST OF MAIN ST

ZIP CODE 58701 1ST AV SW INTERSECTS 104 Vacant 108 Minot Electric Inc Whse

109 Healy James H @ 838-4243 203 Oen Andrew A @ 839-3896

107 Vacant

114 Mc Intosh Kathryn Mrs ©

15 304 Reorganized Church Of Jesus Christ-L D S 838-8800

308 Kavlie Hampton A Rev @

838-9191

NORTHWEST COLLECTION AGENCY Collection No Charge"

Collect Professional - Retail and Wholesale Accounts

Central Ave., 58701

Where To Buy?

Consult the Classified Business Lists This Directory

ATLAS READY-MIX OF MINOT, INC.

4TH AV NW---Contd 312 Vacant 315 Warke Anna M Mrs © 838-9663 322 Wentz Leona A @ 4TH ST NW INTERSECTS

406 * Wetmur James 839-1560 408 Vacant

410 Vacant

413 ★ Hoveskeland Raymond P ⊚ 838-6354

414 Vacant

417 Vedvig Marvin E 839-5039

419 Hanson Evonne J Mrs © 838-4692

422 Knudson Sterling A @ 838-3714

423 Washek Thelma L Mrs © 838-7953

* Johnson Brien C 838-7953

426 * Ward Lance D 838-4390 * La Sova Frank 839-6877

* Norris James 838-4024 429 ★ Fonder Leroy M © 838-9443 5TH ST NW INTERSECTS

504 Wallin Ralph C ⊚ 839-5341 505 Germain David A ⊚ 839-2772

510 Sahl Elaine E Mrs ⊚

839-7011 524 Vacant

600 * Spence Joe L 838-5043

* Hartwell Geo 839-4112 * Robertson Wayne

6001/2 Vacant

608 Watland Melvin O 839-3837

610 Sherwood Juanita M Mrs 838-4630

618 Riebe Mabel E Mrs @ 839-4016

620 Vacant

7TH ST NW INTERSECTS

700 No Return

702 Vacant 706 Vacant

708 Fredrickson Arth C @ 838-8607

712 Rehor Celestine L Mrs © 838-9346

716 Steinborn Harold H ⊚ 839-6734

720 Sailman Bertha M Mrs © 839-1438

8TH ST NW INTERSECTS 800 Walsh James L @ 839-4848

806 Lovdahl Thos H @ 838-3503 809 Jacobsen L Mrs @ 838-0930

812 Lyon Wm R @ 838-5063

813 No Return

814 Dahl Manuel @ 838-2908

818 Linington Victor A @ 839-2477

822 Norem Grant M @ 838-8608 826 Gordon Zalmon @ 838-1582 9TH ST NW INTERSECTS

900 Belinskey Carol Mrs 839-2379 Momerak Andrew © 838-1682

901 Higgins Verlin L 839-5887

902 Reutter Joe T 839-6728

905 Hanson Hannah A Mrs © 838-3937

906 Hanson Mae E Mrs © 838-9237

910 Valor T Alfon @ 838-3071 **★Otterson Robt M 839-7490**

915 Salo Arne A @ 838-1970 916 Bergem Raymond M @

838-3561

Bsmt * Keller Donald J 839-3268 917 Bacon Grace V Mrs @ 838-3070

Bsmt ★ Keefer Alf A Jr 839-7196 920 * Eliason Kelly 838-3201 Alme Paula J 838-4990

1000 Schmidt Russell K @ 839-4657

1001 Darling Donald A @ 839-3502

1004 Carlson Hamphen C @ 838-1972 * Hough Donna E Mrs

839-6889 1005 Bach Lloyd R @ 839-1244

MOUSE RIVER CROSSES

1124 Riviera Lounge Inc 838-9932

1212 Under Constn 1220 Under Constn

1224 Oak Park White Drug 838-0388 White's One Hour Cleaners

838-0104

1300 Oak Park Shopping Center Allen Realty 838-8400

1302 R & L Maytag Home Appliance Center 838-7571

1310 Piggly Wiggly (Br) gros 838-5458

1314 American Family Mutual Ins Co 838-7078

Arnie's Pfaff Sewing Center 839-2503

Marsland Fourth Ave Realty 838-6185

4TH AV NW-Contd

1400 Hylander Center self serv ldnry 838-9741

Oak Park Beauty Salon 839-3616

United Tribes Employment Training Center 838-5494 15TH ST NW INTERSECTS

1500 Oak Park Theatre 838-6008 1500a Mc Millan Co The grain exch 839-7607

1500b Vacant

1500c Benson-Quinn Co (Br Ofc) grain broker 838-5475

1506 Frye Jacob @ 838-0808

1507 ★ Bauer Terrance

838-3955

1508 Merck Cecilia M Mrs 1512 Northwest Sixty Six Service

16TH ST NW INTERSECTS

1602 Oak Park Shopping Center Oak Park Westland 838-9001 Oak Park Barber Shop 839-6593

Roy's Beer Depot 839-6625 Oak Park News Arcade 839-4839

Naslund T V Repair 839-7129

1607 Souris Liquor Store 839-2441

1609 Garden Valley Miracle Mart ret gro 839-2420

1620 Garden Valley Exxon 839-6652

17TH ST NW INTERSECTS 1705 Mc Dowell's Big Boy Take-

Out 839-7771 1706 Oak Park Tastee Freez frozen desserts dlrs 839-1565

18TH ST INTERSECTS 1800 Northwest Laundromat self

serv 838-9737 1801 Owner Direct Real Estate

brokers 838-2131 Mennonite Brethren Church 838-0916

1809 Sersland Conrad H @ 838-5575

1810 Color Processing Center film developers 838-1090

1813 Benson Kenneth @ 839-4473

1820 Time Rentals rental equip 838-7450

Webster Foster & Weston consulting eng 838-9516 19TH ST NW INTERSECTS 1900 Trails Inn Restaurant

838-7740 1909 Karpenko Jean G Mrs © 839-5177

1913 Rodgers Harrison B ⊚ 839-3845

1924 Johnson's Northwest Standard Service 838-9895 Ackerman Peter

20TH ST NW INTERSECTS

2001 Vacant

2010 Northwest Executive Building

Alice's Beauty Salon 838-3068

State Farm Auto Insurance (Claims Ofc) 838-4919 National Guardian Life Ins

Co 838-9255 Hendrickson Chuck Agency

real est 839-5747 Leonard Edmond C archt 838-1130

Provident Life Insurance Co 838-3532

Miller Gordon N lwyr 838-1755

2021 Minot Paint & Glass Co Inc

838-1625 2022 Heisler's Gro (Stge)

2024 Louie's Barber Shop 21ST ST NW INTERSECTS

2108 Granite Springs Refrigerator Service 838-5039

2116 Anderson Wade & Barsness archts 838-5661

2120 Lindsay Soft Water Service 838-5448 Minot Protective Assn

838-5448 22D ST NW INTERSECTS

2200 Price Dale © 838-3192 Bsmt Vacant

2209 Saint Mark's Lutheran Church 839-4663

2212 Olson Richd B @ 838-0228

2309 Peterson Dennis E @ 838-5536

2409 Gilfus Geo A @ 839-7032

U The Alphabetical Section to get Complete Information on a person or firm.

KEITH BONE AND BRAKE HE ATING PLUMBING Tel. 839-6350 or 839-1700

Hwy. 2 Easi

Consult the CLASSIFIED LISTS of the DIRECTORY

If You Would Find What You Wish to Buy

MINOT INSURANCE AGENCY

EVERYTHING IN INSURANCE

26 N. Main St.

Dial 838-2127

3D ST SE--CONTD --- 11TH AV SE INTERSECTS

1106 ESSER LEO F 839-1941 1108 FURULIE CLARENCE A . 839-4592 1201 ROSEHILL CEMETERY ---12TH AV SE INTERSECTS ---13TH AV SE INTERSECTS ---SE ST PETER AV INTERSECTS ---14TH AV SE INTERSECTS

11-3D ST SW -FROM CENTRAL AV SOUTH. 3 WEST OF MAIN ST

---ZIP CODE 58701 ---1ST AV SW INTERSECTS 101 MOVERS INC 838-5666 ANDREW'S VAN LINES INC 838-5666 GLOBAL VAN LINES INC 838-5666 LYON'S VAN LINES INC 838-5666

104 WESTSIDE HOTEL 838-9989 WESTSIDE BAR TAVERN 838-9989

108 MINOT ELECTRIC CO WHSE 110 MINOT ELECTRIC CO.

CONTR 838-7551 115 DI BRILL RAYMOND

--- 2D AV SW INTERSECTS

204 VACANT 208 CRUISER CAB CO

838-8228 AMREIN RAYMOND W 838-8228

209 LEE FRANK R 838-6646 BSMT VACANT

210 BERG AGNES MRS . 838-1651

213 VACANT

214 HALSETH FLORENCE F MRS 839-5384

LAUTENSCHLAGER EUG 215 YOUNG MYRTLE G MRS .

217 ACKERMAN HANNAH S MRS

0 839-3991

---WESTERN AVE INTERSECTS 220 REGISTER GARY L . 838-9510

222 FALCON BETTY L MRS 839-2947

--- 3D AV SW INTERSECTS 300 INTERSTATE TRANS CO

(GAR) 838-3428 316 GRILL THE RESTR

838-9050 GOVAN DEE D 838-9050 --- 4TH AV SW INTERSECTS

408 PETERS ESTHER M MRS 838-1467

412 LANDRY JOHN W 839-2057 420 B & B PLUMBING &

HEATING CO CONTR 838-2822

--- 5TH AV SW INTERSECTS

--- 6TH AV SW INTERSECTS

--- 8TH AV SW INTERSECTS 800 ASPAAS RALPH P .

839-4436

803 JOHNSON DUANE A . 839-3444

804 LYLES ILLADELL MRS .

805 WENGEL HAROLD A . 838-6735

809 PIXOMATIS JUSEPH . 838-2267

---A AV INTERSECTS

812 VACANT

820 PARGE ROBT E . 838-0850

825 OPDAHL HALVOR I .

839-4649 830 WALLER'S APARTMENTS

A PEARSON JOHN 838-3608

B MARTINSEN LELAND F 838-5902

C HOUGE CLYDE H 838-4922

D MOREY A D 839-4881

831 COLLINS GARNETT I . 839-4156

840 WALLER SPECIALTY CO ADV NOVELTIES 839-1324

> WALLER GEO J . 839-1324



TEL. 839-2151

HIGHWAY 83 N. MINOT, N. D. 58701

MINOT LUMBER & HARDWARE CO.

TOYS

"Your Hardware Store"

315 MINOT GRAIN INSPECTION

838-1734

1700 S. Broadway St.

Tel. 838-2591

45

3D ST SW--CONTD --- 9TH AV SW INTERSECTS 901 ROSS LEANDER F ARCHT 838-1854 902 COAD MELVIN 5 . 838-9638 906 SELF IDA MRS . 838-1449 912 KLEIN WM P 839-1733

----10TH AV SW INTERSECTS ---11TH AV SW INTERSECTS 1305 KLEINSASSER VIRGINIA MRS .

1316 UNDERDAHL JOHANNA MRS 839-3223

1317 CARLSON HJALMER & SON SAN SERV GARBAGE COLLN 838-2364 CARLSON HJALMER A . 838-2364

1318 VACANT

1321 VACANT

1327 HAYKO JOHN . 839-5127

1332 OFFICER JOYCE A MRS 838-4898

1333 VACANT

1335 PETERSON AUGUST 838-5263

4TH AV NE -FROM MAIN ST EAST. 1 NORTH OF MOUSE RIVER

---ZIP CODE 58701 11 KINYON LAWRENCE H 839-2986

--- 1ST ST NE INTERSECTS

109 HEALY JAMES H . 838-4239

113 KAPANDAHL ANNIE MRS 117 VACANT

--- 2D ST NE INTERSECTS 203 DEN ANDREW A .

839-3896 207 ZODROW WM H . 838-0897

209 KENYON ELLSWORTH L

211 FOX CHARLES JR 838-0585

---3D ST NE INTERSECTS 304 FILLER GARAGE AUTO

REPR 838-0552 304A BALERUD BEN . 839-4682

308 NORTHERN MACHINE 838-1839

WESTERN SHEET METAL CO 839-3020

400 MINOT WELDING CO 839-0513 401 COLE PETROLEUM CO WHOL 838-9406 404 FAINE JOHN . 838-8674 HOSKINS HARRY 433 VACANT 436 FARMERS UNION CENTRAL EXCHANGE DIL & AUTO PARTS 839-7588 506 MEYERS LINDA MRS 506% BELL ART 506%A WELLCOME CLARENCE O 506%8 BJORN EDWIN O 506%C HOLLAND CONNIE 508 SANDERSON CLARENCE J . 510 LIBERTY GROCERY & MEAT MARKET 510% WOODS ROBERT --- 6TH ST NE INTERSECTS 600 LIBERTY TAVERN 838-9924 601 SEARS SERV CENTER 838-7061 605 MOBIL OIL CO (BULK PLANT) 838-0012 614 EVANS TRANSFER INC 838-2202 STOHR'S DELIVERY &

801 VACANT 826 ROBINSON INSULATION CO WHOL 838-1991

--- 9TH ST NE INTERSECTS

MOVING 839-4506

---7TH ST NE INTERSECTS

---8TH ST NE INTERSECTS

4TH AV NW -FROM MAIN ST WEST. 4 NORTH OF CENTRAL

---ZIP CODE 58701 12 CALLIES RUEBEN W . 838-3695

12% DAY BERNARD 839-5035

14% SMITH ELEANDR MRS . 838-3884

20 VACANT 24 VACANT

25 NORSBY MYRTLE A MRS 839-4560

25% COREY SALLY A 839-7315

29 KNUDSVIG LARRY E 839-5954

BSMT REZIN JOHN C ---1ST ST NW INTERSECTS 100 WEBSTER BETTY M 839-1539

4

0

MINOT STEAM LAUNDRY

ONCE A CUSTOMER, ALWAYS A CUSTOMER

202 1st St. S.W.

Tel. 838-3420

4TH AV NW--CONTD 100% STACH BALZER 838-0106 102 HANNEMAN LARRY 102% HALL LAURENCE R 838-5034 103 GARNESS HARDIE J .

838-3691 105 HOAR HELEN G 839-1802 106 KREFTING ARTHUR F .

838~3675 107 GABRIEL KENNETH A

839-4064 110 TOFTELAND GERALD L

838-3020 DIBBLE DAVID G 838-5806

CONNAN ROBBIE L 111 STRUCKNESS MELVIN T . 838-2608

114 MC INTOSH GEO A . 838-1998

---WALDERS ST INTERSECTS --- 2D NW INTERSECTS --- MOUSE RIVER CROSSES

304 OUR REDEEMERS LUTHERAN BRETHREN CHURCH

308 STORRY ALDRICH REV . 839-7444

310 OLSON NORMAN L .

311 ARNOLD CLARENCE W

312 BULLOCK FLORENCE L MRS 838-2256

315 WARKE ANNA M MRS . 838-9663

BSMT HENSLEY MICHL L 838-4723

316 REID O GLENN •

317 PETERSON LEONARD E . 838-8642 VERNOT YVONNE

319 WARKE ANDREW C . 839-2008

SMOLENSKY PETER 320 FLORAL REBEKAH LODGE NO 14

MINOT LODGE NO 45

(100F) 322 WENTZ LEDNA A .

324 DALY STAN

329 HANSON PETRA B MRS . 839-2071

330 PETERSON SEWALL E 838~2056

335 AUSHERMAN DONALD R . 838-9306

336 APARTMENTS

1 SCHWARTZ NORMAN J 839-1884

2 WEST KENNETH A 839-6902

3 BEEDY MICHL F 838-2735

4 BELL JAMES R 839-5866

--- 4TH ST NW INTERSECTS

405 NO RETURN

406 ENGEBERG ELMER E 838-3850

408 GOGENES LUVERNE K . 839-2285

410 TAYLOR HARVEY A . 838-3269

413 KELLER FRANCIS B 839-2385

414 SORENSEN ANNA M MRS . 838-1793

417 VEDVIG MARVIN E 839-5039

HANSON OLAF B .

838-4692 422 KNUDSON STERLING A .

838-3714 423 WASHEK THELMA L MRS .

838-7953

426 HARRIS DAVID 838-9289 NELSON FREDRICK C 839-2428

WRIGHT GILLIS H 839-3797

429 HARRINGTON RUSSELL . --- 5TH ST NW INTERSECTS

504 WALLIN RALPH C . 839-5341

505 GERMAIN DAVID A . 839-2772

510 SAHL JENS JR . 839-7011

524 STEENSTRUP GAIL S MRS

• 838-1066 600 PETERSON ELIAS .

838-8700 BERG MELVIN 0 838-3663

JORGENSON FRED C

839-4183

MOWBRAY & SON PLUMBING & HEATING, Inc.

PLUMBING - HEATING M & S ROOFING & SHEET METAL INC. 300-310 N. Broadway St.

Dial 838-5491

4TH AV NW--CONTD 600% LUNDT ELMER V 839-3662 608 SUCKERT LELAND 838-7923 610 RICE ROY A 839-2232 618 RIEBE MABEL E MRS . 839-4016 620 NORDMARK PAUL L . 839-5157 --- 7TH ST NW INTERSECTS 700 REISHUS GEO A 838-3050 702 FUCHS LOUISE MRS 838-8408 706 LANGORD CLIFFORD A 838-8171 708 FREDRICKSON ARTH C . 838-8607 712 REHOR CELESTINE L MRS 9 838-9346 716 HAPPEL ERNEST H . 839-3941 720 SAILMAN AUG N . 839-1438 JOHANSEN JOHANNES 839-1424 --- 8TH ST NW INTERSECTS 800 WALSH JAMES L . 839-4848 BSMT HOFER JEFFREY 806 LOVDAHL THOS H . 838-3503 809 JACOBSEN LEURENCE MRS 838-0930 812 LYON WM R . 838-5063 813 HARRISON WM S . 839-1721 814 DAHL MANUEL . 838-2908 818 LININGTON VICTOR A . 839-2477 . 822 NOREM GRANT M . 838-8608 826 GORDON ZALMON . 838-1582 --- 9TH ST NW INTERSECTS 900 BELINSKEY CAROL MRS 839-2379 MOMERAK ANDREW . 838-1682 901 HIGGINS VERLIN L 839-5887 902 DICKERSON CECIL R 839-2355 905 HANSON HENRY M 838-3937 906 HANSON MAE E MRS . 838-9237 909 HAMILTON BERNARD 838-4473 910 VALOR T ALFON . 838-3071 BSMT LEE LAWRENCE M 839-4484 915 SALO ARNE A . 838-1970 916 BERGEM RAYMOND M . 838-3561 BSMT VACANT 917 BACON GRACE V MRS . 838-3070

1004 CARLSON HAMPHEN C . 838-1972 HOLEN GERALD L 838-5601 1005 BACH LLOYD R . 839-1244 ---MOUSE RIVER 1124 RIVIERA LOUNGE TAVERN 838-9932 1212 UNDER CONSTN 1220 UNDER CONSTN 1224 OAK PARK WHITE DRUG 838-0388 WHITE'S ONE HOUR CLEANERS 838-0104 1300 DAK PARK SHOPPING CENTER ALLEN REALTY 838-0922 1302 R & L MAYTAG HOME APPLIANCE CENTER 838-7571 1310 BIG DOLLAR REDEMPTION CENTER PREMIUM STORE 838-4104 PIGGLY WIGGLY (BR) GROS 838-5458 1314 AMERICAN FAMILY MUTUAL INS CO 838-7078 ARNIE'S PFAFF SEWING CENTER 839-2503 1400 HYLANDER CENTER SELF SERV LDNRY 838-9092 ---15TH ST NW INTERSECTS 1500 DAK PARK THEATRE 838-6008 1500A SHEA'S RADIO SERVICE 838-1512 TIME SHOP WICH REPR 838-1148 1500B ARTISTRY IN HAIR FASHION 838-1432 ARTISTRY WIG SALON 838-1409 1500C MUTUAL & UNITED OF OMAHA INS 839-3682 DSBORNE-MC MILLAN ELEVATOR CO (DIST OFC) GRAIN 838-5475 1500A SHEA'S RADIO SERVICE 838-1512 1506 FRYE JACOB • 838-0808 1507 WEBSTER CHRISTINE MRS 839-1471 1508 NORTHWEST 66 SERVICE GAS STA 838-3955 MERCK MICHL . 839-3976 1509 GROSCHE HARRY R . 839-2495

BSMT ADAMS WM 838-5281

1000 GILTNER SIGNE B MRS .

920 ALMA ARNOLD T .

839-4950

838-1935

1001 MACKLEY JOSEPH R .

838-4990

921 VACANT

H₩y. Modern ~ and 52 CONCRETE By-Pass WORK West æ \bar{s} OUR Ons SPECIALT truction, 838-756

Concr

8

m 5 C **50 to** Complet rson Alp F P Infor ica ma, Ü <u>ط</u>ر

NORTHWEST BIBLE COLLEGE

B.A. - RELIGION A.A. - LIBERAL ARTS

SACRED MUSIC -- PRIVATE LESSONS BY APPOINTMENT 1900 VALKER ROAD TEL. TEMPLE 6-8120

48

4TH NE-Contd 1300 Vacant 1301 Bakeman Chas J TE6-6247 1305 Riehm John F @ TE8-0191

1309 Smith Gerald D TE3-7175 1310 Doerr Masonry Co TE7-6220 Doerr Alan L @ TE7-6220

4TH AVENUE NORTHEAST-From Main east to 9th, 1 north of Mouse River at Main

11 Kinyon Willard @ Kinyon Lawrence H TE5-2286

1st NE intersects 109 Muhs Agnes Mrs TE3-5152 113 Lindquist Allan A

TE5-2141 117 Scheltens Ronald E TE2-6164

2d NE intersects 203 Oen Andrew A @

TE5-6296 207 Zodrow Wm H @ TE4-2197

209 Anderson Robt E TE2-0165

Bob's Drywall Service TE2-0165

211 Fox Chas jr TE3-9285 3d NE intersects 304 Filler Garage TE3-9252

304a Balerud Ben © TE6-0282 308 Western Sht Mtl Co TE5-3120

Northern Mach TE2-3239 315 Minot Grain Inspection

TE2-3134 400 Minot Welding Co

TE3-9213 401-03 Cole Petroleum Co whol

TE3-6206 404 Faine John © TE3-3282 Walter Robt TE3-3274

433 Allied Contractors Inc TE8-6300

436 Farmers Union Central Exch oil and auto parts TE6-9161 506 Bounting Alfred S

TE8-5166 506 ½ Wertiko Field TE7-5146 508 Bristol Theo

510 Liberty Gro & Meat Mkt TE3-4119

510 ½ Vacant 6th NE intersects

600 Liberty Tavern beer TE5-9224

601-721 Internatl-Harvester Co (whse)

605 Mobil Oil Co bulk sta TE3-8212

614 Evans Transfer Inc TE2-8202

Bingenheimer Warehouse stge TE4-9220

7th NE intersects 8th NE intersects

801 Minot Fuel Co TE3-2190 826 Robinson Insulation Co

whol TE2-4191

9th NE intersects

4TH NORTHWEST-From GNRv north to 9th av. 4 west of Main at 4th av 1st av NW intersects

101a Lee Nellie

rear Pickett Chelsea E TE5-8184

102 Darl Apartments TE5-6126

Apartments: A Johnson John A TE3-3203

B Ludemann Thos H TE5-3222

C Masteller Clyde V TE4-4275

D Masteller Clyde V TE4-4275

D O'Neil Raymond E TE8-0205

E Baker Darl L @ TE5-6126 rear Fox Carl TE3-6138 Street continued

49 4TH NW-Contd 323 Irwin Roy W TE8-5140 105 Skogstad Carl ® 4th av NW intersects 405 Apartments TE2-3202 Whitaker Roy A 1 Fahy Mary J 837-7157 TE8-3285 2 Boschert Rose G Mrs 108 Kinsella Beata Mrs ⊚ TE4-9237 3 Hagen Geo R TE5-4191 TE4-4161 111 Doyle Lawrence J @ 4 Shanaver Jerry H TE2-7197 TE8-3174 111½ Christianson Gust A 5 Engberg Elmer TE2-7150 Street continued TE4-7185 407 Klimpel Emma Mrs © 112 Perekrestenko Geo E TE6-6146 TE5-8168 115 Husby Lyell M @ 414 Berg Milton A TE3-6258 TE3-0291 416 Jacobson Larry M 115½ Ring Myron L TE7-5177 116 Rein Albert J @ 416 ½ Schwope Neil E TE3-4211 418 Woodiwiss Floyd C ⊚ TE3-3291 2d av NW intersects TE3-2255 200 Blair Lucille Mrs ⊚ 419 Apartments A Dickey Reese M TE5-4194 TE3-3180 201 Berdine Henry G @ B Tryhus Sylvia Mrs TE3-7158 833-5190 204 Bowman Alice L Mrs ® C Aton Almyra V Mrs TE4-6177 TE2-7127 205 Skarsgard Clara S Mrs © D Krueger Jessie E Mrs TE2-5146 834-5180 206 Kossan Peter © TE2-8255 5 Tryhus Sylvia I Mrs 209 Wood John K @ TE4-4165 TE3-5190 214 Stevens Dagmar Mrs @ TE6-2235 Street continued 422 Witt Ehtel C Mrs © Adkins Jerry W TE4-2139 bsmt Oakland Clarence Vick Lloyd J TE8-1117 215 Peterson Dorothy C Mrs @ 424 ½ Slotsve Leo H ⊚ 219 Kruger Robt D @ TE7-4229 426 Bold Howard H @ 221 Snyder Mary Mrs @ TE8-4355 426 ½ Brodell Jacob ⊚ TE5-2261 225 Unruh Milton D TE6-7254 TE4-3143 3d av NW intersects 427 White Vern E @ 301 Gourley Ray TE3-3175 303 Sevland Ole M @ TE4-9132 428 Pierson Clayton E Sevland's Spraying TE6-8160 Mouse River Serv TE4-9132 305 Mona Reuben E

17 5th av NW intersects 503 Thomas Yates © TE3-4172 505 Storbeck Henry W @ TE3-4272 506 Smette Ingel O @

TE6-4266 509 Ganskop Irene Mrs TE5-2159

MAIN 灣ELECTRIC襲,

ELECTRIC CONTRACTORS

501 8th ST. N.E.

316 Vacant

TE6-5120

309 Spankie Jas R TE6-4222

313 Soberg Jos A TE2-3290

320 Fletcher Linda L

315 Hunter Ottawa I TE5-7204

Quinlen Tillie Mrs

TE2-9271

PHONE TEmple 8-5404



WRECKER 0 SERVICE P

Minot TEmple 6-1171

COMPANIES GOOD ENOUGH
3-2217 AND TEMPLE 3-3217 AG

Ŋ

RAMSTAD AGENCY

GENERAL INSURANCE COVERAGE AND BONDS

Personal - Mercantile - Dwelling - Automobile 504-506 1st AV. BLDG. A. A. RAMSTAD, Mgr. PHONE TEmple 4-1107

4TH NW-Contd 510 Hoppman Emily Mrs @ TE3-4255 516 Landis Albert L @ TE2-8249 520 Wagner John E TE5-8136 6th av NW intersects 600 Hill Lloyd TE2-4131 601 Lincoln Park 604 Hill Bertha Mrs © TE2-7145 608 Jordahl Earl A @ TE2-4182 Lincoln av intersects 7th av NW intersects 704 Ystes Chas E TE7-0213 705 Flammang Leo J ⊚ TE2-4181 710 Serdahl Donald H TE7-5160 715 Morey Eva V Mrs © TE4-7207 716 Vacant 719 Tau Kappa Epsilon Fraternity TE2-2100 725 Lierbo Alvin M @ TE3-5249 8th av NW intersects TE4-7217

800 Johnson Ella G Mrs © 803 Gay Marlin L TE5-7288

804 Sperry Gladys Mrs © TE2-4118

805 Matte son Roy I @ 837-6269 807 Aboltins Raimunds O @ TE5-6172

9th av NW intersects

4TH NORTHWEST-From Anderson dr north to city limits

20th av NW intersects 2000 Berry Joseph TE3-5132 2001 Hugh Leroy TE5-5159 2002 Ridgeway Robt J

TE7-0138 2003 Alexander Howard

TE6-7269 2004 Henry Chas B

2006 Whorten Wm M

2008 Glaason David TE8-6097 2010 Nash Jimmy D TE4-9285 2011 Apartments

1 Griffin Jas K TE7-0130 2 Sjol Dennis A TE8-5194

3 Treacy Wm TE8-6397

4 Kennedy Richd C TE6-6217 Street continued

2012 Vacant 2014 Vacant 2015 Apartments

1 Danhof Roger J TE7-0156

2 Pope Ted 3 Greenwood Robt B

TE5-6157

4 Slotsve Ronald E TE7-7294

Street continued 2018 Apartments

1 Polglaze Edw TE6-6279

2 Patterson Forrest E TE8-5284

3 Larson Tyler B TE8-4151 4 Pfau Harvey A TE8-4419

Street continued 2019 Apartments

1 Welty Noel D TE7-4292

2 Horn Wm TE8-6557

3 No Return 4 Merkel Carl G

Street continued 2026 Apartments

1 Zeller Gordon H 836-2155

2 Johnson Martin A

TE7-9119

3 Price Harry TE8-3274 4 Maragos Ted TE6-3234

Street continued 2029 Apartments

1 Walton Don F TE3-6163

2 Vacant

3 Baxter Leland O TE6-5142 4 Albins Billy F 832-2598

Street continued 2032 Apartments

1 Nichols Alf R TE8-4537

2 Whisler Larry D

3 Makcey Horace TE8-0169

4 Brintnoll Wm E TE2-3198 Street continued

2035 Apartments 1 Dalthorp Chas H TE8-1279

2 Kaseman Edw TE2-8169

BENTON LATHING CO.

SIMPSON ACOUSTICAL PRODUCTS TILE - LATHING - PLASTERING

1224 - 6th AV. N.E.

TEL. TEmple 4-2136

Gate City Savings and LOAN ASSOCIATION

300 1st St. SW

Tel. TEmple 2-1171

51

4TH NW-Contd 2035 Apts-Contd

3 Schmaly Bennie J TE7-9250

4 Dobson Shirley TE7-3153 Street continued

2038 Apartments 1 Christy Ray TE7-3132

2 Watson Jesse V jr TE4-8294

3 Albins Dennis

4 Becker Robt T TE8-5860 Street continued

2041 Apartments

1 Barrows Barbara Mrs TE8-5614

2 Jagd Robt W TE2-0202 3 Neperud Jerome J

TE8-6338 4 Galindo Raymond TE4-4136

Street continued 2046 Apartments

1 Lewis Raymond TE8-1125 2 Wentz Ronald R TE4-2211

3 Adams Wayne TE7-5233

4 Robbins Wm Street continued 2047 Apartments

1 Barrow Nancy J 838-4127

2 No Return

3 Zieour David W TE5-4167

4 Kallias Richd J 838-0274 Street continued

2400-2502 Northdale Apartments

2400 Apartments

1 Roberts Larry G TE6-6264

2 Maaher Wm J TE7-4103

3 Owens Donald J TE5-5266

4 Ketchum Richd W TE6-8204

5 Bennett H G TE2-6134 6 Johnson Jerome P

TE4-6232 7 Brandt Evelyn M Mrs

8 Stewart James E TE7-5155

Street continued 2410 Apartments

1 Marshall Robt A TE6-6196

2 Smith Ralph L TE3-2215

3 Yeakley Joe L TE8-5228

4 Shultz Roy

5 Cavanaugh Gordon I TE6-8213

6 Peterson Ronald A TE7-5249

7 Nygard Carl G TE2-8283 8 Nalle Richd G TE8-5275

Street continued 2420 Apartments

1 Taylor Harvey J TE6-8151

2 Carroll Tyrie G TE7-0153 3 Parker Robt TE7-5133

4 Taucher Dean A TE8-3230

5 Vacant

6 Halstead Earl W TE8-4916

7 Napolitano Pat TE6-8273 8 Scerbo Frank J TE8-4283

Street continued 2502 Apartments.

1 Sherwood Stanley W. TE8-4556

2 Hassey Thos E TE7-7150

3 Steele Michl T TE7-5197 4 Paxton Warren K TE8-0238

5 LaBarbara Vincent P

6 Jackson Harold G TE7-5272

7 Newman John D TE8-5547

8 Hoglund Carl M TE3-4286 2512 Plemel Thos E TE8-4852 2525 Schultz Kenneth TE7-0292

4TH AVENUE NORTHWEST-From Main west to limits, 4 north of Central av at 6th

12 Callies Rueben W @ TE2-6195

12½ Haeber Robt 14 North Robt E TE4-6227

20 Dakota Luth Academy Dormitory TE2-3139

TE6-8128

DIAL

24 Vacant 25 Norsby Benj R TE6-0160

25½ Jellum Robt D 29 Kelly Wm H TE8-4482

Rystrom Robt L TE8-0289 bsmt Freeman Clarence E



Where To Buy?

> Consult the Classified Business Lists In

This

Directory



MINOT - CROSBY - WILLISTON - BOTTINEAU - RUGBY - DEVILS LAKE

Distributors of Cordovan Tires
Selling Fleet Owners at Wholesale Prices

MINOT Insurance

Agency

Inc.

M O N T G O M E R Y 'S

General Insurance INCLUDING LIFE



Bonds of All Kinds

> 26 N. MAIN



111 -

TEmple **8-2127**

HOLMES ELECTRIC CO., Inc. Electrical Contractors

10 2d N.E.

DIAL TEmple 2-3115 and 4-3119

52

4TH AV NW-Contd 1st NW intersects 100 Hamilton David H TE7-7129 100 ½ Stach Balzer TE8-0106 102 Logen Donald O TE3-8229 102 1 Nelson Calmer J TE7-7228 103 Garness Hardie J ⊚ TE2-6191 105 Hoar Helen G TE4-6202 106 Krefting Arth @ TE2-6175 107 Crawford Blanche Z Mrs TE2-6275 110 Evenson Maynard M @ TE3-9149 Locken Violet Whorley Richd TE7-6203 111 Struckness Melvin T @ TE3-0208 114 McIntosh Geo A @ TE2-4198 Walders intersects 2d NW intersects Mouse River 15 304 Our Redeemer Luth Church TE7-9244 308 Rogness Rollin W Rev TE7-9244 310 Fiskum Anne Mrs @ TE5-4150 311 Rentschler Elmer @ TE4-5290 312 Bullock Florence L Mrs @ TE2-8256 315 Warke Anna M Mrs @ TE3-7263 bsmt Dye Clinton E 316 Connole Garth D @ TE2-7153 317 Peterson Leonard E @ TE3-3242 Hayes Edna Mrs TE7-0174 bsmt Stadler Marietta M 837-7224 319 Warke Andrew G

324 Leigh Clarence 838-6047 329 Hanson Petra B Mrs @ TE4-7271 330 Peterson Sewall E @ TE2-8156 335 Hutmacher Wanda Mrs TE6-7296 336 Johnson LaVonne R Mrs 838-4808 Witkop Richd E ir 836-5198 4th NW intersects 406 Thorson Wm C @ TE4-8230 B & G Automotive Sup Co TE4-8230 408 Gorgenes Luverne K @ TE4-8185 410 Castleman Violet E Mrs @ TE4-4150 413 Keller Francis B @ 834-8285 414 Sorensen Paul C @ TE2-3193 417 Odland Clifford @ TE4-7242 419 Vacant 422 Knudson Sterling A @ TE2-6214 426 Flanagan Patk J TE7-4260 Wright Gillis H TE5-6197 Jeffery Gary N TE8-0236 429 Fitzmaurice Thos C @ TE4-5174 5th NW intersects 504 Wallin Ralph C TE6-5141 510 Livingston Ernest C @ TE8-0266 524 Steenstrup Gail S Mrs @ TE2-0166 600 Berg Melvin O TE2-6163 Peterson Elias @ TE3-4100 600 ½ Lundt Elmer V TE5-5262 608 Frunz Richd D TE5-2188 610 Collom Norman F 837-0282

KEDNEY WAREHOUSE COMPANY MINOT BRANCH

618 Riebe Mabel E Mrs ©

TE5-7216

MINOT BRANCH
AGENT FOR ALLIED VAN LINES
WORLD'S LARGEST MOVER
11 2d Street N.E. Phone TEmple 8-6825

TEmple 8-7024

ROSSOW ELECTRIC CORPORATION ELECTRICAL CONTRACTORS

4614 Hwy. 2, P.O. Box I

Minot, North Dakota

53

4TH AV NW-Contd
620 Olson Howard S ©
TE5-4202 7th NW intersects
700 Reishus Geo A TE2-4250
702 Shearer Jas R 834-7177
706 Brannan Leo M TE6-6229
708 Fredrickson Arth C ©
TE3-3207
712 Norderhus Lance A © 833-0271
716 Happel Ernest H ⊚ TE4-0265
720 Sailman Aug N.®
TE4-4238
724 Johansen Johannes
8th NW intersects
800 Walsh Jas L @ TE6-2248
806 Lovdahl Thos H ©
TE2-5203
809 Jacbosen Lawrence Mrs ©
TE4-2230
812 Lyon Wm R @ TE8-5063
813 Wilkins Evelyn G Mrs ©
TE4-6121
814 Dahl Manuel © TE3-3108
Schaaf James TE5-6213
818 Linington Victor A ©
TE4-9177
822 Norem Grant M ©
TE3-3208
826 Gordon Zalmon @
TE2-2182
9th NW intersects
900 Momerak Andrew @
TE2-2282
Belinskey Carol R Mrs
TE5-7244
901 Downes Allan J TE8-1170
902 Lindsey Chas G TE5-2245
905 Hanson Henry M 💿
${ m TE}2-7237$
903 Hanson Mae E Mrs @ 833-5237
909 Watland Melvin O
TE3-8129
910 Valor Talfon © TE2-4271
915 Salo Arne A @ TE2-4170
916 Bergem Raymond M ®
TE2-5261
Callana Din 120 mme 1100

Sellers Fred D TE8-1108

917 Bacon Grace V Mrs © TE2-4270 bsmt No Return 920 Carlson Gary H @ TE5-4216 921 Owenson Josie M Mrs @ TE2-7184 1000 Giltner Arth T @ TE6-3150 1001 Mackley Jos R ⊚ TE2-4135 1004 Carlson Hamphen C @ TE2-4172 Janz Harriet Mrs TE2-4238 1005 Bach Lloyd R @ TE4-3244 1124 Rivera Lounge TE5-9232 Mouse River 1300 No Return 15th NW intersects 1506 Frye Jacob © TE4-2108 1507 Webster Christine Mrs @ TE4-4267 1508 Merck Michl @ TE5-7176 1509 Grosche Harry R ⊚ TE4-9195 1520 Northwest "66" Serv gas sta TE2-7255 16th NW intersects 1601 Northwest Texaco gas sta 1602 Oak Park Shopping Center Oak Park ABC Cins TE7-0169 Oak Park Barber Shop TE7-4193 Oak Park Dairy TE7-4225 Oak Park New Arcade TE6-5128 Pop's Cleaners TE8-4415 Farmers Union Grain Terminal Assn track ofc TE6-9171 1609 Super Fair Food Store

No 2 TE4-9120



bsmt Horvat Norman A


322 Wentz Leona A @

TE4-7208




 Parcel Map
 3/5/2015

 Scale: 1 : 718
 5.2015




The materials available at this web site are for informational purposes only and do not constitute a legal document.


1 of 1 3/5/2015 2:06 PM




2011

















1966















1928





Appendix C

Regulatory Reports

reports are available on request

Appendix D Site Visit Photographs

Appendix D Property Inspection Photographs

Fourth Avenue Floodwall Minot, ND 3/17/2015 and 5/17/2015

Dhoto #	3/1//2015 and 5/1//2015
Photo #	Comments
1	17-Mar-15
<u>1</u> 2	Vent pipe near Broadway Bridge
3	Broadway Bridge, looking W. Downstream view from Broadway Bridge.
<u>5</u> 4	Sammy's Pizza on the NE corner of Broadway and 4th Ave. NW.
4	Home Sweet Home Gift Shop, 103 4th Ave. NW.
<u> </u>	Looking upstream from Gift Shop parking lot.
<u></u>	Derby car enthusiast's garage area from alley (414 1st St. NE).
8	Generator west of Lowe's Printing, looking NE from alley.
9	No leaks or staining under generator.
10	Church on the NE corner of Broadway and 5th Ave. NW.
11	Looking downstream from Gift Shop parking lot.
12	Looking upstream from 3rd St. SE Bridge.
13	Lowe's Printing at 129 5th Ave. NW.
13	17-May-15
14	Electrical box between Broadway and 3rd St. NW.
15	Electrical box on the corner of Broadway and 4th Ave. NW.
16	Philotechnics Ltd. Storefront.
17	Body Brite and E-cig storefronts.
18	Giscon building in forefront, Body Brite, E-cig, and Philotechnics up the street.
19	Broadway bridge. Facing ESE.
20	Broadway bridge. Facing ESE. (2)
21	Stormwater drain on S side of Mouse River west of Broadway bridge.
22	Building between Giscon and Body Brite. Facing W.
23	Building between E-cig and Philotechnics. Facing W.
24	Drum and plastic container S of building between E-cig and Philotechnics.
25	0
26	Transformer S of building NW of Giscon.
27	Souris Valley Feed and Seed.
28	Corner of 3rd St. NE and 4th Ave. NE. Facing NE.
29	Building at corner of 5th Ave NE and 3rd St. SE. Facing NE from cul-de-sac
30	Approx. 20 portable heaters in fenced in area. Facing E from W side.
31	0
32	Fenced in area from SE side.
33	[0
34	Fenced in area from NW side.
35	Entrance to fenced area (NW side).
36	Parking lot of Souris River Designs from N facing S.
37	Taxi 9000. No obvious maintence taking place outside.
38	All Washed Up Laundromat facing NNW.
39	Leased commercial garages/shops. Facing NE.
40	Transformers on N Walders St. Facing S.
41	Electrical box on 3rd St NE cul-de-sac. Facing SW towards 3rd St SE bridge.



Photo 1: Vent pipe near Broadway Bridge



Photo 2: Broadway Bridge, looking W.



Photo 3: Downstream view from Broadway Bridge.



Photo 4: Sammy's Pizza on the NE corner of Broadway and 4th Ave. NW.



Photo 5: Home Sweet Home Gift Shop, 103 4th Ave. NW.



Photo 6: Looking upstream from Gift Shop parking lot.



Photo 7: Derby car enthusiast's garage area from alley (414 1st St. NE).



Photo 8: Generator west of Lowe's Printing, looking NE from alley.




Photo 9: No leaks or staining under generator.



Photo 10: Church on the NE corner of Broadway and 5th Ave. NW.



Photo 11: Looking downstream from Gift Shop parking lot.



Photo 12: Looking upstream from 3rd St. SE Bridge.



Photo 13: Lowe's Printing at 129 5th Ave. NW. 17-May-15



Photo 14: Electrical box between Broadway and 3rd St. NW.



Photo 15: Electrical box on the corner of Broadway and 4th Ave. NW.



Photo 16: Philotechnics Ltd. Storefront.



Photo 17: Body Brite and E-cig storefronts.



Photo 18: Giscon building in forefront, Body Brite, E-cig, and Philotechnics up the street.



Photo 19: Broadway bridge. Facing ESE.



Photo 20: Broadway bridge. Facing ESE. (2)



Photo 21: Stormwater drain on S side of Mouse River west of Broadway bridge.



Photo 22: Building between Giscon and Body Brite. Facing W.



Photo 23: Building between E-cig and Philotechnics. Facing W.



Photo 24: Drum and plastic container S of building between E-cig and Philotechnics.



Photo 25: W side of Giscon building. No concrete washouts.



Photo 26: Transformer S of building NW of Giscon.



Photo 27: Souris Valley Feed and Seed.



Photo 28: Corner of 3rd St. NE and 4th Ave. NE. Facing NE.



Photo 29: Building at corner of 5th Ave NE and 3rd St. SE. Facing NE from cul-de-sac



Photo 30: Approx. 20 portable heaters in fenced in area. Facing E from W side.



Photo 31: Fenced in area from SW side. Many vehicles for sale.



Photo 32: Fenced in area from SE side.



Photo 33: Fenced in area from NE side.



Photo 34: Fenced in area from NW side.



Photo 35: Entrance to fenced area (NW side).



Photo 36: Parking lot of Souris River Designs from N facing S.



Photo 37: Taxi 9000. No obvious maintence taking place outside.



Photo 38: All Washed Up Laundromat facing NNW.



Photo 39: Leased commercial garages/shops. Facing NE.



Photo 40: Transformers on N Walders St. Facing S.



Photo 41: Electrical box on 3rd St NE cul-de-sac. Facing SW towards 3rd St SE bridge.

Appendix E

Information Resources

Appendix E Information Resources Minot, North Dakota


The following resources are numbered for use as references.

REF#	Resource	Years
Primary	/ Resources	1
1	U.S. Geological Survey Topographic Maps	1928, 1949, 1966, 1979, 2011
2	Historical Fire Insurance Maps	1904, 1907, 1913, 1918, 1926
3	Aerial Photographs	1938, 1946, 1953, 1961, 1969, 1979, 1991, 1995, 2003, 2009, 2014
4	Soil Survey Staff, Natural Resources Conservation Service, United States Department of Agriculture. Web Soil Survey. Available online at http://websoilsurvey.nrcs.usda.gov/	Accessed March 11, 2015
5	Cvancara, A.M.1976, Report of Investigation No. 57, Geology of the Cannonball Formation in the Willison Basin, with References to Uranium Potential. North Dakota Geological Survey.	1976
6	Anderson, Fred J. 2006. Surface Geology, Minot Quadrangle, North Dakota, 2006. North Dakota Geological Survey	2006
7	Reverse City Directories	1963, 1968, 1973, 1978, 1984, 1988, 1993, 1997, 2004, 2009, 2013
8	Bluemle, John P. 1989. Geology of Renville and Ward Counties, North Dakota, Bulletin 50 Part 1. North Dakota Industrail Commission Geological Survey Division. County Groundwater Studies 11 – Part 1 and Plate 1.	1989
Regula	tory Status Resources	
9	Historical Information Gatherers, Inc. Date: March 10, 2015	2015
Intervi	ews	
10	Dan Jonasson, City of Minot Public Works Director, (701) 857-4112	March 23, 2015
Inspect	ion	
11	Barr Engineering Company: Amanda Strahm; 3/17/15; 40 degrees Fahrenheit and partly cloudy, and May 17, 2015	N/A
Additio	nal Sources	•
12	Braun Intertec. January 2015. Geotechnical Evaluation 4 th Avenue NE – Phase I, Minot North Dakota	2015
13	ND Water Commission Mapservice. Available online at http://mapservice.swc.nd.gov/	Accessed April 6, 2015

REF#	Resource	Years
14	Stantec's Area-Wide Planning Project Boundary Figure. February 2015.	2015
15	City of Minot. March 22, 2015. Available on-line at http://www.minotnd.org/	Accessed March 22, 2015
16	U.S. Army Corps of Engineers. 1992. Hazardous, Toxic and Radioactive Waste (HTRW) Guidance for Civil Works Projects.	1992
17	City of Minot Zoning Map. Available online at: http://www.minotnd.org/pdf/minotzoning.pdf . Accessed March 23, 2015	March 23, 2015
18	Bluemle, John P. 1989. Geology of Renville and Ward Counties, North Dakota, Bulletin 50 Part 1. North Dakota Industrail Commission Geological Survey Division. County Groundwater Studies 11 – Part 1 and Plate 1.	1989
19	North Dakota State Water Commission Available on-line at http://www.swc.nd.gov/	Accessed on March 30, 2015
20	Pusc, Steve W. 1994. Hydrogeology of the Minot Aquifer, Ward County, North Dakota; North Dakota Ground-Water Studies Number 102-Part II. North Dakota State Water Commission.	1994

Appendix F

Braun Intertec Boring Logs





ſ		n Proje	ect B14-	09643	3			BORING	:				T-1	
	GEOTE	CHNIC	AL EVALU	ATION				LOCATION		See	e atta			
<u> </u>			E - Phase Dakota	e I										
ations	WIIIIOL	, NOI III	Dakota											
brevi	DRILLE	R: W.	Barrett		METHOD:	3 1/4" HSA, A	Autohammer	DATE:		1/14	l/15		SCA	LE: 1" = 4'
on of ab	Elev. feet	Depth feet				escription of N			ВІ	PF	WL	ı	P200	Tests or Notes
anatio	1559.3	0.0	Symbol				k-USACE EM1110-		\vdash			%	%	
(See Descriptive Terminology sheet for explanation of abbreviations)		7.0	FILL	FILL: other	Silty Sand, fi organic mate	ine-grained, v rial, brown m I, trace Grave	vith clods of Tops ixed with black, r	soil or noist.		5 5 6 6		15	64	An open triangle in the water level (WL) column indicates the depth at which groundwater was observed while drilling. A solid triangle indicates the groundwater level in the boring on the date indicated. Groundwater levels fluctuate.
:35	1544.3	15.0		OII T		11 Ol h			\prod	_				
15 13	_		ML	mediu		-	rown and gray, v	vet, –	Μ	8				
/6/8	_					(Alluviur	n)	_	▋╹	W		27	55	DD=94.7 pcf LL=25
T.GD.T	1541.3	18.0												PI=2
J BRAUN_V8_CURRENT.GDT 3/9/15 13:35			SM		Y SAND, fine- to loose.	grained, gray (Alluviur	∕, waterbearing, v n)	ery - 	<u> </u>	3	Ā	33	43	
643.GI								_						
JECTS\2014\09		23.0	SM	SILT\ Sand	Y SAND, fine- with Silt, gray	grained, grac y, waterbearir (Alluviur	ling to Poorly Grang, very loose to l	aded oose	-XI	5				
LOG OF BORING N:\GINT\PROJECTS\AX PROJECTS\2014\09643.GPJ BRAUN_V8		20.0						- - - -		3 6			15	Gradation attached.
30RIN	1529.3	30.0	CL CL			lenses of Silt,	gray, wet, rather	soft to	\forall	6				
GOFE	-			mediı	um.	(Alluviur	n)	-	T	w		32		DD=92.6 pcf
으	D14 00642			1		•	ration Plaamington							



		Proje							BORING:		S	T-1	(cc	ont.)
		CHNICA enue N				N			LOCATIO	N: Se	e atta	ched	sketo	ch.
ions)	Minot,	North	Dako	ota										
breviat	DRILLEI	R: W.	Barret	t		METHOD:	3 1/4" HSA, A	utohammer	DATE:	1/14	4/15		SCA	LE: 1" = 4'
on of ab	Elev. feet	Depth feet	_				escription of M			BPF	WL		P200	Tests or Notes
anatic	1527.3	32.0	Sym	nbol				gray, wet, rather				%	%	
See Descriptive Terminology sheet for explanation of abbreviations)	_ _ 				medi	ium.	Alluvium) <i>(cor</i>	-	-	4				
scriptive Termino		39.0	N 41		OII T	aray waterb	paring laces			5		37		LL=41 Pl=30
(See De			ML		SILI	, gray, waterbe	earing, loose. (Alluviun	n)		6				*Water not observed to cave-in depth of 20 feet after withdrawal of auger.
	1516.3	43.0	СН		FAT	CLAY. with le	nses of Silt an	d Silty Sand, gra	av. wet.					Water not observed to cave-in
	_				medi	ium.	(Alluvium	-	-					depth of 18 1/2 feet two days after auger withdrawal.
35	_									8				Vibrating wire piezometers then grouted into
3/9/15 13:35	1511.3	48.0	CL		I E A I	N CLAV with I	longer of Silt o	and Boorly Crade	od Cond					borehole at 25 and 55 feet.
	_		CL		gray,	, wet, very loos	e to medium. (Alluvium		eu Sanu, –					
BRAUN_V8_CURRENT.GDT							()	,		WH/1		29		LL=30 PI=9
OF BORING N:\GINT\PROJECTS\AX PROJECTS\2014\09643.GPJ	- -								- - -	7			93	
NT\PROJECTS\AX P		58.0	SM			Y SAND, fine, waterbearing		lenses of Lean (Clay,	√ 12				Gradation
N:\GI	1498.3	61.0			END	OF BORING.			_	<u> </u>				attached.
	_					er observed at		drilling.*	-					
901	B14-09643					Bros	un Intertec Corno	ration, Bloomington	MN 55438					ST-1 page 2 of



	n Proje	ect B14-		BORING:			5	ST-2	
4th Av	enue N	AL EVALU E - Phase Dakota		LOCATIO	N: See	e atta	ached	sketo	h.
DRILLE	R: W.	Barrett	METHOD: 3 1/4" HSA, Autohammer	DATE:	1/14	4/15		SCA	LE: 1" = 4 '
Elev. feet 1553.2	Depth feet 0.0	Symbol	Description of Materials (Soil-ASTM D2488 or D2487, Rock-USACE EM1110	1-1-2908)	BPF	WL	MC %	P200 %	Tests or Notes
DRILLE Elev. feet 1553.2 1548.2 1548.2	5.0	FILL	FILL: Silty Sand, fine-grained, trace roots and G brown, frozen. FILL: Silty Sand, fine-grained, brown, moist.	Gravel, — — — — — — — — —	5 4		10 4	36	Gradation attached. Gradation attached.
	10.0	SM	SILTY SAND, fine-grained, with lenses of Silt an Graded Sand, scattered fibers, brown and gradi wet to waterbearing, very loose. (Alluvium)		3 WH/I 3		25	26	Gradation attached.
	17.0	SP	POORLY GRADED SAND, fine- to medium-gra lenses of Silty Sand, gray, waterbearing, loose to dense. (Alluvium)	o medium _ 	7	<u></u>	23	5	
	29.0	CL	LEAN CLAY, with lenses of Poorly Graded Sandwet, rather soft. (Alluvium)	d, gray, _ _ _ _	4		30		DD=93.8 pcf LL=30 PI=10 U _c =574 psf
		ML	SANDY SILT, with lenses of Lean Clay, gray, waterbearing, very loose. (Alluvium)		2		32		LL=28 Pl=6



		n Proje								BORI	NG:		S	T-2	(CC	ont.)	
ons)	4th Av	CHNICA enue N , North	E - Ph	ase		N				LOCA	ATIO	N: Se	e atta	ached	l sketo	ch.	
breviati	DRILLE	R: W.	Barrett			METHOD:	;	3 1/4" HSA, Aut	ohammer	DATE	<u> </u>	1/1	4/15		SCA	LE:	1" = 4'
nation of ab	Elev. feet 1521.2	Depth feet 32.0	Symb	ool	(So			cription of Ma D2487, Rock-U	terials JSACE EM1110	-1-2908))	BPF	WL	MC %	P200 %	Tests	or Notes
See Descriptive Terminology sheet for explanation of abbreviations)	1520.2 	33.0	СН		FAT	CLAY, with k	ens	ses of Silt, gra (Alluvium)	y, wet, rather s	soft.		2					
criptive Terminolo	_ _ _ 	39.0									_			34		DD=89 LL=55 PI=35 k=8.9 E	1 pcf -8 cm/sec
(See Des			CL		LEAN gray,	N CLAY, with wet, rather s	n ler soft	nses of Silt an to rather stiff. (Alluvium)	d Poorly Grad	led San	id,	4		33	70		
	- - -										_	7		38		LL=48 PI=28	
13:36	_ 1506.2	47.0	ML		SAN	DY SILT, gra	ay, v	waterbearing,	very loose.								
Т 3/9/15	_ _1504.2	49.0						(Alluvium)				3					
N_V8_CURRENT.GD	 -		СН		FAI	CLAY, gray,	we	it, moist. (Alluvium)				8		27		LL=51 Pl=32	
39643.GPJ BRAU		53.0	CL		LEAN	N CLAY, with	ı ler	nses of Silt, gr (Alluvium)	ray, wet, moist	·.							
ROJECTS\2014\(_ _										_	6				a depth	observed at of 17 feet hdrawal of
LOG OF BORING N:\GINT\PROJECTS\AX PROJECTS\2014\09643.GPJ BRAUN_V8_CURRENT.GDT 3/9/15		58.0 61.0	ML			_		waterbearing, (Alluvium)	very loose.		_	3				a depth when re one day	observed at of 18 feet echecked after wal of the
OF BORING N:	_					OF BORING		while drilling.*			_					Boring grouted	
	B14-09643					- Rr:	aun	Intertec Corpora	tion, Bloomington	MN 5543	88					Sī	-2 page 2 of 2



Braun Proje				BORING:			S	ST-3	
GEOTECHNICA 4th Avenue N Minot, North	E - Phase I	ION		LOCATIO	N: Se	e atta	ached	sketc	h.
DRILLER: W.	Barrett	METHOD:	3 1/4" HSA, Autohammer	DATE:	1/1	5/15		SCA	_E: 1" = 4'
Elev. Depth feet 1554.4 0.0	Symbol		escription of Materials or D2487, Rock-USACE EM1110	-1-2908)	BPF	WL	MC %	P200 %	Tests or Notes
Minot, North DRILLER: W. Elev. Depth feet 1554.4 0.0	FILL F(pg) ML Sgi SM Sw	ILL: Sandy Lean presumed) Cobble ray, frozen to app	Clay, trace Gravel, scattered es, brown mixed with dark bro roximately 4 feet then moist. If Silty Sand, scattered fibers, very loose to loose. (Alluvium) grained, trace Gravel, gray, e. (Alluvium)	brown to	26 12 6 6 7 6 7 6 4	Ā	20	43	Gradation attached. DD=88.6 pcf; LL=58; Pl=37 P _c =1.4 tsf C _c =0.24 C _r =0.04 e _c =0.90 Phi _{cu} =25.0 deg C _{cu} =338 psf k=4.7 E-8 cm/sec




	n Proje								BORING:		•	ST	-3	(cc	nt.)	
4th A	ECHNICA Venue N t, North	E - Pł	nase		J				LOCATIC	N:	See at	tac	hed	sketc	h.	
DRILLE	R: W.	Barrett			METHOD:		3 1/4" HSA, Autohammer		DATE:	•	/15/15	5		SCA	LE:	1" = 4'
Elev. feet 1522.4	Depth feet 32.0	Sym	bol		il-ASTM D248	38 o	scription of Materials or D2487, Rock-USACE EM			BF	F W		MC %	P200 %	Tes	s or Notes
Minot	35.0	CL		gray,	wet, rather	sof (A	ses of Silt and Poorly Grit to moist. Alluvium) (continued) Wet, moist to rather stiff. (Alluvium)	raded	Sand,		3		30		DD=93 LL=43 PI=26 U _c =61	
- - - - - - - 1496.4 - 1493.4	58.0 61.0	SP		Silt, g	gray, waterbe	ear G.	SAND, fine-grained, wit ing, loose. (Alluvium)	th lens	ses of	<u> </u>					a dept after w auger. Water a dept when i one da withdra auger. Vibratii piezon groute	awal of the ng wire neter then



	n Proje							BORING:			S	ST-4		
	CHNIC/ enue N				N			LOCATIO	N: Se	e atta	ched	sketcl	h.	
ହାଁ Minot	, North	Dako	ota											
DRILLE	R: W.	Barret	t		METHOD:	3 1/4" HSA	, Autohammer	DATE:	1/14	4/15		SCAL	-E: 1	" = 4'
Elev.	Depth feet				De	scription of	Materials		BPF	WL	мс	P200	Tests or	· Notes
1554.7	0.0	Sym	bol		oil-ASTM D2488	or D2487, Ro	ock-USACE EM1110-				%	%		
expla -		FILL		bitun			ed, trace Gravel, so frozen to approxim							
eet tor				icei i	men moist.			_						
- Ago								-	74		13	45		
								-						
——————————————————————————————————————									7					
ito 1547.7	7.0													
ORILLE Elev. feet 1554.7 1547.7 1545.7		CL		LEA	N CLAY, browi	n, moist, me Alluviu	edium. um)	_	6		20	73		
<u>545.7</u>	9.0	SM		SII T	YSAND fine-	grained bro	own, wet, loose.							
				O.L.	. 6, 15, 16 ;	(Alluviu	um)		ý 5					
_ 1542.7	12.0							+	\\					
1042.7	12.0	ML		SAN	DY SILT, brow	n, wet, ver (Alluvi			√ √ 3					
						(Alluvii	aiii)							
မ္က 1539.7	15.0													
/15 13:		SM		brow	yn to gray, wet	grained, wit to waterbea Alluvit)	th lenses of Lean Caring, very loose to	loose.	2	$ \nabla$				
NT.GDT 3/9/15 13:36						(Alluvii	uiii)	_						
- 4505.7	40.0							_	5					
1535.7	19.0	ML	1413133		DY SILT, with rbearing, very		ean Clay, gray,							
KAUN ————————————————————————————————————				wate	ibealing, very	(Alluviu	um)		4					
1532.7	22.0		<u> </u>											
1,0964:		SP				waterbearin	ne- to medium-graing, very loose to loo		2					
						(Alluviu	літ <i>)</i>	-						
PROJEC 								_	7		26	4		
								+						
\PROJEC								_	10					
1525.7	29.0								1					
A SING W		СН		FAT	CLAY, trace fil	bers, gray, v (Alluvit	wet, moist to rathe um)	r stiff.	1 10				DD=93.2 LL=67	ocf
1535.7								_	10		31		PI=44	
B14-09643					Rrai	ın Intertec Cor	poration, Bloomington	MN 55438					ST-1	page 1 of







ſ		n Proje	ect B14-	09643	BORING:			5	ST-5	
			AL EVALU E - Phase		LOCATIO	N: Se	e atta			
ns)			Dakota	'						
viation										
abbre	DRILLE		Barrett	METHOD: 3 1/4" HSA, Autohammer	DATE:	1/1	9/15		SCA	LE: 1" = 4'
ation of	Elev. feet 1553.4	Depth feet 0.0	Symbol	Description of Materials (Soil-ASTM D2488 or D2487, Rock-USACE EM1110-1	-2908)	BPF	WL	MC %	P200 %	Tests or Notes
kplan	1552.4	1.0	FILL	FILL: Sandy Lean Clay, trace roots, dark brown, f	frozen.					
eet for e	_		FILL	FILL: Clayey Sand, fine-grained, brown, frozen.	_					
ology sh	 _1549.4	4.0	FILL	FILL: Silty Sand, fine-grained, brown, moist.	_ <u>/</u>	17		8	47	Gradation attached.
e Termir				FILE. Sity Sand, inte-grained, brown, moist.		6				
See Descriptive Terminology sheet for explanation of abbreviations)	_									
(See [_				- <u>\</u> -	9				
	 1542.4	11.0				5		9	24	Gradation attached.
	_		sc ///	CLAYEY SAND, fine-grained, trace fibers, brown, medium.	moist,					
	_			(Alluvium)	_	6	Ī	23	44	
	_				_					
3/9/15 13:36	 1537.4	16.0	SP-	POORLY GRADED SAND with SILT, fine-grained	-					
	_		SM	grading to Poorly Graded Sand, gray, waterbearin loose.	ig, _	/ / 6	$\overline{\Delta}$	25	11	Gradations
RRENT	_ 1534.4	19.0		(Alluvium)	-/	¥ 0		25	4	attached.
JN_V8_CU			SM	SILTY SAND, fine-grained, gray, waterbearing, loc (Alluvium)	ose.	/ / 6				
J BRA	_				+					
4\09643.GP		22.0	SM	SILTY SAND, fine-grained, gray, waterbearing, medense. (Alluvium)	edium	11		13	16	Gradation attached.
CTS\201	1529.4	24.0	ML	SILT, gray, waterbearing, very loose.						allacrieu.
\AX PROJE	_			(Alluvium)		4			97	Gradation attached.
LOG OF BORING N:\GINT\PROJECTS\AX PROJECTS\2014\09643.GPJ BRAUN_V8_CURRENT.GDT		27.0	SP	POORLY GRADED SAND with SILT, fine-grained waterbearing, loose to medium dense. (Alluvium)	d, gray,	13				
ING N:\G				, ,						
3 OF BOR	1522.4	31.0	ML			5		29	9	
ĕ	D14 00642			Proug Intertee Corneration Pleamington M						ST 5 page 1 of 2



		ect B14-		BORING		S	T-5	(CC	ont.)
4th A۱	enue N	AL EVALU IE - Phase Dakota		LOCATIO	ON: Se	e atta	iched	sketo	h.
DRILLE	R: W.	Barrett	METHOD: 3 1/4" HSA, Autohammer	DATE:	1/19	9/15		SCA	LE: 1" = 4'
Elev. feet 1521.4	Depth feet 32.0	Symbol	Description of Materials (Soil-ASTM D2488 or D2487, Rock-USACE EM1110		BPF	WL	MC %	P200 %	Tests or Notes
_			SILT, trace Poorly Graded Sand, gray, waterbea loose. (Alluvium) (continued)	aring, –	6		29		LL=31 PI=7
 1517.4	36.0			_			32		DD=88.9 pcf U _c =1,228 psf k=3.8 E-7 cm/sec
_		SC //	CLAYEY SAND, fine-grained, with lenses of Silt, wet, rather stiff. (Alluvium)	gray,					
1515.4 	38.0	СН	FAT CLAY, scattered fibers, gray, wet, moist to stiff. (Alluvium)	rather –	11			46	LL=73 PI=48
			(villaviarri)		11		35		LL=68 PI=48
_				-					
_				_	 7				
	46.0	ML	SILT, with lenses of Lean Clay, gray, waterbearing medum dense. (Alluvium)	ng,	N				
	54.0			_	15				
	51.0	SP- SM	POORLY GRADED SAND with SILT, fine-graing grading to Poorly Graded Sand, gray, waterbear medium dense. (Alluvium)	ed, ing, _	/\				
_			(Allaviarri)	_					
_				_	14		31	6 4	Gradations attached.
_ _				- -					*Water observed 13 feet immediate after withdrawal o auger.
 1492.4	61.0		END OF BORING.		13				Vibrating wire piezometers then grouted into
		1 1	LIND OF DORING.		1.1	1	1	1	borehole at 17 1/2



		ect B14-		BORING			S	ST-6	<u> </u>
4th Av	enue N	AL EVALU E - Phase Dakota		LOCATIO	DN: Se	e atta	ched	l sketo	ch.
DRILLE	R: W.	Barrett	METHOD: 3 1/4" HSA, Autohamn	ner DATE:	1/1	9/15		SCA	LE: 1" = 4'
Elev. feet 1554.3	Depth feet 0.0	Symbol	Description of Materials (Soil-ASTM D2488 or D2487, Rock-USACE	EM1110-1-2908)	BPF	WL	MC %	P200 %	Tests or Notes
	9.0 17.0 19.0	FILL CL SP	FILL: Clayey Sand, fine-grained, trace Croots, brown, frozen to approximately 4 roots, brown, frozen to wet, medium (Alluvium) SANDY SILT, gray, waterbearing, very le (Alluvium) POORLY GRADED SAND, fine-grained Lean Clay, gray, waterbearing, loose to (Alluvium)	Fravel, scattered feet then moist.		Ϋ́	21 31 27	76	LL=49 PI=30 Gradation attached.
	26.0	CL	LEAN CLAY, with lenses of Poorly Grad wet, rather soft. (Alluvium)	- -					
1024.5	30.0	СН	FAT CLAY, with lenses of Silt and Silty S rather soft. (Alluvium)	Sand, gray, wet,	33				DD=89.1 pcf U _c =786 psf



-		n Proje						BORING:		S	T-6	(cc	nt.)	
ations)	4th Av	enue N , North	E - Pha	se I	ON			LOCATIO	N: Se	e atta	iched	sketc	h.	
Drevig	DRILLE	R: W.	Barrett		METHOD:	3 1/4" HSA, Autohan	nmer	DATE:	1/19	9/15		SCA	LE:	1" = 4'
lanation of ab	Elev. feet 1522.3	Depth feet 32.0	Symbo		oil-ASTM D2488	escription of Materia or D2487, Rock-USAC nses of Silt and Silty	CE EM1110-		BPF	WL	MC %	P200 %	Tests	or Notes
LOG OF BORING N:\GINT\PROJECTS\AX PROJECTS\2014\09643.GPJ BRAUN_V8_CURRENT.GDT 3/9/15 13:36 (See Descriptive Terminology sheet for explanation of abbreviations)		43.0	SC CL	CL/ wet	er soft. (AYEY SAND, fi , rather stiff.	Alluvium) (continued ne-grained, with lens (Alluvium)	ses of Silt,	gray,	10 10 7 15 15 15 15 15 15 15 15 15 15 15 15 15		35 31	46	LL=75 PI=53 DD=92 U _c =724 LL=29 PI=8	1 pcf psf
N:\GIN I \PROJEC	1493.3	61.0							7				15 feet	observed at immediately hdrawal of
JG OF BORING IN	_				O OF BORING. ter observed at	17 feet while drilling] .*	-					Boring t	



	n Proje							BORING:			S	ST-7	,
4th Av	ECHNICA Venue N San North	IE - Pl	hase		N			LOCATIO	N: Se	e atta	ached	sketo	h.
DRILLE	R: W.	Barrett	t		METHOD:	3 1/4" HSA, Au	utohammer	DATE:	1/20	0/15		SCA	LE: 1" = 4 '
Elev. feet 1552.6	Depth feet 0.0	Sym	ıbol		il-ASTM D2488		USACE EM1110-		BPF	WL	MC %	P200 %	Tests or Notes
3 - 1550.6	2.0	FILL			nents, dark bi		ace foots, bitumi	irious _					
otive l'erminology sneet		FILL		FILL brow	: Clayey Sanı ın and black,∵	d, fine-grained, frozen to moist	with clods of Le	ean Clay, - - - -	7		32	47	
1545.6 25	7.0	CL		SAN	DY LEAN CL	AY, brown, mo (Alluvium	ist, soft to rathe)	r soft.	4		17	54	
	12.0	SC		CLA	YEY SAND, fi	ine-grained, bro (Alluvium	own, wet, soft.)		2	Ţ	29		DD=95.8 pcf
	19.0	SP		grad	PRLY GRADE ing to Silty Sa loose to loose	ind, trace Grave e.	to medium-grai el, gray, waterbe	ned,	3 3		27	46	Gradation attached.
- - - -						(Alluvium)	-	6		18	4 24	Gradations attached.
1533.6	27.0	CL		LEAI soft.	N CLAY, trace	e fibers, with ler (Alluvium	nses of Silt, gray	y, wet,	3		33		LL=47 PI=31 LL=84 PI=58
B14-09643							ation, Bloomington	- ANI 55 (00					ST-7 page 1 of



		n Proje							BORING:		S	T-7	(cc	ont.)	
itions)	4th Av	enue N , North	E - Pha	ise I		V			LOCATIO	N: See	e atta	ached	sketo	h.	
brevia	DRILLE	R: W.	Barrett			METHOD:	3 1/4" HSA	A, Autohammer	DATE:	1/20	0/15		SCA	LE:	1" = 4'
nation of ab	Elev. feet 1520.6	Depth feet 32.0	Symbo			il-ASTM D2488		ock-USACE EM1110	-	BPF	WL	MC %	P200 %	Test	s or Notes
(See Descriptive Terminology sheet for explanation of abbreviations)		43.0	CH		FAT	(Alluvium) <i>(c</i> nses of Silt, (Alluvi	gray, wet, rather	_	3√√√√9		33	80	k=1.8 l	E-6 cm/sec
LOG OF BORING N:\GINT\PROJECTS\AX PROJECTS\2014\09643.GPJ BRAUN_V8_CURRENT.GDT 3/9/15 13:37		48.0	SM		SILT' gray,	Y SAND, fine- waterbearing	grained, wi , loose to m (Alluvi	th lenses of Lean nedium dense. um)	Clay,	9		21	9	12 feet	
OG OF BORING N:\GINT\P	 1491.6 _ _	61.0				OF BORING		ing.	-	7				Vibratir piezom grouted boreho and 50	neters d into ble at 22 1/2



	-	ect B14					BORING:			5	8-T	
4th Av	enue N	AL EVALU E - Phase Dakota		N			LOCATIO	N: Se	e atta	ached	l sketo	h.
DRILLE	R: W.	Barrett		METHOD:	3 1/4" HSA, Autoh	ammer	DATE:	1/2	0/15		SCA	LE: 1" = 4 '
Elev. feet 1551.8	Depth feet 0.0	Symbol	(Sc		escription of Mater or D2487, Rock-US		-1-2908)	BPF	WL	MC %	P200 %	Tests or Notes
Minot DRILLE DR	22.0 24.0	SM CL SC	LEA brow	Sandy Lean vn, dark browr then moist. N CLAY, trace vn to gray, mo	e Poorly Graded Sist to wet, soft to ra (Alluvium) AY, gray, wet, soft (Alluvium)	and Gravel, n to approxing and, lenses ather soft.	of Silt,	45 7 5 3 3 4 3 6	¥	17 28 28	53 63	DD=97.1 pcf LL=42; PI=23 P _c =1.3 tsf C _c =0.23 C _r =0.03 e _c =0.87 Phi _{cu} =27.6 deg C _{cu} =358 pcf k=8.9 E-8 cm/sec Gradation attached. LL=39; PI=22 DD=91.3 pcf P _c =2.2 tsf, C _c =0.21 C _r =0.03 e _c =0.85 Phi _{cu} =24.2 deg C _{cu} =560 psf k=2.5 E-6 cm/sec
			wet,	soft.	(Alluvium)			3			48	Gradation attached.
1519.8 B14-09643	32.0				un Intertec Corporation	- Diagonia	NAN 55400					ST-8 page 1 of



		ect B14-					BORING:		S	T-8	(cc	ont.)
4th Av	enue N	AL EVALU IE - Phase Dakota		N			LOCATIO	N: Se	e atta	ached	l sketc	h.
DRILLE	R: W.	Barrett		METHOD:	3 1/4" HSA, Auto	ohammer	DATE:	1/2	0/15		SCA	LE: 1" = 4'
Elev. feet 1519.8	Depth feet 32.0	Symbol CH		oil-ASTM D2488	escription of Mat or D2487, Rock-U nses of Silt, trace	SACE EM1110		BPF	WL	MC %	P200 %	Tests or Notes
Minot DRILLE Elev. feet 1519.8 1519.8			mois		(Alluvium)	o libers, gray,		6		40		DD=83.0 pcf
7. (See Descriptive Terminology 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 1213:98 12	38.0	CL	SAN stiff.	DY LEAN CLA	AY, with lenses o	of Silt, gray, w	et, rather	9				*Water observed at 12 feet immediately after withdrawal of auger.
BRAUN_V8_CURRENT.GDT 3/9/15 13:37	48.0 53.0	CH			nses of Silt, gray (Alluvium)	v, wet, moist.		8				Vibrating wire piezometers grouted into borehole at 22 1/2 and 30 feet.
OJECTS\2014\09643.GPJ		ML	SILI	, gray, waterb	earing, loose. (Alluvium)		- - -	6		30		LL=31 PI=5
LOG OF BORING N:\GINT\PROJECTS\AX PROJECTS\2014\09643.GPJ	58.0	CH		CLAY, gray, v	(Alluvium)			7		35		LL=53 Pl=34
90 90 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0				er not observe	d while drilling.*	Discoving the second						ST-8 page 2 of 2



ſ		n Proje	ect B14-	09643	BORING:				T-9	ı
	GEOTE	CHNICA	AL EVALU	ATION	LOCATIO		e atta			
			E - Phase	1						
tions	WIIIIOU	, NOI III	Dakota							
brevia	DRILLE	R: W.	Barrett	METHOD: 3 1/4" HSA, Autohammer	DATE:	1/20	0/15		SCA	LE: 1" = 4'
See Descriptive Terminology sheet for explanation of abbreviations)	Elev. feet	Depth feet	C: mah al	Description of Materials	4 2000)	BPF	WL	MC	1	Tests or Notes
anat	1553.5	0.0	Symbol FILL	(Soil-ASTM D2488 or D2487, Rock-USACE EM1110- FILL: Sandy Lean Clay, trace Gravel and roots,				%	%	
or expl	1552.0	1.5		frozen.	_					
eet fo	_		FILL	FILL: Clayey Sand, fine-grained, brown, frozen tapproximately 4 feet then moist.	to _					
y sh	_			.,,	_	23				
olog	_				_					
ermi								9	41	Gradation
ve T	_				_	8		9	41	attached.
cripti	1546.5	7.0								
Des	_		FILL	FILL: Silty Sand, fine-grained, brown, moist.	_	7		9	31	Gradation
(See						М				attached.
	_				_		Ţ			
						6	<u>-</u>			
	_	40.0			_	Ĥ				
	1541.5	12.0	CL ///	SANDY LEAN CLAY, with lenses of Silt, gray, w	et, soft.					
	_			(Alluvium)	_	3		30		LL=41 PI=23
	1539.5	14.0	SM :	SILTY SAND, fine-grained, gray, waterbearing, v	erv		$ \nabla$			5
13:37				loose to loose.		M 5				
/15 13	_			(Alluvium)	_	M 3				
г 3/9/15	_				_					
CURRENT.GDT	_					5		29	27	Gradation
JRREN						Η				attached.
	_				_					
AUN	1532.5	21.0				3				
PJ BR	1002.0	21.0	SP-	POORLY GRADED SAND with SILT, fine-graine	ed, gray,	Ħ				
643.G	_		SM	waterbearing, loose. (Alluvium)	_					
14\09	_				_	7		25	8	Gradation attached.
TS\20	_				_					
SOJEC						 9				
AX PF	1527.5	26.0	CL ///	CANDVI EAN CLAV grow wat rather soft to m	odium	И				
JECTS	_			SANDY LEAN CLAY, gray, wet, rather soft to me (Alluvium)	zului II. —					
r\PRO	_				_	4				
LNI9/:	_									
NG NG										
OF BORING N:\GINT\PROJECTS\AX PROJECTS\2014\09643.GPJ BRAUN_V8										
LOG OF	-				_					
닠	D14 00642		\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Proup Intertoe Corporation, Plaamington					1	ST 0 page 1 of 0



ſ		Proje								BORING:		S	T-9	(CC	ont.)	
tions)	4th Av	CHNICA enue N North	E - Ph	ase l						LOCATIO	N: Se	e atta	ached	sketo	ch.	
brevia	DRILLE	R: W.	Barrett		ı	METHOD:	3 1/4'	' HSA, Autoh	ammer	DATE:	1/2	0/15		SCA	LE:	1" = 4'
nation of ab	Elev. feet 1521.5	Depth feet 32.0	Symb	ool	-	ASTM D2488	or D248		ACE EM1110-		BPF	WL	MC %	P200 %	Tests	or Notes
See Descriptive Terminology sheet for explanation of abbreviations)	- - -				SAND	Y LEAN CL	AY, gra (Alluviu	ay, wet, rath m) <i>(continu</i>	er soft to me ed)	edium.	7		32		LL=45 PI=26 DD=89. LL=41	5 pcf
(See Descriptiv	1514.5	39.0	СН		FAT C mediur	LAY, with len.		f Silt, gray, v Alluvium)	wet, rather s	soft to	6		27		PI=21 U _c =831 LL=65 PI=43	psf
BRAUN_V8_CURRENT.GDT 3/9/15 13:37	- - - - -									- - - - - -	5					
LOG OF BORING N:\GINT\PROJECTS\AX PROJECTS\2014\09643.GPJ BRAL		53.0	CL		SAND' mediur	Y LEAN CL m.		h lenses of Alluvium)	Silt, gray, w	et,	8		35	74		
GINT\PROJECTS\AX PR	1495.5	58.0 61.0	СН		FAT C	LAY, gray, v		her stiff. Alluvium)			10				10 feet after wit auger.	observed at immediately hdrawal of
OG OF BORING N:\	-	01.0				OF BORING		th of 14 feet	t while drillin	g.* _					Boring to	then ed.
	B14-09643				_	Bra	aun Intert	ec Corporation	n, Bloomington	MN 55438					ST	-9 page 2



			ct B14					BORING:			S	T-10)
			AL EVAL E - Phas		N			LOCATIO	N: Se	e atta	ached	sketc	h.
ons)			Dakota										
See Descriptive Terminology sheet for explanation of abbreviations)	DRILLE	R: W.	Barrett		METHOD:	3 1/4" HSA, A	Autohammer	DATE:	2/1	7/15		SCA	LE: 1" = 4'
of abb	Elev.	Depth			<u> </u>	escription of N	Matariala		DDE	\^//	MC	Dago	
nation	feet 1551.5	feet 0.0	Symbol		oil-ASTM D2488	or D2487, Roc	k-USACE EM1110-		BPF	WL	MC %	P200 %	Tests or Notes
explar	_		FILL	FILL brov	Sandy Lean vn, frozen to a	Clay, fine-graph pproximately	ained, trace Grav 4 feet then moist	el, 					
et for (_							_					
y she	_							_	29		16	61	
inolog	_							_					
Term	_								10				
riptive	_ 1544.5	7.0						_					
Desc	1044.0	7.0	FILL	FILL		ine-grained, ti	race Gravel, brov	vn,	 8		14	45	
(See	1542.5	9.0		\otimes									
			FILL	FILL	.: Sandy Lean	ı Clay, trace G	Gravel, brown, we	et. ——	V -		10	F0	
	_							_	7		19	58	
	1539.5	12.0	SC //	CLA	YEY SAND, fi	ne-grained, g	ravelly lense at th	ie					
	-			/ 15-fc	oot sample de ither stiff.	pth, gray and	brown, wet, rafth	ner soft _	4				
	-					(Alluviur	n)	_					
5 13:35									*	T			*50 blows to set 4 inches.
NT.GDT 3/9/15	_							_		-			
NT.GD1	_							_	9				
CURRE	1532.5	19.0	ML	SAN	IDV SILT fine	arained arad	ling to Poorly Gra	nded.					
N_V8_				San	d and Silty Sai	nd, gray, wate Alluviur)	erbearing, very loo	ose	 M 4		24	55	
J BRAI	_	00.0				(a +101	·· · /	_	Λ				
3643.GF	1529.5	22.0	CL	LEA	N CLAY, gray				M 4				
2014\0	_					(Alluviur	п)	_	4				
JECTS\;	1526.5	25.0									32		DD=89.4 pcf P _c =1.43 tsf
AX PRO	_		СН	FAT	CLAY, gray, v	wet, rather sof Alluviur)	ft to medium. n)	_					C _c =0.23; C _r =0.05;
)JECTS	_							_					e _o =0.89 k=4.5 E-1 cm/sec
INT\PR(-							_	7				
3 N:\G	-							_					
BORING									5				
LOG OF BORING N:\GINT\PROJECTS\AX PROJECTS\2014\09643.GPJ BRAUN_V8_	_												
_	B14-09643				Bra	un Intertec Corne	oration, Bloomington	MNI 55/38					ST-10 page 1 of 2



	-	ct B14					BORING:		Sī	Γ-10) (c	ont.)	
4th A۱	enue N	AL EVAL E - Phas Dakota		N			LOCATIO	N: Se	e atta	ached	sketc	h.	
DRILLE	R: W.	Barrett		METHOD:	3 1/4" HSA, Autoh	ammer	DATE:	2/1	7/15	Ì	SCA	LE:	1" = 4'
Elev. feet 1519.5	Depth feet 32.0	Symbol	-	oil-ASTM D2488	escription of Mater or D2487, Rock-US/ wet, rather soft to r	ACE EM1110-	-1-2908)	BPF	WL	MC %	P200 %	Test	s or Notes
DRILLE Elev. feet 1519.5 1513.5				CLAT, gray, v	(Alluvium) (continu	ed)	- - - -	6		40		DD=80).6 pcf
- - - -	38.0	CL	LEA	N CLAY, gray	, wet, medium. (Alluvium)		-	6 6					
	46.0	ML	SAN Grad	NDY SILT, with ded Sand, gra	l lenses of Lean Cl y, wet to waterbea (Alluvium)	lay and Pool ring, loose.	rly	<u> </u>					
	58.0	СН			īibers, gray, wet, m (Alluvium)	nedium.	-	8				16 feet	observed a immediatel ithdrawal of
_	2.1.3			O OF BORING ter not observe	ed while drilling.*		- -					Boring grouted	



Braun P					TEST PIT	Γ:		TP	-100)1
GEOTECH 4th Aven Minot, N	ue N	orthe	east		LOCATIO	N: Se	e atta	ached	l sketc	h.
DRILLER:	Dit	It Up B	ackho	e ServiceMETHOD: 3 1/4" HSA, Autohammer	DATE:	2/19	9/15		SCA	LE: 1" = 4 '
Elev. De feet fo	epth eet 0.0	AST Sym		Description of Materials (ASTM D2488 or D2487)		BPF	WL	MC %	P200 %	Tests or Notes
1551.9 1551.4	1.5 2.0	FILL AGG		FILL: Lean Clay, trace Gravel, dark brown, froze	en. 	-				
<u> </u>	N		0	6 inches aggregate base.		1				
See Describtive Jest Jes		FILL		8 inches bituminous pavement. FILL: Clayey Sand, trace Gravel, pieces of condwood, brown, frozen to moist.	crete and -			7	44	Bag sample taken from 5 to 6 feet. LL=29; PI=15 MDD=pcf
1545.4	8.0		× × ×	_ Buried tree trunk (Impenetrable).						PMC=%
LOG OF TEST PIT N:\GINT\PROJECTS\AX PROJECTS\2014\09643-TEST PIT.GPJ BRAUN_V8_CURRENT.GDT 3/11/15 09:46 (See Descriptive Te				END OF TEST PIT. No groundwater observed to bottom of test pit u completion. Test pit then backfilled.	Ipon					Phi _{cu} =Deg C _{cu} =psf k=cm/sec 2 grab samples taken at 7 1/2 feet.



Braun Project B14-09643 GEOTECHNICAL EVALUATION 4th Avenue Northeast - Phase I Minot, North Dakota DRILLER: Dit It Up Backhoe Serv eMETHOD: 3 1/4" HSA, Autohammer DATE: 2/19 Elev. Depth feet 1554.1 0.0 Symbol (ASTM D2488 or D2487) FILL FILL: Sandy Lean Clay, trace Gravel, brown, frozen. FILL FILL: Poorly Graded Sand, fine- to medium-grained, trace roots and branches, brown, moist.	ee attache	SCA C P200	ALE: 1" = 4' Tests or Notes Bag sample taken
Minot, North Dakota DRILLER: Dit It Up Backhoe ServiceMETHOD: 3 1/4" HSA, Autohammer DATE: 2/19	WL M	C P200	Tests or Notes Bag sample taken
DRILLER: Dit It Up Backhoe ServiceMETHOD: 3 1/4" HSA, Autohammer DATE: 2/19	WL M	C P200	Tests or Notes Bag sample taken
Floy Donth	WL M	C P200	Tests or Notes Bag sample taken
Elev. feet 1554.1 Depth feet 1554.1 FILL: Sandy Lean Clay, trace Gravel, brown, frozen. FILL FILL: Poorly Graded Sand, fine- to medium-grained, trace roots and branches, brown, moist.			Bag sample taken
1554.1 0.0 Symbol (ASTM D2488 or D2487) FILL: Sandy Lean Clay, trace Gravel, brown, frozen. FILL: Poorly Graded Sand, fine- to medium-grained, trace roots and branches, brown, moist.			Bag sample taken
FILL Sandy Lean Clay, trace Gravel, brown, frozen. FILL Sandy Lean Clay, trace Gravel, brown, frozen. FILL: Sandy Lean Clay, trace Gravel, brown, frozen. FILL: Poorly Graded Sand, fine- to medium-grained, trace roots and branches, brown, moist. ———————————————————————————————————			Bag sample taken
1541.6 12.5	7	7 40	Bag sample taken from 11 to 12 feet. Grab sample taken at 12 1/2 feet.



		n Proje		14-0	09643	TEST PIT	· :		TP	-100	03
		CHNIC				LOCATIO	N: Se	e atta			
		enue N , North			- Phase I						
	DRILLE	R: Dit	It Up B	ackho	e ServiceMETHOD: 3 1/4" HSA, Autohammer	DATE:	2/19	9/15		SCA	LE: 1" = 4'
itions)	Elev. feet 1553.1	Depth feet 0.0	AS ¹ Sym	- 1	Description of Materials (ASTM D2488 or D2487)		BPF	WL	MC %	P200 %	Tests or Notes
revia	1000.1	0.0	FILL	<u>₩</u>	FILL: Sandy Lean Clay, trace Gravel, dark brow	/n,			/0	70	
(See Descriptive Lerminology sheet for explanation of abbreviations)		4.0	FILL		FILL: Poorly Graded Sand, fine- to medium-grabecoming Clayey near bottom of test pit, brown	ined,			8	38	Bag sample taken from 5 to 6 feet. Bag sample taken from 9 to 10 feet. Grab sample taken at 10 1/2 feet.
LOG OF TEST PIT N:\GINT\PROJECTS\AX PROJECTS\2014\09643-TEST PIT.GPJ BRAUN_V8_CURRENT.GDT 3/11/15 09:46					Stopped due to utility conflict. No groundwater observed to bottom of test pit ut completion. Test pit then backfilled.						TD 1002 page 1 of 1



						EST PIT: TP-1004							
GEOTECHNICAI 4th Avenue No Minot, North D	rtheast		LOCATIO	N: See	e atta	ched sketch.							
DRILLER: Dit It	Up Backho	e ServiceMETHOD: 3 1/4" HSA, Autohammer	DATE:	2/19	9/15	SCALE:	1" = 4'						
Elev. Depth feet 1552.9 0.0	ASTM Symbol	·				Tests or	Notes						
5 - 5 - 6 - 7 - 7 - 8 - 1548.9 4.0		,											
F F F F F F F F F F F F F F F F F F F	FILL	FILL: Poorly Graded Sand, fine- to medium-gra brown, moist.	ined, — — — —			Bag sample taken at 5 to 6 feet.							
	FILL	FILL: Clayey Sand, fine-grained, brown, wet.	_ 			Bag sample take 11 feet.	n from 10 to						
1340.9 12.0	SC	CLAYEY SAND, fine-grained, trace roots, brown (Alluvium) END OF TEST PIT. No groundwater observed to bottom of test pit u completion. Test pit then backfilled.				Bag sample taken from 10 11 feet. Grab sample taken at 12 fe							



Γ		n Project B14-09643 TEST PI						TP-1005					
	4th Av	enue N	AL EVALU ortheast Dakota	JATION : - Phase I	LOCATION: S					h.			
	DRILLE	R: Dit	It Up Backh	oe ServiceMETHOD: 3 1/4" HSA, Autohammer	DATE:	2/19	9/15		SCA	LE: 1" = 4'			
viations)	Elev. feet 1553.9	Depth feet 0.0	ASTM Symbol	Description of Materials (ASTM D2488 or D2487)		BPF	WL	MC %	P200 %	Tests or Notes			
fabbre	1552.4	1.5	FILL	FILL: Lean Clay, with Gravel, brown, frozen.	_								
for explanation o	- - 1548.9	5.0	FILL	FILL: Lean Clay, dark brown, frozen.	- - -	-							
(See Descriptive Lerminology sheet for explanation of abbreviations)	-	5.0	FILL	FILL: Silty Sand, fine- to medium-grained, brow	n, moist. - - -					Bag sample taken from 8 to 9 feet.			
	-	42.5				-		6	26	Bag sample taken from 10 to 11 feet.			
LOG OF TEST PIT N:\GINT\PROJECTS\AX PROJECTS\2014\09643-TEST PIT.GPJ BRAUN_V8_CURRENT.GDT 3/11/15 09:46	1541.4 1540.9	12.5 13.0	ML III	SANDY SILT, brown, wet. (Alluvium) END OF TEST PIT. No groundwater observed to bottom of test pit us completion. Test pit then backfilled.	J upon —					Grab sample taken at 13 feet.			
LOG OF TEST PIT N:\GINT\PI				Braun Intertec Corporation, Bloomingtor	- - - -					TP-1005 page 1 of 7			



ſ	Braun Project B14-09643 TEST PIT							T: TP-1006						
١		TECHNICAL EVALUATION Avenue Northeast - Phase I							N: See attached sketch.					
١		enue N , North			- Phase I									
	DRILLE	R: Dit	It Up B	ackho	e ServiceMETHOD: 3 1/4" HSA, Autohammer	DATE:	2/19	9/15		SCA	LE: 1" = 4'			
(SI	Elev. feet	Depth feet	AS ⁻	тм	Description of Materials		BPF	WL	MC	P200	Tests or Notes			
latio	1552.6	0.0	Sym		(ASTM D2488 or D2487)		ы	***	%	%	resis or notes			
			FILL		FILL: Lean Clay, trace Gravel, dark brown, froz	en.								
ota														
atior	1549.6	3.0				_								
xplar			FILL		FILL: Sandy Lean Clay, with brick fragments, G glass and concrete, dark brown, moist.	iravel,								
or le	_				glass and concrete, dank brown, moist.	_								
sheel											Bag sample taken from 5 to 6 feet.			
go	- 1545.6	7.0				_					nom 5 to 6 leet.			
(See Descriptive Terminology sheet for explanation of abbreviations)	10-10.0	7.0	FILL		FILL: Sandy Lean Clay, brown, moist.									
e <u>e</u>	- 1543.6	9.0				_			22	70	Bag sample taken			
iriptiv	1343.0	9.0	ML	\mathbb{M}	SANDY SILT, brown, wet.	_			23	78	from 8 to 9 feet. LL=37; PI=20			
Desc	 1541.6	11.0			(Alluvium)						Ough a grouple telling			
See	1541.0	11.0			END OF TEST PIT.						Grab sample taken at 10 1/2 feet.			
	-				No groundwater observed to bottom of test pit u	ipon –								
:47	_				completion.	_								
/15 09	_				Test pit then backfilled.	_								
CURRENT.GDT 3/11/15 09:47	_													
T.GDT	_					_								
URREI	_					_								
	-					_								
RAUN	-					_								
GPJ B														
ST PIT	_					_								
543-TE	_					_								
14\096	_					_								
TS\20	-					_								
ROJEC														
S/AX P	_					_								
OJECT.	-					_								
VT/PR	_					_								
LOG OF TEST PIT N:\GINT\PROJECTS\AX PROJECTS\2014\09643-TEST PIT.GPJ BRAUN_V8	_					_								
ST PIT														
OF TEX	_					_								
90	214 00642				Proup Intertoe Corporation, Pleamington						TD 1006 page 1 of 1			



ſ	Braun Project B14-09643 TEST PIT:						IT: ТР-1007						
١		TECHNICAL EVALUATION Avenue Northeast - Phase I						N: See attached sketch.					
Minot, North Dakota					- Filase i								
ŀ		_							- i				
ŀ	DRILLE		It Up B	ackho	e ServiceMETHOD: 3 1/4" HSA, Autohammer	DATE:	2/19	9/15		SCA	LE: 1" = 4'		
ous)	Elev. feet	Depth feet	AS	- 1	Description of Materials		BPF	WL		P200	Tests or Notes		
eviati	1552.9	0.0	Sym FILL	ıbol	(ASTM D2488 or D2487) FILL: Lean Clay, trace Gravel, brown, frozen.		1		%	%			
abbr	_		FILL		FILL. Lean Clay, trace Graver, brown, nozen.	_							
on of	_					_							
anati	1549.9	3.0	FILL		Ell L: Sandy Lean Clay valley brown with black	200000							
exb	_		FILL		FILL: Sandy Lean Clay, yellow-brown with black moist.	seams,							
ō ∫gt	_										Grab sample taken		
she l	_					_					of black and yellow soil at 4 1/2 feet.		
golou	_					_					Bag sample taken		
	4544.4	0.5				_					from 6 1/2 to 7 1/2 feet.		
tive I	1544.4	8.5	FILL		FILL: Lean Clay, trace fibers, brown, moist.	_			13	84	Bag sample taken from 8 to 9 feet.		
scrip	1542.9	10.0									LL=37; PI=18		
(See Descriptive Terminology sheet for explanation of abbreviations)	_				END OF TEST PIT.	_							
<u></u>	_				No groundwater observed to bottom of test pit up completion.	oon —							
	_				Test pit then backfilled.	_							
5 09:4	_					_							
CURRENT.GDT 3/11/15 09:47						_							
SDT 3	_					_							
RENT.	_					_							
	_					_							
) 	_					_							
y BRA													
PIT.GF	_					_							
3-TEST	_					_							
\0964	_					_							
\2014	_					_							
) ECTS	_												
AX PRO	_					_							
LOG OF TEST PIT N:\GINY\PROJECTS\AX PROJECTS\2014\09643-TEST PIT.GPJ BRAUN_V8	_												
r\PRO.	_					_							
I:\GIN	_												
N													
F TEST	_												
0 501	214 00642				Proup Intertoe Corporation Planminaton						TD 1007 _ page 1 of 1		

Appendix G

Limitations and Qualifications

Limitations

The detailed history of ownership and land-use to satisfy the requirements and purpose of the Assessment was determined from the activities listed in the report, and a title review was not needed.

The scope of the HTRW did not involve the collection and analysis of any type of sample. The Assessment did not involve completion of any surveys or the offering of any opinions or advice with respect to structural engineering matters, asbestos-containing materials, radon, lead-based paint, lead in drinking water, wetlands, compliance with environmental regulations, cultural and historic resources, industrial hygiene, health and safety, ecological resources, endangered species, indoor air quality, biological agents, mold, or other conditions that are beyond the scope of the HTRW guidance.

Barr Engineering Co. has performed its work in a manner consistent with the care and skill ordinarily exercised by members of the environmental profession under similar budget and time constraints. Within this context, Barr assumes responsibility for its own observations, along with its interpretation of the information gathered. No other warranty is made or intended.

Because Barr was not retained to verify information, Barr assumes no responsibility for the accuracy of information that it obtained from other sources including, without limitation, regulatory and government agencies, persons interviewed about the Property, and vendors of public data. Performance of the Assessment is intended to reduce, but will not eliminate uncertainty regarding the presence of HTRW conditions within the Assessment Area. To the extent that Barr does not identify HTRW conditions within the Assessment Area, Barr's opinions in the report are not representations that the Property is free of such conditions. Under no circumstances can Barr represent or warrant that releases of hazardous substances or petroleum products do not exist on the Property.

Appendix H Contingency Plan

Appendix H Site Contingency Plan 4th Avenue Floodwall May 2015

Barr Engineering Co. completed a Hazardous, Toxic, and Radioactive Waste Assessment (HTRW Assessment) on the 4th Avenue NE segment of the Flood Protection Project (Project) located in the City of Minot, Ward County, North Dakota. This HTRW Assessment focuses on the 4th Avenue Floodwall segment, where construction of a new floodwall, levee, transportation closures, and related utility relocations are planned as part of the Project (Assessment Area)

Barr performed this HTRW Assessment in general conformance with ER 1156-2-132 U.S. Army Corps of Engineers Water Resources Policies and Authorities, Hazardous, Toxic and Radioactive Waste Guidance for Civil Works Projects.

The HTRW reported a number of findings including: a PVC vent pipe, vacant buildings, historical industrial buildings located upgradient, or adjacent to, the Assessment Area, and fill with inert debris located throughout the Assessment Area. No fuel oil tanks, vent pipes, leaking transformers, or other soruces of hazardous materials or petroleum products were observed.

1.0 Introduction and Purpose

This Site Contingency Plan will be used if contamination is encountered during construction activities on the site.

During construction activities, the people involved need to be alert to the possibility that unexpected hazardous substances or petroleum products may be encountered. If unexpected hazardous substances or petroleum products are encountered during construction activities, the parties onsite will need to make decisions on short notice. These decisions potentially have serous impacts and consequences. To help ensure that situations are handled properly, personnel involved in construction-related activities must be trained in the immediate recognition of a wide range of potential hazards and be ready to respond in accordance with a previously prepared general plan of action. Such a plan is commonly referred to as a Site Contingency Plan.

This Site Contingency Plan is a stand-alone document. A copy will be available at the site during construction activities and individuals onsite that are responsible for managing the construction activities, especially those involving excavation work, will be provided with a copy and be familiar with its contents.

The manager of the construction project will be responsible for being informed regarding the philosophy behind and the content of this Site Contingency Plan. The construction manager must also be responsible for informing the onsite workers involved with excavation activities about actions to be taken if contingent situations described in this plan are encountered. The need for taking appropriate actions should also be reinforced in daily safety meetings held at the site.

Contingent conditions that may be encountered could include uncovering an unknown underground storage tank, a water well or vent pipe, debris, containers, contaminated soils, or contaminated water that accumulates in the excavation. These and other unexpected conditions will be addressed according to the procedures described in this Site Contingency Plan.

Obvious signs of contamination in a contingency situation can include:

- Strong or unusual chemical odors during excavation (e.g., solvent, petroleum, etc.).
- Encountering industrial wastes such as tar, sludge, semisolids, powders, resins, or ash.
- Discolored soil that is different than encountered elsewhere on the site.
- Drums and/or containers.
- Buried debris such as metal scrap, cans, jars, brick, concrete, asphalt, trash, or wood.
- Objects such as vent pipes or wells.
- Asbestos-containing materials.
- Persons who suddenly become ill at the site (keep in mind that certain hazardous substances such as methane gas which is odorless and colorless cannot be detected visually or by smell).

2.0 Initial Actions

If the items above are observed during earthwork activities, the following actions must be taken:

- 1. IMMEDIATELY STOP WORK IN THE AREA OF UNEXPECTED CONTAMINATION, PROVIDE FOR WORKER SAFETY, AND SECURE THE AREA;
- 2. Contact the property owner or other person responsible for overseeing the construction project if that person is onsite or contact the office project manager.
- 3. Do not rebury the hazardous substances or petroleum products that are encountered. The area of any exposed hazardous substances or petroleum products must be secured.

3.0 Assessing the Situation

An environmental professional will be responsible for inspecting the area of contamination or contingent situation and developing a plan of action that is consistent with this Site Contingency Plan. This may involve implementing measures to further secure the area (e.g., installing fencing or posting warning signs), collecting samples to identify the type and magnitude of contamination that is present, and placing test pits to help define the extent of contamination that is present.

The environmental professional responsible for managing the contingency situation or the client representative will contact the appropriate North Dakota Department of Health (NDDH) representative to

make them aware of the situation and to determine the process for NDDH input and review of the plan to assess and manage the contingent action.

Once work in the area has stopped, the work site has been secured, the notification process has been implemented, the situation has been adequately assessed, and a plan of contingent action has been established, a OSHA HAZWOPER-trained contractor with properly trained or certified work crews (for issues such as tank removal, asbestos containing materials handling, hazardous waste management, water well abandonment, etc.) will implement the contingent action plan. Activities implemented through the Site Contingency Plan will only be performed by OSHA HAZWOPER-trained personnel with the proper licensing for any specialty work and under a Project Health and Safety Plan (PHASP) that will be prepared for the contingent action. The original onsite contractor will be allowed to continue work on portions of the site that are not involved with the contingency situation.

4.0 Contingent Actions

The following paragraphs describe the general contingent actions that will be taken in the event that contamination or other contingent conditions are encountered during project construction.

Specific requirements for the OSHA HAZWOPER-trained contractor as they relate to the implementation of contingent actions may include erosion control, runon and runoff controls, air emission controls, decontamination facilities, notification procedures, construction on temporary contaminated soil stockpile area, and contaminated media profiling and treatment/disposal.

4.1 Contaminated Soils (not a RCRA-regulated hazardous waste)

Soils potentially containing hazardous substances or petroleum products may be encountered during earthwork activities associated with site construction. If, based upon visual or olfactory evidence, such materials are encountered during earthwork activities, excavation of the impacted area will cease until the appropriate regulatory agency is notified, samples are collected, results are reviewed, and a plan of action is developed as described in Sections 2.0 and 3.0 of this Site Contingency Plan.

General requirements are described in the following paragraphs.

- An environmental professional familiar with site conditions and the plan for contingent action will
 be present during excavation of contaminated soils to screen and classify the soils (based on
 appearance, odor and organic vapor headspace measurements) and to collect analytical samples
 for further characterization and for sidewall and base of excavation verification.
- A contaminated soil stockpile area will be constructed onsite by creating an impervious surface by
 placing plastic sheets (minimum 10-mil) on the ground or similar. A plastic cover (minimum 10mil) will be placed over the stockpiled materials at the end of each work day and after excavation
 is complete and will be held in place with weights such as tires, bags of sand or clean soil. All
 plastic sheets will overlap at least 3 feet at seams. The contractor will be instructed to control all
 runoff from the stockpile area.

- After field screening indicates that the limits of the contaminated soil has been reached, soil samples will be collected from the base and sidewalls of the excavation in accordance with NDDH Cleanup Action Levels for Gasoline and Other Petroleum Hydrocarbons dated Dec, 2006 (http://www.ndhealth.gov/wm/Publications/CleanupActionLevelsForGasolineAndOtherPetroleum Hydrocarbons.pdf) or in accordance with the verification sampling plan negotiated with the regulatory agency for the contingent action. Soil samples will be analyzed for the appropriate parameters designated by the environmental professional in consultation with the NDDH based on the likely source and type of contamination and field observations. The results from the analysis of the verification samples will be compared to NDDH risk-based screening levels consistent with the land use anticipated for the site. Unless otherwise described in the plan for contingent action, the intent will be that excavation of contaminated soil will continue until appropriate risk-based cleanup levels are attained. The NDDH will be consulted regarding any issues associated with an inability to meet appropriate risk-based cleanup levels.
- Soil samples from the stockpiled contaminated soil will be collected in accordance with NDDH guidance such as NDDH's Investigations of Contaminant Release Sites dated November 2006 (http://www.ndhealth.gov/wm/Publications/InvestigationsOfContaminantReleaseSites.pdf) and as necessary to complete waste profiling for disposal purposes after the material has been excavated. A plan for disposing of or otherwise managing the stockpiled soils will be prepared after the results from all the sampling are available.

4.2 RCRA-Regulated Hazardous Waste

Materials that are characterized as a RCRA-regulated hazardous waste and that are generated in the initial excavation will be containerized and temporarily stored onsite on an impervious surface in a secured area until disposal arrangements are determined. If practicable, the remaining hazardous waste will be left in place until disposal arrangements are made. The area of contamination must be secured with fencing and posted with warning signs. Storage on the site will not exceed a duration of 120 days once the material has been determined to be a hazardous waste.

All hazardous wastes will be stored, transported, treated and disposed of in accordance with all applicable rules and regulations. The general requirements for construction of the storage area, waste characterization, and confirmation sampling will be implemented as described in 4.1 of this section.

4.3 Buried Drums or Containers

If drums or containers are encountered, they will be individually removed and their condition assessed. If the excavated drums and containers are not in good condition (e.g., severe rusting, structural defects, leaking, etc.), contents will be transferred to new drums, overpacks, or U.S. Department of Transportation (DOT)-approved containers. These containers will meet the appropriate requirements of U.S.DOT, OSHA and U.S.EPA regulations for the applicable materials.

Intact and repacked drums and containers will be transported to an onsite, secure, impervious storage area and/or placed in roll-off boxes. If appropriate, liquids may be removed from drums and containers and bulk-stored in tanks. Roll-off boxes will be lined to contain accumulated materials. The unused

volume in the roll-off boxes will be sufficient to contain 10 percent of the volume of the drums or the volume of the largest container, whichever is greater. The roll-off boxes will be covered to prevent collection of precipitation.

Samples will be collected from the drums/containers and analyzed as appropriate to characterize the contents. After the contents of the drums/containers have been characterized, arrangements will be made for disposal. The disposal method will be discussed with the DOH and will be implemented after regulatory agency approval.

Soil surrounding the buried tanks or containers will be managed in accordance with 4.1 of this section.

4.4 Underground Storage Tanks

In the event an underground storage tank is encountered during an excavation associated with a construction project, removal of the tank and excavation of any petroleum-contaminated soils in the tank basin will be conducted in accordance with NDDH's Cleanup Action Levels for Gasoline and Other Petroleum Hydrocarbons and Investigation of Contaminant Release Sites. The underground tank will be removed by an underground storage tank contractor or a contractor recommended by the NDDH that will be mobilized to the site.

The storage tank contractor will confirm that the underground storage tank is isolated from all piping and that utilities in the area have been adequately located and marked and that they can be avoided as the tank and any contaminated soil is removed. To the maximum extent practicable, the tank excavation contractor will remove and containerize residual tank contents prior to tank excavation. Appropriately trained personnel will handle all residual tank contents in accordance with NDDH and OSHA requirements. Tank excavation and removal will be completed in a manner that minimizes the potential for spillage of residual tank contents. Temporary onsite storage of the removed tank will be on plastic sheeting (minimum of 10-mil) to prevent incidental soil contamination.

In the event of a visible release of petroleum product or hazardous substances from the tank, assessment and notifications procedures described in Section 3.0 will be implemented and any resulting contaminated soil will be managed in accordance with procedures described in 4.1 of this section.

4.5 Buried Debris Including Asbestos-Containing Waste Materials

Buried debris unexpectedly encountered during an excavation that does not contain asbestos-containing material will be excavated, temporarily stored onsite, and disposed of at the Minot Landfill; no analytical sampling is required for disposal of debris.

Buried debris sometimes contains asbestos-containing material (ACM). The environmental professional that is sent to assess the discovery of buried debris in a contingency situation will be trained in asbestos awareness as required for Class IV asbestos work.

If suspected ACM is identified by the asbestos awareness-trained environmental professional, the material will be sampled by a fully-certified and licensed asbestos inspector to help identify the proper separation,

handling, and disposal of the material. If excavation of ACM is required, a licensed abatement asbestos contractor will be used to provide the proper handling and disposal of the ACM. All asbestos-related work will be conducted in accordance with North Dakota and federal National Emission Standards for Hazardous Air Pollutants (NESHAP) requirements. Monitoring of airborne asbestos concentrations will be conducted in accordance with the OSHA, asbestos requirements for the construction industry (29 CFR 1926.1101.

An emission control plan will be prepared and implemented for the work if regulated quantities (over 260 lf, 160 sf or 35 cf) of ACM or ACM and soil mixture are encountered during the excavation activities. The ACM contractor will use standard operating procedures during excavation and abatement work to ensure maximum protection and to safeguard workers, visitors, tenants, site employees and the environment.

4.6 Water Accumulation in the Excavation

In the event an excavation must be dewatered during construction activities and procedures describing this dewatering are not contained in the project specifications, the contractor will first contain the water and then notify the construction manager following the notification procedures in Section 2.0 of this Plan). If the water is in contact with potentially-contaminated soil, or displays an odor, sheen, or another indication of contamination, the water will be sampled by an environmental professional and the results of the sampling will be used to design a plan for treating and disposing of the water and acquiring the necessary permits for discharge to an approved facility (sanitary sewer, storm sewer, or other facility).

4.7 Objects Such as Wells or Vent Pipes

In the event a metal vent pipe is uncovered during an excavation, the excavation will be continued to a depth of 10 to 15 feet below the ground surface to determine if the pipe is connected to a tank. If the pipe is not connected to a tank or if the feature appears to be a water well, a licensed water well contractor will be mobilized to permanently seal the well in accordance with state, county and local requirements and to file the appropriate paperwork to complete the sealing operation. If the feature is not a well or a potential downward conduit for contamination (e.g., an old piling, etc), it will be cut off at a reasonable depth and the location will be recorded with GPS coordinates.

5.0 Documentation and Reporting

The implementation of the contingent actions will be documented and reported in a Contingent Action Report in accordance with DOH reporting requirements. The Contingent Action Report will include a text description of the contingent work with supporting documentation which may include tables summarizing the results of field screening and analytical sampling (including waste profile samples); figures documenting the location of contingent activities, a photo log, manifests for all waste disposed offsite, field notes, and laboratory analytical reports. The report will be prepared by the environmental professional responsible for implementing the contingent action.

The Contingent Action Report will be submitted to the NDDH upon completion of the project and will provide the NDDH documentation that the contingent actions were completed in accordance with the Site Contingency Plan.

Appendix F

Hazardous, Toxic, and Radioactive Waste Field Investigation Phase 1-4th Avenue Floodwall, Minot North Dakota Memo

Memorandum

To: Souris River Joint Board

From: Dan Fetter and Amanda Bohnenblust, Barr Engineering Co. **Subject:** Hazardous, Toxic, and Radioactive Waste Field Investigation

Phase 1-4th Avenue Floodwall, Minot North Dakota

Date: February 25, 2016

Project: Mouse River Enhanced Flood Protection Project

This memo summarizes the results from the soil and groundwater field investigation (Investigation) performed as part of the Hazardous, Toxic, and Radioactive Waste (HTRW) Assessment for the Mouse River Enhanced Food Protection Project (Project). The Investigation was conducted as part of the Preconstruction Engineering Design (PED) phase of the Project, targeting historical properties of interest (Site) that were identified during a previous phase of HTRW Assessment activities (Barr, 2015) for the 4th Avenue Floodwall segment of the Project. The Investigation location (Site) and 2015 HTRW Assessment area are shown on Figure 1. The Site layout and the historical properties of interest from the previous HTRW Assessment activities are shown in Figure 2.

This report includes: a summary of the Site background, a description of the Investigation scope and methods, a discussion of the results of the Investigation, and recommendations for further actions. The purpose of this Investigation is to assess for the absence or presence of shallow soil and groundwater contamination associated with the historic properties of interest that are located near the anticipated construction areas for the Project.

Scope of Work

As part of the Investigation, Barr provided the following scope of work:

- Prepared a project-specific health and safety plan (PHASP) prior to performing investigation sampling.
- Mobilized to the Site and conducted public and private utility locates.
- Advanced six borings to between 8 and 20 feet below ground surface (bgs).
- Field screened the material encountered, which included soil classification, inspection for visual evidence of contamination (i.e. odor, discoloration, sheen, or other field indications of potential soil impacts) and headspace volatile organic vapor screening.
- Collected two soil samples per boring, based on field screening results, and submitted them for laboratory analysis of gasoline range organics (GRO), diesel range organics (DRO), semi-volatile organic compounds (SVOCs), volatile organic compounds (VOCs), and Resource Conservation and Recovery Act (RCRA) metals.

To: Souris River Joint Board

From: Dan Fetter and Amanda Bohnenblust, Barr Engineering Co.

Subject: Hazardous, Toxic, and Radioactive Waste Field Investigation

Phase 1-4th Avenue Floodwall, Minot North Dakota

Date: February 25, 2016

Page: 2

 Converted four borings to temporary monitoring wells to collect groundwater samples and submitted them for laboratory analysis of GRO, DRO, SVOCs, VOCs, and three of the groundwater samples were also analyzed for RCRA metals.

 Prepared this report, which presents the findings and results of the Investigation and provides recommendations and conclusions for potential further actions based on these findings and results.

Investigation Results

On November 23, and November 24, 2015, Barr advanced 4 soil borings on the Site to a depth of 20 feet bgs and 2 soil borings to a depth of 8 feet bgs; sampling locations are shown on Figure 3.

Soil was field screened continuously at each boring for visual classification, moisture, odor, discoloration, sheen, and the presence of organic soil gas vapors using an 11.7 electron-volt (eV) photoionization detector (PID). Soils were generally described in accordance with American Society for Testing and Materials (ASTM) D-2488, Standard Practice for Description and Identification of Soils (Visual/Manual Method). The boring logs are provided in Appendix A. The depths of the soil samples collected are listed under the remarks section of the logs. A photo log of the Investigation activities and select soils found at the Site are provided in Appendix B. Sampling equipment that came in contact with soil and groundwater were decontaminated between collected samples. All samples were collected into laboratory-supplied sample containers and standard chain-of-custody procedures were maintained for handling samples.

Borings B-1, B-2a, B-3, and B-4 were converted to temporary monitoring wells, for the purposes of collecting shallow groundwater samples. Laboratory reports are included in Appendix C.

Soil and groundwater samples collected were analyzed using the following methods: DRO and GRO by EPA method 8015D, RCRA metals by EPA method 6010C, SVOCs by EPA method 8270D, VOCs by EPA method 8260B. Laboratory services were provided by Legend Technical Services (Legend) of St. Paul, Minnesota.

The analytical results for soil are summarized on Table 1. The soil analytical results were compared to Environmental Protection Agency's (EPA) Industrial Carcinogenic and Non-Carcinogenic values and North Dakota Department of Health (NDDH) Guidelines for the Assessment and Cleanup of Saltwater Releases – Soil Cleanup Standards.

The groundwater analytical results are summarized on Table 2. The analytical groundwater results were compared to EPA Secondary Drinking Water Regulations, NDDH Guidelines for the Assessment and Cleanup of Saltwater Releases – Groundwater Cleanup Standards, EPA Maximum Contaminant Levels, and ND surface water standards (ND Water Quality Criteria – Human Health Values, and ND Maximum Limits for Substances in or Characteristics of Class 1 Streams – Chronic).

Souris River Joint Board To:

From: Dan Fetter and Amanda Bohnenblust, Barr Engineering Co. Subject: Hazardous, Toxic, and Radioactive Waste Field Investigation

Phase 1-4th Avenue Floodwall, Minot North Dakota

Date: February 25, 2016

Page:

Soil borings had similar classifications at similar depth intervals. Fill varied from 1 foot thick at boring B-5 to 12 feet thick at boring B-1 and consisted of varying amounts of fat clay, coarse sand, and gravel (CH to GC). Below the fill, native fat clay (CH) which was occasionally sandy or fine-grained clayey sand (SC) was encountered. Coarser sand was encountered near the groundwater table, which was observed at approximately 10' bgs at most of the deeper borings.

Field screening indicated no elevated headspace readings (less than 1.5 parts per million (ppm)). An odor was encountered at boring B-1 at a depth of 7.5' bgs. No other discoloration, sheen, or odor was observed at any other depth or boring. Approximately 4 inches of weathered concrete was observed at 6' bgs at boring B-4.

Two geotechnical borings were also completed in the Site area by Braun in January 2015, as shown on Figure 3. The boring logs for those two borings identified approximately 12 feet of fill, underlain by sandy lean clay and clayey sand. No debris, or evidence of contamination were noted in the log (e.g., no odors or staining).

The soil analytical results indicate that shallow soil concentrations exceed EPA Industrial Carcinogenic and Non-Carcinogenic criteria and the NDDH Guidelines for the Assessment and Cleanup of Saltwater Releases for arsenic and chromium. Arsenic concentrations are within the reported background range of <0.1 – 34 milligrams/kilogram (mg/kg) as documented by USGS studies (reference [1]). Most of the Chromium analytical results for soil, which range from 4.4 mg/kg to 20 mg/kg, exceeded EPA industrial value of 6.3 mg/kg, although the soil analytical results were for total chromium, while the EPA values are associated with only hexavalent chromium. It is unlikely that the observed total chromium concentrations are comprised of only hexavalent chromium species as the other chromium species are normally present in soil and the historical land uses in this area are not typically associated with hexavalent chromium sources. DRO and GRO were both detected at concentrations below 10 mg/kg.

Groundwater concentrations of DRO exceed NDDH Guidelines for the Assessment and Cleanup of Saltwater Releases – Groundwater Cleanup Standards in boring B-1 through B-5. However, based on the site setting, a comparison of the groundwater analytical results to the surface water standards for the river is more appropriate as discussed below.

During the previous HTRW Assessment efforts, groundwater flow direction at the Site is anticipated to be south towards the Mouse River; however, due to pumping from public water supply wells, groundwater flow reverses direction away from the river and towards the public water supply in the area. The City of Minot requires all residents within the city limits to be connected to Minot's water supply system. Since there is no known groundwater use at the Site, the surface water at the river is the presumed receptor of potential concern for the Site area, and so the groundwater results are also compared to the ND surface water quality standards (SWQS).

The groundwater analytical results indicate that Bis (2-ethylhexyl)phthalate slightly exceeds ND Water Quality Criteria – Human Health Values – Chronic and EPA's MCL in Boring B-1. However, Bis

Souris River Joint Board To:

From: Dan Fetter and Amanda Bohnenblust, Barr Engineering Co. Subject: Hazardous, Toxic, and Radioactive Waste Field Investigation

Phase 1-4th Avenue Floodwall, Minot North Dakota

Date: February 25, 2016

Page:

(2-ethylhexyl)phthalate is a common laboratory contaminant and the detections noted are potentially a result of the analytical testing process. The groundwater sample at B-4 had slightly low dissolved oxygen and all but one of the samples had slightly low pH for Class 1a waters (Table 2). However, the average dissolved oxygen in the groundwater samples at the site area meets the SWQS (minimum 5 mg/l), and the average pH in the groundwater samples at the site was 6.9, which was just out of range for the SWQS (pH between 7 and 9).

Conclusions and Recommendations

An odor was noted during field screening; however, no detections were reported for soil and groundwater near the boring.

Arsenic and total chromium exceed EPA Industrial Carcinogenic and Non-Carcinogenic criteria and the NDDH Guidelines for the Assessment and Cleanup of Saltwater Releases. However, arsenic is within the reported background ranges, and total chromium is unlikely comprised of hexavalent chromium that is the basis for the criteria. The soil analytical results did not identify significant concerns and so no further HTRW assessments for soil in the Site are recommended for the Project.

DRO concentrations exceed Guidelines for the Assessment and Cleanup of Saltwater Releases – Groundwater Cleanup Standard; however, groundwater encountered during temporary dewatering during construction will be discharged to the Mouse River, indicating that SWQS are more relevant to assess groundwater impacts. There are no SWQS for DRO, but no individual petroleum constituents were detected at concentrations exceeding ND SWQS. Dissolved oxygen and pH were slightly below SWQS limits in some groundwater samples, but the average concentration for those parameters across the study area does not indicate a significant risk to the river for the temporary construction dewater that is anticipated during Project construction. Therefore, no additional HTRW assessments are anticipated for the Site.

These field investigation results and preliminary recommendations were discussed with staff at NDDH Surface Water Division, and they did not identify any further concerns pending their review of this written report.

A Contingency Plan has been developed to guide actions in the event that unanticipated environmental conditions are encountered during construction.

References

[1] Association for the Environmental Health of Soils, Study of State Soil Arsenic Regulations, Amherst, MA, p. 40.

						IVIII IOI, I									
			Location	B-1	B-1	B-2a	B-2a	B-3	B-3	B-4	B-4	B-5	B-5	B-6	B-6
			Date	11/23/2015	11/23/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015
			Depth	10 - 12 ft	16 - 18 ft	2 - 4 ft	4 - 6 ft	0 - 2 ft	6 - 8 ft	2 - 4 ft	8 - 10 ft	0 - 2 ft	6 - 8 ft	0 - 2 ft	6 - 8 ft
		EPA Industrial	NDDoH Guidelines for												
	Analysis	Carcinogenic and	the Assessment and												
Parameter	Analysis	Non-Carcinogenic	Cleanup of Saltwater												
	Location	RSL TR=1E-06 or	Releases - Soil Cleanup												
			Standards												
Effective Date		THQ=0.1													
		06/01/2015 Bold	12/01/2014 No Exceed												-
General Parameters		Bola	No exceed												
Solids, percent	Lab			74 %	77 %	83 %	83 %	89 %	77 %	94 %	83 %	91 %	91 %	89 %	79 %
Metals	Lau			74 70	// /0	03 /0	03 /0	09 70	// 70	94 %	03 70	91 %	91 %	09 70	79 76
	Lala	2 0 a*D		4.1	21 mg/kg	6.2	4 F	11	60	0.0 //	21 //	6.0 mm //rm	2.6	F 2 mm //m	4.6
Arsenic	Lab	3.0 c*R mg/kg		4.1 mg/kg	2.1 mg/kg	6.2 mg/kg	4.5 mg/kg	11 mg/kg	6.0 mg/kg	8.9 mg/kg	2.1 mg/kg	6.0 mg/kg	3.6 mg/kg	5.3 mg/kg	4.6 mg/kg
Barium	Lab	22000 n mg/kg		150 mg/kg	190 mg/kg	310 mg/kg	210 mg/kg	230 mg/kg	140 mg/kg	100 mg/kg	72 mg/kg	160 mg/kg	110 mg/kg	150 mg/kg	160 mg/kg
Chromium	Lab Lab	98 n mg/kg		< 0.34 mg/kg	< 0.32 mg/kg	< 0.30 mg/kg	< 0.30 mg/kg	< 0.28 mg/kg	1.9 mg/kg	< 0.27 mg/kg	< 0.30 mg/kg	< 0.27 mg/kg	< 0.27 mg/kg	J. J.	J. J.
Chromium Lead	Lab	6.3 c*CR6 mg/kg 800 L mg/kg		15 mg/kg 8.0 mg/kg	19 mg/kg 8.6 mg/kg	14 mg/kg 12 mg/kg	16 mg/kg 8.5 mg/kg	11 mg/kg 31 mg/kg	20 mg/kg 8.2 mg/kg	12 mg/kg 5.2 mg/kg	4.4 mg/kg 2.6 mg/kg	12 mg/kg 7.3 mg/kg	8.1 mg/kg 4.1 mg/kg	11 mg/kg 12 mg/kg	17 mg/kg 9.0 mg/kg
	Lab	.,				., .,	., .,		< 0.65 mg/kg				< 0.55 mg/kg		
Mercury Selenium	Lab	4.0 ns mg/kg 580 n mg/kg		< 0.68 mg/kg < 1.4 mg/kg	< 0.65 mg/kg < 1.3 mg/kg	< 0.60 mg/kg < 1.2 mg/kg	< 0.60 mg/kg < 1.2 mg/kg	< 0.56 mg/kg < 1.1 mg/kg	< 1.3 mg/kg	< 0.53 mg/kg < 1.1 mg/kg	< 0.60 mg/kg < 1.2 mg/kg	< 0.55 mg/kg < 1.1 mg/kg	< 1.1 mg/kg	< 0.56 mg/kg < 1.1 mg/kg	< 1.3 mg/kg
Silver	Lab	580 n mg/kg		< 0.34 mg/kg	< 0.32 mg/kg	< 0.30 mg/kg	J. J.	< 0.28 mg/kg	< 0.32 mg/kg	< 0.27 mg/kg			< 0.27 mg/kg		
SVOCs	Lau	Joo II IIIg/kg		· U.J- IIIg/kg	10.52 mg/kg	\ 0.50 mg/kg	< 0.50 mg/kg	* 0.20 mg/kg	1 0.52 mg/kg	- 0.27 Hig/kg	- 0.50 mg/kg	\ 0.27 Hig/kg	\ 0.27 mg/kg	\ 0.20 mg/kg	10.52 mg/kg
1,2,4-Trichlorobenzene	Lab	26 n mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg	< 0.40 mg/kg	< 0.37 ma/ka	< 0.43 mg/kg	< 0.35 ma/ka	< 0.40 mg/kg	< 0.36 mg/kg	< 0.36 ma/ka	< 0.37 ma/ka	< 0.42 mg/kg
1.2-Dichlorobenzene	Lab	930 ns mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg		< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg		< 0.36 mg/kg	< 0.36 mg/kg		
1.3-Dichlorobenzene	Lab	550 H3 HIg/ kg		< 0.45 mg/kg	J. J.		< 0.40 mg/kg	< 0.37 mg/kg	5 3		< 0.40 mg/kg	<i>J</i> , <i>J</i>	<i>J. J.</i>	< 0.37 mg/kg	J. J.
1,4-Dichlorobenzene	Lab	11 c mg/kg		< 0.45 mg/kg		< 0.40 mg/kg	J. J.	< 0.37 mg/kg	5 3	<i>J</i> , <i>J</i>	< 0.40 mg/kg	<i>J</i> , <i>J</i>		< 0.37 mg/kg	
2,3,4,6-Tetrachlorophenol	Lab	2500 n mg/kg		< 0.91 mg/kg	< 0.87 mg/kg	< 0.81 mg/kg	J. J.	< 0.75 mg/kg	< 0.87 mg/kg	< 0.71 mg/kg			< 0.74 mg/kg	J. J.	J. J.
2,4,5-Trichlorophenol	Lab	8200 n mg/kg		< 0.91 mg/kg	.,			< 0.75 mg/kg		< 0.71 mg/kg	.,, .,		.,,	< 0.75 mg/kg	.,,
2,4,6-Trichlorophenol	Lab	82 n mg/kg		< 0.91 mg/kg	< 0.87 mg/kg			< 0.75 mg/kg		< 0.71 mg/kg				< 0.75 mg/kg	.,,
2,4-Dichlorophenol	Lab	250 n mg/kg		< 0.91 mg/kg	< 0.87 mg/kg		< 0.81 mg/kg	< 0.75 mg/kg		< 0.71 mg/kg	.,		< 0.74 mg/kg		
2,4-Dimethylphenol	Lab	1600 n mg/kg		< 0.91 mg/kg	J. J.		< 0.81 mg/kg	< 0.75 mg/kg		<i>J. J.</i>	< 0.81 mg/kg			< 0.75 mg/kg	
2,4-Dinitrophenol	Lab	160 n mg/kg		< 0.91 mg/kg	J. J.		J. J.	< 0.75 mg/kg	5 3	< 0.71 mg/kg	J. J			< 0.75 mg/kg	
2,4-Dinitrotoluene	Lab	7.4 c* mg/kg		< 0.45 mg/kg	J. J.	< 0.40 mg/kg	J. J.	< 0.37 mg/kg	J J	< 0.35 mg/kg	J. J	J. J.		< 0.37 mg/kg	
2,6-Dichlorophenol	Lab	3. 3		< 0.91 mg/kg	< 0.87 mg/kg	< 0.81 mg/kg	< 0.81 mg/kg	< 0.75 mg/kg		< 0.71 mg/kg	< 0.81 mg/kg			< 0.75 mg/kg	
2,6-Dinitrotoluene	Lab	1.5 c* mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg	< 0.40 mg/kg	< 0.37 mg/kg	< 0.43 mg/kg		< 0.40 mg/kg			< 0.37 mg/kg	< 0.42 mg/kg
2-Chloronaphthalene	Lab	6000 n mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg	< 0.40 mg/kg	< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg	< 0.40 mg/kg	< 0.36 mg/kg	< 0.36 mg/kg	< 0.37 mg/kg	< 0.42 mg/kg
2-Chlorophenol	Lab	580 n mg/kg		< 0.91 mg/kg	< 0.87 mg/kg	< 0.81 mg/kg	< 0.81 mg/kg	< 0.75 mg/kg	< 0.87 mg/kg	< 0.71 mg/kg	< 0.81 mg/kg	< 0.74 mg/kg	< 0.74 mg/kg	< 0.75 mg/kg	< 0.85 mg/kg
2-Methyl-4,6-dinitrophenol	Lab	6.6 n mg/kg		< 0.91 mg/kg	< 0.87 mg/kg		< 0.81 mg/kg	< 0.75 mg/kg	< 0.87 mg/kg	< 0.71 mg/kg	< 0.81 mg/kg	< 0.74 mg/kg	< 0.74 mg/kg	< 0.75 mg/kg	
2-Methylnaphthalene	Lab	300 n mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg	< 0.40 mg/kg	< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg	< 0.40 mg/kg	< 0.36 mg/kg	< 0.36 mg/kg	< 0.37 mg/kg	< 0.42 mg/kg
2-Methylphenol (o-cresol)	Lab	4100 n mg/kg		< 0.91 mg/kg	< 0.87 mg/kg	<i>J</i> , <i>J</i>	J. J.	< 0.75 mg/kg	< 0.87 mg/kg	< 0.71 mg/kg	< 0.81 mg/kg		<i>J. J.</i>	< 0.75 mg/kg	J. J.
2-Nitroaniline	Lab	800 n mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg	< 0.40 mg/kg	< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg	J. J	J. J.	< 0.36 mg/kg	<i>J. J.</i>	
2-Nitrophenol	Lab			< 0.91 mg/kg	< 0.87 mg/kg	< 0.81 mg/kg	< 0.81 mg/kg	< 0.75 mg/kg	<i>J</i> , <i>J</i>	< 0.71 mg/kg	< 0.81 mg/kg	< 0.74 mg/kg	< 0.74 mg/kg	< 0.75 mg/kg	< 0.85 mg/kg
3,3`-Dichlorobenzidine	Lab	5.1 c mg/kg		< 2.2 mg/kg	< 2.1 mg/kg	< 1.9 mg/kg		< 1.8 mg/kg	< 2.1 mg/kg		< 1.9 mg/kg	< 1.8 mg/kg	< 1.8 mg/kg	< 1.8 mg/kg	< 2.0 mg/kg
3,4-Methylphenol (m,p cresols)	Lab			< 0.91 mg/kg	< 0.87 mg/kg		< 0.81 mg/kg	< 0.75 mg/kg		< 0.71 mg/kg				< 0.75 mg/kg	
3-Nitroaniline	Lab			< 0.45 mg/kg	< 0.43 mg/kg			< 0.37 mg/kg		< 0.35 mg/kg					< 0.42 mg/kg
4-Bromophenyl phenyl ether	Lab	0200 #		< 0.45 mg/kg	< 0.43 mg/kg			< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg		< 0.36 mg/kg	.,,	< 0.37 mg/kg	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
4-Chloro-3-methylphenol	Lab	8200 n mg/kg		< 0.91 mg/kg	< 0.87 mg/kg		< 0.81 mg/kg	< 0.75 mg/kg	J. J.	< 0.71 mg/kg		J. J.		< 0.75 mg/kg	
4-Chloroaniline 4-Chlorophenyl phenyl ether	Lab	11 c* mg/kg		< 0.91 mg/kg			< 0.81 mg/kg	< 0.75 mg/kg			< 0.81 mg/kg	J. J.		< 0.75 mg/kg	
1 / 1 /	Lab	110 c** m a //ca		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg		< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg	< 0.40 mg/kg	< 0.36 mg/kg	< 0.36 mg/kg		
4-Nitrophanal	Lab	110 c** mg/kg		< 0.45 mg/kg	J. J.	J. J.	J. J	< 0.37 mg/kg	J. J.	< 0.35 mg/kg		J. J		< 0.37 mg/kg	
4-Nitrophenol Acenaphthene	Lab Lab	4500 p.ma/ka		< 0.91 mg/kg	< 0.87 mg/kg < 0.43 mg/kg	J. J.	J. J.	< 0.75 mg/kg	< 0.87 mg/kg < 0.43 mg/kg	< 0.71 mg/kg	J. J	J. J.	J. J.	< 0.75 mg/kg	J. J.
Acenaphthylene	Lab	4500 n mg/kg		< 0.45 mg/kg < 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg < 0.40 mg/kg		< 0.37 mg/kg < 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg < 0.35 mg/kg	< 0.40 mg/kg < 0.40 mg/kg	< 0.36 mg/kg < 0.36 mg/kg	< 0.36 mg/kg	< 0.37 mg/kg < 0.37 mg/kg	
Aniline	Lab	400 c** mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg	., .,	< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg		< 0.36 mg/kg		< 0.37 mg/kg	
Anthracene	Lab	23000 n mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	.,, .,	.,, .,	< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg		< 0.36 mg/kg	< 0.36 mg/kg		
Azobenzene	Lab	26 c mg/kg		< 0.45 mg/kg	< 0.43 mg/kg			< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg				< 0.37 mg/kg	
Benz(a)anthracene	Lab	2.9 c mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg		< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg	< 0.40 mg/kg	< 0.36 mg/kg	< 0.36 mg/kg		
Benzidine	Lab	0.010 c mg/kg		< 3.4 mg/kg	< 3.2 mg/kg	< 3.0 mg/kg	< 3.0 mg/kg	< 2.8 mg/kg	< 3.2 mg/kg	< 2.7 mg/kg	< 3.0 mg/kg	< 2.7 mg/kg	< 2.7 mg/kg	< 2.8 mg/kg	
Benzo(a)pyrene	Lab	0.29 c mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg		< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg				< 0.37 mg/kg	
Benzo(b)fluoranthene	Lab	2.9 c mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg	J. J.	< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg				< 0.37 mg/kg	
Benzo(g,h,i)perylene	Lab	2.5 c mg/kg		< 0.45 mg/kg	< 0.43 mg/kg			< 0.37 mg/kg		< 0.35 mg/kg				< 0.37 mg/kg	
Benzo(k)fluoranthene	Lab	29 c mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg		< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg		< 0.36 mg/kg		< 0.37 mg/kg	
Benzoic acid	Lab	330000 nm mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg		< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg				< 0.37 mg/kg	.,,
Benzyl alcohol	Lab	8200 n mg/kg		< 0.91 mg/kg	< 0.87 mg/kg		< 0.81 mg/kg	< 0.75 mg/kg							< 0.85 mg/kg
Bis(2-chloroethoxy)methane	Lab	250 n mg/kg		< 0.45 mg/kg	J. J.		< 0.40 mg/kg	J. J.	5 3	J. J.	J. J	J. J.			< 0.42 mg/kg
DISTE CHIOTOCHIONY/ITICHIOTIC	Lab	230 H Hig/kg	1	- 0.15 mg/kg	1 0.15 mg/kg	1 0. 10 mg/kg	* 0.10 mg/kg	1 0.57 mg/kg	1 0. 15 Hig/ kg	. 0.55 mg/kg	. v. iv ilig/kg	1 0.50 mg/kg	1 0.50 mg/kg	* 0.57 mg/kg	1 0.12 mg/kg

Page 1 of 3 2/22/2016

						Minot, I	ND								
			Location	B-1	B-1	B-2a	B-2a	B-3	B-3	B-4	B-4	B-5	B-5	B-6	B-6
			Date	11/23/2015	11/23/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015
		EPA Industrial	NDDoH Guidelines for	10 - 12 ft	16 - 18 ft	2 - 4 ft	4 - 6 ft	0 - 2 ft	6 - 8 ft	2 - 4 ft	8 - 10 ft	0 - 2 ft	6 - 8 ft	0 - 2 ft	6 - 8 ft
Davarantan	Analysis	Carcinogenic and	the Assessment and												
Parameter	Location	Non-Carcinogenic	Cleanup of Saltwater												
		RSL TR=1E-06 or	Releases - Soil Cleanup												
		THQ=0.1	Standards												
Effective Date		06/01/2015 Bold	12/01/2014 No Exceed												
Exceedance Key Bis(2-chloroethyl)ether	Lab	1.0 c mg/kg	No exceed	< 0.45 mg/kg	< 0.43 ma/ka	< 0.40 mg/kg	< 0.40 mg/kg	< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 ma/ka	< 0.40 mg/kg	< 0.36 mg/kg	< 0.36 ma/ka	< 0.37 mg/kg	< 0.42 mg/kg
Bis(2-chloroisopropyl)ether	Lab	1.0 c mg/ kg		< 0.45 mg/kg	< 0.43 mg/kg	יני יני		< 0.37 mg/kg		< 0.35 mg/kg	J. J.	< 0.36 mg/kg	< 0.36 mg/kg		
Bis(2-ethylhexyl)phthalate	Lab	160 c* mg/kg		< 0.45 mg/kg		< 0.40 mg/kg	J. J.	< 0.37 mg/kg	J. J.	J. J	< 0.40 mg/kg	< 0.36 mg/kg	J. J.	< 0.37 mg/kg	J. J.
Butyl benzyl phthalate	Lab	1200 c* mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	.,,	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	< 0.37 mg/kg		.,,	< 0.40 mg/kg	< 0.36 mg/kg	., .,	.,,	< 0.42 mg/kg
Carbazole	Lab			< 0.45 mg/kg	< 0.43 mg/kg		.,	< 0.37 mg/kg		< 0.35 mg/kg		< 0.36 mg/kg	< 0.36 mg/kg		
Chrysene	Lab	290 c mg/kg		< 0.45 mg/kg		J. J.	J. J.	< 0.37 mg/kg	3. 3		< 0.40 mg/kg	< 0.36 mg/kg		< 0.37 mg/kg	
Dibenz(a,h)anthracene Dibenzofuran	Lab Lab	0.29 c mg/kg 100 n mg/kg		< 0.45 mg/kg	J. J.	< 0.40 mg/kg < 0.40 mg/kg	J. J.	< 0.37 mg/kg < 0.37 mg/kg	J. J.	< 0.35 mg/kg < 0.35 mg/kg	< 0.40 mg/kg	< 0.36 mg/kg	< 0.36 mg/kg	J. J.	< 0.42 mg/kg
Diethyl phthalate	Lab	66000 n mg/kg		< 0.45 mg/kg < 0.45 mg/kg	< 0.43 mg/kg < 0.43 mg/kg	< 0.40 mg/kg	J, J	< 0.37 mg/kg	J. J.	J. J	< 0.40 mg/kg < 0.40 mg/kg	< 0.36 mg/kg < 0.36 mg/kg	J. J.	< 0.37 mg/kg < 0.37 mg/kg	
Dimethyl phthalate	Lab	occooning/kg		< 0.45 mg/kg	J. J.	<i>J. J.</i>	J. J.	< 0.37 mg/kg	J. J.	< 0.35 mg/kg	J. J.	< 0.36 mg/kg	J. J.	< 0.37 mg/kg	J. J.
Di-n-butyl phthalate	Lab	8200 n mg/kg		< 0.45 mg/kg	J. J.	< 0.40 mg/kg	J. J.	< 0.37 mg/kg	<i>J</i> , <i>J</i>	< 0.35 mg/kg		< 0.36 mg/kg	J. J.	< 0.37 mg/kg	J. J.
Di-n-octyl phthalate	Lab	820 n mg/kg		< 0.45 mg/kg	.,,	.,,	< 0.40 mg/kg	< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg	< 0.40 mg/kg	.,		< 0.37 mg/kg	., .,
Fluoranthene	Lab	3000 n mg/kg		< 0.45 mg/kg	< 0.43 mg/kg			< 0.37 mg/kg	.,	< 0.35 mg/kg		< 0.36 mg/kg	., .,	< 0.37 mg/kg	.,, .,
Fluorene Hexachlorobenzene	Lab	3000 n mg/kg		< 0.45 mg/kg	J. J	< 0.40 mg/kg	J. J.	< 0.37 mg/kg	J, J	J. J.	< 0.40 mg/kg	< 0.36 mg/kg	< 0.36 mg/kg	J. J.	J. J.
Hexachlorobenzene Hexachlorobutadiene	Lab Lab	0.96 c* mg/kg 5.3 c* mg/kg		< 0.45 mg/kg < 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg < 0.40 mg/kg	J. J.	< 0.37 mg/kg < 0.37 mg/kg		J. J.	< 0.40 mg/kg < 0.40 mg/kg	< 0.36 mg/kg < 0.36 mg/kg		< 0.37 mg/kg < 0.37 mg/kg	
Hexachlorocyclopentadiene	Lab	0.75 n mg/kg		< 0.45 mg/kg		< 0.40 mg/kg	J. J.	< 0.37 mg/kg	J. J.	J. J.	< 0.40 mg/kg	< 0.36 mg/kg	J. J.	J. J.	< 0.42 mg/kg
Hexachloroethane	Lab	8.0 c** mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	J. J.	J. J.	< 0.37 mg/kg	<i>J</i> , <i>J</i>	< 0.35 mg/kg	J. J.	< 0.36 mg/kg	J. J.	< 0.37 mg/kg	J. J.
Indeno(1,2,3-cd)pyrene	Lab	2.9 c mg/kg		< 0.45 mg/kg		< 0.40 mg/kg		< 0.37 mg/kg	J. J.	< 0.35 mg/kg	J. J.	< 0.36 mg/kg		< 0.37 mg/kg	
Isophorone	Lab	2400 c** mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg	< 0.40 mg/kg	< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg	< 0.40 mg/kg	< 0.36 mg/kg	< 0.36 mg/kg	< 0.37 mg/kg	< 0.42 mg/kg
Naphthalene	Lab	17 c** mg/kg		< 0.45 mg/kg	< 0.43 mg/kg			< 0.37 mg/kg		< 0.35 mg/kg		< 0.36 mg/kg		< 0.37 mg/kg	
Nitrobenzene	Lab	22 c** mg/kg		< 0.45 mg/kg		< 0.40 mg/kg		< 0.37 mg/kg		< 0.35 mg/kg		< 0.36 mg/kg		< 0.37 mg/kg	
N-Nitrosodimethylamine N-Nitrosodi-n-propylamine	Lab Lab	0.034 c* mg/kg 0.33 c mg/kg		< 0.45 mg/kg < 0.45 mg/kg	< 0.43 mg/kg < 0.43 mg/kg	J. J.	< 0.40 mg/kg < 0.40 mg/kg	< 0.37 mg/kg < 0.37 mg/kg	J. J.	< 0.35 mg/kg < 0.35 mg/kg	< 0.40 mg/kg < 0.40 mg/kg	< 0.36 mg/kg < 0.36 mg/kg	J. J.	< 0.37 mg/kg	< 0.42 mg/kg < 0.42 mg/kg
N-Nitrosodi-n-propylamine N-Nitrosodiphenylamine	Lab	470 c mg/kg		< 0.45 mg/kg		< 0.40 mg/kg	J. J.	< 0.37 mg/kg	J. J.	J. J	< 0.40 mg/kg	< 0.36 mg/kg		< 0.37 mg/kg	J. J.
Pentachlorophenol	Lab	4.0 c* mg/kg		< 0.91 mg/kg		J. J.	< 0.81 mg/kg	J. J.	< 0.87 mg/kg	J. J	< 0.81 mg/kg				< 0.85 mg/kg
Phenanthrene	Lab	<i>J. J</i>		< 0.45 mg/kg	< 0.43 mg/kg	J. J.	J. J.	< 0.37 mg/kg	J. J.	< 0.35 mg/kg	J. J.	< 0.36 mg/kg	< 0.36 mg/kg	J. J.	J. J.
Phenol	Lab	25000 n mg/kg		< 0.91 mg/kg	< 0.87 mg/kg		< 0.81 mg/kg	< 0.75 mg/kg		< 0.71 mg/kg		< 0.74 mg/kg		< 0.75 mg/kg	
Pyrene	Lab	2300 n mg/kg		< 0.45 mg/kg	< 0.43 mg/kg	< 0.40 mg/kg	< 0.40 mg/kg	< 0.37 mg/kg	< 0.43 mg/kg	< 0.35 mg/kg	< 0.40 mg/kg	< 0.36 mg/kg	< 0.36 mg/kg	< 0.37 mg/kg	< 0.42 mg/kg
VOCs		0.0 #		0.07 #	0.00	004 #	0.04	0.01	0.00	0.04	0.01	0.01	0.00	0.00	205 #
1,1,1,2-Tetrachloroethane	Lab	8.8 c mg/kg		< 0.27 mg/kg	< 0.26 mg/kg		< 0.24 mg/kg		< 0.26 mg/kg		< 0.24 mg/kg			< 0.22 mg/kg	
1,1,1-Trichloroethane 1,1,2,2-Tetrachloroethane	Lab Lab	3600 ns mg/kg 2.7 c mg/kg		< 0.27 mg/kg < 0.27 mg/kg			< 0.24 mg/kg		< 0.26 mg/kg < 0.26 mg/kg		< 0.24 mg/kg				< 0.25 mg/kg
1,1,2-Trichloroethane	Lab	0.63 n mg/kg		< 0.27 mg/kg	< 0.26 mg/kg			< 0.21 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg			< 0.25 mg/kg
1,1-Dichloro-1-propene	Lab	ever wwg, wg		< 0.27 mg/kg	< 0.26 mg/kg			< 0.21 mg/kg	<i>J</i> , <i>J</i>	< 0.21 mg/kg	J, J			< 0.22 mg/kg	
1,1-Dichloroethane	Lab	16 c mg/kg		< 0.27 mg/kg			< 0.24 mg/kg	< 0.21 mg/kg			< 0.24 mg/kg				< 0.25 mg/kg
1,1-Dichloroethylene	Lab	100 n mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	J. J.	J. J.	< 0.21 mg/kg	J. J.	< 0.21 mg/kg	J, J	< 0.21 mg/kg		J. J.	< 0.25 mg/kg
1,2,3-Trichlorobenzene	Lab	93 n mg/kg		< 0.68 mg/kg	< 0.65 mg/kg	.,,	< 0.60 mg/kg	< 0.53 mg/kg		< 0.53 mg/kg		< 0.52 mg/kg		< 0.56 mg/kg	
1,2,3-Trichloropropane 1,2,4-Trichlorobenzene	Lab Lab	0.11 c* mg/kg 26 n mg/kg		< 0.27 mg/kg	< 0.26 mg/kg < 0.65 mg/kg		< 0.24 mg/kg < 0.60 mg/kg	< 0.21 mg/kg		< 0.21 mg/kg < 0.53 mg/kg	< 0.24 mg/kg < 0.60 mg/kg	< 0.21 mg/kg < 0.52 mg/kg	< 0.22 mg/kg < 0.55 mg/kg	.,,	< 0.25 mg/kg
1,2,4-Trichlorobenzene	Lab	24 n mg/kg		< 0.68 mg/kg < 0.27 mg/kg	< 0.26 mg/kg		.,	< 0.53 mg/kg < 0.21 mg/kg				< 0.32 mg/kg		< 0.22 mg/kg	
1,2-Dibromo-3-chloropropane	Lab	0.064 c* mg/kg		< 0.68 mg/kg			< 0.60 mg/kg	< 0.53 mg/kg			< 0.60 mg/kg				< 0.63 mg/kg
1,2-Dibromoethane	Lab	0.16 c mg/kg		< 0.27 mg/kg	< 0.26 mg/kg			< 0.21 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg			< 0.25 mg/kg
1,2-Dichlorobenzene	Lab	930 ns mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.26 mg/kg	< 0.21 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.22 mg/kg	< 0.22 mg/kg	< 0.25 mg/kg
1,2-Dichloroethane	Lab	2.0 c** mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	J. J.	J. J.	< 0.21 mg/kg	J. J.	< 0.21 mg/kg	J. J.	< 0.21 mg/kg	J. J.	J. J.	< 0.25 mg/kg
1,2-Dichloroethylene, cis	Lab	230 n mg/kg	-	< 0.27 mg/kg	< 0.26 mg/kg			< 0.21 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg	., .,	< 0.22 mg/kg	., .,
1,2-Dichloroethylene, trans 1,2-Dichloropropane	Lab Lab	2300 ns mg/kg 4.4 c** mg/kg		< 0.27 mg/kg < 0.27 mg/kg	< 0.26 mg/kg < 0.26 mg/kg		.,	< 0.21 mg/kg < 0.21 mg/kg		< 0.21 mg/kg < 0.21 mg/kg		< 0.21 mg/kg < 0.21 mg/kg	., .,	.,,	< 0.25 mg/kg < 0.25 mg/kg
1,3,5-Trimethylbenzene	Lab	1200 ns mg/kg		< 0.27 mg/kg < 0.27 mg/kg	< 0.26 mg/kg		< 0.24 mg/kg < 0.24 mg/kg	< 0.21 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg < 0.21 mg/kg		< 0.22 mg/kg	., .,
1,3-Dichloro-1-propene, cis	Lab	8.2 c** (1) mg/kg		< 0.27 mg/kg	< 0.26 mg/kg		< 0.24 mg/kg	< 0.21 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg			< 0.25 mg/kg
1,3-Dichloro-1-propene, trans	Lab	8.2 c** (1) mg/kg		< 0.27 mg/kg	< 0.26 mg/kg			< 0.21 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg			< 0.25 mg/kg
1,3-Dichlorobenzene	Lab			< 0.27 mg/kg	< 0.26 mg/kg	J. J.		< 0.21 mg/kg		< 0.21 mg/kg	J. J.	< 0.21 mg/kg			< 0.25 mg/kg
1,3-Dichloropropane	Lab	2300 ns mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	J. J.	J. J.	< 0.21 mg/kg	J. J.	< 0.21 mg/kg	J. J.				< 0.25 mg/kg
1,4-Dichlorobenzene	Lab	11 c mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	J. J.	< 0.24 mg/kg	< 0.21 mg/kg	J. J.	< 0.21 mg/kg	J. J.	J. J.		< 0.22 mg/kg	
2,2-Dichloropropane	Lab			< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.26 mg/kg	< 0.21 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.22 mg/kg	< 0.22 mg/kg	< 0.25 mg/kg


						iviinot, r	ND ND								
	B-1	B-1	B-2a	B-2a	B-3	B-3	B-4	B-4	B-5	B-5	B-6	B-6			
	11/23/2015	11/23/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015	11/24/2015			
			Depth	10 - 12 ft	16 - 18 ft	2 - 4 ft	4 - 6 ft	0 - 2 ft	6 - 8 ft	2 - 4 ft	8 - 10 ft	0 - 2 ft	6 - 8 ft	0 - 2 ft	6 - 8 ft
	!	EPA Industrial	NDDoH Guidelines for	1											
	Amalysis	Carcinogenic and	the Assessment and	1											
Parameter	Analysis	Non-Carcinogenic	Cleanup of Saltwater	1											
	Location	RSL TR=1E-06 or	Releases - Soil Cleanup	1											
	!	THQ=0.1	Standards	1											
Effective Date	+	06/01/2015	12/01/2014												
Exceedance Key	+	Bold	No Exceed	 											
Acetone	Lab	67000 n mg/kg	NO EXCCCU	< 1.4 mg/kg	< 1.3 mg/kg	< 1.2 mg/kg	< 1.2 mg/kg	< 1.1 mg/kg	< 1.3 mg/kg	< 1.1 mg/kg	< 1.2 mg/kg	< 1.0 mg/kg	< 1.1 mg/kg	< 1.1 mg/kg	< 1.3 mg/kg
Allyl Chloride	Lab	0.69 n mg/kg		< 0.27 mg/kg		< 0.24 mg/kg	J. J.	J. J.	< 0.26 mg/kg	5 3			J. J.	J. J	< 0.25 mg/kg
Benzene	Lab	5.1 c** mg/kg	1	< 0.27 mg/kg					< 0.26 mg/kg				< 0.22 mg/kg	J. J.	J. J.
Bromobenzene	Lab	180 n mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg	.,			., .,	< 0.25 mg/kg
Bromochloromethane	Lab	63 n mg/kg		< 0.27 mg/kg	.,, .,	< 0.24 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg	.,				< 0.25 mg/kg
Bromodichloromethane	Lab	1.3 c mg/kg		< 0.27 mg/kg		< 0.24 mg/kg	., .,		< 0.26 mg/kg				< 0.22 mg/kg		< 0.25 mg/kg
Bromoform	Lab	86 c* mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.26 mg/kg	< 0.21 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.22 mg/kg	< 0.22 mg/kg	< 0.25 mg/kg
Bromomethane	Lab	3.0 n mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.26 mg/kg	< 0.21 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.22 mg/kg	< 0.22 mg/kg	< 0.25 mg/kg
Butyl benzene	Lab	5800 ns mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.26 mg/kg	< 0.21 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.22 mg/kg	< 0.22 mg/kg	< 0.25 mg/kg
Butylbenzene, sec	Lab	12000 ns mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg	J. J.	< 0.21 mg/kg	J. J.	< 0.21 mg/kg	< 0.24 mg/kg	J. J.	J. J.	J. J	< 0.25 mg/kg
Butylbenzene, tert	Lab	12000 ns mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg	.11	< 0.21 mg/kg		< 0.21 mg/kg	.,		.,,		< 0.25 mg/kg
Carbon tetrachloride	Lab	2.9 c* mg/kg		< 0.27 mg/kg	.,, .,	< 0.24 mg/kg		.,,	< 0.26 mg/kg		.,		< 0.22 mg/kg		
Chlorobenzene	Lab	130 n mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg	.,		.,,		< 0.25 mg/kg
Chlorodibromomethane	Lab	3.3 c mg/kg		< 0.27 mg/kg	J. J.	< 0.24 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg				J. J.	< 0.25 mg/kg
Chloroethane	Lab	5700 ns mg/kg		J. J.	< 0.26 mg/kg	< 0.24 mg/kg	J. J.	J. J.	< 0.26 mg/kg	J. J.	J. J.	J, J	< 0.22 mg/kg	J. J	J. J.
Chloroform	Lab	1.4 c* mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg	J. J.	J. J.	J. J.	J. J.	< 0.25 mg/kg
Chloromethane	Lab	46 n mg/kg		< 0.27 mg/kg	<u> </u>	< 0.24 mg/kg	J. J.	< 0.21 mg/kg	J. J.	< 0.21 mg/kg	J. J.	J. J.	< 0.22 mg/kg	<i>J</i> . <i>J</i>	J. J.
Chlorotoluene, o Chlorotoluene, p	Lab Lab	2300 ns mg/kg 2300 ns mg/kg		< 0.27 mg/kg < 0.27 mg/kg	<u> </u>	< 0.24 mg/kg < 0.24 mg/kg	J. J	< 0.21 mg/kg	< 0.26 mg/kg < 0.26 mg/kg	, ,	J. J.	J. J.	< 0.22 mg/kg < 0.22 mg/kg	<i>J</i> . <i>J</i>	< 0.25 mg/kg
Cumene (isopropyl benzene)	Lab	990 ns mg/kg		< 0.27 mg/kg	.,, .,	< 0.24 mg/kg		.,,	< 0.26 mg/kg		.,		< 0.22 mg/kg	.,,	
Cymene p- (Toluene isopropyl p-)	Lab	330 H3 HIg/kg	-	< 0.27 mg/kg		< 0.24 mg/kg		< 0.21 mg/kg					< 0.22 mg/kg	.,,	< 0.25 mg/kg
Dibromomethane (methylene bromide)	Lab	9.8 n mg/kg		< 0.27 mg/kg		< 0.24 mg/kg			< 0.26 mg/kg					., .,	< 0.25 mg/kg
Dichlorodifluoromethane (CFC-12)	Lab	37 n mg/kg		< 0.27 mg/kg	J. J.	< 0.24 mg/kg			< 0.26 mg/kg				< 0.22 mg/kg	J. J.	J. J.
Dichlorofluoromethane (CFC-21)	Lab			< 0.27 mg/kg		< 0.24 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg			J. J.	<i>J</i> . <i>J</i>	< 0.25 mg/kg
Ethyl benzene	Lab	25 c* mg/kg		< 0.27 mg/kg		< 0.24 mg/kg			< 0.26 mg/kg	, ,	J. J.	J. J.	< 0.22 mg/kg	<i>J</i> . <i>J</i>	J. J.
Ethyl ether	Lab	23000 ns mg/kg		< 0.27 mg/kg	<u> </u>	< 0.24 mg/kg	J. J.	<i>y</i>	< 0.26 mg/kg	, ,	J. J.		J. J.	< 0.22 mg/kg	J. J.
Hexachlorobutadiene	Lab	5.3 c* mg/kg		< 0.68 mg/kg	< 0.65 mg/kg	< 0.60 mg/kg		< 0.53 mg/kg		< 0.53 mg/kg			< 0.55 mg/kg	< 0.56 mg/kg	< 0.63 mg/kg
Methyl ethyl ketone (2-butanone)	Lab	19000 n mg/kg		< 1.4 mg/kg	< 1.3 mg/kg	< 1.2 mg/kg	< 1.2 mg/kg	< 1.1 mg/kg			< 1.2 mg/kg	< 1.0 mg/kg		< 1.1 mg/kg	< 1.3 mg/kg
Methyl isobutyl ketone (MIBK)	Lab	5600 ns mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.26 mg/kg	< 0.21 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.22 mg/kg	< 0.22 mg/kg	< 0.25 mg/kg
Methyl tertiary butyl ether (MTBE)	Lab	210 c* mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg		< 0.21 mg/kg	< 0.22 mg/kg	< 0.22 mg/kg	< 0.25 mg/kg
Methylene chloride	Lab	320 n mg/kg		< 0.68 mg/kg		< 0.60 mg/kg	J, J	J. J.	< 0.65 mg/kg	J, J	J. J.	J. J.	< 0.55 mg/kg	J. J.	J. J.
Naphthalene	Lab	17 c** mg/kg				< 0.60 mg/kg			< 0.65 mg/kg				< 0.55 mg/kg		
Propylbenzene	Lab	2400 ns mg/kg							< 0.26 mg/kg						
Styrene	Lab	3500 ns mg/kg		J, J	< 0.26 mg/kg	J, J			< 0.26 mg/kg				< 0.22 mg/kg	<i>J</i> . <i>J</i>	J. J.
Tetrachloroethylene	Lab	39 n mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg					J. J.	J. J.	< 0.25 mg/kg
Tetrahydrofuran	Lab	9600 n mg/kg		< 1.4 mg/kg		< 1.2 mg/kg	< 1.2 mg/kg	< 1.1 mg/kg	< 1.3 mg/kg	< 1.1 mg/kg	< 1.2 mg/kg	< 1.0 mg/kg	.,, .,	.,, .,	.,,
Toluene	Lab	4700 ns mg/kg		< 0.27 mg/kg		< 0.24 mg/kg			< 0.26 mg/kg				., .,		< 0.25 mg/kg
Trichloroethylene Trichlorofluoromethane	Lab Lab	1.9 n mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg		< 0.21 mg/kg < 0.21 mg/kg		< 0.21 mg/kg				., .,	< 0.25 mg/kg < 0.25 mg/kg
Trichlorotrifluoroethane (Freon 113)	Lab	310 n mg/kg 17000 ns mg/kg	 	< 0.27 mg/kg	< 0.26 mg/kg < 0.26 mg/kg	< 0.24 mg/kg < 0.24 mg/kg			< 0.26 mg/kg	< 0.21 mg/kg				< 0.22 mg/kg	J. J.
Vinyl chloride	Lab	1.7 c* mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	J. J.	, ,	< 0.24 mg/kg	< 0.21 mg/kg	J. J.	J. J.	< 0.25 mg/kg
Xylene, m & p	Lab	240 n (2) mg/kg		< 0.54 mg/kg		< 0.48 mg/kg	< 0.24 mg/kg	< 0.21 mg/kg	< 0.52 mg/kg	, ,		J. J.			< 0.51 mg/kg
Xylene, o	Lab	280 n mg/kg		< 0.27 mg/kg	< 0.26 mg/kg	< 0.24 mg/kg	< 0.24 mg/kg	< 0.42 mg/kg	< 0.26 mg/kg		J. J.	J. J.	J. J.		J. J.
Xylene, Total	Barr Calcuation	280 ns mg/kg		ND mg/kg	ND mg/kg	ND mg/kg	ND mg/kg	ND mg/kg	ND mg/kg	ND mg/kg	ND mg/kg	ND mg/kg	ND mg/kg	ND mg/kg	ND mg/kg
Total Petroleum Hydrocarbons	22.000.011				9/9										
,	+ '	†—————————————————————————————————————	100 ** //	11 /	. 10 //	0.6 (1	0.6 (1	20 //	10 (0.5 (0.0 "			0.0 #	. 10 /
Diesel Range Organics, C10-C28	Lab	1	100 ** mg/kg	< 11 mg/kg	< 10 mg/kg	< 9.6 mg/kg	< 9.6 mg/kg	30 mg/kg	< 10 mg/kg	< 8.5 mg/kg	< 9.6 mg/kg	13 mg/kg	< 8.8 mg/kg	< 9.0 mg/kg	< 10 mg/kg


_				IVIIII	טו, ואט						
						Location	B-1	B-2	2A	B-3	B-4
						Date	11/24/2015	11/25/2015		11/24/2015	11/25/2015
						Depth	10 - 20 ft		9.87 - 19.87 ft	8.6 - 18.6 ft	8.6 - 18.6 ft
						•					
		_		T	•	Sample Type	N	N	FD	N	N
			NDDoH Guidelines for the			ND Maximum Limits for					
	Analysis	EPA Secondary	Assessment and Cleanup of	EPA Maximum	ND Water Quality	Substances in or					
Parameter	Analysis	Drinking Water	Saltwater Releases -		Criteria (1) - Human						
	Location	Regulations	Groundwater Cleanup	Contaminant Levels	Health Values, Class 1	Characteristics of Class 1					
		19	Standards			Streams - Chronic					
Effective Date		06/20/2002	12/01/2014	05/01/2009	06/01/2001	06/01/2001					
Exceedance Key		No Exceed	<u>Underline</u>	Italic	Shade	Bold					
General Parameters		TVO EXCECU	<u> </u>	nutte	Shaac	Doid					
Dissolved oxygen	Field					5 mg/l	18.7 mg/l	31.67 mg/l		5.21 mg/l	4.52 mg/l
pH	Field	6.5 - 8.5 pH units				7.0 - 9.0 pH units	6.77 pH units	6.84 pH units		6.63 pH units	7.27 pH units
Specific Conductance @ 25 °C	Field		1500 *** umhos/cm				1598 umhos/cm	3029 umhos/cm		3447 umhos/cm	2196 umhos/cm
Temperature	Field					29.44 deg C	6.5 deg C	6.00 deg C		10.21 deg C	9.75 deg C
Metals (Dissolved)											
Arsenic	Lab		0.01 * mg/l	0.01 mg/l	0.01 (7) T mg/l			< 0.010 mg/l	< 0.010 mg/l	< 0.010 mg/l	< 0.010 mg/l
Barium	Lab		2 * mg/l	2 mg/l		1.0 T mg/l		0.087 mg/l	0.097 mg/l	0.050 mg/l	0.15 mg/l
Cadmium	Lab		0.005 * mg/l	0.005 mg/l	0.005 (7) T mg/l			< 0.0010 mg/l	< 0.0010 mg/l	< 0.0010 mg/l	< 0.0010 mg/l
Chromium	Lab		0.1 * mg/l	0.1 mg/l				< 0.010 mg/l	< 0.010 mg/l	< 0.010 mg/l	< 0.010 mg/l
Lead	Lab		0.015 * mg/l	0.015 TT (7) mg/l	0.015 (7) T mg/l			0.012 mg/l	0.0068 mg/l	0.014 mg/l	< 0.0050 mg/l
Mercury	Lab		0.002 * mg/l	0.002 mg/l	0.000050 T mg/l			< 0.010 mg/l	< 0.010 mg/l	< 0.010 mg/l	< 0.010 mg/l
Selenium	Lab	0.1 (1	0.05 * mg/l	0.05 mg/l	0.05 (7) T mg/l			< 0.030 mg/l	< 0.030 mg/l	< 0.030 mg/l	< 0.030 mg/l
Silver	Lab	0.1 mg/l	0.1 ** mg/l					< 0.0050 mg/l	< 0.0050 mg/l	< 0.0050 mg/l	< 0.0050 mg/l
SVOCs				70 (25 (1		0.2 (1	0.2 #	0.4 #	10 //	10 //
1,2,4-Trichlorobenzene	Lab			70 ug/l	35 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
1,2-Dichlorobenzene	Lab			600 ug/l	420 (7) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
1,3-Dichlorobenzene 1,4-Dichlorobenzene	Lab Lab			75 ug/l	320 ug/l 63 (7) ug/l		< 9.3 ug/l < 9.3 ug/l	< 9.3 ug/l < 9.3 ug/l	< 9.4 ug/l < 9.4 ug/l	< 10 ug/l < 10 ug/l	< 10 ug/l < 10 ug/l
2,3,4,6-Tetrachlorophenol	Lab			/5 ug/I	63 (7) ug/1		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2,4,5-Trichlorophenol	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2,4,6-Trichlorophenol	Lab				1.4 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2,4-Dichlorophenol	Lab				77 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2,4-Dimethylphenol	Lab				380 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2,4-Dinitrophenol	Lab				69 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2,4-Dinitrotoluene	Lab				0.11 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2,6-Dichlorophenol	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2,6-Dinitrotoluene	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2-Chloronaphthalene	Lab				1000 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2-Chlorophenol	Lab				81 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2-Methyl-4,6-dinitrophenol	Lab				13 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2-Methylnaphthalene	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2-Methylphenol (o-cresol)	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2-Nitroaniline	Lab				1		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
2-Nitrophenol	Lab				0.001 (4) (4		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
3,3`-Dichlorobenzidine	Lab				0.021 (4) ug/l		< 23 ug/l	< 23 ug/l	< 24 ug/l	< 25 ug/l	< 25 ug/l
3,4-Methylphenol (m,p cresols)	Lab Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
3-Nitroaniline	Lab				+		< 9.3 ug/l < 9.3 ug/l	< 9.3 ug/l < 9.3 ug/l	< 9.4 ug/l < 9.4 ug/l	< 10 ug/l < 10 ug/l	< 10 ug/l < 10 ug/l
4-Bromophenyl phenyl ether 4-Chloro-3-methylphenol	Lab				3000 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
4-Chloroaniline	Lab				5000 ug/1		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
4-Chlorophenyl phenyl ether	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
4-Nitroaniline	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
4-Nitrophenol	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Acenaphthene	Lab				670 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Acenaphthylene	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Aniline	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Anthracene	Lab				8300 (5) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Azobenzene	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Benz(a)anthracene	Lab				0.0038 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Benzidine	Lab				0.000086 (4) ug/l		< 93 ug/l	< 93 ug/l	< 94 ug/l	< 100 ug/l	< 100 ug/l
Benzo(a)pyrene	Lab			0.2 ug/l	0.0038 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l

					Ot, ND	Location	D 1	B-2	λ	D 3	D 4
							B-1			B-3	B-4
						Date	11/24/2015	11/25,		11/24/2015	11/25/2015
						Depth	10 - 20 ft	9.87 - 19.87 ft	9.87 - 19.87 ft	8.6 - 18.6 ft	8.6 - 18.6 ft
						Sample Type	N	N	FD	N	N
			NDDoH Guidelines for the			115.14					
		EPA Secondary	Assessment and Cleanup of		ND Water Quality	ND Maximum Limits for					
Parameter	Analysis	Drinking Water	Saltwater Releases -	EPA Maximum	Criteria (1) - Human	Substances in or					
rarameter	Location	Regulations	Groundwater Cleanup	Contaminant Levels	Health Values, Class 1	Characteristics of Class 1					
		Regulations	Standards		ricaitii vaides, Class 1	Streams - Chronic					
Effective Date		06/20/2002	12/01/2014	05/01/2009	06/01/2001	06/01/2001					
Exceedance Key		No Exceed	<u>Underline</u>	Italic	Shade	Bold					
Benzo(b)fluoranthene	Lab	110 2/10004	<u> </u>	reace	0.0038 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Benzo(g,h,i)perylene	Lab				(/ - 3/		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Benzo(k)fluoranthene	Lab				0.0038 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Benzoic acid	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Benzyl alcohol	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Bis(2-chloroethoxy)methane	Lab	1					< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Bis(2-chloroethyl)ether	Lab				0.030 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Bis(2-chloroisopropyl)ether	Lab		<u> </u>		10/:-		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Bis(2-ethylhexyl)phthalate	Lab	1		6 ug/l	1.2 (4) ug/l		9.8 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Butyl benzyl phthalate	Lab Lab	1			1500 ug/l		< 9.3 ug/l < 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l < 9.4 ug/l	< 10 ug/l	< 10 ug/l < 10 ug/l
Carbazole					0.0020 (4)			< 9.3 ug/l < 9.3 ug/l		< 10 ug/l	< 10 ug/l
Chrysene Dibenz(a,h)anthracene	Lab Lab	+			0.0038 (4) ug/l 0.0038 (4) ug/l		< 9.3 ug/l < 9.3 ug/l	< 9.3 ug/l < 9.3 ug/l	< 9.4 ug/l < 9.4 ug/l	< 10 ug/l < 10 ug/l	< 10 ug/l
Dibenzofuran	Lab				0.0038 (4) ug/1		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Diethyl phthalate	Lab				17000 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Dimethyl phthalate	Lab				270000 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Di-n-butyl phthalate	Lab				2000 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Di-n-octyl phthalate	Lab				, , , , , , , , , , , , , , , , , , ,		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Fluoranthene	Lab				130 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Fluorene	Lab				1100 (5) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Hexachlorobenzene	Lab			1 ug/l	0.00028 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Hexachlorobutadiene	Lab				0.44 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Hexachlorocyclopentadiene	Lab			50 ug/l	40 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Hexachloroethane	Lab				1.4 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Indeno(1,2,3-cd)pyrene	Lab				0.0038 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Isophorone Naphthalene	Lab Lab				35 (4) ug/l		< 9.3 ug/l < 9.3 ug/l	< 9.3 ug/l < 9.3 ug/l	< 9.4 ug/l < 9.4 ug/l	< 10 ug/l < 10 ug/l	< 10 ug/l < 10 ug/l
Nitrobenzene	Lab				17 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
N-Nitrosodimethylamine	Lab				0.00069 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
N-Nitrosodi-n-propylamine	Lab				0.005 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
N-Nitrosodiphenylamine	Lab				3.3 (4) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Pentachlorophenol	Lab			1 ug/l	0.27 ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Phenanthrene	Lab						< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Phenol	Lab				10000 ug/l	300 ug/l	< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
Pyrene	Lab	1			830 (5) ug/l		< 9.3 ug/l	< 9.3 ug/l	< 9.4 ug/l	< 10 ug/l	< 10 ug/l
VOCs		1									
1,1,1,2-Tetrachloroethane	Lab						< 1.0 ug/l				
1,1,1-Trichloroethane	Lab	1		200 ug/l	200 (7) ug/l		< 1.0 ug/l				
1,1,2,2-Tetrachloroethane	Lab	1		F/I	0.17 (4) ug/l		< 1.0 ug/l				
1,1,2-Trichloroethane	Lab	1		5 ug/l	0.59 (4) ug/l		< 1.0 ug/l				
1,1-Dichloro-1-propene 1,1-Dichloroethane	Lab Lab	+					< 1.0 ug/l < 1.0 ug/l				
1,1-Dichloroethane 1,1-Dichloroethylene	Lab	+		7 ug/l	7 (7) ug/l		< 1.0 ug/l < 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l
1,2,3-Trichlorobenzene	Lab	1	+	/ ug/i	/ (/) ug/i		< 5.0 ug/l				
1,2,3-Trichloropropane	Lab						< 2.5 ug/l				
1,2,4-Trichlorobenzene	Lab	†		70 ug/l	35 ug/l		< 5.0 ug/l				
1,2,4-Trimethylbenzene	Lab			~9/.	~g/.		< 1.0 ug/l				
1,2-Dibromo-3-chloropropane	Lab			0.2 ug/l			< 5.0 ug/l				
1,2-Dibromoethane	Lab			0.05 ug/l	0.05 (7) ug/l		< 2.5 ug/l				
1,2-Dichlorobenzene	Lab			600 ug/l	420 (7) ug/l		< 1.0 ug/l				
1,2-Dichloroethane	Lab			5 ug/l	0.38 (4) ug/l		< 1.0 ug/l				
1,2-Dichloroethylene, cis	Lab			70 ug/l	70 (7) ug/l		< 1.0 ug/l				
1,2-Dichloroethylene, trans	Lab			100 ug/l	100 (7) ug/l	1	< 1.0 ug/l				

Parenter					141111	ot, ND						
Parenter							Location	B-1	B-2	2A	B-3	B-4
Parenter Angles							Date	11/24/2015	11/25,	/2015	11/24/2015	11/25/2015
Parenter Angles							Denth		9 87 - 19 87 ft	9 87 - 19 87 ft		
Paymenter Analysis Feb. Norward Analysis Double Feb. Norward Analysis Double Expendence Feb. Norward Analysis Solvent Committee Feb. Norward Fe							<u>-</u>					
Parameter Laciston Parameter and Centers of Parameter and Centers		1		T	T	T	Sample Type	N	N	FD	N	N
Postmarter Pos							ND Maximum Limits for					
Promotion Distriction Di		Analysis		•	FPA Maximum	•						
Part	Parameter		Drinking Water	Saltwater Releases -			Characteristics of Class 1					
Security		Location	Regulations	Groundwater Cleanup	Contaminant Levels	Health Values, Class 1						
Marchane			J	Standards			Streams - Chronic					
According No Extend Impairing Animal Short Short Color of Col	Effective Date		06/20/2002		05/01/2009	06/01/2001	06/01/2001					
2-Defenderprocesses	Exceedance Key											
3.5 From Physics Lab		Lab						< 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l
3 Obthoroproper trans	1,3,5-Trimethylbenzene	Lab							< 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l
120 ugl	1,3-Dichloro-1-propene, cis	Lab							< 1.0 ug/l	< 1.0 ug/l		< 1.0 ug/l
3.000000000000000000000000000000000000	1,3-Dichloro-1-propene, trans	Lab						< 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l
	1,3-Dichlorobenzene					320 ug/l			< 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l	< 1.0 ug/l
2 Obtherproperse	1,3-Dichloropropane											< 1.0 ug/l
A	1,4-Dichlorobenzene				75 ug/l	63 (7) ug/l						
Strong												
Section Sect	Acetone											< 20 ug/l
10 mg/m 110 mg/m	,											
Commontationmentation Commontation Commontati	Benzene			5 * ug/l	5 ug/l	2.2 (4) ug/l						
Section Commonstance Commonsta												
Commodram Lab B0 (6) ug/l 42 (5) ug/l 50 ug/l					00 (6) (1	0.55 (5) (1			<i>J</i> ,			
Commontane												
utyl bennene Lab < 25 ug/l < 20 ug/l < 10 ug/l<					80 (6) ug/l							
Libb SugA C.10 ugA C.10 ugA						47 ug/I						
Lightenere, tert	,											
Supplementation Supplementary Supplement	,											
Thirdepenance Lab	,				5 ug/l	0.22 (4) ug/l			J.			J.
A									<i>J</i> ,			<i>J</i>
Chlorestane Lab												
Elboroform					00 (0) 49/1	0.10 (5) ug/1						
Chloromethane Cab					80 (6) ua/l	5 7 (4) ug/l						
Chlorotoluene o					00 (0) ug/.	3.7 (1) dg/1						
Chlorotoluene_p Lab									.,,			
Linene (sporpey) benzene Lab	Chlorotoluene, p											< 1.0 ug/l
Symene p- (Toluene isopropyl p-) Lab	Cumene (isopropyl benzene)											< 1.0 ug/l
	Cymene p- (Toluene isopropyl p-)	Lab						< 2.5 ug/l	< 2.5 ug/l	< 2.5 ug/l	< 2.5 ug/l	< 2.5 ug/l
Sichlorofuoromethane (CFC-21) Lab Sind org/lucy Sind	Dibromomethane (methylene bromide)	Lab						< 2.5 ug/l	< 2.5 ug/l	< 2.5 ug/l	< 2.5 ug/l	< 2.5 ug/l
thyl benzne	Dichlorodifluoromethane (CFC-12)											< 5.0 ug/l
thylether Lab	Dichlorofluoromethane (CFC-21)											< 1.0 ug/l
lexachlorobutadiene Lab Lab	Ethyl benzene				700 ug/l	530 (7) ug/l						< 1.0 ug/l
Aethyl ethyl ketone (2-butanone) Lab	Ethyl ether								.,,		.,,	< 5.0 ug/l
Methyl isobutyl ketone (MIBK) Lab	Hexachlorobutadiene					0.44 (4) ug/l						< 10 ug/l
Methyl tertiany butyl ether (MTBE)												
Methylene chloride												
Solution					F . A	4.6.(4)						
Composition					5 ug/l	4.6 (4) ug/l						
Styrene Lab 100 ug/l 100 (7) ug/l												
Etrachloroethylene					100/	100 (7) //			.,,		.,,	.,,
Column C									.,,			
Soluene Solu					o ug/i	0.09 (4) ug/1						
Trickloroethylene Lab Sug/l 2.5 (4) ug/l < 1.0					1000 ua/l	1000 (7) ug/l			J.			
Carichlorofluoromethane Carichlorofluoromethane Carichlorofluoromethane Carichlorofluoromethane Carichloromethane												
richlorotrifluoroethane (Freon 113) Lab					J ug/I	2.3 (4) ug/1						
Vinyl chloride Lab 2 ug/l 0.025 (4) ug/l < 1.0 ug/l									<i>J</i> ,			
Kylene, m & p Lab < 2.0 ug/l < 1.0 ug/l < 1.0 ug/l < 1.0 ug/l < 1.0 ug/l ND ug/l					2 μα/Ι	0.025 (4) μα/Ι			<i>J</i> ,			
Kylene, o Lab < 1.0 ug/l ND ug/l					2 ug/1	0.023 (T) ug/1						
Kylene, Total Barr Calculation 1000 ug/l 10000 (7) ug/l ND ug/l <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>.,,</td><td></td><td>.,,</td><td></td></th<>									.,,		.,,	
					1000 ua/l	10000 (7) ua/l						
1700017 1000 1001 1000 1000 1000 1000 1	Total Petroleum Hydrocarbons	za carcalation				(/, ug/1	 	49,1	ug/	чул	49,1	49/1

						Location	B-1	B-2	2A	B-3	B-4
						Date	11/24/2015	11/25,	/2015	11/24/2015	11/25/2015
						Depth	10 - 20 ft	9.87 - 19.87 ft	9.87 - 19.87 ft	8.6 - 18.6 ft	8.6 - 18.6 ft
						Sample Type	N	N	FD	N	N
Parameter	Analysis Location	EPA Secondary Drinking Water Regulations	NDDoH Guidelines for the Assessment and Cleanup of Saltwater Releases - Groundwater Cleanup Standards	EPA Maximum Contaminant Levels	ND Water Quality Criteria (1) - Human Health Values, Class 1	Characteristics of Class 1					
Effective Date		06/20/2002	12/01/2014	05/01/2009	06/01/2001	06/01/2001					
Exceedance Key		No Exceed	<u>Underline</u>	Italic	Shade	Bold					
Diesel Range Organics, C10-C28	Lab		<u>40 **** ug/l</u>				<u>120 ug/l</u>	130 ug/l	<u>190 ug/l</u>	<u>210 ug/l</u>	<u>110 ug/l</u>
Gasoline Range Organics, C6-C10	Lab		10 **** ug/l	·			< 100 ug/l				





4th Ave. Floodwall HTRW Assessment Area (2015)

* All locations are approximate





Figure 2


HTRW HISTORIC PROPERTIES
OF INTEREST
Mouse River Project



Appendices

Appendix A

Boring Logs



LOG OF BORING B-1

SHEET 1 OF 1

Project:Mouse River Project No.:34511010 Location:Minot, ND

Coordinates:N 453,453.0 ft E 1,776,991.0 ft

Surface Elevation:N/A
Drilling Method:Push

Sampling Method:Continuous

Datum: NAD83 - StatePlane North Dakota North Feet Completion Depth:20.0 ft feet Sample Type & Recovery Graphic Log MAJOR UNIT feet Š USCS Elevation, Sample ! **ENVIRONMENTAL** Depth, 1 LITHOLOGIC DESCRIPTION DATA GRAVEL WITH SANDY CLAY (GC): coarse grained; very dark gray (3/1/7.5YR); moist; 60% gravel, 20% sand, 20% fines PID:0.0 ppm D/O/S:None/ None/ None At 1-2.5': SANDY CLAY WITH GRAVEL, low plasticity. GC GRAVELLY SAND WITH CLAY (SW-SC): coarse grained; black (2/1/10YR); moist; 20% gravel, 60% sand, 20% fines. PID:0.0 ppm D/O/S:None/ None/ None 5 PID:0.0 ppm D/O/S:None/ None/ None SW-SC Ξ PID:0.0 ppm D/O/S:None/ None/ None At 7': Damp, trace oxidization staining. PID:0.0 ppm D/O/S:None/ Sulfuric/ None FAT CLAY (CH): black (2/1/10YR); 0% gravel, 10% sand, 90% fines, damp, high plasticity. 10 CH 10-12 PID:0.0 ppm D/O/S:None/ None/ None FAT CLAY (NATIVE) (CH): very dark greenish gray (3/10Y/Gley 1); dry; high plasticity; 0% gravel, 10% sand, 90% fines, abundant roots, shells, some fine sand stringers. **PID:**0.0 ppm D/O/S:None/ None/ None 15 PID:0.0 ppm D/O/S:None/ None/ None СН 16-18 PID:0.0 ppm D/O/S:None/ None/ None **PID:**0.0 ppm D/O/S:None/ None/ None 20 End of boring 20.0 feet

O:\GINT\PROJECTS\34511010.00.GPJ BARRLIBRARY.GLB ENVIRO LOG BARR TEMPLATE.GDT

Date Boring Started: 11/23/15 2:00 pm

Date Boring Completed: 11/23/15 2:30 pm

Logged By: AMK2

Drilling Contractor: Stevens

Drill Rig: Track Rig

Remarks:

Background PID: 0.00 ppm

PID = Headspace; D/O/S = Discoloration/Odor/Sheen; FID/MC = FID/Methane Corrected Additional data may have been collected in the field which is not included on this log. Weather: 33°F, 10 mph W wind



LOG OF BORING B-2a

SHEET 1 OF 1

Surface Elevation:N/A Drilling Method:Push


The state of the s		453,488.0 ft E 1,776,824.0			Sampling Method:Continuous		
ENVIRONMENTAL DATA S DE DOS None None None DIOS:None None None None None DIOS:None None None None None None None DIOS:None None None None None None None None	atum:NAD83	3 - StatePlane North Dakota	North	Feet	t Completion Depth:20.0 ft		Т
SARIDY FAT CLAY (CH): Integrained; dark prown (32/7.5YR), most; low to medium plasticity; 10% gravel, 30% sand, 60% fines, some rounded gravel, trace roots. At 1': Sandler, color change to black (2.5/1/7.5YR). At 3': Less sand. FAT CLAY (CH): dark grayish brown (4/2/10YR); high plasticity; 0% gravel, 10% sand, 90% fines, native, trace fine sand stringers. CH PID:0.3 ppm DIOIS:None/ None None PID:0.3 ppm DIOIS:None/ None None PID:0.4 ppm DIOIS:None/ None None At 11': Groundwater. At 11': Groundwater.		ENVIRONMENTAL DATA	U S C S	Graphic Log	LITHOLOGIC DESCRIPTION	MAJOR UNIT	
At 3: Less sand. FAT CLAY (CH): dark gray/ish brown (4/2/10YR); high plasticity; 0% gravel, 10% sand, 90% fines, native, trace fine sand stringers. CH PID:0.3 ppm D/O/S:None/ None None WELL SORTED SAND (SW-SC): fine grained; dark gray/ish brown (4/2/10YR); moist; 0% gravel, 90% sand, 10% fines, loose, some clay. PID:0.4 ppm D/O/S:None/ None None PID:0.4 ppm D/O/S:None/ None None At 11': Groundwater. PID:0.4 ppm D/O/S:None/ None/ None At 15': Coarser sand.		PID:1.4 ppm D/O/S:None/ None/ None	СН			FILL	
PID:0.4 ppm D/O/S:None/ None/ None PID:0.4 ppm D/O/S:None/ None/ None PID:0.4 ppm D/O/S:None/ None/ None At 11': Groundwater. PID:0.4 ppm D/O/S:None/ None/ None None At 11': Groundwater.	2-4	4 PID:0.3 ppm D/O/S:None/ None/ None			FAT CLAY (CH): dark grayish brown (4/2/10YR); high plasticity; 0% gravel, 10% sand, 90% fines, native,		_
PID: 0.4 ppm D/O/S:None/ None/ None PID: 0.4 ppm D/O/S:None/ None/ None At 11': Groundwater. PID: 0.4 ppm D/O/S:None/ None/ None SC PID: 0.4 ppm D/O/S:None/ None/ None At 11': Groundwater.	4-6	6 PID:0.3 ppm D/O/S:None/ None/ None	СН				
PID:0.4 ppm D/O/S:None/ None SW- D/O/S:None/ None SC PID:0.4 ppm D/O/S:None/ None SC At 11': Groundwater.		PID:0.3 ppm D/O/S:None/ None/ None	•		WELL SORTED SAND (SW-SC): fine grained; dark grayish brown (4/2/10YR); moist; 0% gravel, 90% sand, 10% fines, loose, some clay.		
PID:0.4 ppm SC SC PID:0.4 ppm At 15': Coarser sand.		PID:0.4 ppm D/O/S:None/ None/ None					
PID:0.4 ppm D/O/S:None/ None/ None PID:0.4 ppm At 15': Coarser sand.		PID:0.4 ppm D/O/S:None/ None/ None			At 11': Groundwater.	NATIVE	
/\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		PID:0.4 ppm D/O/S:None/ None/ None	SW- SC				
- Diois. Note: Note Note	5-	PID:0.4 ppm D/O/S:None/ None/ None			At 15': Coarser sand.		
PID:0.6 ppm D/O/S:None/ None At 18': Gradual color change to dark greenish gray (4/10Y/Gley 1).		PID:0.6 ppm D/O/S:None/ None/ None	* * * * * * * * * * * * * * * * * * *		At 18': Gradual color change to dark greenish gray (4/10Y/Gley 1).		
PID:0.5 ppm D/O/S:None/ None End of boring 20.0 feet							

11/24/15 8:20 am

Date Boring Started:
Date Boring Completed:
Logged By:
Drilling Contractor:
Drill Rig: AMK2 Stevens Track Rig

Background PID: 0.00 ppm

 ${\sf PID = Headspace; D/O/S = Discoloration/Odor/Sheen; FID/MC = FID/Methane\ Corrected}$ Additional data may have been collected in the field which is not included on this log. Weather: $27^{\circ}F$, calm, overcast, cloudy



LOG OF BORING B-3

SHEET 1 OF 1

Project:Mouse River Project No.:34511010 Location:Minot, ND

Coordinates:N 453,443.0 ft E 1,776,627.0 ft

Surface Elevation:N/A Drilling Method:Push

Sampling Method:Continuous


Datu	m:NAI	D83 - S	StatePlane North Dakota	Nort	h Fee	t Completion Depth:20.0 ft		T
Depth, feet	Sample Type & Recovery	Sample No.	ENVIRONMENTAL DATA	U S C S	Graphic Log	LITHOLOGIC DESCRIPTION	MAJOR UNIT	Elevation, feet
-0		0-2	PID:0.1 ppm D/O/S:None/ None/ None	СН		SANDY FAT CLAY WITH GRAVEL (CH): very dark gray (3/1/10YR); moist; medium to high plasticity; 20% gravel, 20% sand, 60% fines, rounded.	FILL	
-			PID:0.1 ppm D/O/S:None/ None/ None	sc		CLAYEY SAND (SC): fine grained; light reddish brown (6/3/2.5Y); moist; 0% gravel, 70% sand, 30% fines, well sorted. At 3': Oxidization staining, gradual color change to dark gray (4/1/2.5Y).		_
5 -			PID:0.1 ppm D/O/S:None/ None/ None	СН		SANDY FAT CLAY (CH): light olive brown (5/4/2.5Y); moist; medium plasticity; 0% gravel, 40% sand, 60% fines, trace oxidization staining. At 6': Color change to dark olive brown (3/3/2.5Y).		
	-	6-8	PID:0.0 ppm D/O/S:None/ None/ None					
10-			PID:0.1 ppm D/O/S:None/ None/ None			SAND WITH CLAY (SP-SC): fine grained; olive brown (4/3/2.5Y); moist; 0% gravel, 80% sand, 20% fines, well sorted, trace white stringers of silt, trace oxidization mottling, soft. At 10': Groundwater.		
-			PID:0.2 ppm D/O/S:None/ None/ None				NATIVE	
15-			PID:0.2 ppm D/O/S:None/ None/ None	SP- SC		At 14-15': Color change to dark gray (4/1/2.5Y).		
15-			PID:0.1 ppm D/O/S:None/ None/ None			At 15': Mustard yellow color. At 15.5-16': Heavily oxidization stained.		
20-			PID:0.2 ppm D/O/S:None/ None/ None			At 17': Mustard yellow color. At 17-17.5': Heavy oxidization stained. At 17.5': Coarser sand.		
20.00 PARA			PID:0.0 ppm D/O/S:None/ None/ None					
20-					r1/-7	End of boring 20.0 feet		
Date Logg	Boring ed By:		pleted: 11/24/15 10:3 AMK2			Remarks: Background PID: 0.00 ppm	1	
Drilling Drill F	-	ntracto	r: Stevens Track Rig			PID = Headspace; D/O/S = Discoloration/Odor/Sheen; FID/MC = FID/Methane Corrected Additional data may have been collected in the field which is not included on this log. Weather: 27°F, calm, overcast, cloudy		

LOG OF BORING B-4

SHEET 1 OF 1

Surface Elevation:N/A Drilling Method:Push

Sampling Method:Continuous



Date Boring Completed:

11/24/15 11:30 am

Logged By:

AMK2


Drilling Contractor: Stevens

Track Rig Drill Rig:

Remarks:

Background PID: 0.3 ppm

 $PID = Headspace; \ D/O/S = Discoloration/Odor/Sheen; \ FID/MC = FID/Methane \ Corrected$ Additional data may have been collected in the field which is not included on this log. Weather: 27°F, calm, overcast, cloudy



20.0 Loate Boring Started:

11/24/15 12:30 pm

Date Boring Completed: Logged By:

11/24/15 1:00 pm

Drilling Contractor:

Drill Rig:


AMK2 Stevens

Track Rig

Background PID: 0.00 ppm

Remarks:

 $PID = Headspace; \ D/O/S = Discoloration/Odor/Sheen; \ FID/MC = FID/Methane \ Corrected$ Additional data may have been collected in the field which is not included on this log. Weather: $27^\circ F,\ calm,\ overcast,\ cloudy$



Track Rig

Drill Rig:

Appendix B

Photo Log

Appendix B Photo Log

4th Avenue Floodwall Minot, ND November 23-34, 2015

Photo #	Comments
1	B-1. 0-2' bgs. Gravel with sandy clay (GC, Fill).
2	B-4. 2-4' bgs. Gravel with clay (GC, Fill).
3	B-4. 6-8' bgs. Weathered concrete at 6'.
4	B-5. 6-8' bgs. Sandy fat clay (CH, Native).
5	B-6. 4-6' bgs. Well sorted sand (SP, Fill) to fat clay (CH, Fill).
6	B-2a. 10-12' bgs. Well sorted sand (SW-SC, Native). Groundwater at 11' bgs.
7	B-2a. 14-16' bgs. Coarser well sorted sand (SW-SC, Native).
8	B-3. 12-14' bgs. Sand with clay (SP-SC, Native). Trace white silt and sand.
9	B-3. 16-18' bgs. Sand with clay (SP-SC, Native). Heavily oxidized coarse ox.
10	B-1. 18-20' bgs. Fat clay (CH, Native).



Photo 1: B-1. 0-2' bgs. Gravel with sandy clay (GC, Fill).



Photo 2: B-4. 2-4' bgs. Gravel with clay (GC, Fill).



Photo 3: B-4. 6-8' bgs. Weathered concrete at 6'.



Photo 4: B-5. 6-8' bgs. Sandy fat clay (CH, Native).



Photo 5: B-6. 4-6' bgs. Well sorted sand (SP, Fill) to fat clay (CH, Fill).



Photo 6: B-2a. 10-12' bgs. Well sorted sand (SW-SC, Native). Groundwater at 11' bgs.



Photo 7: B-2a. 14-16' bgs. Coarser well sorted sand (SW-SC, Native).



Photo 8: B-3. 12-14' bgs. Sand with clay (SP-SC, Native). Trace white silt and oxidation mottling.



Photo 9: B-3. 16-18' bgs. Sand with clay (SP-SC, Native). Heavily oxidized coarse sand.



Photo 10: B-1. 18-20' bgs. Fat clay (CH, Native).

Appendix C

Laboratory Analytical Report



88 Empire Drive St Paul, MN 55103 Tel: 651-642-1150 Fax: 651-642-1239

December 10, 2015

Ms. Andrea Nord Barr Engineering Co. 4300 MarketPointe Drive, Suite 200 Minneapolis, MN 55435

Work Order Number: 1505280

RE: 34511010

Enclosed are the results of analyses for samples received by the laboratory on 11/25/15. If you have any questions concerning this report, please feel free to contact me.

Results are not blank corrected unless noted within the report. Additionally, all QC results meet requirements unless noted.

All samples will be retained by Legend Technical Services, Inc., unless consumed in the analysis, at ambient conditions for 30 days from the date of this report and then discarded unless other arrangements are made. All samples were received in acceptable condition unless otherwise noted.

ND Accreditation #R-065

Prepared by, LEGEND TECHNICAL SERVICES, INC

Bach Pham
Client Manager II
bpham@legend-group.com



Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
B-1_10-12	1505280-01	Soil	11/23/15 17:15	11/25/15 09:30
B-1_16-18	1505280-02	Soil	11/23/15 17:15	11/25/15 09:30
B-2a_2-4	1505280-03	Soil	11/24/15 10:00	11/25/15 09:30
B-2a_4-6	1505280-04	Soil	11/24/15 10:00	11/25/15 09:30
B-3_6-8	1505280-05	Soil	11/24/15 11:00	11/25/15 09:30
B-3_0-2	1505280-06	Soil	11/24/15 11:00	11/25/15 09:30
B-4_2-4	1505280-07	Soil	11/24/15 12:00	11/25/15 09:30
B-4_8-10	1505280-08	Soil	11/24/15 12:00	11/25/15 09:30
B-5_0-2	1505280-09	Soil	11/24/15 12:45	11/25/15 09:30
B-5_6-8	1505280-10	Soil	11/24/15 12:45	11/25/15 09:30
B-6_0-2	1505280-11	Soil	11/24/15 13:30	11/25/15 09:30
B-6_6-8	1505280-12	Soil	11/24/15 13:30	11/25/15 09:30

Shipping Container Information

Default Cooler Temperature (°C): 3.7

Received on ice: Yes Temperature blank was present Received on ice pack: No Received on melt water: No Ambient: No

Custody seals: No

Acceptable (IH/ISO only): No

Case Narrative:

Recovery for the 8270 surrogate terphenyl-d14 was below laboratory acceptance limits in sample B-5_0-2. The remaining sample surrogates passed acceptance criteria.

The MSD recovery for barium was outside the method control limits for the 6010C batch B5L0124. The LCS, LCS duplicate, and % RPD were within the control limits. The source sample was B-1_10-12.

The DRO chromatograms are attached for all samples.



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280

Date Reported: 12/10/15

8015D DRO Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-12 (1505280-01) So	il Sampled: 11/23/15	17:15	Received	l: 11/25/15 9:3	30					
Diesel Range Organics	<11	11	2.3	mg/kg dry	1	B5L0301	12/03/15	12/04/15	EPA 8015D	
Surrogate: Triacontane (C-30)	106			70-130 %		"	"	"	"	
B-1_16-18 (1505280-02) So	il Sampled: 11/23/15	17:15	Received	l: 11/25/15 9:3	30					
Diesel Range Organics	<10	10	2.2	mg/kg dry	1	B5L0301	12/03/15	12/03/15	EPA 8015D	
Surrogate: Triacontane (C-30)	113			70-130 %		"	"	"	"	
B-2a_2-4 (1505280-03) Soil	Sampled: 11/24/15 1	10:00	Received:	11/25/15 9:30)					
Diesel Range Organics	<9.6	9.6	2.0	mg/kg dry	1	B5L0301	12/03/15	12/03/15	EPA 8015D	
Surrogate: Triacontane (C-30)	104			70-130 %		"	"	"	"	
B-2a_4-6 (1505280-04) Soil	Sampled: 11/24/15	10:00	Received:	11/25/15 9:30)					_
Diesel Range Organics	<9.6	9.6	2.0	mg/kg dry	1	B5L0301	12/03/15	12/03/15	EPA 8015D	
Surrogate: Triacontane (C-30)	109			70-130 %		"	"	"	"	
B-3_6-8 (1505280-05) Soil	Sampled: 11/24/15 11	1:00	Received: 1	1/25/15 9:30						
Diesel Range Organics	<10	10	2.2	mg/kg dry	1	B5L0301	12/03/15	12/03/15	EPA 8015D	
Surrogate: Triacontane (C-30)	114			70-130 %		"	"	"	"	
B-3_0-2 (1505280-06) Soil	Sampled: 11/24/15 11	1:00	Received: 1	1/25/15 9:30						
Diesel Range Organics	30	9.0	1.9	mg/kg dry	1	B5L0301	12/03/15	12/03/15	EPA 8015D	L1
Surrogate: Triacontane (C-30)	103			70-130 %		"	"	"	"	
B-4_2-4 (1505280-07) Soil	Sampled: 11/24/15 12	2:00	Received: 1	11/25/15 9:30						_
Diesel Range Organics	<8.5	8.5	1.8	mg/kg dry	1	B5L0301	12/03/15	12/04/15	EPA 8015D	
Surrogate: Triacontane (C-30)	102			70-130 %		"	"	"	"	
B-4_8-10 (1505280-08) Soil	Sampled: 11/24/15	12:00	Received:	11/25/15 9:30)					
Diesel Range Organics	<9.6	9.6	2.0	mg/kg dry	1	B5L0301	12/03/15	12/04/15	EPA 8015D	
Surrogate: Triacontane (C-30)	107			70-130 %		"	"	"	"	
B-5_0-2 (1505280-09) Soil	Sampled: 11/24/15 12	2:45	Received: 1	11/25/15 9:30						
Diesel Range Organics	13	8.8	1.9	mg/kg dry	1	B5L0301	12/03/15	12/03/15	EPA 8015D	L1
Surrogate: Triacontane (C-30)	109			70-130 %		"	"	"	"	
B-5_6-8 (1505280-10) Soil	Sampled: 11/24/15 12	2:45	Received: 1	11/25/15 9:30						
Diesel Range Organics	<8.8	8.8	1.9	mg/kg dry	1	B5L0301	12/03/15	12/04/15	EPA 8015D	
Surrogate: Triacontane (C-30)	107			70-130 %		"	"	"	"	
B-6_0-2 (1505280-11) Soil	Sampled: 11/24/15 13	3:30	Received: 1	1/25/15 9:30						
Diesel Range Organics	<9.0	9.0	1.9	mg/kg dry	1	B5L0301	12/03/15	12/03/15	EPA 8015D	
Surrogate: Triacontane (C-30)	113			70-130 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Work Order #: 1505280
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/10/15

8015D DRO Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-6_6-8 (1505280-12) Soil	Sampled: 11/24/15 1	13:30	Received:	11/25/15 9:30						
Diesel Range Organics	<10	10	2.2	mg/kg dry	1	B5L0301	12/03/15	12/04/15	EPA 8015D	
Surrogate: Triacontane (C-30)	108			70-130 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Work Order #: 1505280
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/10/15

8015D GRO Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-12 (1505280-01) Soil	Sampled: 11/23/15	17:15	Received	: 11/25/15 9:3	30					
Gasoline range organics	<6.8	6.8	0.73	mg/kg dry	1	B5L0123	12/01/15	12/01/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	97.1			80-150 %		"	"	"	"	
B-1_16-18 (1505280-02) Soil	Sampled: 11/23/15	17:15	Received	: 11/25/15 9:3	30					
Gasoline range organics	<6.5	6.5	0.70	mg/kg dry	1	B5L0123	12/01/15	12/01/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	98.2			80-150 %		"	"	"	"	
B-2a_2-4 (1505280-03) Soil	Sampled: 11/24/15 1	0:00	Received:	11/25/15 9:30)					
Gasoline range organics	<6.0	6.0	0.65	mg/kg dry	1	B5L0123	12/01/15	12/01/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	98.0			80-150 %		"	"	"	"	
B-2a_4-6 (1505280-04) Soil	Sampled: 11/24/15 1	0:00	Received:	11/25/15 9:30)					
Gasoline range organics	<6.0	6.0	0.65	mg/kg dry	1	B5L0123	12/01/15	12/02/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	97.5			80-150 %		"	"	"	"	
B-3_6-8 (1505280-05) Soil S	ampled: 11/24/15 11	:00	Received: 1	1/25/15 9:30						
Gasoline range organics	<6.5	6.5	0.70	mg/kg dry	1	B5L0123	12/01/15	12/02/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	97.1			80-150 %		"	"	"	"	
B-3_0-2 (1505280-06) Soil S	ampled: 11/24/15 11	:00	Received: 1	1/25/15 9:30						
Gasoline range organics	<5.3	5.3	0.57	mg/kg dry	1	B5L0123	12/01/15	12/02/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	96.8			80-150 %		"	"	"	"	
B-4_2-4 (1505280-07) Soil S	ampled: 11/24/15 12	:00	Received: 1	1/25/15 9:30						
Gasoline range organics	<5.3	5.3	0.57	mg/kg dry	1	B5L0123	12/01/15	12/02/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	133			80-150 %		"	"	"	"	
B-4_8-10 (1505280-08) Soil	Sampled: 11/24/15 1	2:00	Received:	11/25/15 9:30)					
Gasoline range organics	<6.0	6.0	0.65	mg/kg dry	1	B5L0123	12/01/15	12/02/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	100			80-150 %		"	"	"	"	
B-5_0-2 (1505280-09) Soil S	ampled: 11/24/15 12	:45	Received: 1	1/25/15 9:30						
Gasoline range organics	<5.2	5.2	0.56	mg/kg dry	1	B5L0123	12/01/15	12/02/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	101			80-150 %		"	"	"	"	
B-5_6-8 (1505280-10) Soil S	ampled: 11/24/15 12	:45	Received: 1	1/25/15 9:30						<u></u>
Gasoline range organics	<5.5	5.5	0.59	mg/kg dry	1	B5L0123	12/01/15	12/02/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	100			80-150 %		"	"	"	"	
B-6_0-2 (1505280-11) Soil S	ampled: 11/24/15 13	:30	Received: 1	1/25/15 9:30						
Gasoline range organics	<5.6	5.6	0.61	mg/kg dry	1	B5L0123	12/01/15	12/02/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	100			80-150 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Work Order #: 1505280 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/10/15

8015D GRO Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-6_6-8 (1505280-12) Soil Sampled	: 11/24/15 13:	30 F	Received: 1	1/25/15 9:30						
Gasoline range organics	<6.3	6.3	0.68	mg/kg dry	1	B5L0123	12/01/15	12/02/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	101			80-150 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280 Date Reported: 12/10/15

TOTAL METALS ANALYSIS Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-12 (1505280-01) Soil	Sampled: 11/23/15	17:15	Received	: 11/25/15 9::	30					
Arsenic	4.1	0.68	0.14	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Barium	150	1.4	0.089	mg/kg dry	1	"	ı	"	"	M1
Cadmium	<0.34	0.34	0.012	mg/kg dry	1	"	"	"	"	
Chromium	15	0.68	0.049	mg/kg dry	1	"	"	"	"	
Lead	8.0	1.4	0.084	mg/kg dry	1	"	II .	"	"	
Mercury	<0.68	0.68	0.31	mg/kg dry	1	"	II .	"	"	
Selenium	<1.4	1.4	0.39	mg/kg dry	1	"	II .	"	"	
Silver	<0.34	0.34	0.016	mg/kg dry	1	"	II .	"	"	
B-1_16-18 (1505280-02) Soil	Sampled: 11/23/15	17:15	Received	: 11/25/15 9::	30					
Arsenic	2.1	0.65	0.13	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Barium	190	1.3	0.086	mg/kg dry	1	"	"	"	"	
Cadmium	<0.32	0.32	0.011	mg/kg dry	1	"	"	"	"	
Chromium	19	0.65	0.047	mg/kg dry	1	"	"	"	"	
Lead	8.6	1.3	0.081	mg/kg dry	1	"	II .	"	"	
Mercury	<0.65	0.65	0.30	mg/kg dry	1	"	II .	"	"	
Selenium	<1.3	1.3	0.38	mg/kg dry	1	"	II .	"	"	
Silver	<0.32	0.32	0.016	mg/kg dry	1	"	II .	"	"	
B-2a_2-4 (1505280-03) Soil	Sampled: 11/24/15 1	0:00	Received:	11/25/15 9:30	0					
Arsenic	6.2	0.60	0.12	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Barium	310	1.2	0.080	mg/kg dry	1	"	"	"	"	
Cadmium	<0.30	0.30	0.010	mg/kg dry	1	"	II .	"	"	
Chromium	14	0.60	0.043	mg/kg dry	1	"	"	"	"	
Lead	12	1.2	0.075	mg/kg dry	1	"	II .	"	"	
Mercury	<0.60	0.60	0.28	mg/kg dry	1	"	II .	"	"	
Selenium	<1.2	1.2	0.35	mg/kg dry	1	"	II .	"	"	
Silver	<0.30	0.30	0.014	mg/kg dry	1	"	"	"	"	
B-2a_4-6 (1505280-04) Soil	Sampled: 11/24/15 1	0:00	Received:	11/25/15 9:30	0					
Arsenic	4.5	0.60	0.12	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Barium	210	1.2	0.080	mg/kg dry	1	"	"	"	"	
Cadmium	<0.30	0.30	0.010	mg/kg dry	1	"	"	"	"	
Chromium	16	0.60	0.043	mg/kg dry	1	"	"	"	"	
Lead	8.5	1.2	0.075	mg/kg dry	1	"	"	"	"	
Mercury	<0.60	0.60	0.28	mg/kg dry	1	"	"	"	"	
Selenium	<1.2	1.2	0.35	mg/kg dry	1	"	"	"	"	
Silver	<0.30	0.30	0.014	mg/kg dry	1	"	"	"	"	
B-3_6-8 (1505280-05) Soil S	Sampled: 11/24/15 11	:00 F	Received: 1	1/25/15 9:30						
Arsenic	6.0	0.65	0.13	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
				5 5 7						



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

TOTAL METALS ANALYSIS Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_6-8 (1505280-05) Soil	Sampled: 11/24/15 11	00 F	Received: 11	/25/15 9:30						
Barium	140	1.3	0.086	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Cadmium	1.9	0.32	0.011	mg/kg dry	1	"	"	"	II .	
Chromium	20	0.65	0.047	mg/kg dry	1	"	"	"	II .	
Lead	8.2	1.3	0.081	mg/kg dry	1	"	"	"	"	
Mercury	<0.65	0.65	0.30	mg/kg dry	1	"	"	"	n .	
Selenium	<1.3	1.3	0.38	mg/kg dry	1	"	"	"	II .	
Silver	<0.32	0.32	0.016	mg/kg dry	1	"	"	"	"	
B-3_0-2 (1505280-06) Soil	Sampled: 11/24/15 11	00 F	Received: 11	/25/15 9:30						
Arsenic	11	0.56	0.11	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Barium	230	1.1	0.074	mg/kg dry	1	"	"	"	H .	
Cadmium	<0.28	0.28	0.0098	mg/kg dry	1	"	"	"	II .	
Chromium	11	0.56	0.040	mg/kg dry	1	"	"	"	n .	
Lead	31	1.1	0.070	mg/kg dry	1	"	"	"	H .	
Mercury	<0.56	0.56	0.26	mg/kg dry	1	"	"	"	II .	
Selenium	<1.1	1.1	0.33	mg/kg dry	1	"	"	"	II .	
Silver	<0.28	0.28	0.013	mg/kg dry	1	"	"	"	"	
B-4_2-4 (1505280-07) Soil	Sampled: 11/24/15 12	00 F	Received: 11	/25/15 9:30						
Arsenic	8.9	0.53	0.11	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Barium	100	1.1	0.070	mg/kg dry	1	"	"	"	"	
Cadmium	<0.27	0.27	0.0093	mg/kg dry	1	"	"	"	"	
Chromium	12	0.53	0.038	mg/kg dry	1	"	"	"	H .	
Lead	5.2	1.1	0.066	mg/kg dry	1	"	"	"	n .	
Mercury	<0.53	0.53	0.24	mg/kg dry	1	"	"	"	H .	
Selenium	<1.1	1.1	0.31	mg/kg dry	1	"	"	"	II .	
Silver	<0.27	0.27	0.013	mg/kg dry	1	"	"	"	"	
B-4_8-10 (1505280-08) Soil	Sampled: 11/24/15 1	2:00	Received: 1	1/25/15 9:30)					
Arsenic	2.1	0.60	0.12	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Barium	72	1.2	0.080	mg/kg dry	1	"	"	"	H .	
Cadmium	<0.30	0.30	0.010	mg/kg dry	1	"	"	"	II .	
Chromium	4.4	0.60	0.043	mg/kg dry	1	"	"	"	II .	
Lead	2.6	1.2	0.075	mg/kg dry	1	"	"	"	H .	
Mercury	<0.60	0.60	0.28	mg/kg dry	1	"	"	"	II .	
Selenium	<1.2	1.2	0.35	mg/kg dry	1	"	"	"	II .	
Silver	<0.30	0.30	0.014	mg/kg dry	1	"	"	"	"	
B-5_0-2 (1505280-09) Soil	Sampled: 11/24/15 12	45 F	Received: 11	/25/15 9:30						
Arsenic	6.0	0.55	0.11	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Barium	160	1.1	0.073	mg/kg dry	1		"		"	



Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

TOTAL METALS ANALYSIS Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-5_0-2 (1505280-09) Soil	Sampled: 11/24/15 12	2:45	Received: 11	/25/15 9:30						
Cadmium	<0.27	0.27	0.0096	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Chromium	12	0.55	0.040	mg/kg dry	1	"	· ·	II .	"	
Lead	7.3	1.1	0.068	mg/kg dry	1	"	"	"	"	
Mercury	<0.55	0.55	0.25	mg/kg dry	1	"	"	"	"	
Selenium	<1.1	1.1	0.32	mg/kg dry	1	"	"	"	"	
Silver	<0.27	0.27	0.013	mg/kg dry	1	"	"	II .	"	
B-5_6-8 (1505280-10) Soil	Sampled: 11/24/15 12	2:45	Received: 11	/25/15 9:30						
Arsenic	3.6	0.55	0.11	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Barium	110	1.1	0.073	mg/kg dry	1	"	"	"	"	
Cadmium	<0.27	0.27	0.0096	mg/kg dry	1	"	"	II .	"	
Chromium	8.1	0.55	0.040	mg/kg dry	1	"	"	II .	"	
Lead	4.1	1.1	0.068	mg/kg dry	1	"	"	II .	"	
Mercury	<0.55	0.55	0.25	mg/kg dry	1	"	"	II .	"	
Selenium	<1.1	1.1	0.32	mg/kg dry	1	"	"	II .	"	
Silver	<0.27	0.27	0.013	mg/kg dry	1	"	"	ı	"	
B-6_0-2 (1505280-11) Soil	Sampled: 11/24/15 13	30 I	Received: 11	/25/15 9:30						
Arsenic	5.3	0.56	0.11	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Barium	150	1.1	0.074	mg/kg dry	1	"	"	II .	"	
Cadmium	<0.28	0.28	0.0098	mg/kg dry	1	"	"	II .	"	
Chromium	11	0.56	0.040	mg/kg dry	1	"	"	II .	"	
Lead	12	1.1	0.070	mg/kg dry	1	"	"	II .	"	
Mercury	<0.56	0.56	0.26	mg/kg dry	1	"	"	II .	"	
Selenium	<1.1	1.1	0.33	mg/kg dry	1	"	"	II .	"	
Silver	<0.28	0.28	0.013	mg/kg dry	1	"	"	II .	"	
B-6_6-8 (1505280-12) Soil	Sampled: 11/24/15 13	3:30 I	Received: 11	/25/15 9:30						
Arsenic	4.6	0.63	0.13	mg/kg dry	1	B5L0124	12/02/15	12/09/15	EPA 6010C	
Barium	160	1.3	0.084	mg/kg dry	1	"	"	"	"	
Cadmium	<0.32	0.32	0.011	mg/kg dry	1	"	"	"	"	
Chromium	17	0.63	0.046	mg/kg dry	1	"	"	"	"	
Lead	9.0	1.3	0.078	mg/kg dry	1	"	"	"	"	
Mercury	<0.63	0.63	0.29	mg/kg dry	1	"	"	ıı	·	
Selenium	<1.3	1.3	0.37	mg/kg dry	1	"	"	"	"	
Silver	<0.32	0.32	0.015	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Work Order #: 1505280

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

ager: Ms. Andrea Nord Date Reported: 12/10/15
PERCENT SOLIDS

PERCENT SOLIDS Legend Technical Services, Inc.

Analyte	Result RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-12 (1505280-01) Soil S	Sampled: 11/23/15 17:15	Received:	11/25/15 9:3	0					
% Solids	74		%	1	B5L0306	12/03/15	12/03/15	% calculation	
B-1_16-18 (1505280-02) Soil S	Sampled: 11/23/15 17:15	Received:	11/25/15 9:3	0					
% Solids	77		%	1	B5L0306	12/03/15	12/03/15	% calculation	
B-2a_2-4 (1505280-03) Soil Sa	ampled: 11/24/15 10:00	Received: 1	11/25/15 9:30						
% Solids	83		%	1	B5L0306	12/03/15	12/03/15	% calculation	
B-2a_4-6 (1505280-04) Soil Sa	ampled: 11/24/15 10:00	Received: 1	11/25/15 9:30						
% Solids	83		%	1	B5L0306	12/03/15	12/03/15	% calculation	
B-3_6-8 (1505280-05) Soil Sar	mpled: 11/24/15 11:00	Received: 11	/25/15 9:30						
% Solids	77		%	1	B5L0306	12/03/15	12/03/15	% calculation	
B-3_0-2 (1505280-06) Soil Sar	mpled: 11/24/15 11:00	Received: 11	/25/15 9:30						
% Solids	89		%	1	B5L0306	12/03/15	12/03/15	% calculation	
B-4_2-4 (1505280-07) Soil Sar	mpled: 11/24/15 12:00	Received: 11	/25/15 9:30						
% Solids	94		%	1	B5L0306	12/03/15	12/03/15	% calculation	
B-4_8-10 (1505280-08) Soil Sa	ampled: 11/24/15 12:00	Received: 1	11/25/15 9:30						
% Solids	83		%	1	B5L0306	12/03/15	12/03/15	% calculation	
B-5_0-2 (1505280-09) Soil Sar	mpled: 11/24/15 12:45	Received: 11	/25/15 9:30						
% Solids	91		%	1	B5L0306	12/03/15	12/03/15	% calculation	
B-5_6-8 (1505280-10) Soil Sar	mpled: 11/24/15 12:45	Received: 11	/25/15 9:30						
% Solids	91		%	1	B5L0306	12/03/15	12/03/15	% calculation	
B-6_0-2 (1505280-11) Soil Sar	mpled: 11/24/15 13:30	Received: 11	/25/15 9:30						
% Solids	89		%	1	B5L0306	12/03/15	12/03/15	% calculation	
B-6_6-8 (1505280-12) Soil Sar	mpled: 11/24/15 13:30	Received: 11	/25/15 9:30						
% Solids	79		%	1	B5L0306	12/03/15	12/03/15	% calculation	



Fax: 651-642-1239

Work Order #: 1505280

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Date Reported: 12/10/15

Fig. Control Fig. Control Fig. Control Fig. Control Fig. Fig. Control Fig.	Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
1.2 Dishlordenzene 1.2 Dishlordenzene 1.4 Dishlorde	B-1_10-12 (1505280-01) Soil Samp	oled: 11/23/15	17:15	Received	: 11/25/15 9:	30					
1.2-Diphenylyhorational color 1.2-Diphenylyhorational colo	1,2,4-Trichlorobenzene	< 0.45	0.45	0.10	mg/kg dry	1	B5K3002	11/30/15	11/30/15	EPA 8270D	
1,3-Dichlorobenzene 40,45 0.45 0.093 mg/kg dy 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1,2-Dichlorobenzene	< 0.45	0.45	0.091	mg/kg dry	1	"	"	II .	"	
1.4-Dichlorobenzene	1,2-Diphenylhydrazine as Azobenzene	<0.45	0.45	0.078	mg/kg dry	1	"	"	"	"	
2,3,6-Tetrachiorophenol 4,91 0,91 0,26 mg/kg dry 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1,3-Dichlorobenzene	<0.45	0.45	0.093	mg/kg dry	1	"	"	"	"	
2.4.5-Trichlorophenol 4.9.1 0.91 0.92 mg/kg dry 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1,4-Dichlorobenzene	<0.45	0.45	0.092	mg/kg dry	1	"	"	"	"	
2.4. G-Trichlorophenol 4.91 0.91 0.22 mg/kg dry 1 6 6 6 6 6 6 2 2 24-Dinitorophenol 4.91 0.91 0.20 mg/kg dry 1 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	2,3,4,6-Tetrachlorophenol	<0.91	0.91	0.26	mg/kg dry	1	"	"	"	"	
2.4-Dichlorophenol 4.091 0.91 0.20 mg/kg dry 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2,4,5-Trichlorophenol	<0.91	0.91	0.096	mg/kg dry	1	"	"	"	"	
2.4-Dimethylphenol 4.0.91 0.91 0.18 mg/kg dry 1 * * * * 2.4-Dimitrophenol 4.0.91 0.91 0.928 mg/kg dry 1 * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * * *	2,4,6-Trichlorophenol	<0.91	0.91	0.22	mg/kg dry	1	"	"	"	"	
2.4-Dinitrophenol 4.9.1 0.91 0.96 mg/kg dry 1 * * * * 2.4-Dinitrophenol 4.0.45 0.45 0.492 mg/kg dry 1 * * * * 2.6-Dinitrophenol 4.0.45 0.45 0.10 mg/kg dry 1 * * * * 2.6-Dinitrophenol 4.0.45 0.45 0.10 mg/kg dry 1 * * * * 2Chlorophenol 4.0.45 0.45 0.46 0.01 mg/kg dry 1 * * * * 2Methylphaphrol 40.45 0.45 0.11 mg/kg dry 1 * * * * * 2Methylphenol 40.45 0.45 0.03 mg/kg dry 1 * * * * * * * * * * * * * * * * * * * *	2,4-Dichlorophenol	<0.91	0.91	0.20	mg/kg dry	1	"	"	"	"	
2.4-Dinitrotoluene <0.45	2,4-Dimethylphenol	<0.91	0.91	0.18	mg/kg dry	1	"	"	"	"	
2.6-Dichlorophenol c.0.91 0.91 0.18 mg/kg dry 1 " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " "	2,4-Dinitrophenol	<0.91	0.91	0.096	mg/kg dry	1	"	"	"	"	
2.6-Dinitrotoluene <0.45	2,4-Dinitrotoluene	<0.45	0.45	0.092	mg/kg dry	1	"	"	"	"	
2-Chloronaphthalene <0.45 0.45 0.92 mg/kg dry 1 1 1 1 1 1 1 1 1	2,6-Dichlorophenol	<0.91	0.91	0.18	mg/kg dry	1	"	"	"	"	
2-Chlorophenol <.0.91	2,6-Dinitrotoluene	< 0.45	0.45	0.10	mg/kg dry	1	"	"	"	"	
2-Methylnaphthalene <0.45	2-Chloronaphthalene	<0.45	0.45	0.092	mg/kg dry	1	"	"	"	"	
2-Methylphenol <0.91	2-Chlorophenol	<0.91	0.91	0.20	mg/kg dry	1	"	"	"	"	
2-Nitroaniline <.0.45	2-Methylnaphthalene	<0.45	0.45	0.11	mg/kg dry	1	"	"	"	"	
2-Nitrophenol	2-Methylphenol	<0.91	0.91	0.11	mg/kg dry	1	"	"	"	"	
384-Methylphenol <.0.91	2-Nitroaniline	<0.45	0.45	0.093	mg/kg dry	1	"	"	"	"	
3,3'-Dichlorobenzidine <2.2	2-Nitrophenol	<0.91	0.91	0.24	mg/kg dry	1	"	"	"	"	
3-Nitroaniline <0.45 0.45 0.097 mg/kg dry 1 " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " "	3&4-Methylphenol	<0.91	0.91	0.11	mg/kg dry	1	"	"	"	"	
4,6-Dinitro-2-methylphenol <0.91	3,3'-Dichlorobenzidine	<2.2	2.2	0.61	mg/kg dry	1	"	"	"	"	
4-Bromophenyl phenyl ether	3-Nitroaniline	< 0.45	0.45	0.097	mg/kg dry	1	"	"	"	"	
4-Chloro-3-methylphenol <0.91	4,6-Dinitro-2-methylphenol	<0.91	0.91	0.15	mg/kg dry	1	"	"	"	"	
4-Chloroaniline <0.91	4-Bromophenyl phenyl ether	< 0.45	0.45	0.092	mg/kg dry	1	"	"	"	"	
4-Chlorophenyl phenyl ether	4-Chloro-3-methylphenol	<0.91	0.91	0.19	mg/kg dry	1	"	"	"	"	
4-Nitroaniline	4-Chloroaniline	<0.91	0.91	0.091	mg/kg dry	1	"	"	u u	"	
4-Nitrophenol <0.91	4-Chlorophenyl phenyl ether	<0.45	0.45	0.092	mg/kg dry	1	"	"	u u	"	
Acenaphthene <0.45	4-Nitroaniline	<0.45	0.45	0.11	mg/kg dry	1	"	"	"	"	
Acenaphthylene <0.45	4-Nitrophenol	<0.91	0.91	0.23	mg/kg dry	1	"	"	II .	"	
Aniline <0.91 0.91 0.089 mg/kg dry 1 " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " "	Acenaphthene	<0.45	0.45	0.085	mg/kg dry	1	"	"	II .	"	
Anthracene <0.45 0.45 0.093 mg/kg dry 1 " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " <t< td=""><td>Acenaphthylene</td><td><0.45</td><td>0.45</td><td>0.096</td><td>mg/kg dry</td><td>1</td><td>"</td><td>"</td><td>II .</td><td>"</td><td></td></t<>	Acenaphthylene	<0.45	0.45	0.096	mg/kg dry	1	"	"	II .	"	
Benzidine <3.4 3.4 0.59 mg/kg dry 1 " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " "<	Aniline	<0.91	0.91	0.089	mg/kg dry	1	"	"	u u	"	
Benzo(a)anthracene <0.45 0.45 0.088 mg/kg dry 1 " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " " "	Anthracene	<0.45	0.45	0.093	mg/kg dry	1	"	"	II .	"	
Benzo(a)pyrene <0.45 0.45 0.095 mg/kg dry 1 " " " " " Benzo(b)fluoranthene <0.45	Benzidine	<3.4	3.4	0.59	mg/kg dry	1	"	"	II .	"	
Benzo(b)fluoranthene <0.45 0.45 0.080 mg/kg dry 1 " " " "	Benzo(a)anthracene	<0.45	0.45	0.088	mg/kg dry	1	"	"	II .	"	
	Benzo(a)pyrene	< 0.45	0.45	0.095	mg/kg dry	1	"	"	"	"	
Benzo(a,h.i)pervlene <0.45 0.45 0.096 mg/kg dry 1 " " " "	Benzo(b)fluoranthene	<0.45	0.45	0.080	mg/kg dry	1	"	"	"	"	
	Benzo(g,h,i)perylene	<0.45	0.45	0.096	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Work Order #: 1505280

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

nager: Ms. Andrea Nord Date Reported: 12/10/15

SVOC 8270D

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-12 (1505280-01) Soil	Sampled: 11/23/15	17:15	Received	11/25/15 9:	30					
Benzo(k)fluoranthene	<0.45	0.45	0.095	mg/kg dry	1	B5K3002	11/30/15	11/30/15	EPA 8270D	
Benzoic acid	<0.45	0.45	0.086	mg/kg dry	1	"	"	"	"	
Benzyl alcohol	<0.91	0.91	0.20	mg/kg dry	1	"	"	"	"	
Bis(2-chloroethoxy)methane	<0.45	0.45	0.10	mg/kg dry	1	"	"	"	"	
Bis(2-chloroethyl)ether	<0.45	0.45	0.093	mg/kg dry	1	"	"	"	"	
Bis(2-chloroisopropyl)ether	<0.45	0.45	0.11	mg/kg dry	1	"	"	"	"	
Bis(2-ethylhexyl)phthalate	<0.45	0.45	0.11	mg/kg dry	1	"	"	"	"	
Butyl benzyl phthalate	<0.45	0.45	0.11	mg/kg dry	1	"	"	"	"	
Carbazole	<0.45	0.45	0.10	mg/kg dry	1	"	· ·	II .	"	
Chrysene	<0.45	0.45	0.086	mg/kg dry	1	"	· ·	II .	"	
Dibenz(a,h)anthracene	<0.45	0.45	0.11	mg/kg dry	1	"	u u	n n	"	
Dibenzofuran	<0.45	0.45	0.092	mg/kg dry	1	"	"	"	"	
Diethyl phthalate	<0.45	0.45	0.085	mg/kg dry	1	"	"	"	"	
Dimethyl phthalate	<0.45	0.45	0.093	mg/kg dry	1	"	"	"	"	
Di-n-butyl phthalate	<0.45	0.45	0.11	mg/kg dry	1	"	"	"	"	
Di-n-octyl phthalate	<0.45	0.45	0.14	mg/kg dry	1	"	"	"	"	
Fluoranthene	<0.45	0.45	0.092	mg/kg dry	1	"	"	"	"	
Fluorene	<0.45	0.45	0.088	mg/kg dry	1	"	"	"	"	
Hexachlorobenzene	<0.45	0.45	0.084	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.45	0.45	0.10	mg/kg dry	1	"	"	"	"	
Hexachlorocyclopentadiene	<0.45	0.45	0.093	mg/kg dry	1	"	"	"	"	
Hexachloroethane	<0.45	0.45	0.11	mg/kg dry	1	"	"	u u	"	
Indeno (1,2,3-cd) pyrene	<0.45	0.45	0.097	mg/kg dry	1	"	"	u u	"	
Isophorone	<0.45	0.45	0.10	mg/kg dry	1	"	"	u u	"	
Naphthalene	<0.45	0.45	0.096	mg/kg dry	1	"	"	"	"	
Nitrobenzene	<0.45	0.45	0.11	mg/kg dry	1	"	"	"	"	
N-Nitrosodimethylamine	<0.45	0.45	0.095	mg/kg dry	1	"	"	"	"	
N-Nitrosodi-n-propylamine	<0.45	0.45	0.099	mg/kg dry	1	"	u u	n n	"	
N-Nitrosodiphenylamine	<0.45	0.45	0.091	mg/kg dry	1	"	"	"	"	
Pentachlorophenol	<0.91	0.91	0.26	mg/kg dry	1	"	"	"	"	
Phenanthrene	<0.45	0.45	0.089	mg/kg dry	1	"	"	"	"	
Phenol	<0.91	0.91	0.19	mg/kg dry	1	"	"	"	"	
Pyrene	<0.45	0.45	0.080	mg/kg dry	1	"	"	"	"	
Surrogate: 2,4,6-Tribromophenol	81.8			53-107 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	67.9			53.9-97.9 %		"	"	"	"	
Surrogate: 2-Fluorophenol	71.0			42.5-94.9 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	56.5			48.9-100 %		"	"	"	"	
Surrogate: Phenol-d6	75.3			50.4-99.6 %					"	
Surrogate: Terphenyl-d14	58.9			51-99.6 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_16-18 (1505280-02) Soil Sample	ed: 11/23/15	17:15	Received:	11/25/15 9:3	30					
1,2,4-Trichlorobenzene	<0.43	0.43	0.097	mg/kg dry	1	B5K3002	11/30/15	11/30/15	EPA 8270D	
1,2-Dichlorobenzene	<0.43	0.43	0.087	mg/kg dry	1	"	"	"	"	
1,2-Diphenylhydrazine as Azobenzene	<0.43	0.43	0.075	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.43	0.43	0.090	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.43	0.43	0.088	mg/kg dry	1	"	"	"	"	
2,3,4,6-Tetrachlorophenol	<0.87	0.87	0.25	mg/kg dry	1	"	"	"	"	
2,4,5-Trichlorophenol	<0.87	0.87	0.092	mg/kg dry	1	"	"	"	"	
2,4,6-Trichlorophenol	<0.87	0.87	0.21	mg/kg dry	1	"	"	"	"	
2,4-Dichlorophenol	<0.87	0.87	0.19	mg/kg dry	1	"	"	"	"	
2,4-Dimethylphenol	<0.87	0.87	0.17	mg/kg dry	1	"	"	"	"	
2,4-Dinitrophenol	<0.87	0.87	0.092	mg/kg dry	1	"	"	"	"	
2,4-Dinitrotoluene	<0.43	0.43	0.088	mg/kg dry	1	"	"	"	"	
2,6-Dichlorophenol	<0.87	0.87	0.17	mg/kg dry	1	"	"	"	"	
2,6-Dinitrotoluene	<0.43	0.43	0.10	mg/kg dry	1	"	"	"	"	
2-Chloronaphthalene	<0.43	0.43	0.088	mg/kg dry	1	"	"	"	"	
2-Chlorophenol	<0.87	0.87	0.19	mg/kg dry	1	"	"	"	"	
2-Methylnaphthalene	<0.43	0.43	0.10	mg/kg dry	1	"	"	"	"	
2-Methylphenol	<0.87	0.87	0.11	mg/kg dry	1	"	"	"	"	
2-Nitroaniline	<0.43	0.43	0.090	mg/kg dry	1	"	"	"	"	
2-Nitrophenol	<0.87	0.87	0.23	mg/kg dry	1	"	"	"	"	
3&4-Methylphenol	<0.87	0.87	0.11	mg/kg dry	1	"	"	"	"	
3,3´-Dichlorobenzidine	<2.1	2.1	0.58	mg/kg dry	1	"	"	"	"	
3-Nitroaniline	<0.43	0.43	0.094	mg/kg dry	1	"	"	"	"	
4,6-Dinitro-2-methylphenol	<0.87	0.87	0.14	mg/kg dry	1	"	"	"	"	
4-Bromophenyl phenyl ether	<0.43	0.43	0.088	mg/kg dry	1	"	"	"	"	
4-Chloro-3-methylphenol	<0.87	0.87	0.18	mg/kg dry	1	"	"	"	"	
4-Chloroaniline	<0.87	0.87	0.087	mg/kg dry	1	"	"	"	II .	
4-Chlorophenyl phenyl ether	<0.43	0.43	0.088	mg/kg dry	1	"	"	"	II .	
4-Nitroaniline	<0.43	0.43	0.11	mg/kg dry	1	"	"	"	"	
4-Nitrophenol	<0.87	0.87	0.22	mg/kg dry	1	"	"	"	"	
Acenaphthene	<0.43	0.43	0.082	mg/kg dry	1	"	"	"	II .	
Acenaphthylene	<0.43	0.43	0.092	mg/kg dry	1	"	"	"	"	
Aniline	<0.87	0.87	0.086	mg/kg dry	1	"	"	"	"	
Anthracene	<0.43	0.43	0.090	mg/kg dry	1	"	"	"	"	
Benzidine	<3.2	3.2	0.57	mg/kg dry	1	"	"	"	"	
Benzo(a)anthracene	<0.43	0.43	0.084	mg/kg dry	1	"	"	"	"	
Benzo(a)pyrene	<0.43	0.43	0.091	mg/kg dry	1	"	"	"	"	
Benzo(b)fluoranthene	<0.43	0.43	0.077	mg/kg dry	1	"	"	"	"	
Benzo(g,h,i)perylene	<0.43	0.43	0.092	mg/kg dry	1	"	"	"	п	



Fax: 651-642-1139

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_16-18 (1505280-02) Soil	Sampled: 11/23/15	17:15	Received:	11/25/15 9:3	30					
Benzo(k)fluoranthene	<0.43	0.43	0.091	mg/kg dry	1	B5K3002	11/30/15	11/30/15	EPA 8270D	
Benzoic acid	<0.43	0.43	0.083	mg/kg dry	1	"	"	"	II .	
Benzyl alcohol	<0.87	0.87	0.19	mg/kg dry	1	"	"	"	"	
Bis(2-chloroethoxy)methane	<0.43	0.43	0.10	mg/kg dry	1	"	"	"	"	
Bis(2-chloroethyl)ether	<0.43	0.43	0.090	mg/kg dry	1	"	"	"	"	
Bis(2-chloroisopropyl)ether	<0.43	0.43	0.10	mg/kg dry	1	"	"	"	"	
Bis(2-ethylhexyl)phthalate	<0.43	0.43	0.11	mg/kg dry	1	"	"	"	"	
Butyl benzyl phthalate	<0.43	0.43	0.11	mg/kg dry	1	"	"	"	"	
Carbazole	<0.43	0.43	0.099	mg/kg dry	1	"	"	"	"	
Chrysene	<0.43	0.43	0.083	mg/kg dry	1	"	"	"	"	
Dibenz(a,h)anthracene	<0.43	0.43	0.11	mg/kg dry	1	"	"	"	"	
Dibenzofuran	<0.43	0.43	0.088	mg/kg dry	1	"	"	"	"	
Diethyl phthalate	<0.43	0.43	0.082	mg/kg dry	1	"	"	"	"	
Dimethyl phthalate	<0.43	0.43	0.090	mg/kg dry	1	"	"	"	"	
Di-n-butyl phthalate	<0.43	0.43	0.10	mg/kg dry	1	"	"	"	"	
Di-n-octyl phthalate	<0.43	0.43	0.13	mg/kg dry	1	"	"	"	"	
Fluoranthene	<0.43	0.43	0.088	mg/kg dry	1	"	"	"	"	
Fluorene	<0.43	0.43	0.084	mg/kg dry	1	"	"	"	"	
Hexachlorobenzene	<0.43	0.43	0.081	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.43	0.43	0.10	mg/kg dry	1	"	"	"	"	
Hexachlorocyclopentadiene	<0.43	0.43	0.090	mg/kg dry	1	"	"	"	"	
Hexachloroethane	<0.43	0.43	0.11	mg/kg dry	1	"	"	"	"	
Indeno (1,2,3-cd) pyrene	<0.43	0.43	0.094	mg/kg dry	1	"	"	"	"	
Isophorone	<0.43	0.43	0.099	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.43	0.43	0.092	mg/kg dry	1	"	"	"	"	
Nitrobenzene	<0.43	0.43	0.10	mg/kg dry	1	"	"	"	"	
N-Nitrosodimethylamine	<0.43	0.43	0.091	mg/kg dry	1	"	"	"	"	
N-Nitrosodi-n-propylamine	<0.43	0.43	0.095	mg/kg dry	1	"	"	"	"	
N-Nitrosodiphenylamine	<0.43	0.43	0.087	mg/kg dry	1	"	"	"	"	
Pentachlorophenol	<0.87	0.87	0.25	mg/kg dry	1	"	"	"	"	
Phenanthrene	<0.43	0.43	0.086	mg/kg dry	1	"	"	"	"	
Phenol	<0.87	0.87	0.18	mg/kg dry	1	"	"	"	u .	
Pyrene	<0.43	0.43	0.077	mg/kg dry	1	"	"	"	u .	
Surrogate: 2,4,6-Tribromophenol	81.9			53-107 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	64.9			53.9-97.9 %		"	"	"	"	
Surrogate: 2-Fluorophenol	70.7			42.5-94.9 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	65.9			48.9-100 %		"	"	"	"	
Surrogate: Phenol-d6 Surrogate: Terphenyl-d14	74.8 67.2			50.4-99.6 % 51-99.6 %		"	"	"	"	



Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-2a_2-4 (1505280-03) Soil Sampled:	11/24/15 1	0:00	Received:	11/25/15 9:30)					
1,2,4-Trichlorobenzene	<0.40	0.40	0.090	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
1,2-Dichlorobenzene	< 0.40	0.40	0.081	mg/kg dry	1	"	"	"	"	
1,2-Diphenylhydrazine as Azobenzene	< 0.40	0.40	0.070	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	< 0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	< 0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
2,3,4,6-Tetrachlorophenol	<0.81	0.81	0.23	mg/kg dry	1	"	"	"	"	
2,4,5-Trichlorophenol	<0.81	0.81	0.086	mg/kg dry	1	"	"	"	"	
2,4,6-Trichlorophenol	<0.81	0.81	0.19	mg/kg dry	1	"	"	"	"	
2,4-Dichlorophenol	<0.81	0.81	0.18	mg/kg dry	1	"	"	"	"	
2,4-Dimethylphenol	<0.81	0.81	0.16	mg/kg dry	1	"	"	"	"	
2,4-Dinitrophenol	<0.81	0.81	0.086	mg/kg dry	1	"	"	"	•	
2,4-Dinitrotoluene	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
2,6-Dichlorophenol	<0.81	0.81	0.16	mg/kg dry	1	"	"	"	"	
2,6-Dinitrotoluene	< 0.40	0.40	0.093	mg/kg dry	1	"	"	"	"	
2-Chloronaphthalene	< 0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
2-Chlorophenol	<0.81	0.81	0.18	mg/kg dry	1	"	"	"	"	
2-Methylnaphthalene	< 0.40	0.40	0.096	mg/kg dry	1	"	II .	"	"	
2-Methylphenol	<0.81	0.81	0.099	mg/kg dry	1	"	II .	"	"	
2-Nitroaniline	< 0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
2-Nitrophenol	<0.81	0.81	0.22	mg/kg dry	1	"	II .	"	"	
3&4-Methylphenol	<0.81	0.81	0.099	mg/kg dry	1	"	"	"	"	
3,3´-Dichlorobenzidine	<1.9	1.9	0.54	mg/kg dry	1	"	"	"	"	
3-Nitroaniline	< 0.40	0.40	0.087	mg/kg dry	1	"	"	"	"	
4,6-Dinitro-2-methylphenol	<0.81	0.81	0.13	mg/kg dry	1	"	"	"	"	
4-Bromophenyl phenyl ether	< 0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
4-Chloro-3-methylphenol	<0.81	0.81	0.17	mg/kg dry	1	"	"	"	"	
4-Chloroaniline	<0.81	0.81	0.081	mg/kg dry	1	"	"	"	"	
4-Chlorophenyl phenyl ether	< 0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
4-Nitroaniline	< 0.40	0.40	0.10	mg/kg dry	1	"	"	"	"	
4-Nitrophenol	<0.81	0.81	0.20	mg/kg dry	1	"	"	"	"	
Acenaphthene	<0.40	0.40	0.076	mg/kg dry	1	"	"	"	"	
Acenaphthylene	<0.40	0.40	0.086	mg/kg dry	1	"	"	"	"	
Aniline	<0.81	0.81	0.080	mg/kg dry	1	"	"	"	"	
Anthracene	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
Benzidine	<3.0	3.0	0.53	mg/kg dry	1	"	"	"	"	
Benzo(a)anthracene	<0.40	0.40	0.078	mg/kg dry	1	"	"	"	"	
Benzo(a)pyrene	<0.40	0.40	0.084	mg/kg dry	1	"	"	"	"	
Benzo(b)fluoranthene	<0.40	0.40	0.071	mg/kg dry	1	"	"	"	"	
Benzo(g,h,i)perylene	<0.40	0.40	0.086	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Work Order #: 1505280

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

oject Manager: Ms. Andrea Nord SVOC 8270D Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-2a_2-4 (1505280-03) Soil	Sampled: 11/24/15 1	0:00	Received:	11/25/15 9:30	1					
Benzo(k)fluoranthene	<0.40	0.40	0.084	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
Benzoic acid	<0.40	0.40	0.077	mg/kg dry	1		"	"	"	
Benzyl alcohol	<0.81	0.81	0.18	mg/kg dry	1	"	"	"	"	
Bis(2-chloroethoxy)methane	<0.40	0.40	0.093	mg/kg dry	1	"	"	"	II .	
Bis(2-chloroethyl)ether	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	II .	
Bis(2-chloroisopropyl)ether	<0.40	0.40	0.094	mg/kg dry	1	"	"	"	II .	
Bis(2-ethylhexyl)phthalate	<0.40	0.40	0.098	mg/kg dry	1	"	"	"	II .	
Butyl benzyl phthalate	<0.40	0.40	0.10	mg/kg dry	1	"	"	"	п	
Carbazole	<0.40	0.40	0.092	mg/kg dry	1	"	n .	n .	ı	
Chrysene	<0.40	0.40	0.077	mg/kg dry	1	"	"	"	п	
Dibenz(a,h)anthracene	<0.40	0.40	0.099	mg/kg dry	1	"	"	"	п	
Dibenzofuran	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
Diethyl phthalate	<0.40	0.40	0.076	mg/kg dry	1	"	"	"	"	
Dimethyl phthalate	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
Di-n-butyl phthalate	<0.40	0.40	0.095	mg/kg dry	1	"	"	"	"	
Di-n-octyl phthalate	<0.40	0.40	0.12	mg/kg dry	1	"	"	"	"	
Fluoranthene	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
Fluorene	<0.40	0.40	0.078	mg/kg dry	1	"	"	"	"	
Hexachlorobenzene	<0.40	0.40	0.075	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.40	0.40	0.093	mg/kg dry	1	"	"	"	"	
Hexachlorocyclopentadiene	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
Hexachloroethane	<0.40	0.40	0.099	mg/kg dry	1	"	"	"	"	
Indeno (1,2,3-cd) pyrene	<0.40	0.40	0.087	mg/kg dry	1	"	"	"	H .	
Isophorone	<0.40	0.40	0.092	mg/kg dry	1	"	"	"	H .	
Naphthalene	<0.40	0.40	0.086	mg/kg dry	1	"	"	"	"	
Nitrobenzene	<0.40	0.40	0.096	mg/kg dry	1	"	"	"	"	
N-Nitrosodimethylamine	<0.40	0.40	0.084	mg/kg dry	1	"	"	"	H .	
N-Nitrosodi-n-propylamine	<0.40	0.40	0.088	mg/kg dry	1	"	"	"	H .	
N-Nitrosodiphenylamine	<0.40	0.40	0.081	mg/kg dry	1	"	"	"	"	
Pentachlorophenol	<0.81	0.81	0.23	mg/kg dry	1	"	"	"	H .	
Phenanthrene	<0.40	0.40	0.080	mg/kg dry	1	"	"	"	H .	
Phenol	<0.81	0.81	0.17	mg/kg dry	1	"	"	"	"	
Pyrene	<0.40	0.40	0.071	mg/kg dry	1	"	"	"	"	
Surrogate: 2,4,6-Tribromophenol	83.0			53-107 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	70.1			53.9-97.9 %		"	"	"	"	
Surrogate: 2-Fluorophenol	52.9			42.5-94.9 %		"				
Surrogate: Nitrobenzene-d5	66.3			48.9-100 %		,,	"	"	"	
Surrogate: Phenol-d6 Surrogate: Terphenyl-d14	67.5 53.9			50.4-99.6 % 51-99.6 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-2a_4-6 (1505280-04) Soil Sampled	d: 11/24/15 1	0:00	Received: 1	1/25/15 9:30)					
1,2,4-Trichlorobenzene	<0.40	0.40	0.090	mg/kg dry	1	B5K3002	11/30/15	11/30/15	EPA 8270D	
1,2-Dichlorobenzene	<0.40	0.40	0.081	mg/kg dry	1	"	"	"	"	
1,2-Diphenylhydrazine as Azobenzene	<0.40	0.40	0.070	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
2,3,4,6-Tetrachlorophenol	<0.81	0.81	0.23	mg/kg dry	1	"	"	"	"	
2,4,5-Trichlorophenol	<0.81	0.81	0.086	mg/kg dry	1	"	"	"	"	
2,4,6-Trichlorophenol	<0.81	0.81	0.19	mg/kg dry	1	"	"	"	"	
2,4-Dichlorophenol	<0.81	0.81	0.18	mg/kg dry	1	"	"	"	"	
2,4-Dimethylphenol	<0.81	0.81	0.16	mg/kg dry	1	"	"	"	"	
2,4-Dinitrophenol	<0.81	0.81	0.086	mg/kg dry	1	"	"	"	"	
2,4-Dinitrotoluene	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
2,6-Dichlorophenol	<0.81	0.81	0.16	mg/kg dry	1	"	"	"	"	
2,6-Dinitrotoluene	<0.40	0.40	0.093	mg/kg dry	1	"	"	"	"	
2-Chloronaphthalene	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
2-Chlorophenol	<0.81	0.81	0.18	mg/kg dry	1	"	"	"	"	
2-Methylnaphthalene	<0.40	0.40	0.096	mg/kg dry	1	"	"	"	"	
2-Methylphenol	<0.81	0.81	0.099	mg/kg dry	1	"	"	"	"	
2-Nitroaniline	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
2-Nitrophenol	<0.81	0.81	0.22	mg/kg dry	1	"	"	"	"	
3&4-Methylphenol	<0.81	0.81	0.099	mg/kg dry	1	"	"	"	"	
3,3´-Dichlorobenzidine	<1.9	1.9	0.54	mg/kg dry	1	"	"	"	"	
3-Nitroaniline	<0.40	0.40	0.087	mg/kg dry	1	"	"	"	"	
4,6-Dinitro-2-methylphenol	<0.81	0.81	0.13	mg/kg dry	1	"	"	"	"	
4-Bromophenyl phenyl ether	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
4-Chloro-3-methylphenol	<0.81	0.81	0.17	mg/kg dry	1	"	"	"	"	
4-Chloroaniline	<0.81	0.81	0.081	mg/kg dry	1	"	"	"	"	
4-Chlorophenyl phenyl ether	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
4-Nitroaniline	<0.40	0.40	0.10	mg/kg dry	1	"	"	"	"	
4-Nitrophenol	<0.81	0.81	0.20	mg/kg dry	1	"	"	"	"	
Acenaphthene	<0.40	0.40	0.076	mg/kg dry	1	"	"	"	"	
Acenaphthylene	<0.40	0.40	0.086	mg/kg dry	1	"	"	"	"	
Aniline	<0.81	0.81	0.080	mg/kg dry	1	"	"	"	"	
Anthracene	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
Benzidine	<3.0	3.0	0.53	mg/kg dry	1	"	"	"	"	
Benzo(a)anthracene	<0.40	0.40	0.078	mg/kg dry	1	"	"	"	"	
Benzo(a)pyrene	<0.40	0.40	0.084	mg/kg dry	1	"	"	"	"	
Benzo(b)fluoranthene	<0.40	0.40	0.071	mg/kg dry	1	"	"	"	"	
Benzo(g,h,i)perylene	< 0.40	0.40	0.086	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-2a_4-6 (1505280-04) Soil	Sampled: 11/24/15 1	0:00	Received:	11/25/15 9:30)					
Benzo(k)fluoranthene	<0.40	0.40	0.084	mg/kg dry	1	B5K3002	11/30/15	11/30/15	EPA 8270D	
Benzoic acid	<0.40	0.40	0.077	mg/kg dry	1	"	"	"	"	
Benzyl alcohol	<0.81	0.81	0.18	mg/kg dry	1	"	"	"	"	
Bis(2-chloroethoxy)methane	<0.40	0.40	0.093	mg/kg dry	1	"	"	II .	II .	
Bis(2-chloroethyl)ether	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
Bis(2-chloroisopropyl)ether	<0.40	0.40	0.094	mg/kg dry	1	"	"	"	"	
Bis(2-ethylhexyl)phthalate	<0.40	0.40	0.098	mg/kg dry	1	"	"	"	"	
Butyl benzyl phthalate	<0.40	0.40	0.10	mg/kg dry	1	"	"	"	"	
Carbazole	<0.40	0.40	0.092	mg/kg dry	1	"	"	"	"	
Chrysene	<0.40	0.40	0.077	mg/kg dry	1	"	"	II .	"	
Dibenz(a,h)anthracene	<0.40	0.40	0.099	mg/kg dry	1	"	"	"	"	
Dibenzofuran	<0.40	0.40	0.082	mg/kg dry	1	"	"	n .	u u	
Diethyl phthalate	<0.40	0.40	0.076	mg/kg dry	1	"	"	n .	u u	
Dimethyl phthalate	<0.40	0.40	0.083	mg/kg dry	1	"	"	n .	u u	
Di-n-butyl phthalate	<0.40	0.40	0.095	mg/kg dry	1	"	"	"	"	
Di-n-octyl phthalate	<0.40	0.40	0.12	mg/kg dry	1	"	"	"	"	
Fluoranthene	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
Fluorene	<0.40	0.40	0.078	mg/kg dry	1	"	"	II .	"	
Hexachlorobenzene	<0.40	0.40	0.075	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.40	0.40	0.093	mg/kg dry	1	"	"	"	"	
Hexachlorocyclopentadiene	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
Hexachloroethane	<0.40	0.40	0.099	mg/kg dry	1	"	"	"	"	
Indeno (1,2,3-cd) pyrene	<0.40	0.40	0.087	mg/kg dry	1	"	"	"	"	
Isophorone	<0.40	0.40	0.092	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.40	0.40	0.086	mg/kg dry	1	"	"	"	"	
Nitrobenzene	<0.40	0.40	0.096	mg/kg dry	1	"	"	"	"	
N-Nitrosodimethylamine	<0.40	0.40	0.084	mg/kg dry	1	"	"	"	"	
N-Nitrosodi-n-propylamine	<0.40	0.40	0.088	mg/kg dry	1	"	"	"	"	
N-Nitrosodiphenylamine	<0.40	0.40	0.081	mg/kg dry	1	"	"	"	"	
Pentachlorophenol	<0.81	0.81	0.23	mg/kg dry	1	"	"	"	"	
Phenanthrene	<0.40	0.40	0.080	mg/kg dry	1	"	"	"	"	
Phenol	<0.81	0.81	0.17	mg/kg dry	1	"	"	"	"	
Pyrene	<0.40	0.40	0.071	mg/kg dry	1	"	"	"	"	
Surrogate: 2,4,6-Tribromophenol	80.9			53-107 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	62.7			53.9-97.9 %		"	"	"	"	
Surrogate: 2-Fluorophenol	55.1			42.5-94.9 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	63.9			48.9-100 %		"	"	"	"	
Surrogate: Phenol-d6	68.8			50.4-99.6 %		"	"	"	"	
Surrogate: Terphenyl-d14	51.8			51-99.6 %				"	.,	



Analyte

88 Empire Drive St Paul, MN 55103 Tel: 651-642-1150

Fax: 651-642-1239

Work Order #:

Date Reported: 12/10/15

Method

1505280

Notes

Barr Engineering Co. 34511010 Project: 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Result

RL

0.87

0.43

3.2

0.43

0.43

0.43

0.43

< 0.87

< 0.43

<3.2

< 0.43

< 0.43

< 0.43

< 0.43

0.086

0.090

0.57

0.084

0.091

0.077

0.092

1

1

1

1

1

1

1

mg/kg dry

SVOC 8270D Legend Technical Services, Inc.

Batch

Prepared

Analyzed

B-3_6-8 (1505280-05) Soil Sampled: 11/24/15 11:00 Received: 11/25/15 9:30 1,2,4-Trichlorobenzene < 0.43 0.43 0.097 mg/kg dry 1 B5K3002 11/30/15 11/30/15 **EPA 8270D** 1,2-Dichlorobenzene < 0.43 0.43 0.087 mg/kg dry 1 0.075 1,2-Diphenylhydrazine as Azobenzene < 0.43 0.43 1 mg/kg dry < 0.43 0.43 0.090 1 1.3-Dichlorobenzene mg/kg dry < 0.43 0.43 0.088 1 1.4-Dichlorobenzene mg/kg dry 0.87 2,3,4,6-Tetrachlorophenol < 0.87 0.25 mg/kg dry 1 2,4,5-Trichlorophenol < 0.87 0.87 0.092 mg/kg dry 1 2,4,6-Trichlorophenol < 0.87 0.87 0.21 mg/kg dry 1 2,4-Dichlorophenol < 0.87 0.87 0.19 mg/kg dry 1 0.87 1 2,4-Dimethylphenol < 0.87 0.17 mg/kg dry 0.87 0.092 1 2,4-Dinitrophenol < 0.87 mg/kg dry 0.43 0.088 2.4-Dinitrotoluene < 0.43 1 ma/ka drv 2,6-Dichlorophenol < 0.87 0.87 0.17 mg/kg dry 1 2,6-Dinitrotoluene < 0.43 0.43 0.10 mg/kg dry 1 2-Chloronaphthalene 0.43 0.088 1 < 0.43 mg/kg dry 2-Chlorophenol < 0.87 0.87 0.19 mg/kg dry 1 2-Methylnaphthalene 1 < 0.43 0.43 0.10 mg/kg dry 2-Methylphenol < 0.87 0.87 0.11 mg/kg dry 1 2-Nitroaniline 0.43 0.090 1 < 0.43 mg/kg dry 2-Nitrophenol < 0.87 0.87 0.23 1 mg/kg dry 3&4-Methylphenol < 0.87 0.87 0.11 1 mg/kg dry 3,3'-Dichlorobenzidine <2.1 2.1 0.58 mg/kg dry 1 3-Nitroaniline < 0.43 0.43 0.094 mg/kg dry 1 4,6-Dinitro-2-methylphenol < 0.87 0.87 0.14 mg/kg dry 1 4-Bromophenyl phenyl ether < 0.43 0.43 0.088 mg/kg dry 1 0.87 4-Chloro-3-methylphenol < 0.87 0.18 1 mg/kg dry 0.87 4-Chloroaniline < 0.87 0.087 1 mg/kg dry 4-Chlorophenyl phenyl ether < 0.43 0.43 0.088 mg/kg dry 1 mg/kg dry 4-Nitroaniline < 0.43 0.43 0.11 1 4-Nitrophenol < 0.87 0.87 0.22 mg/kg dry 1 Acenaphthene < 0.43 0.43 0.082 mg/kg dry 1 Acenaphthylene < 0.43 0.43 0.092 mg/kg dry 1

Units

Dilution

Aniline

Anthracene

Benzidine

Benzo(a)anthracene

Benzo(b)fluoranthene

Benzo(g,h,i)perylene

Benzo(a)pyrene



Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_6-8 (1505280-05) Soil	Sampled: 11/24/15 11:	:00	Received: 1	1/25/15 9:30						
Benzo(k)fluoranthene	<0.43	0.43	0.091	mg/kg dry	1	B5K3002	11/30/15	11/30/15	EPA 8270D	
Benzoic acid	<0.43	0.43	0.083	mg/kg dry	1	"	"	II .	"	
Benzyl alcohol	<0.87	0.87	0.19	mg/kg dry	1	"	u u	II .	n .	
Bis(2-chloroethoxy)methane	<0.43	0.43	0.10	mg/kg dry	1	"	"	"	n .	
Bis(2-chloroethyl)ether	<0.43	0.43	0.090	mg/kg dry	1	"	"	"	"	
Bis(2-chloroisopropyl)ether	<0.43	0.43	0.10	mg/kg dry	1	"	"	"	"	
Bis(2-ethylhexyl)phthalate	<0.43	0.43	0.11	mg/kg dry	1	"	"	"	n .	
Butyl benzyl phthalate	<0.43	0.43	0.11	mg/kg dry	1	"	"	"	"	
Carbazole	<0.43	0.43	0.099	mg/kg dry	1	"	"	"	"	
Chrysene	<0.43	0.43	0.083	mg/kg dry	1	"	"	"	"	
Dibenz(a,h)anthracene	<0.43	0.43	0.11	mg/kg dry	1	"	"	"	"	
Dibenzofuran	<0.43	0.43	0.088	mg/kg dry	1	"	"	"	"	
Diethyl phthalate	<0.43	0.43	0.082	mg/kg dry	1	"	"	"	"	
Dimethyl phthalate	<0.43	0.43	0.090	mg/kg dry	1	"	"	"	n .	
Di-n-butyl phthalate	<0.43	0.43	0.10	mg/kg dry	1	"	"	"	n .	
Di-n-octyl phthalate	<0.43	0.43	0.13	mg/kg dry	1	"	"	"	"	
Fluoranthene	<0.43	0.43	0.088	mg/kg dry	1	"	"	"	"	
Fluorene	<0.43	0.43	0.084	mg/kg dry	1	"	"	II .	II .	
Hexachlorobenzene	<0.43	0.43	0.081	mg/kg dry	1	"	"	II .	n .	
Hexachlorobutadiene	<0.43	0.43	0.10	mg/kg dry	1	"	"	"	"	
Hexachlorocyclopentadiene	<0.43	0.43	0.090	mg/kg dry	1	"	"	"	n .	
Hexachloroethane	<0.43	0.43	0.11	mg/kg dry	1	"	"	"	"	
Indeno (1,2,3-cd) pyrene	<0.43	0.43	0.094	mg/kg dry	1	"	"	"	"	
Isophorone	<0.43	0.43	0.099	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.43	0.43	0.092	mg/kg dry	1	"	"	"	"	
Nitrobenzene	<0.43	0.43	0.10	mg/kg dry	1	"	"	"	"	
N-Nitrosodimethylamine	<0.43	0.43	0.091	mg/kg dry	1	"	"	"	"	
N-Nitrosodi-n-propylamine	<0.43	0.43	0.095	mg/kg dry	1	"	"	"	"	
N-Nitrosodiphenylamine	<0.43	0.43	0.087	mg/kg dry	1	"	"	"	"	
Pentachlorophenol	<0.87	0.87	0.25	mg/kg dry	1	"	"	"	"	
Phenanthrene	<0.43	0.43	0.086	mg/kg dry	1	"	"	"	"	
Phenol	<0.87	0.87	0.18	mg/kg dry	1	"	"	ıı	n .	
Pyrene	<0.43	0.43	0.077	mg/kg dry	1	"	"	"	"	
Surrogate: 2,4,6-Tribromopheno	l 83.9			53-107 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	63.3			53.9-97.9 %		"	"	"	"	
Surrogate: 2-Fluorophenol	63.3			42.5-94.9 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	65.0			48.9-100 %		"	"	"	"	
Surrogate: Phenol-d6 Surrogate: Terphenyl-d14	73.0 54.6			50.4-99.6 %		"	"	"	"	
Surrogate. Terprienyi-u14	34.0			51-99.6 %				**	**	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_0-2 (1505280-06) Soil Sampled	I: 11/24/15 11	:00 Re	eceived: 11	/25/15 9:30						
1,2,4-Trichlorobenzene	<0.37	0.37	0.084	mg/kg dry	1	B5K3002	11/30/15	11/30/15	EPA 8270D	
1,2-Dichlorobenzene	< 0.37	0.37	0.075	mg/kg dry	1	"	"	"	u u	
1,2-Diphenylhydrazine as Azobenzene	< 0.37	0.37	0.065	mg/kg dry	1	"	II .	"	II .	
1,3-Dichlorobenzene	< 0.37	0.37	0.078	mg/kg dry	1	"	II .	"	"	
1,4-Dichlorobenzene	< 0.37	0.37	0.076	mg/kg dry	1	"	II .	"	II .	
2,3,4,6-Tetrachlorophenol	< 0.75	0.75	0.21	mg/kg dry	1	"	II .	"	"	
2,4,5-Trichlorophenol	< 0.75	0.75	0.080	mg/kg dry	1	"	II .	"	"	
2,4,6-Trichlorophenol	<0.75	0.75	0.18	mg/kg dry	1	"	II .	"	II .	
2,4-Dichlorophenol	< 0.75	0.75	0.17	mg/kg dry	1	"	II .	"	"	
2,4-Dimethylphenol	< 0.75	0.75	0.15	mg/kg dry	1	"	II .	"	"	
2,4-Dinitrophenol	< 0.75	0.75	0.080	mg/kg dry	1	"	II .	"	"	
2,4-Dinitrotoluene	< 0.37	0.37	0.076	mg/kg dry	1	"	II .	"	"	
2,6-Dichlorophenol	< 0.75	0.75	0.15	mg/kg dry	1	"	II .	"	"	
2,6-Dinitrotoluene	<0.37	0.37	0.087	mg/kg dry	1	"	"	"	"	
2-Chloronaphthalene	<0.37	0.37	0.076	mg/kg dry	1	"	"	"	"	
2-Chlorophenol	< 0.75	0.75	0.17	mg/kg dry	1	"	II .	"	"	
2-Methylnaphthalene	< 0.37	0.37	0.090	mg/kg dry	1	"	"	"	u u	
2-Methylphenol	<0.75	0.75	0.092	mg/kg dry	1	"	"	"	"	
2-Nitroaniline	< 0.37	0.37	0.078	mg/kg dry	1	"	"	"	"	
2-Nitrophenol	< 0.75	0.75	0.20	mg/kg dry	1	"	"	"	"	
3&4-Methylphenol	<0.75	0.75	0.092	mg/kg dry	1	"	"	"	u u	
3,3´-Dichlorobenzidine	<1.8	1.8	0.51	mg/kg dry	1	"	"	"	u u	
3-Nitroaniline	< 0.37	0.37	0.081	mg/kg dry	1	"	"	"	u u	
4,6-Dinitro-2-methylphenol	<0.75	0.75	0.12	mg/kg dry	1	"	"	"	u u	
4-Bromophenyl phenyl ether	<0.37	0.37	0.076	mg/kg dry	1	"	"	"	"	
4-Chloro-3-methylphenol	<0.75	0.75	0.16	mg/kg dry	1	"	"	"	"	
4-Chloroaniline	<0.75	0.75	0.075	mg/kg dry	1	"	II .	"	"	
4-Chlorophenyl phenyl ether	< 0.37	0.37	0.076	mg/kg dry	1	"	II .	"	"	
4-Nitroaniline	<0.37	0.37	0.093	mg/kg dry	1	"	"	"	"	
4-Nitrophenol	<0.75	0.75	0.19	mg/kg dry	1	"	"	"	"	
Acenaphthene	<0.37	0.37	0.071	mg/kg dry	1	"	"	"	"	
Acenaphthylene	<0.37	0.37	0.080	mg/kg dry	1	"	"	"	"	
Aniline	<0.75	0.75	0.074	mg/kg dry	1	"	"	"	"	
Anthracene	<0.37	0.37	0.078	mg/kg dry	1	"	"	"	"	
Benzidine	<2.8	2.8	0.49	mg/kg dry	1	"	"	"	"	
Benzo(a)anthracene	<0.37	0.37	0.073	mg/kg dry	1	"	"	"	"	
Benzo(a)pyrene	< 0.37	0.37	0.079	mg/kg dry	1	"	"	"	"	
Benzo(b)fluoranthene	< 0.37	0.37	0.066	mg/kg dry	1	"	"	"	"	
Benzo(g,h,i)perylene	< 0.37	0.37	0.080	mg/kg dry	1	п	II .	"	m .	
				,						



Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_0-2 (1505280-06) Soil	Sampled: 11/24/15 11:	00	Received: 1	1/25/15 9:30						
Benzo(k)fluoranthene	<0.37	0.37	0.079	mg/kg dry	1	B5K3002	11/30/15	11/30/15	EPA 8270D	
Benzoic acid	<0.37	0.37	0.072	mg/kg dry	1	"	"	n .	п	
Benzyl alcohol	<0.75	0.75	0.17	mg/kg dry	1	"	"	n .	п	
Bis(2-chloroethoxy)methane	<0.37	0.37	0.087	mg/kg dry	1	"	"	n .	п	
Bis(2-chloroethyl)ether	<0.37	0.37	0.078	mg/kg dry	1	"	"	"	"	
Bis(2-chloroisopropyl)ether	<0.37	0.37	0.088	mg/kg dry	1	"	"	"	"	
Bis(2-ethylhexyl)phthalate	<0.37	0.37	0.091	mg/kg dry	1	"	"	n .	II .	
Butyl benzyl phthalate	<0.37	0.37	0.093	mg/kg dry	1	"	"	"	"	
Carbazole	<0.37	0.37	0.085	mg/kg dry	1	"	"	"	"	
Chrysene	<0.37	0.37	0.072	mg/kg dry	1	"	"	"	"	
Dibenz(a,h)anthracene	<0.37	0.37	0.092	mg/kg dry	1	"	"	"	"	
Dibenzofuran	<0.37	0.37	0.076	mg/kg dry	1	"	"	"	"	
Diethyl phthalate	<0.37	0.37	0.071	mg/kg dry	1	"	"	"	"	
Dimethyl phthalate	<0.37	0.37	0.078	mg/kg dry	1	"	"	"	"	
Di-n-butyl phthalate	<0.37	0.37	0.089	mg/kg dry	1	"	"	"	"	
Di-n-octyl phthalate	<0.37	0.37	0.11	mg/kg dry	1	"	"	"	"	
Fluoranthene	<0.37	0.37	0.076	mg/kg dry	1	"	"	"	"	
Fluorene	<0.37	0.37	0.073	mg/kg dry	1	"	"	"	"	
Hexachlorobenzene	<0.37	0.37	0.070	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.37	0.37	0.087	mg/kg dry	1	"	"	"	"	
Hexachlorocyclopentadiene	<0.37	0.37	0.078	mg/kg dry	1	"	"	"	"	
Hexachloroethane	<0.37	0.37	0.092	mg/kg dry	1	"	"	"	"	
Indeno (1,2,3-cd) pyrene	<0.37	0.37	0.081	mg/kg dry	1	"	"	"	"	
Isophorone	<0.37	0.37	0.085	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.37	0.37	0.080	mg/kg dry	1	"	"	"	"	
Nitrobenzene	<0.37	0.37	0.090	mg/kg dry	1	"	"	"	"	
N-Nitrosodimethylamine	<0.37	0.37	0.079	mg/kg dry	1	"	"	"	u u	
N-Nitrosodi-n-propylamine	<0.37	0.37	0.082	mg/kg dry	1	"	"	"	"	
N-Nitrosodiphenylamine	<0.37	0.37	0.075	mg/kg dry	1	"	"	"	"	
Pentachlorophenol	<0.75	0.75	0.21	mg/kg dry	1	"	"	"	"	
Phenanthrene	<0.37	0.37	0.074	mg/kg dry	1	"	"	"	"	
Phenol	<0.75	0.75	0.16	mg/kg dry	1	"	"	"	"	
Pyrene	<0.37	0.37	0.066	mg/kg dry	1	"	"	"	"	
Surrogate: 2,4,6-Tribromopheno	ol 83.4			53-107 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	68.2			53.9-97.9 %		"	"	"	"	
Surrogate: 2-Fluorophenol	57.0			42.5-94.9 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	68.2			48.9-100 %			"	"		
Surrogate: Phenol-d6 Surrogate: Terphenyl-d14	70.4 52.0			50.4-99.6 %		"	"	"	"	
оиноуате, тегрпепут-а14	52.0			51-99.6 %						



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4_2-4 (1505280-07) Soil Sampled	l: 11/24/15 12	:00 R	eceived: 1	1/25/15 9:30						
1,2,4-Trichlorobenzene	< 0.35	0.35	0.080	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
1,2-Dichlorobenzene	< 0.35	0.35	0.071	mg/kg dry	1	"	"	"	"	
1,2-Diphenylhydrazine as Azobenzene	< 0.35	0.35	0.062	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	< 0.35	0.35	0.073	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.35	0.35	0.072	mg/kg dry	1	"	n .	"	"	
2,3,4,6-Tetrachlorophenol	<0.71	0.71	0.20	mg/kg dry	1	"	II .	"	"	
2,4,5-Trichlorophenol	<0.71	0.71	0.076	mg/kg dry	1	"	"	"	"	
2,4,6-Trichlorophenol	<0.71	0.71	0.17	mg/kg dry	1	"	n .	"	"	
2,4-Dichlorophenol	<0.71	0.71	0.16	mg/kg dry	1	"	n .	"	· ·	
2,4-Dimethylphenol	<0.71	0.71	0.14	mg/kg dry	1	"	n .	"	"	
2,4-Dinitrophenol	<0.71	0.71	0.076	mg/kg dry	1	"	n .	"	"	
2,4-Dinitrotoluene	<0.35	0.35	0.072	mg/kg dry	1	"	n .	"	· ·	
2,6-Dichlorophenol	<0.71	0.71	0.14	mg/kg dry	1	"	"	"	"	
2,6-Dinitrotoluene	<0.35	0.35	0.082	mg/kg dry	1	"	n .	"	"	
2-Chloronaphthalene	<0.35	0.35	0.072	mg/kg dry	1	"	n .	"	· ·	
2-Chlorophenol	<0.71	0.71	0.16	mg/kg dry	1	"	"	"	"	
2-Methylnaphthalene	<0.35	0.35	0.085	mg/kg dry	1	"	"	"	"	
2-Methylphenol	<0.71	0.71	0.087	mg/kg dry	1	"	"	"	· ·	
2-Nitroaniline	< 0.35	0.35	0.073	mg/kg dry	1	"	"	"	"	
2-Nitrophenol	<0.71	0.71	0.19	mg/kg dry	1	"	"	"	· ·	
3&4-Methylphenol	<0.71	0.71	0.087	mg/kg dry	1	"	n .	"	"	
3,3´-Dichlorobenzidine	<1.7	1.7	0.48	mg/kg dry	1	"	"	"	"	
3-Nitroaniline	<0.35	0.35	0.077	mg/kg dry	1	"	"	"	"	
4,6-Dinitro-2-methylphenol	<0.71	0.71	0.12	mg/kg dry	1	"	"	"	"	
4-Bromophenyl phenyl ether	<0.35	0.35	0.072	mg/kg dry	1	"	"	"	"	
4-Chloro-3-methylphenol	<0.71	0.71	0.15	mg/kg dry	1	"	"	"	"	
4-Chloroaniline	<0.71	0.71	0.071	mg/kg dry	1	"	"	"	"	
4-Chlorophenyl phenyl ether	<0.35	0.35	0.072	mg/kg dry	1	"	"	"	"	
4-Nitroaniline	<0.35	0.35	0.088	mg/kg dry	1	"	"	"	"	
4-Nitrophenol	<0.71	0.71	0.18	mg/kg dry	1	"	"	"	"	
Acenaphthene	<0.35	0.35	0.067	mg/kg dry	1	"	"	"	"	
Acenaphthylene	<0.35	0.35	0.076	mg/kg dry	1	"	"	"	"	
Aniline	<0.71	0.71	0.070	mg/kg dry	1	"	"	"	"	
Anthracene	<0.35	0.35	0.073	mg/kg dry	1	"	"	"	"	
Benzidine	<2.7	2.7	0.47	mg/kg dry	1	"	"	"	"	
Benzo(a)anthracene	<0.35	0.35	0.069	mg/kg dry	1	"	"	"	"	
Benzo(a)pyrene	<0.35	0.35	0.074	mg/kg dry	1	"	n .	"	· ·	
Benzo(b)fluoranthene	<0.35	0.35	0.063	mg/kg dry	1	"	"	"	"	
Benzo(g,h,i)perylene	< 0.35	0.35	0.076	mg/kg dry	1	"	"	"		



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Date Reported: 12/10/15

Work Order #: 1505280

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4_2-4 (1505280-07) Soil	Sampled: 11/24/15 12:	00	Received:	11/25/15 9:30						
Benzo(k)fluoranthene	<0.35	0.35	0.074	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
Benzoic acid	<0.35	0.35	0.068	mg/kg dry	1	"	"	п	"	
Benzyl alcohol	<0.71	0.71	0.16	mg/kg dry	1	"	"	II .	II .	
Bis(2-chloroethoxy)methane	<0.35	0.35	0.082	mg/kg dry	1	"	"	II .	II .	
Bis(2-chloroethyl)ether	<0.35	0.35	0.073	mg/kg dry	1	"	"	II .	II .	
Bis(2-chloroisopropyl)ether	<0.35	0.35	0.083	mg/kg dry	1	"	"	II .	II .	
Bis(2-ethylhexyl)phthalate	<0.35	0.35	0.086	mg/kg dry	1	"	"	II .	II .	
Butyl benzyl phthalate	<0.35	0.35	0.088	mg/kg dry	1	"	"	II .	II .	
Carbazole	<0.35	0.35	0.081	mg/kg dry	1	"	"	II .	II .	
Chrysene	<0.35	0.35	0.068	mg/kg dry	1	"	"	II .	II .	
Dibenz(a,h)anthracene	<0.35	0.35	0.087	mg/kg dry	1	"	"	II .	II .	
Dibenzofuran	<0.35	0.35	0.072	mg/kg dry	1	"	"	II .	II .	
Diethyl phthalate	<0.35	0.35	0.067	mg/kg dry	1	"	"	II .	II .	
Dimethyl phthalate	<0.35	0.35	0.073	mg/kg dry	1	"	"	"	"	
Di-n-butyl phthalate	<0.35	0.35	0.084	mg/kg dry	1	"	"	"	"	
Di-n-octyl phthalate	<0.35	0.35	0.11	mg/kg dry	1	"	"	"	"	
Fluoranthene	<0.35	0.35	0.072	mg/kg dry	1	"	"	II .	II .	
Fluorene	<0.35	0.35	0.069	mg/kg dry	1	"	"	II .	II .	
Hexachlorobenzene	<0.35	0.35	0.066	mg/kg dry	1	"	"	II .	II .	
Hexachlorobutadiene	<0.35	0.35	0.082	mg/kg dry	1	"	"	II .	II .	
Hexachlorocyclopentadiene	<0.35	0.35	0.073	mg/kg dry	1	"	"	II .	II .	
Hexachloroethane	<0.35	0.35	0.087	mg/kg dry	1	"	"	II .	II .	
Indeno (1,2,3-cd) pyrene	<0.35	0.35	0.077	mg/kg dry	1	"	"	II .	II .	
Isophorone	<0.35	0.35	0.081	mg/kg dry	1	"	"	II .	II .	
Naphthalene	<0.35	0.35	0.076	mg/kg dry	1	"	"	"	"	
Nitrobenzene	<0.35	0.35	0.085	mg/kg dry	1	"	"	"	"	
N-Nitrosodimethylamine	<0.35	0.35	0.074	mg/kg dry	1	"	"	II .	II .	
N-Nitrosodi-n-propylamine	<0.35	0.35	0.078	mg/kg dry	1	"	"	II .	II .	
N-Nitrosodiphenylamine	<0.35	0.35	0.071	mg/kg dry	1	"	"	"	"	
Pentachlorophenol	<0.71	0.71	0.20	mg/kg dry	1	"	"	"	"	
Phenanthrene	<0.35	0.35	0.070	mg/kg dry	1	"	"	"	"	
Phenol	<0.71	0.71	0.15	mg/kg dry	1	"	"	"	"	
Pyrene	<0.35	0.35	0.063	mg/kg dry	1	"	"	"	"	
Surrogate: 2,4,6-Tribromopheno	ol 86.0			53-107 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	74.9			53.9-97.9 %		"	"	"	"	
Surrogate: 2-Fluorophenol	56.7			42.5-94.9 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	71.8			48.9-100 %		"	"	"	"	
Surrogate: Phenol-d6	73.2			50.4-99.6 %					"	
Surrogate: Terphenyl-d14	53.6			51-99.6 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4_8-10 (1505280-08) Soil Sampled	l: 11/24/15 1	2:00	Received: 1	11/25/15 9:30)					
1,2,4-Trichlorobenzene	<0.40	0.40	0.090	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
1,2-Dichlorobenzene	<0.40	0.40	0.081	mg/kg dry	1	"	"	"		
1,2-Diphenylhydrazine as Azobenzene	<0.40	0.40	0.070	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	II .	
1,4-Dichlorobenzene	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	II .	
2,3,4,6-Tetrachlorophenol	<0.81	0.81	0.23	mg/kg dry	1	"	n .	II .	п	
2,4,5-Trichlorophenol	<0.81	0.81	0.086	mg/kg dry	1	"	"	"	II .	
2,4,6-Trichlorophenol	<0.81	0.81	0.19	mg/kg dry	1	"	"	"	II .	
2,4-Dichlorophenol	<0.81	0.81	0.18	mg/kg dry	1	"	n .	II .	п	
2,4-Dimethylphenol	<0.81	0.81	0.16	mg/kg dry	1	"	"	"	II .	
2,4-Dinitrophenol	<0.81	0.81	0.086	mg/kg dry	1	"	n .	II .	п	
2,4-Dinitrotoluene	<0.40	0.40	0.082	mg/kg dry	1	"	n .	II .	п	
2,6-Dichlorophenol	<0.81	0.81	0.16	mg/kg dry	1	"	n .	II .	п	
2,6-Dinitrotoluene	<0.40	0.40	0.093	mg/kg dry	1	"	"	"	II .	
2-Chloronaphthalene	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	II .	
2-Chlorophenol	<0.81	0.81	0.18	mg/kg dry	1	"	"	"	II .	
2-Methylnaphthalene	<0.40	0.40	0.096	mg/kg dry	1	"	n .	"	II .	
2-Methylphenol	<0.81	0.81	0.099	mg/kg dry	1	"	n .	"	II .	
2-Nitroaniline	<0.40	0.40	0.083	mg/kg dry	1	"	n .	"	II .	
2-Nitrophenol	<0.81	0.81	0.22	mg/kg dry	1	"	n .	"	II .	
3&4-Methylphenol	<0.81	0.81	0.099	mg/kg dry	1	"	"	"	II .	
3,3´-Dichlorobenzidine	<1.9	1.9	0.54	mg/kg dry	1	"	"	"	II .	
3-Nitroaniline	<0.40	0.40	0.087	mg/kg dry	1	"	n .	II .	п	
4,6-Dinitro-2-methylphenol	<0.81	0.81	0.13	mg/kg dry	1	"	"	"	m .	
4-Bromophenyl phenyl ether	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	II .	
4-Chloro-3-methylphenol	<0.81	0.81	0.17	mg/kg dry	1	"	"	"	II .	
4-Chloroaniline	<0.81	0.81	0.081	mg/kg dry	1	"	"	"	II .	
4-Chlorophenyl phenyl ether	<0.40	0.40	0.082	mg/kg dry	1	"	n .	II .	п	
4-Nitroaniline	<0.40	0.40	0.10	mg/kg dry	1	"	"	"	II .	
4-Nitrophenol	<0.81	0.81	0.20	mg/kg dry	1	"	n .	II .	п	
Acenaphthene	<0.40	0.40	0.076	mg/kg dry	1	"	n .	II .	п	
Acenaphthylene	<0.40	0.40	0.086	mg/kg dry	1	"	n .	II .	п	
Aniline	<0.81	0.81	0.080	mg/kg dry	1	"	"	"	п	
Anthracene	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	II .	
Benzidine	<3.0	3.0	0.53	mg/kg dry	1	"	n .	II .	п	
Benzo(a)anthracene	<0.40	0.40	0.078	mg/kg dry	1	"	"	"	п	
Benzo(a)pyrene	<0.40	0.40	0.084	mg/kg dry	1	"	"	"	"	
Benzo(b)fluoranthene	<0.40	0.40	0.071	mg/kg dry	1	"	"	"	"	
Benzo(g,h,i)perylene	<0.40	0.40	0.086	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4_8-10 (1505280-08) Soil	Sampled: 11/24/15 1	2:00	Received:	11/25/15 9:30)					
Benzo(k)fluoranthene	<0.40	0.40	0.084	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
Benzoic acid	<0.40	0.40	0.077	mg/kg dry	1	"	"	"	"	
Benzyl alcohol	<0.81	0.81	0.18	mg/kg dry	1	"	"	n n	"	
Bis(2-chloroethoxy)methane	<0.40	0.40	0.093	mg/kg dry	1	"	"	"	"	
Bis(2-chloroethyl)ether	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
Bis(2-chloroisopropyl)ether	<0.40	0.40	0.094	mg/kg dry	1	"	"	"	"	
Bis(2-ethylhexyl)phthalate	<0.40	0.40	0.098	mg/kg dry	1	"	"	"	"	
Butyl benzyl phthalate	<0.40	0.40	0.10	mg/kg dry	1	"	"	"	"	
Carbazole	<0.40	0.40	0.092	mg/kg dry	1	"	"	"	"	
Chrysene	<0.40	0.40	0.077	mg/kg dry	1	"	"	"	"	
Dibenz(a,h)anthracene	<0.40	0.40	0.099	mg/kg dry	1	"	"	"	"	
Dibenzofuran	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
Diethyl phthalate	<0.40	0.40	0.076	mg/kg dry	1	"	"	"	"	
Dimethyl phthalate	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
Di-n-butyl phthalate	<0.40	0.40	0.095	mg/kg dry	1	"	"	"	"	
Di-n-octyl phthalate	<0.40	0.40	0.12	mg/kg dry	1	"	"	"	"	
Fluoranthene	<0.40	0.40	0.082	mg/kg dry	1	"	"	"	"	
Fluorene	<0.40	0.40	0.078	mg/kg dry	1	"	"	"	"	
Hexachlorobenzene	<0.40	0.40	0.075	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.40	0.40	0.093	mg/kg dry	1	"	"	"	"	
Hexachlorocyclopentadiene	<0.40	0.40	0.083	mg/kg dry	1	"	"	"	"	
Hexachloroethane	<0.40	0.40	0.099	mg/kg dry	1	"	"	"	"	
Indeno (1,2,3-cd) pyrene	<0.40	0.40	0.087	mg/kg dry	1	"	"	"	"	
Isophorone	<0.40	0.40	0.092	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.40	0.40	0.086	mg/kg dry	1	"	"	"	"	
Nitrobenzene	<0.40	0.40	0.096	mg/kg dry	1	"	"	"	"	
N-Nitrosodimethylamine	<0.40	0.40	0.084	mg/kg dry	1	"	"	"	"	
N-Nitrosodi-n-propylamine	<0.40	0.40	0.088	mg/kg dry	1	"	"	"	"	
N-Nitrosodiphenylamine	<0.40	0.40	0.081	mg/kg dry	1	"	"	"	"	
Pentachlorophenol	<0.81	0.81	0.23	mg/kg dry	1	"	"	"	"	
Phenanthrene	<0.40	0.40	0.080	mg/kg dry	1	"	"	"	"	
Phenol	<0.81	0.81	0.17	mg/kg dry	1	"	"	"	"	
Pyrene	<0.40	0.40	0.071	mg/kg dry	1	"	"	"	"	
Surrogate: 2,4,6-Tribromophenol	84.1			53-107 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	62.8			53.9-97.9 %		"	"	"	"	
Surrogate: 2-Fluorophenol	57.3			42.5-94.9 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	63.8			48.9-100 %					"	
Surrogate: Phenol-d6 Surrogate: Terphenyl-d14	67.1 54.0			50.4-99.6 %		"	"	"	"	
Surrogate. Terpriettyr-U14	J 4 .0			51-99.6 %		*	**	*	•	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280

Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-5_0-2 (1505280-09) Soil Sampled	d: 11/24/15 12	:45 I	Received:	11/25/15 9:30						
1,2,4-Trichlorobenzene	<0.36	0.36	0.082	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
1,2-Dichlorobenzene	< 0.36	0.36	0.074	mg/kg dry	1	"	II .	"	"	
1,2-Diphenylhydrazine as Azobenzene	<0.36	0.36	0.064	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.36	0.36	0.076	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.36	0.36	0.075	mg/kg dry	1	"	"	"	"	
2,3,4,6-Tetrachlorophenol	<0.74	0.74	0.21	mg/kg dry	1	"	"	"	•	
2,4,5-Trichlorophenol	<0.74	0.74	0.078	mg/kg dry	1	"	"	"	"	
2,4,6-Trichlorophenol	<0.74	0.74	0.18	mg/kg dry	1	"	"	"	"	
2,4-Dichlorophenol	<0.74	0.74	0.16	mg/kg dry	1	"	"	"	•	
2,4-Dimethylphenol	<0.74	0.74	0.14	mg/kg dry	1	"	"	"	"	
2,4-Dinitrophenol	<0.74	0.74	0.078	mg/kg dry	1	"	"	"	•	
2,4-Dinitrotoluene	<0.36	0.36	0.075	mg/kg dry	1	"	"	"	"	
2,6-Dichlorophenol	<0.74	0.74	0.14	mg/kg dry	1	"	"	"	"	
2,6-Dinitrotoluene	<0.36	0.36	0.085	mg/kg dry	1	"	"	"	"	
2-Chloronaphthalene	<0.36	0.36	0.075	mg/kg dry	1	"	"	"	•	
2-Chlorophenol	<0.74	0.74	0.16	mg/kg dry	1	"	"	"	•	
2-Methylnaphthalene	<0.36	0.36	0.088	mg/kg dry	1	"	"	"	"	
2-Methylphenol	<0.74	0.74	0.090	mg/kg dry	1	"	"	"	•	
2-Nitroaniline	< 0.36	0.36	0.076	mg/kg dry	1	"	"	"	•	
2-Nitrophenol	<0.74	0.74	0.20	mg/kg dry	1	"	"	"	•	
3&4-Methylphenol	<0.74	0.74	0.090	mg/kg dry	1	"	"	"	"	
3,3´-Dichlorobenzidine	<1.8	1.8	0.49	mg/kg dry	1	"	"	"	•	
3-Nitroaniline	<0.36	0.36	0.079	mg/kg dry	1	"	"	"	"	
4,6-Dinitro-2-methylphenol	<0.74	0.74	0.12	mg/kg dry	1	"	"	"	"	
4-Bromophenyl phenyl ether	<0.36	0.36	0.075	mg/kg dry	1	"	"	"	"	
4-Chloro-3-methylphenol	<0.74	0.74	0.15	mg/kg dry	1	"	"	"	"	
4-Chloroaniline	<0.74	0.74	0.074	mg/kg dry	1	"	· ·	"	"	
4-Chlorophenyl phenyl ether	< 0.36	0.36	0.075	mg/kg dry	1	"	II .	"	"	
4-Nitroaniline	<0.36	0.36	0.091	mg/kg dry	1	"	· ·	"	"	
4-Nitrophenol	< 0.74	0.74	0.19	mg/kg dry	1	"	II .	"	"	
Acenaphthene	<0.36	0.36	0.069	mg/kg dry	1	"	"	"	"	
Acenaphthylene	<0.36	0.36	0.078	mg/kg dry	1	"	"	"	"	
Aniline	<0.74	0.74	0.073	mg/kg dry	1	II .	II .	"	"	
Anthracene	<0.36	0.36	0.076	mg/kg dry	1	"	"	"	"	
Benzidine	<2.7	2.7	0.48	mg/kg dry	1	II .	II .	"	"	
Benzo(a)anthracene	<0.36	0.36	0.071	mg/kg dry	1	II .	II .	"	"	
Benzo(a)pyrene	<0.36	0.36	0.077	mg/kg dry	1	"	"	"	"	
Benzo(b)fluoranthene	<0.36	0.36	0.065	mg/kg dry	1	"	"	"	"	
Benzo(g,h,i)perylene	<0.36	0.36	0.078	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-5_0-2 (1505280-09) Soil	Sampled: 11/24/15 12:	45	Received:	11/25/15 9:30						
Benzo(k)fluoranthene	<0.36	0.36	0.077	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
Benzoic acid	<0.36	0.36	0.070	mg/kg dry	1	"	II .	II .	"	
Benzyl alcohol	<0.74	0.74	0.16	mg/kg dry	1	"	II .	II .	"	
Bis(2-chloroethoxy)methane	<0.36	0.36	0.085	mg/kg dry	1	"	II .	II .	"	
Bis(2-chloroethyl)ether	<0.36	0.36	0.076	mg/kg dry	1	"	II .	II .	"	
Bis(2-chloroisopropyl)ether	<0.36	0.36	0.086	mg/kg dry	1	"	"	"	"	
Bis(2-ethylhexyl)phthalate	<0.36	0.36	0.089	mg/kg dry	1	"	II .	II .	"	
Butyl benzyl phthalate	<0.36	0.36	0.091	mg/kg dry	1	"	"	"	"	
Carbazole	<0.36	0.36	0.084	mg/kg dry	1	"	"	"	"	
Chrysene	<0.36	0.36	0.070	mg/kg dry	1	"	II .	II .	"	
Dibenz(a,h)anthracene	<0.36	0.36	0.090	mg/kg dry	1	"	п	п	"	
Dibenzofuran	<0.36	0.36	0.075	mg/kg dry	1	"	II .	II .	"	
Diethyl phthalate	<0.36	0.36	0.069	mg/kg dry	1	"	п	п	"	
Dimethyl phthalate	<0.36	0.36	0.076	mg/kg dry	1	"	II .	II .	"	
Di-n-butyl phthalate	<0.36	0.36	0.087	mg/kg dry	1	"	II .	II .	"	
Di-n-octyl phthalate	<0.36	0.36	0.11	mg/kg dry	1	"	II .	II .	"	
Fluoranthene	<0.36	0.36	0.075	mg/kg dry	1	"	"	"	"	
Fluorene	<0.36	0.36	0.071	mg/kg dry	1	"	"	"	"	
Hexachlorobenzene	<0.36	0.36	0.068	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.36	0.36	0.085	mg/kg dry	1	"	"	"	"	
Hexachlorocyclopentadiene	<0.36	0.36	0.076	mg/kg dry	1	"	"	"	"	
Hexachloroethane	<0.36	0.36	0.090	mg/kg dry	1	"	"	"	"	
ndeno (1,2,3-cd) pyrene	<0.36	0.36	0.079	mg/kg dry	1	"	"	"	"	
sophorone	<0.36	0.36	0.084	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.36	0.36	0.078	mg/kg dry	1	"	"	"		
Nitrobenzene	<0.36	0.36	0.088	mg/kg dry	1	"	"	"		
N-Nitrosodimethylamine	<0.36	0.36	0.077	mg/kg dry	1	"	"	"	"	
N-Nitrosodi-n-propylamine	<0.36	0.36	0.080	mg/kg dry	1	"	"	"	"	
N-Nitrosodiphenylamine	<0.36	0.36	0.074	mg/kg dry	1	"	"	"		
Pentachlorophenol	<0.74	0.74	0.21	mg/kg dry	1	"	"	"	"	
Phenanthrene	<0.36	0.36	0.073	mg/kg dry	1	"	"	"	"	
Phenol	<0.74	0.74	0.15	mg/kg dry	1	"	"	"		
Pyrene	<0.36	0.36	0.065	mg/kg dry	1	"	"	"	"	
Surrogate: 2,4,6-Tribromophend				53-107 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	67.9			53.9-97.9 %		"	"	"	"	
Surrogate: 2-Fluorophenol	57.6			42.5-94.9 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	65.6			48.9-100 %		"	"	"	"	
Surrogate: Phenol-d6	68.8			50.4-99.6 %		"	"	"	"	
Surrogate: Terphenyl-d14	49.0			51-99.6 %		"	"	"	"	S-GC



Fax: 651-642-1239

Work Order #: 1505280

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-5_6-8 (1505280-10) Soil Sampled:	11/24/15 12	:45 F	Received: 1	1/25/15 9:30						
1,2,4-Trichlorobenzene	<0.36	0.36	0.082	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
1,2-Dichlorobenzene	<0.36	0.36	0.074	mg/kg dry	1	"	"	n n	"	
1,2-Diphenylhydrazine as Azobenzene	<0.36	0.36	0.064	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	< 0.36	0.36	0.076	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.36	0.36	0.075	mg/kg dry	1	"	"	"	"	
2,3,4,6-Tetrachlorophenol	<0.74	0.74	0.21	mg/kg dry	1	"	"	"	"	
2,4,5-Trichlorophenol	<0.74	0.74	0.078	mg/kg dry	1	"	"	"	"	
2,4,6-Trichlorophenol	<0.74	0.74	0.18	mg/kg dry	1	"	"	"	"	
2,4-Dichlorophenol	<0.74	0.74	0.16	mg/kg dry	1	"	"	"	"	
2,4-Dimethylphenol	<0.74	0.74	0.14	mg/kg dry	1	"	"	"	"	
2,4-Dinitrophenol	< 0.74	0.74	0.078	mg/kg dry	1	"	"	"	"	
2,4-Dinitrotoluene	<0.36	0.36	0.075	mg/kg dry	1	"	"	"	"	
2,6-Dichlorophenol	< 0.74	0.74	0.14	mg/kg dry	1	"	"	"	"	
2,6-Dinitrotoluene	<0.36	0.36	0.085	mg/kg dry	1	"	"	"	"	
2-Chloronaphthalene	<0.36	0.36	0.075	mg/kg dry	1	"	"	u u	"	
2-Chlorophenol	<0.74	0.74	0.16	mg/kg dry	1	"	"	u u	"	
2-Methylnaphthalene	< 0.36	0.36	0.088	mg/kg dry	1	"	II .	II .	"	
2-Methylphenol	< 0.74	0.74	0.090	mg/kg dry	1	"	"	II .	"	
2-Nitroaniline	< 0.36	0.36	0.076	mg/kg dry	1	"	II .	II .	"	
2-Nitrophenol	< 0.74	0.74	0.20	mg/kg dry	1	"	"	"	"	
3&4-Methylphenol	<0.74	0.74	0.090	mg/kg dry	1	"	"	II .	"	
3,3´-Dichlorobenzidine	<1.8	1.8	0.49	mg/kg dry	1	"	"	"	"	
3-Nitroaniline	< 0.36	0.36	0.079	mg/kg dry	1	"	"	"	"	
4,6-Dinitro-2-methylphenol	< 0.74	0.74	0.12	mg/kg dry	1	"	"	"	"	
4-Bromophenyl phenyl ether	<0.36	0.36	0.075	mg/kg dry	1	"	"	"	"	
4-Chloro-3-methylphenol	< 0.74	0.74	0.15	mg/kg dry	1	"	"	"	"	
4-Chloroaniline	<0.74	0.74	0.074	mg/kg dry	1	"	"	"	"	
4-Chlorophenyl phenyl ether	<0.36	0.36	0.075	mg/kg dry	1	"	"	"	"	
4-Nitroaniline	<0.36	0.36	0.091	mg/kg dry	1	"	"	"	"	
4-Nitrophenol	<0.74	0.74	0.19	mg/kg dry	1	"	"	"	"	
Acenaphthene	<0.36	0.36	0.069	mg/kg dry	1	"	"	"	"	
Acenaphthylene	<0.36	0.36	0.078	mg/kg dry	1	"	"	"	"	
Aniline	<0.74	0.74	0.073	mg/kg dry	1	"	"	"	"	
Anthracene	<0.36	0.36	0.076	mg/kg dry	1	"	"	"	"	
Benzidine	<2.7	2.7	0.48	mg/kg dry	1	"	"	"	"	
Benzo(a)anthracene	<0.36	0.36	0.071	mg/kg dry	1	"	"	"	"	
Benzo(a)pyrene	<0.36	0.36	0.077	mg/kg dry	1	"	"	"	"	
Benzo(b)fluoranthene	<0.36	0.36	0.065	mg/kg dry	1	"	"	"	"	
Benzo(g,h,i)perylene	<0.36	0.36	0.078	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-5_6-8 (1505280-10) Soil	Sampled: 11/24/15 12:	:45	Received:	11/25/15 9:30						
Benzo(k)fluoranthene	<0.36	0.36	0.077	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
Benzoic acid	<0.36	0.36	0.070	mg/kg dry	1	"	"	"	"	
Benzyl alcohol	<0.74	0.74	0.16	mg/kg dry	1	"	"	"	"	
Bis(2-chloroethoxy)methane	<0.36	0.36	0.085	mg/kg dry	1	"	"	"	"	
Bis(2-chloroethyl)ether	<0.36	0.36	0.076	mg/kg dry	1	"	"	II .	II .	
Bis(2-chloroisopropyl)ether	<0.36	0.36	0.086	mg/kg dry	1	"	u u	II .	II .	
Bis(2-ethylhexyl)phthalate	<0.36	0.36	0.089	mg/kg dry	1	"	u u	II .	II .	
Butyl benzyl phthalate	<0.36	0.36	0.091	mg/kg dry	1	"	u u	II .	II .	
Carbazole	<0.36	0.36	0.084	mg/kg dry	1	"	· ·	II .	II .	
Chrysene	<0.36	0.36	0.070	mg/kg dry	1	"	"	II .	II .	
Dibenz(a,h)anthracene	<0.36	0.36	0.090	mg/kg dry	1	"	"	II .	II .	
Dibenzofuran	<0.36	0.36	0.075	mg/kg dry	1	"	"	II .	II .	
Diethyl phthalate	<0.36	0.36	0.069	mg/kg dry	1	"	"	п	II .	
Dimethyl phthalate	<0.36	0.36	0.076	mg/kg dry	1	"	"	"	"	
Di-n-butyl phthalate	<0.36	0.36	0.087	mg/kg dry	1	"	"	II .	II .	
Di-n-octyl phthalate	<0.36	0.36	0.11	mg/kg dry	1	"	"	II .	II .	
Fluoranthene	<0.36	0.36	0.075	mg/kg dry	1	"	"	II .	II .	
Fluorene	<0.36	0.36	0.071	mg/kg dry	1	"	"	"	II .	
Hexachlorobenzene	<0.36	0.36	0.068	mg/kg dry	1	"	"	II .	II .	
Hexachlorobutadiene	<0.36	0.36	0.085	mg/kg dry	1	"	"	II .	II .	
Hexachlorocyclopentadiene	<0.36	0.36	0.076	mg/kg dry	1	"	u u	II .	II .	
Hexachloroethane	<0.36	0.36	0.090	mg/kg dry	1	"	"	II .	II .	
Indeno (1,2,3-cd) pyrene	<0.36	0.36	0.079	mg/kg dry	1	"	u u	II .	II .	
Isophorone	<0.36	0.36	0.084	mg/kg dry	1	"	· ·	II .	II .	
Naphthalene	<0.36	0.36	0.078	mg/kg dry	1	"	"	II .	II .	
Nitrobenzene	<0.36	0.36	0.088	mg/kg dry	1	"	"	"	"	
N-Nitrosodimethylamine	<0.36	0.36	0.077	mg/kg dry	1	"	"	II .	II .	
N-Nitrosodi-n-propylamine	<0.36	0.36	0.080	mg/kg dry	1	"	u u	II .	II .	
N-Nitrosodiphenylamine	<0.36	0.36	0.074	mg/kg dry	1	"	"	"	"	
Pentachlorophenol	<0.74	0.74	0.21	mg/kg dry	1	"	"	"	"	
Phenanthrene	<0.36	0.36	0.073	mg/kg dry	1	"	"	"	"	
Phenol	<0.74	0.74	0.15	mg/kg dry	1	"	"	"	"	
Pyrene	<0.36	0.36	0.065	mg/kg dry	1	"	"	"	"	
Surrogate: 2,4,6-Tribromopheno	ol 89.4			53-107 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	69.6			53.9-97.9 %		"	"	"	"	
Surrogate: 2-Fluorophenol	58.0			42.5-94.9 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	67.2			48.9-100 %		"	"	"	"	
Surrogate: Phenol-d6	71.7			50.4-99.6 %					"	
Surrogate: Terphenyl-d14	53.8			51-99.6 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-6_0-2 (1505280-11) Soil Sampled	l: 11/24/15 13	:30 Re	eceived: 11	/25/15 9:30						
1,2,4-Trichlorobenzene	< 0.37	0.37	0.084	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
1,2-Dichlorobenzene	<0.37	0.37	0.075	mg/kg dry	1	"	· ·	II .	"	
1,2-Diphenylhydrazine as Azobenzene	< 0.37	0.37	0.065	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	< 0.37	0.37	0.078	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.37	0.37	0.076	mg/kg dry	1	"	"	"	"	
2,3,4,6-Tetrachlorophenol	< 0.75	0.75	0.21	mg/kg dry	1	"	"	"	"	
2,4,5-Trichlorophenol	<0.75	0.75	0.080	mg/kg dry	1	"	"	"	"	
2,4,6-Trichlorophenol	< 0.75	0.75	0.18	mg/kg dry	1	"	"	"	"	
2,4-Dichlorophenol	< 0.75	0.75	0.17	mg/kg dry	1	"	"	"	"	
2,4-Dimethylphenol	<0.75	0.75	0.15	mg/kg dry	1	"	· ·	II .	"	
2,4-Dinitrophenol	<0.75	0.75	0.080	mg/kg dry	1	"	· ·	II .	"	
2,4-Dinitrotoluene	<0.37	0.37	0.076	mg/kg dry	1	"	· ·	II .	"	
2,6-Dichlorophenol	<0.75	0.75	0.15	mg/kg dry	1	"	· ·	II .	"	
2,6-Dinitrotoluene	< 0.37	0.37	0.087	mg/kg dry	1	"	"	II .	"	
2-Chloronaphthalene	< 0.37	0.37	0.076	mg/kg dry	1	"	"	II .	"	
2-Chlorophenol	<0.75	0.75	0.17	mg/kg dry	1	"	"	II .	"	
2-Methylnaphthalene	< 0.37	0.37	0.090	mg/kg dry	1	"	"	II .	II .	
2-Methylphenol	<0.75	0.75	0.092	mg/kg dry	1	"	"	"	"	
2-Nitroaniline	< 0.37	0.37	0.078	mg/kg dry	1	"	"	"	"	
2-Nitrophenol	<0.75	0.75	0.20	mg/kg dry	1	"	"	"	"	
3&4-Methylphenol	<0.75	0.75	0.092	mg/kg dry	1	"	"	"	"	
3,3´-Dichlorobenzidine	<1.8	1.8	0.51	mg/kg dry	1	"	"	"	"	
3-Nitroaniline	< 0.37	0.37	0.081	mg/kg dry	1	"	"	II .	"	
4,6-Dinitro-2-methylphenol	<0.75	0.75	0.12	mg/kg dry	1	"	"	II .	"	
4-Bromophenyl phenyl ether	<0.37	0.37	0.076	mg/kg dry	1	"	"	"	"	
4-Chloro-3-methylphenol	<0.75	0.75	0.16	mg/kg dry	1	"	"	II .	"	
4-Chloroaniline	<0.75	0.75	0.075	mg/kg dry	1	"	· ·	II .	"	
4-Chlorophenyl phenyl ether	<0.37	0.37	0.076	mg/kg dry	1	"	"	"	"	
4-Nitroaniline	<0.37	0.37	0.093	mg/kg dry	1	"	u u	II .	II .	
4-Nitrophenol	<0.75	0.75	0.19	mg/kg dry	1	"	u u	II .	II .	
Acenaphthene	<0.37	0.37	0.071	mg/kg dry	1	"	u u	II .	II .	
Acenaphthylene	< 0.37	0.37	0.080	mg/kg dry	1	"	"	"	"	
Aniline	<0.75	0.75	0.074	mg/kg dry	1	"	"	п	"	
Anthracene	< 0.37	0.37	0.078	mg/kg dry	1	"	"	п	"	
Benzidine	<2.8	2.8	0.49	mg/kg dry	1	"	"	п	"	
Benzo(a)anthracene	<0.37	0.37	0.073	mg/kg dry	1	"	"	"	"	
Benzo(a)pyrene	<0.37	0.37	0.079	mg/kg dry	1	"	"	"	"	
Benzo(b)fluoranthene	<0.37	0.37	0.066	mg/kg dry	1	"	"	"	"	
Benzo(g,h,i)perylene	< 0.37	0.37	0.080	mg/kg dry	1				"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280

Date Reported: 12/10/15

) C 0 0 (4505000 44) C-:I		RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
3-6_0-2 (1505280-11) 5011	Sampled: 11/24/15 13:	30	Received:	11/25/15 9:30						
Benzo(k)fluoranthene	<0.37	0.37	0.079	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
Benzoic acid	<0.37	0.37	0.072	mg/kg dry	1	"	"	"	"	
Benzyl alcohol	<0.75	0.75	0.17	mg/kg dry	1	"	"	"	"	
Bis(2-chloroethoxy)methane	<0.37	0.37	0.087	mg/kg dry	1	"	"	"	"	
Bis(2-chloroethyl)ether	<0.37	0.37	0.078	mg/kg dry	1	"	"	"	"	
Bis(2-chloroisopropyl)ether	<0.37	0.37	0.088	mg/kg dry	1	"	"	"	"	
Bis(2-ethylhexyl)phthalate	<0.37	0.37	0.091	mg/kg dry	1	"	"	"	"	
Butyl benzyl phthalate	<0.37	0.37	0.093	mg/kg dry	1	"	"	"	"	
Carbazole	<0.37	0.37	0.085	mg/kg dry	1	"	"	"	"	
Chrysene	<0.37	0.37	0.072	mg/kg dry	1	"	"	"	"	
Dibenz(a,h)anthracene	<0.37	0.37	0.092	mg/kg dry	1	"	"	"	"	
Dibenzofuran	<0.37	0.37	0.076	mg/kg dry	1	"	"	"	"	
Diethyl phthalate	<0.37	0.37	0.071	mg/kg dry	1	"	"	"	"	
Dimethyl phthalate	<0.37	0.37	0.078	mg/kg dry	1	"	"	"	"	
Di-n-butyl phthalate	<0.37	0.37	0.089	mg/kg dry	1	"	"	"	"	
Di-n-octyl phthalate	<0.37	0.37	0.11	mg/kg dry	1	"	"	"	"	
Fluoranthene	<0.37	0.37	0.076	mg/kg dry	1	"	"	"	"	
Fluorene	<0.37	0.37	0.073	mg/kg dry	1	"	"	"	"	
Hexachlorobenzene	<0.37	0.37	0.070	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.37	0.37	0.087	mg/kg dry	1	"	"	"	"	
Hexachlorocyclopentadiene	<0.37	0.37	0.078	mg/kg dry	1	"	"	"	"	
Hexachloroethane	<0.37	0.37	0.092	mg/kg dry	1	"	"	"	"	
ndeno (1,2,3-cd) pyrene	<0.37	0.37	0.081	mg/kg dry	1	"	"	"	"	
sophorone	<0.37	0.37	0.085	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.37	0.37	0.080	mg/kg dry	1	"	"	"	"	
Nitrobenzene	<0.37	0.37	0.090	mg/kg dry	1	"	"	"	"	
N-Nitrosodimethylamine	<0.37	0.37	0.079	mg/kg dry	1	"	"	"	"	
N-Nitrosodi-n-propylamine	<0.37	0.37	0.082	mg/kg dry	1	"	"	"	"	
N-Nitrosodiphenylamine	<0.37	0.37	0.075	mg/kg dry	1	"	"	"	"	
Pentachlorophenol	<0.75	0.75	0.21	mg/kg dry	1	"	"	"	"	
Phenanthrene	<0.37	0.37	0.074	mg/kg dry	1	"	"	"	"	
Phenol	<0.75	0.75	0.16	mg/kg dry	1	"	"	"	"	
Pyrene	<0.37	0.37	0.066	mg/kg dry	1	"	"	"	"	
Surrogate: 2,4,6-Tribromopheno.	ol 89.5			53-107 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	70.2			53.9-97.9 %		"	"	"	"	
Surrogate: 2-Fluorophenol	60.5			42.5-94.9 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	67.4			48.9-100 %		"	"	"	"	
Surrogate: Phenol-d6 Surrogate: Terphenyl-d14	72.7 55.1			50.4-99.6 % 51-99.6 %		"	"	"	"	



Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-6_6-8 (1505280-12) Soil Sampled	l: 11/24/15 13	:30 R	eceived: 1	1/25/15 9:30						
1,2,4-Trichlorobenzene	<0.42	0.42	0.095	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
1,2-Dichlorobenzene	<0.42	0.42	0.085	mg/kg dry	1	"	"	"	"	
1,2-Diphenylhydrazine as Azobenzene	<0.42	0.42	0.073	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.42	0.42	0.087	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.42	0.42	0.086	mg/kg dry	1	"	n .	"	"	
2,3,4,6-Tetrachlorophenol	<0.85	0.85	0.24	mg/kg dry	1	"	n .	"	"	
2,4,5-Trichlorophenol	<0.85	0.85	0.090	mg/kg dry	1	"	"	"	"	
2,4,6-Trichlorophenol	<0.85	0.85	0.20	mg/kg dry	1	"	n .	"	"	
2,4-Dichlorophenol	<0.85	0.85	0.19	mg/kg dry	1	"	II .	"	·	
2,4-Dimethylphenol	<0.85	0.85	0.16	mg/kg dry	1	"	n .	"	"	
2,4-Dinitrophenol	<0.85	0.85	0.090	mg/kg dry	1	"	n .	"	"	
2,4-Dinitrotoluene	<0.42	0.42	0.086	mg/kg dry	1	"	n .	"	"	
2,6-Dichlorophenol	<0.85	0.85	0.16	mg/kg dry	1	"	"	"	"	
2,6-Dinitrotoluene	<0.42	0.42	0.097	mg/kg dry	1	"	n .	"	"	
2-Chloronaphthalene	<0.42	0.42	0.086	mg/kg dry	1	"	"	"	"	
2-Chlorophenol	<0.85	0.85	0.19	mg/kg dry	1	"	"	"	"	
2-Methylnaphthalene	<0.42	0.42	0.10	mg/kg dry	1	"	"	"	"	
2-Methylphenol	<0.85	0.85	0.10	mg/kg dry	1	"	"	"	·	
2-Nitroaniline	<0.42	0.42	0.087	mg/kg dry	1	"	"	"	"	
2-Nitrophenol	<0.85	0.85	0.23	mg/kg dry	1	"	"	"	·	
3&4-Methylphenol	<0.85	0.85	0.10	mg/kg dry	1	n n	n .	"	"	
3,3´-Dichlorobenzidine	<2.0	2.0	0.57	mg/kg dry	1	"	n .	"	·	
3-Nitroaniline	<0.42	0.42	0.091	mg/kg dry	1	"	"	"	"	
4,6-Dinitro-2-methylphenol	<0.85	0.85	0.14	mg/kg dry	1	"	"	"	"	
4-Bromophenyl phenyl ether	<0.42	0.42	0.086	mg/kg dry	1	"	"	"	"	
4-Chloro-3-methylphenol	<0.85	0.85	0.18	mg/kg dry	1	"	"	"	"	
4-Chloroaniline	<0.85	0.85	0.085	mg/kg dry	1	"	"	"	"	
4-Chlorophenyl phenyl ether	< 0.42	0.42	0.086	mg/kg dry	1	"	"	"	"	
4-Nitroaniline	<0.42	0.42	0.11	mg/kg dry	1	"	"	"	"	
4-Nitrophenol	<0.85	0.85	0.22	mg/kg dry	1	"	"	"	"	
Acenaphthene	<0.42	0.42	0.080	mg/kg dry	1	"	"	"	"	
Acenaphthylene	< 0.42	0.42	0.090	mg/kg dry	1	"	"	"	"	
Aniline	<0.85	0.85	0.084	mg/kg dry	1	"	"	"	"	
Anthracene	< 0.42	0.42	0.087	mg/kg dry	1	"	"	"	"	
Benzidine	<3.2	3.2	0.56	mg/kg dry	1	"	"	"	"	
Benzo(a)anthracene	<0.42	0.42	0.082	mg/kg dry	1	"	"	"	"	
Benzo(a)pyrene	<0.42	0.42	0.089	mg/kg dry	1	"	n .	"	"	
Benzo(b)fluoranthene	<0.42	0.42	0.075	mg/kg dry	1	"	n .	"	·	
Benzo(g,h,i)perylene	< 0.42	0.42	0.090	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-6_6-8 (1505280-12) Soil	Sampled: 11/24/15 13	:30 R	eceived: 1	1/25/15 9:30						
Benzo(k)fluoranthene	<0.42	0.42	0.089	mg/kg dry	1	B5K3002	11/30/15	12/01/15	EPA 8270D	
Benzoic acid	<0.42	0.42	0.081	mg/kg dry	1	"	"	"	"	
Benzyl alcohol	<0.85	0.85	0.19	mg/kg dry	1	"	"	u u	"	
Bis(2-chloroethoxy)methane	<0.42	0.42	0.097	mg/kg dry	1	"	u u	II .	II .	
Bis(2-chloroethyl)ether	<0.42	0.42	0.087	mg/kg dry	1	"	u u	II .	II .	
Bis(2-chloroisopropyl)ether	<0.42	0.42	0.099	mg/kg dry	1	n .	· ·	II .	"	
Bis(2-ethylhexyl)phthalate	<0.42	0.42	0.10	mg/kg dry	1	"	"	u u	"	
Butyl benzyl phthalate	<0.42	0.42	0.11	mg/kg dry	1	"	u u	II .	II .	
Carbazole	<0.42	0.42	0.096	mg/kg dry	1	n .	· ·	II .	"	
Chrysene	<0.42	0.42	0.081	mg/kg dry	1	"	"	"	"	
Dibenz(a,h)anthracene	< 0.42	0.42	0.10	mg/kg dry	1	"	"	"	"	
Dibenzofuran	<0.42	0.42	0.086	mg/kg dry	1	"	"	"	"	
Diethyl phthalate	<0.42	0.42	0.080	mg/kg dry	1	"	"	"	"	
Dimethyl phthalate	<0.42	0.42	0.087	mg/kg dry	1	"	"	"	"	
Di-n-butyl phthalate	<0.42	0.42	0.10	mg/kg dry	1	"	"	"	"	
Di-n-octyl phthalate	<0.42	0.42	0.13	mg/kg dry	1	"	"	"	"	
Fluoranthene	<0.42	0.42	0.086	mg/kg dry	1	"	"	"	"	
Fluorene	<0.42	0.42	0.082	mg/kg dry	1	"	"	m m	"	
Hexachlorobenzene	<0.42	0.42	0.078	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.42	0.42	0.097	mg/kg dry	1	"	"	"	"	
Hexachlorocyclopentadiene	<0.42	0.42	0.087	mg/kg dry	1	"	"	"	"	
Hexachloroethane	<0.42	0.42	0.10	mg/kg dry	1	"	"	n n	"	
Indeno (1,2,3-cd) pyrene	<0.42	0.42	0.091	mg/kg dry	1	"	"	"	"	
Isophorone	<0.42	0.42	0.096	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.42	0.42	0.090	mg/kg dry	1	"	"	"	"	
Nitrobenzene	<0.42	0.42	0.10	mg/kg dry	1	"	"	"	"	
N-Nitrosodimethylamine	<0.42	0.42	0.089	mg/kg dry	1	"	"	"	"	
N-Nitrosodi-n-propylamine	<0.42	0.42	0.092	mg/kg dry	1	"	"	"	"	
N-Nitrosodiphenylamine	<0.42	0.42	0.085	mg/kg dry	1	"	"	n n	"	
Pentachlorophenol	<0.85	0.85	0.24	mg/kg dry	1	n n	"	n	m .	
Phenanthrene	<0.42	0.42	0.084	mg/kg dry	1	n n	"	n	m .	
Phenol	<0.85	0.85	0.18	mg/kg dry	1	"	"	"	"	
Pyrene	<0.42	0.42	0.075	mg/kg dry	1	"	"	"	"	
Surrogate: 2,4,6-Tribromopheno				53-107 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	56.4			53.9-97.9 %		"	"	"	"	
Surrogate: 2-Fluorophenol	53.5			42.5-94.9 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	60.6			48.9-100 %		"	"	"	"	
Surrogate: Phenol-d6	68.3			50.4-99.6 %		"	"	"	"	
Surrogate: Terphenyl-d14	60.9			51-99.6 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-12 (1505280-01) Soil	Sampled: 11/23/15	17:15	Received:	11/25/15 9:3	30					
1,1,1,2-Tetrachloroethane	<0.27	0.27	0.027	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,1,1-Trichloroethane	<0.27	0.27	0.031	mg/kg dry	1	"	"	"	"	
1,1,2,2-Tetrachloroethane	<0.27	0.27	0.022	mg/kg dry	1	"	"	"	"	
1,1,2-Trichloroethane	<0.27	0.27	0.019	mg/kg dry	1	"	"	u u	"	
1,1,2-Trichlorotrifluoroethane	<0.27	0.27	0.027	mg/kg dry	1	"	u u	II .	"	T5
1,1-Dichloroethane	<0.27	0.27	0.013	mg/kg dry	1	"	"	u u	"	
1,1-Dichloroethene	<0.27	0.27	0.018	mg/kg dry	1	"	"	"	"	
1,1-Dichloropropene	<0.27	0.27	0.020	mg/kg dry	1	"	"	u u	"	
1,2,3-Trichlorobenzene	<0.68	0.68	0.13	mg/kg dry	1	"	"	u u	"	
1,2,3-Trichloropropane	<0.27	0.27	0.041	mg/kg dry	1	"	"	"	"	
1,2,4-Trichlorobenzene	<0.68	0.68	0.096	mg/kg dry	1	"	"	"	"	
1,2,4-Trimethylbenzene	<0.27	0.27	0.024	mg/kg dry	1	"	"	"	"	
1,2-Dibromo-3-chloropropane	<0.68	0.68	0.062	mg/kg dry	1	"	"	"	"	
1,2-Dibromoethane (EDB)	<0.27	0.27	0.032	mg/kg dry	1	"	"	"		
1,2-Dichlorobenzene	<0.27	0.27	0.018	mg/kg dry	1	"	"	"		
1,2-Dichloroethane	<0.27	0.27	0.030	mg/kg dry	1	"	"	"		
1,2-Dichloropropane	<0.27	0.27	0.028	mg/kg dry	1	"	"	"		
1,3,5-Trimethylbenzene	<0.27	0.27	0.034	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.27	0.27	0.012	mg/kg dry	1	"	"	"		
1,3-Dichloropropane	<0.27	0.27	0.020	mg/kg dry	1	"	"	"		
1,4-Dichlorobenzene	<0.27	0.27	0.022	mg/kg dry	1	"	"	"		
2,2-Dichloropropane	<0.27	0.27	0.070	mg/kg dry	1	"	"	"		
2-Butanone	<1.4	1.4	0.13	mg/kg dry	1	"	"	"		
2-Chlorotoluene	<0.27	0.27	0.027	mg/kg dry	1	"	"	"	"	
4-Chlorotoluene	<0.27	0.27	0.030	mg/kg dry	1	"	"	"		
Acetone	<1.4	1.4	0.16	mg/kg dry	1	"	"	"		
Allyl chloride	<0.27	0.27	0.034	mg/kg dry	1	"	"	"		
Benzene	<0.27	0.27	0.020	mg/kg dry	1	"	"	"	"	
Bromobenzene	<0.27	0.27	0.027	mg/kg dry	1	"	"	"	"	
Bromochloromethane	<0.27	0.27	0.031	mg/kg dry	1	"	"	"	"	
Bromodichloromethane	<0.27	0.27	0.026	mg/kg dry	1	"	"	"	"	
Bromoform	<0.27	0.27	0.049	mg/kg dry	1	"	"	n n		
Bromomethane	<0.27	0.27	0.041	mg/kg dry	1	"	"	n n		
Carbon tetrachloride	<0.27	0.27	0.034	mg/kg dry	1	n n	"	n	"	
Chlorobenzene	<0.27	0.27	0.019	mg/kg dry	1	"	"	"		
Chloroethane	<0.27	0.27	0.041	mg/kg dry	1	"	"	"		
Chloroform	<0.27	0.27	0.042	mg/kg dry	1	"	"	"	"	
Chloromethane	<0.27	0.27	0.036	mg/kg dry	1	"	"	"	"	
cis-1,2-Dichloroethene	<0.27	0.27	0.016	mg/kg dry	1	"	"	"	"	
	- ·-			5 5 7						



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-12 (1505280-01) Soil	Sampled: 11/23/15	17:15	Received	11/25/15 9:3	30					•
cis-1,3-Dichloropropene	<0.27	0.27	0.034	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
Dibromochloromethane	<0.27	0.27	0.034	mg/kg dry	1	"	"	II .	п	
Dibromomethane	<0.27	0.27	0.034	mg/kg dry	1	"	"	"	II .	
Dichlorodifluoromethane	<0.27	0.27	0.050	mg/kg dry	1	"	"	"	"	
Dichlorofluoromethane	<0.27	0.27	0.014	mg/kg dry	1	"	"	"	"	T5
Ethyl ether	<0.27	0.27	0.032	mg/kg dry	1	"	"	"	"	
Ethylbenzene	<0.27	0.27	0.028	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.68	0.68	0.11	mg/kg dry	1	"	"	"	"	
Isopropylbenzene	<0.27	0.27	0.041	mg/kg dry	1	"	"	"	"	
m,p-Xylene	<0.54	0.54	0.065	mg/kg dry	1	"	"	"	"	
Methyl isobutyl ketone	<0.27	0.27	0.058	mg/kg dry	1	"	"	"	"	
Methyl tert-butyl ether	<0.27	0.27	0.013	mg/kg dry	1	"	"	"	"	
Methylene chloride	<0.68	0.68	0.081	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.68	0.68	0.065	mg/kg dry	1	"	"	"	"	
n-Butylbenzene	<0.27	0.27	0.022	mg/kg dry	1	"	"	· ·	II .	
n-Propylbenzene	<0.27	0.27	0.014	mg/kg dry	1	"	"	II .	"	
o-Xylene	<0.27	0.27	0.023	mg/kg dry	1	"	II .	II .	II .	
p-Isopropyltoluene	<0.27	0.27	0.015	mg/kg dry	1	"	"	II .	II .	
sec-Butylbenzene	<0.27	0.27	0.030	mg/kg dry	1	"	"	II .	II .	
Styrene	<0.27	0.27	0.022	mg/kg dry	1	"	"	"	"	
tert-Butylbenzene	<0.27	0.27	0.035	mg/kg dry	1	"	"	"	"	
Tetrachloroethene	<0.27	0.27	0.051	mg/kg dry	1	"	"	"	"	
Tetrahydrofuran	<1.4	1.4	0.15	mg/kg dry	1	"	"	"	"	T5
Toluene	<0.27	0.27	0.0092	mg/kg dry	1	"	"	"	"	
trans-1,2-Dichloroethene	<0.27	0.27	0.024	mg/kg dry	1	"	"	"	"	
trans-1,3-Dichloropropene	<0.27	0.27	0.027	mg/kg dry	1	"	"	"	"	
Trichloroethene	<0.27	0.27	0.024	mg/kg dry	1	"	"	"	"	
Trichlorofluoromethane	<0.27	0.27	0.039	mg/kg dry	1	"	"	"	"	
Vinyl chloride	<0.27	0.27	0.028	mg/kg dry	1	"	"	"	"	
Surrogate: 4-Bromofluorobenzene	88.5			80-124 %		"	"	"	"	
Surrogate: Dibromofluoromethane				77.1-123 %		"	"	"	"	
Surrogate: Toluene-d8	95.3			78.1-125 %		"	"		"	
B-1_16-18 (1505280-02) Soil	Sampled: 11/23/15	17:15	Received	11/25/15 9:3	30					
1,1,1,2-Tetrachloroethane	<0.26	0.26	0.026	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,1,1-Trichloroethane	<0.26	0.26	0.030	mg/kg dry	1	"	"	II .	"	
1,1,2,2-Tetrachloroethane	<0.26	0.26	0.021	mg/kg dry	1	"	"	"	"	
1,1,2-Trichloroethane	<0.26	0.26	0.018	mg/kg dry	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<0.26	0.26	0.026	mg/kg dry	1	"	"	"	"	T5
1,1-Dichloroethane	<0.26	0.26	0.013	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_16-18 (1505280-02) Soil	Sampled: 11/23/15	17:15	Received:	11/25/15 9:	30					
1,1-Dichloroethene	<0.26	0.26	0.017	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,1-Dichloropropene	<0.26	0.26	0.019	mg/kg dry	1	"	"	"	"	
1,2,3-Trichlorobenzene	<0.65	0.65	0.13	mg/kg dry	1	"	"	"	"	
1,2,3-Trichloropropane	<0.26	0.26	0.039	mg/kg dry	1	"	n .	m .	"	
1,2,4-Trichlorobenzene	<0.65	0.65	0.092	mg/kg dry	1	"	"	"	"	
1,2,4-Trimethylbenzene	<0.26	0.26	0.023	mg/kg dry	1	"	"	"	"	
1,2-Dibromo-3-chloropropane	<0.65	0.65	0.060	mg/kg dry	1	"	n .	"	"	
1,2-Dibromoethane (EDB)	<0.26	0.26	0.031	mg/kg dry	1	"	"	"	"	
1,2-Dichlorobenzene	<0.26	0.26	0.017	mg/kg dry	1	"	"	"	"	
1,2-Dichloroethane	<0.26	0.26	0.029	mg/kg dry	1	"	"	"	"	
1,2-Dichloropropane	<0.26	0.26	0.027	mg/kg dry	1	"	"	"	"	
1,3,5-Trimethylbenzene	<0.26	0.26	0.032	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.26	0.26	0.012	mg/kg dry	1	"	"	"	"	
1,3-Dichloropropane	<0.26	0.26	0.019	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.26	0.26	0.021	mg/kg dry	1	"	"	"	"	
2,2-Dichloropropane	<0.26	0.26	0.068	mg/kg dry	1	"	"	"	"	
2-Butanone	<1.3	1.3	0.12	mg/kg dry	1	"	"	"	"	
2-Chlorotoluene	<0.26	0.26	0.026	mg/kg dry	1	"	"	"	"	
4-Chlorotoluene	<0.26	0.26	0.029	mg/kg dry	1	"	"	"	"	
Acetone	<1.3	1.3	0.16	mg/kg dry	1	"	"	"	"	
Allyl chloride	<0.26	0.26	0.032	mg/kg dry	1	"	"	"	"	
Benzene	<0.26	0.26	0.019	mg/kg dry	1	"	"	"	"	
Bromobenzene	<0.26	0.26	0.026	mg/kg dry	1	"	"	"	"	
Bromochloromethane	<0.26	0.26	0.030	mg/kg dry	1	"	"	"	"	
Bromodichloromethane	<0.26	0.26	0.025	mg/kg dry	1	"	"	"	"	
Bromoform	<0.26	0.26	0.047	mg/kg dry	1	"	"	"	"	
Bromomethane	<0.26	0.26	0.039	mg/kg dry	1	"	"	"	"	
Carbon tetrachloride	<0.26	0.26	0.032	mg/kg dry	1	"	"	"	"	
Chlorobenzene	<0.26	0.26	0.018	mg/kg dry	1	"	"	"	"	
Chloroethane	<0.26	0.26	0.039	mg/kg dry	1	"	"	"	"	
Chloroform	<0.26	0.26	0.040	mg/kg dry	1	"	"	"	"	
Chloromethane	<0.26	0.26	0.035	mg/kg dry	1	"	"	"	"	
cis-1,2-Dichloroethene	<0.26	0.26	0.016	mg/kg dry	1	"	"	"	"	
cis-1,3-Dichloropropene	<0.26	0.26	0.032	mg/kg dry	1	"	"	"	"	
Dibromochloromethane	<0.26	0.26	0.032	mg/kg dry	1	"	"	"	"	
Dibromomethane	<0.26	0.26	0.032	mg/kg dry	1	"	"	"	"	
Dichlorodifluoromethane	<0.26	0.26	0.048	mg/kg dry	1	"	II .	"	"	
Dichlorofluoromethane	<0.26	0.26	0.013	mg/kg dry	1	"	"	"	"	T5
Ethyl ether	<0.26	0.26	0.031	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_16-18 (1505280-02) Soil	Sampled: 11/23/15	17:15	Received:	11/25/15 9:3	30					
Ethylbenzene	<0.26	0.26	0.027	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
Hexachlorobutadiene	<0.65	0.65	0.10	mg/kg dry	1	"	"	"	"	
Isopropylbenzene	<0.26	0.26	0.039	mg/kg dry	1	"	"	"	"	
m,p-Xylene	<0.52	0.52	0.062	mg/kg dry	1	"	"	"	"	
Methyl isobutyl ketone	<0.26	0.26	0.056	mg/kg dry	1	"	"	"	"	
Methyl tert-butyl ether	<0.26	0.26	0.013	mg/kg dry	1	"	"	"	"	
Methylene chloride	<0.65	0.65	0.078	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.65	0.65	0.062	mg/kg dry	1	"	"	"	"	
n-Butylbenzene	<0.26	0.26	0.021	mg/kg dry	1	"	"	"	"	
n-Propylbenzene	<0.26	0.26	0.013	mg/kg dry	1	"	"	"	"	
o-Xylene	<0.26	0.26	0.022	mg/kg dry	1	"	"	"	"	
p-Isopropyltoluene	<0.26	0.26	0.014	mg/kg dry	1	"	"	"	"	
sec-Butylbenzene	<0.26	0.26	0.029	mg/kg dry	1	"	"	"	"	
Styrene	<0.26	0.26	0.021	mg/kg dry	1	"	"	"	"	
tert-Butylbenzene	<0.26	0.26	0.034	mg/kg dry	1	"	"	"	"	
Tetrachloroethene	<0.26	0.26	0.049	mg/kg dry	1	"	"	"	"	
Tetrahydrofuran	<1.3	1.3	0.14	mg/kg dry	1	"	"	"	"	T5
Toluene	<0.26	0.26	0.0088	mg/kg dry	1	"	"	"	"	
trans-1,2-Dichloroethene	<0.26	0.26	0.023	mg/kg dry	1	"	"	"	"	
trans-1,3-Dichloropropene	<0.26	0.26	0.026	mg/kg dry	1	"	"	"	"	
Trichloroethene	<0.26	0.26	0.023	mg/kg dry	1	"	"	"	"	
Trichlorofluoromethane	<0.26	0.26	0.038	mg/kg dry	1	"	"	"	"	
Vinyl chloride	<0.26	0.26	0.027	mg/kg dry	1	"	"	"	"	
Surrogate: 4-Bromofluorobenzene	89.4			80-124 %		"	"	"	"	
Surrogate: Dibromofluoromethane	97.3			77.1-123 %		"	"	"	"	
Surrogate: Toluene-d8	94.6			78.1-125 %		"	"	"	"	
B-2a_2-4 (1505280-03) Soil	Sampled: 11/24/15 1	0:00	Received:	11/25/15 9:30)					
1,1,1,2-Tetrachloroethane	<0.24	0.24	0.024	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,1,1-Trichloroethane	<0.24	0.24	0.028	mg/kg dry	1	"	"	II .	"	
1,1,2,2-Tetrachloroethane	<0.24	0.24	0.019	mg/kg dry	1	"	"	"	"	
1,1,2-Trichloroethane	<0.24	0.24	0.017	mg/kg dry	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<0.24	0.24	0.024	mg/kg dry	1	"	"	"	"	T5
1,1-Dichloroethane	<0.24	0.24	0.012	mg/kg dry	1	"	"	"	"	
1,1-Dichloroethene	<0.24	0.24	0.016	mg/kg dry	1	"	· ·	II .	"	
1,1-Dichloropropene	<0.24	0.24	0.018	mg/kg dry	1	"	· ·	II .	"	
1,2,3-Trichlorobenzene	<0.60	0.60	0.12	mg/kg dry	1	"	· ·	II .	"	
1,2,3-Trichloropropane	<0.24	0.24	0.036	mg/kg dry	1	"	"	II .	"	
1,2,4-Trichlorobenzene	<0.60	0.60	0.086	mg/kg dry	1	"	"	"	"	
1,2,4-Trimethylbenzene	<0.24	0.24	0.022	mg/kg dry	1	"	"		"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-2a_2-4 (1505280-03) Soil	Sampled: 11/24/15 1	0:00	Received: 1	11/25/15 9:30)					
1,2-Dibromo-3-chloropropane	<0.60	0.60	0.055	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,2-Dibromoethane (EDB)	<0.24	0.24	0.029	mg/kg dry	1	"	"	"	"	
1,2-Dichlorobenzene	<0.24	0.24	0.016	mg/kg dry	1	"	"	"	u .	
1,2-Dichloroethane	<0.24	0.24	0.027	mg/kg dry	1	"	"	"	n .	
1,2-Dichloropropane	<0.24	0.24	0.025	mg/kg dry	1	"	"	"	"	
1,3,5-Trimethylbenzene	<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.24	0.24	0.011	mg/kg dry	1	"	"	"	"	
1,3-Dichloropropane	<0.24	0.24	0.018	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.24	0.24	0.019	mg/kg dry	1	"	"	"	"	
2,2-Dichloropropane	<0.24	0.24	0.063	mg/kg dry	1	"	"	"	"	
2-Butanone	<1.2	1.2	0.11	mg/kg dry	1	"	"	"	"	
2-Chlorotoluene	<0.24	0.24	0.024	mg/kg dry	1	"	"	"	"	
4-Chlorotoluene	<0.24	0.24	0.027	mg/kg dry	1	"	"	"	"	
Acetone	<1.2	1.2	0.14	mg/kg dry	1	"	"	"	"	
Allyl chloride	<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	
Benzene	<0.24	0.24	0.018	mg/kg dry	1	"	"	"	"	
Bromobenzene	<0.24	0.24	0.024	mg/kg dry	1	"	"	II .	II .	
Bromochloromethane	<0.24	0.24	0.028	mg/kg dry	1	"	"	"	"	
Bromodichloromethane	<0.24	0.24	0.023	mg/kg dry	1	"	"	II .	II .	
Bromoform	<0.24	0.24	0.043	mg/kg dry	1	"	"	II .	II .	
Bromomethane	<0.24	0.24	0.036	mg/kg dry	1	"	"	"	u u	
Carbon tetrachloride	<0.24	0.24	0.030	mg/kg dry	1	"	"	II .	II .	
Chlorobenzene	<0.24	0.24	0.017	mg/kg dry	1	"	m .	m .	II .	
Chloroethane	<0.24	0.24	0.036	mg/kg dry	1	"	"	"	"	
Chloroform	<0.24	0.24	0.037	mg/kg dry	1	"	"	"	"	
Chloromethane	<0.24	0.24	0.033	mg/kg dry	1	"	"	"	"	
cis-1,2-Dichloroethene	<0.24	0.24	0.014	mg/kg dry	1	"	"	"	"	
cis-1,3-Dichloropropene	<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	
Dibromochloromethane	<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	
Dibromomethane	<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	
Dichlorodifluoromethane	<0.24	0.24	0.045	mg/kg dry	1	"	"	"	"	
Dichlorofluoromethane	<0.24	0.24	0.012	mg/kg dry	1	"	"	"	II .	T5
Ethyl ether	<0.24	0.24	0.029	mg/kg dry	1	"	"	"	"	
Ethylbenzene	<0.24	0.24	0.025	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.60	0.60	0.095	mg/kg dry	1	"	"	"	"	
Isopropylbenzene	<0.24	0.24	0.036	mg/kg dry	1	"	"	"	"	
m,p-Xylene	<0.48	0.48	0.058	mg/kg dry	1	"	"	"	"	
Methyl isobutyl ketone	<0.24	0.24	0.052	mg/kg dry	1	"	"	"	"	
Methyl tert-butyl ether	<0.24	0.24	0.012	mg/kg dry	1	"	"	"	"	

Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-2a_2-4 (1505280-03) Soil Sa	mpled: 11/24/15 10	0:00	Received:	11/25/15 9:30)					
Methylene chloride	<0.60	0.60	0.072	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
Naphthalene	<0.60	0.60	0.058	mg/kg dry	1	"	"	"	II .	
n-Butylbenzene	<0.24	0.24	0.019	mg/kg dry	1	"	u u	u u	п	
n-Propylbenzene	<0.24	0.24	0.012	mg/kg dry	1	"	· ·	· ·	"	
o-Xylene	<0.24	0.24	0.020	mg/kg dry	1	"	"	"	"	
p-Isopropyltoluene	<0.24	0.24	0.013	mg/kg dry	1	"	"	"	"	
sec-Butylbenzene	<0.24	0.24	0.027	mg/kg dry	1	"	"	"	"	
Styrene	<0.24	0.24	0.019	mg/kg dry	1	"	"	"	"	
tert-Butylbenzene	<0.24	0.24	0.031	mg/kg dry	1	"	"	"	"	
Tetrachloroethene	<0.24	0.24	0.046	mg/kg dry	1	"	"	"	"	
Tetrahydrofuran	<1.2	1.2	0.13	mg/kg dry	1	"	"	"	"	T5
Toluene	<0.24	0.24	0.0082	mg/kg dry	1	"	"	"	"	
trans-1,2-Dichloroethene	<0.24	0.24	0.022	mg/kg dry	1	"	"	"	"	
trans-1,3-Dichloropropene	<0.24	0.24	0.024	mg/kg dry	1	"	"	"	"	
Trichloroethene	<0.24	0.24	0.022	mg/kg dry	1	"	"	"	"	
Trichlorofluoromethane	<0.24	0.24	0.035	mg/kg dry	1	"	"	"	"	
Vinyl chloride	<0.24	0.24	0.025	mg/kg dry	1	"	"	"	n n	
Surrogate: 4-Bromofluorobenzene	89.9			80-124 %		"	"	"	"	
Surrogate: Dibromofluoromethane	96.9			77.1-123 %		"	"	"	"	
Surrogate: Toluene-d8	95.6			78.1-125 %		"	"	"	"	
B-2a_4-6 (1505280-04) Soil Sa	mpled: 11/24/15 10):00	Received:	11/25/15 9:30)					
1,1,1,2-Tetrachloroethane	<0.24	0.24	0.024	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,1,1-Trichloroethane	<0.24	0.24	0.028	mg/kg dry	1	"	"	"	"	
1,1,2,2-Tetrachloroethane	<0.24	0.24	0.019	mg/kg dry	1	"	"	"	II	
1,1,2-Trichloroethane	<0.24	0.24	0.017	mg/kg dry	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<0.24	0.24	0.024	mg/kg dry	1	"	"	"	II	T5
1,1-Dichloroethane	<0.24	0.24	0.012	mg/kg dry	1	"	"	"	II .	
1,1-Dichloroethene	<0.24	0.24	0.016	mg/kg dry	1	"	"	"	"	
1,1-Dichloropropene	<0.24	0.24	0.018	mg/kg dry	1	"	"	"	"	
1,2,3-Trichlorobenzene	<0.60	0.60	0.12	mg/kg dry	1	"	"	"	"	
1,2,3-Trichloropropane	<0.24	0.24	0.036	mg/kg dry	1	"	"	"	"	
1,2,4-Trichlorobenzene	<0.60	0.60	0.086	mg/kg dry	1	"	"	"	"	
1,2,4-Trimethylbenzene	<0.24	0.24	0.022	mg/kg dry	1	"	"	"	"	
1,2-Dibromo-3-chloropropane	<0.60	0.60	0.055	mg/kg dry	1	"	· ·	II .	II .	
1,2-Dibromoethane (EDB)	<0.24	0.24	0.029	mg/kg dry	1	"	· ·	II .	II .	
	<0.24	0.24	0.016	mg/kg dry	1	"	"	"	II .	
1,2-Dichlorobenzene										
1,2-Dichlorobenzene 1,2-Dichloroethane	<0.24	0.24	0.027	mg/kg dry	1					
•	<0.24 <0.24	0.24 0.24	0.027 0.025	mg/kg dry mg/kg dry	1 1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co.Project:345110104300 MarketPointe Drive, Suite 200Project Number:34511010Minneapolis, MN 55435Project Manager:Ms. Andrea Nord

Work Order #: 1505280

Date Reported: 12/10/15

Analyte		Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-2a_4-6 (1505280-04) Soil	Sampled:	11/24/15 1	0:00	Received: 1	11/25/15 9:30)					
1,3-Dichlorobenzene		<0.24	0.24	0.011	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,3-Dichloropropane		<0.24	0.24	0.018	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene		<0.24	0.24	0.019	mg/kg dry	1	"	"	"	"	
2,2-Dichloropropane		<0.24	0.24	0.063	mg/kg dry	1	"	"	u u	II .	
2-Butanone		<1.2	1.2	0.11	mg/kg dry	1	"	"	u u	II .	
2-Chlorotoluene		<0.24	0.24	0.024	mg/kg dry	1	"	II .	u u	"	
4-Chlorotoluene		<0.24	0.24	0.027	mg/kg dry	1	"	"	u u	II .	
Acetone		<1.2	1.2	0.14	mg/kg dry	1	"	"	"	"	
Allyl chloride		<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	
Benzene		<0.24	0.24	0.018	mg/kg dry	1	"	"	u u	II .	
Bromobenzene		<0.24	0.24	0.024	mg/kg dry	1	"	n .	m .	"	
Bromochloromethane		<0.24	0.24	0.028	mg/kg dry	1	"	n .	"	"	
Bromodichloromethane		<0.24	0.24	0.023	mg/kg dry	1	"	"	"	"	
Bromoform		<0.24	0.24	0.043	mg/kg dry	1	"	n .	"	"	
Bromomethane		<0.24	0.24	0.036	mg/kg dry	1	"	"	"	"	
Carbon tetrachloride		<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	
Chlorobenzene		<0.24	0.24	0.017	mg/kg dry	1	"	"	"	"	
Chloroethane		<0.24	0.24	0.036	mg/kg dry	1	"	"	"	"	
Chloroform		<0.24	0.24	0.037	mg/kg dry	1	"	"	"	"	
Chloromethane		<0.24	0.24	0.033	mg/kg dry	1	"	"	"	"	
cis-1,2-Dichloroethene		<0.24	0.24	0.014	mg/kg dry	1	"	"	"	"	
cis-1,3-Dichloropropene		<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	
Dibromochloromethane		<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	
Dibromomethane		<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	
Dichlorodifluoromethane		<0.24	0.24	0.045	mg/kg dry	1	"	"	"	"	
Dichlorofluoromethane		<0.24	0.24	0.012	mg/kg dry	1	"	"	"	"	T5
Ethyl ether		<0.24	0.24	0.029	mg/kg dry	1	"	"	"	"	
Ethylbenzene		<0.24	0.24	0.025	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene		<0.60	0.60	0.095	mg/kg dry	1	"	"	"	"	
Isopropylbenzene		<0.24	0.24	0.036	mg/kg dry	1	"	"	"	"	
m,p-Xylene		<0.48	0.48	0.058	mg/kg dry	1	"	"	"	"	
Methyl isobutyl ketone		<0.24	0.24	0.052	mg/kg dry	1	"	"	"	"	
Methyl tert-butyl ether		<0.24	0.24	0.012	mg/kg dry	1	"	"	"	"	
Methylene chloride		<0.60	0.60	0.072	mg/kg dry	1	"	"	"	"	
Naphthalene		<0.60	0.60	0.058	mg/kg dry	1	"	"	"	"	
n-Butylbenzene		<0.24	0.24	0.019	mg/kg dry	1	"	"	"	"	
n-Propylbenzene		<0.24	0.24	0.012	mg/kg dry	1	"	"	"	"	
o-Xylene		<0.24	0.24	0.020	mg/kg dry	1	"	"	"	"	
p-Isopropyltoluene		<0.24	0.24	0.013	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280

Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-2a_4-6 (1505280-04) Soil Samp	oled: 11/24/15 1	0:00	Received:	11/25/15 9:30)					
sec-Butylbenzene	<0.24	0.24	0.027	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
Styrene	<0.24	0.24	0.019	mg/kg dry	1	"	"	"	II .	
tert-Butylbenzene	<0.24	0.24	0.031	mg/kg dry	1	"	"	"	ı	
Tetrachloroethene	<0.24	0.24	0.046	mg/kg dry	1	"	"	"	ı	
Tetrahydrofuran	<1.2	1.2	0.13	mg/kg dry	1	"	"	"	"	T5
Toluene	<0.24	0.24	0.0082	mg/kg dry	1	"	"	"	"	
trans-1,2-Dichloroethene	<0.24	0.24	0.022	mg/kg dry	1	"	"	"	"	
trans-1,3-Dichloropropene	<0.24	0.24	0.024	mg/kg dry	1	"	"	"	"	
Trichloroethene	<0.24	0.24	0.022	mg/kg dry	1	"	"	"	"	
Trichlorofluoromethane	<0.24	0.24	0.035	mg/kg dry	1	"	"	"	ı	
Vinyl chloride	<0.24	0.24	0.025	mg/kg dry	1	"	n n	n .	II .	
Surrogate: 4-Bromofluorobenzene	88.7			80-124 %		"	"	"	"	
Surrogate: Dibromofluoromethane	97.0			77.1-123 %		"	"	"	"	
Surrogate: Toluene-d8	96.6			78.1-125 %		"	"	"	"	
B-3_6-8 (1505280-05) Soil Sample	ed: 11/24/15 11	:00 I	Received: 11	/25/15 9:30						
1,1,1,2-Tetrachloroethane	<0.26	0.26	0.026	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,1,1-Trichloroethane	<0.26	0.26	0.030	mg/kg dry	1	"	"	"	II .	
1,1,2,2-Tetrachloroethane	<0.26	0.26	0.021	mg/kg dry	1	"	"	u u	"	
1,1,2-Trichloroethane	<0.26	0.26	0.018	mg/kg dry	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<0.26	0.26	0.026	mg/kg dry	1	"	"	"	"	T5
1,1-Dichloroethane	<0.26	0.26	0.013	mg/kg dry	1	"	"	"	"	
1,1-Dichloroethene	<0.26	0.26	0.017	mg/kg dry	1	"	"	"	"	
1,1-Dichloropropene	<0.26	0.26	0.019	mg/kg dry	1	"	"	"	"	
1,2,3-Trichlorobenzene	<0.65	0.65	0.13	mg/kg dry	1	"	"	"	"	
1,2,3-Trichloropropane	<0.26	0.26	0.039	mg/kg dry	1	"	"	"	"	
1,2,4-Trichlorobenzene	<0.65	0.65	0.092	mg/kg dry	1	"	"	"	"	
1,2,4-Trimethylbenzene	<0.26	0.26	0.023	mg/kg dry	1	n .	II .	II .	"	
1,2-Dibromo-3-chloropropane	<0.65	0.65	0.060	mg/kg dry	1	n .	II .	II .	"	
1,2-Dibromoethane (EDB)	<0.26	0.26	0.031	mg/kg dry	1	n .	II .	II .	"	
1,2-Dichlorobenzene	<0.26	0.26	0.017	mg/kg dry	1	"	u u	u u	"	
1,2-Dichloroethane	<0.26	0.26	0.029	mg/kg dry	1	n n	n n	n n	п	
1,2-Dichloropropane	<0.26	0.26	0.027	mg/kg dry	1	"	"	"	II .	
1,3,5-Trimethylbenzene	<0.26	0.26	0.032	mg/kg dry	1	"	"	"	II .	
1,3-Dichlorobenzene	<0.26	0.26	0.012	mg/kg dry	1	"	"	"	"	
1,3-Dichloropropane	<0.26	0.26	0.019	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.26	0.26	0.021	mg/kg dry	1	"	"	"	"	
2,2-Dichloropropane	<0.26	0.26	0.068	mg/kg dry	1	"	п	n	II .	
2-Butanone	<1.3	1.3	0.12	mg/kg dry	1	"			"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280

Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_6-8 (1505280-05) Soil	Sampled: 11/24/15 11:	00 F	Received: 1	1/25/15 9:30						
4-Chlorotoluene	<0.26	0.26	0.029	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
Acetone	<1.3	1.3	0.16	mg/kg dry	1	"	"	"	"	
Allyl chloride	<0.26	0.26	0.032	mg/kg dry	1	n n	II .	"	п	
Benzene	<0.26	0.26	0.019	mg/kg dry	1	"	"	"	"	
Bromobenzene	<0.26	0.26	0.026	mg/kg dry	1	"	"	"	"	
Bromochloromethane	<0.26	0.26	0.030	mg/kg dry	1	"	"	"	"	
Bromodichloromethane	<0.26	0.26	0.025	mg/kg dry	1	"	"	"	"	
Bromoform	<0.26	0.26	0.047	mg/kg dry	1	"	"	"	II .	
Bromomethane	<0.26	0.26	0.039	mg/kg dry	1	"	u u	"	II .	
Carbon tetrachloride	<0.26	0.26	0.032	mg/kg dry	1	"	u u	"	II .	
Chlorobenzene	<0.26	0.26	0.018	mg/kg dry	1	"	u u	"	II .	
Chloroethane	<0.26	0.26	0.039	mg/kg dry	1	"	"	"	"	
Chloroform	<0.26	0.26	0.040	mg/kg dry	1	"	II .	"	II .	
Chloromethane	<0.26	0.26	0.035	mg/kg dry	1	"	II .	"	II .	
cis-1,2-Dichloroethene	<0.26	0.26	0.016	mg/kg dry	1	"	II .	"	II .	
cis-1,3-Dichloropropene	<0.26	0.26	0.032	mg/kg dry	1	"	"	"	"	
Dibromochloromethane	<0.26	0.26	0.032	mg/kg dry	1	"	"	"	"	
Dibromomethane	<0.26	0.26	0.032	mg/kg dry	1	"	"	"	"	
Dichlorodifluoromethane	<0.26	0.26	0.048	mg/kg dry	1	"	"	"	"	
Dichlorofluoromethane	<0.26	0.26	0.013	mg/kg dry	1	"	"	"	"	T5
Ethyl ether	<0.26	0.26	0.031	mg/kg dry	1	"	"	"	"	
Ethylbenzene	<0.26	0.26	0.027	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.65	0.65	0.10	mg/kg dry	1	"	"	"	"	
Isopropylbenzene	<0.26	0.26	0.039	mg/kg dry	1	"	"	"	II .	
m,p-Xylene	<0.52	0.52	0.062	mg/kg dry	1	"	"	"	"	
Methyl isobutyl ketone	<0.26	0.26	0.056	mg/kg dry	1	"	"	"	"	
Methyl tert-butyl ether	<0.26	0.26	0.013	mg/kg dry	1	"	"	"	"	
Methylene chloride	<0.65	0.65	0.078	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.65	0.65	0.062	mg/kg dry	1	"	"	"	"	
n-Butylbenzene	<0.26	0.26	0.021	mg/kg dry	1	"	"	"	"	
n-Propylbenzene	<0.26	0.26	0.013	mg/kg dry	1	"	"	"	II .	
o-Xylene	<0.26	0.26	0.022	mg/kg dry	1	"	"	"	"	
p-Isopropyltoluene	<0.26	0.26	0.014	mg/kg dry	1	"	"	"	"	
sec-Butylbenzene	<0.26	0.26	0.029	mg/kg dry	1	"	"	"	"	
Styrene	<0.26	0.26	0.021	mg/kg dry	1	"	"	"	"	
tert-Butylbenzene	<0.26	0.26	0.034	mg/kg dry	1	"	"	"	"	
Tetrachloroethene	<0.26	0.26	0.049	mg/kg dry	1	"	"	"	"	
Tetrahydrofuran	<1.3	1.3	0.14	mg/kg dry	1	"	"	"	"	T5
Toluene	<0.26	0.26	0.0088	mg/kg dry	1	"	"	"	II .	



Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_6-8 (1505280-05) Soil Sampled:	11/24/15 11	:00 Re	ceived: 1	1/25/15 9:30						
trans-1,2-Dichloroethene	<0.26	0.26	0.023	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
trans-1,3-Dichloropropene	<0.26	0.26	0.026	mg/kg dry	1	"	"	"	"	
Trichloroethene	<0.26	0.26	0.023	mg/kg dry	1	"	"	"	"	
Trichlorofluoromethane	<0.26	0.26	0.038	mg/kg dry	1	"	"	"	"	
Vinyl chloride	<0.26	0.26	0.027	mg/kg dry	1	"	"	u u	"	
Surrogate: 4-Bromofluorobenzene	88.9			80-124 %		"	"	"	"	
Surrogate: Dibromofluoromethane	96.5			77.1-123 %		"	"	"	"	
Surrogate: Toluene-d8	94.7			78.1-125 %		"	"	"	"	
B-3_0-2 (1505280-06) Soil Sampled:	11/24/15 11	:00 Re	ceived: 1	1/25/15 9:30						
1,1,1,2-Tetrachloroethane	<0.21	0.21	0.021	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,1,1-Trichloroethane	<0.21	0.21	0.024	mg/kg dry	1	"	"	"	"	
1,1,2,2-Tetrachloroethane	<0.21	0.21	0.017	mg/kg dry	1	"	"	"	"	
1,1,2-Trichloroethane	<0.21	0.21	0.015	mg/kg dry	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<0.21	0.21	0.021	mg/kg dry	1	"	"	"	•	T5
1,1-Dichloroethane	<0.21	0.21	0.010	mg/kg dry	1	"	"	"	"	
1,1-Dichloroethene	<0.21	0.21	0.014	mg/kg dry	1	"	"	"	"	
1,1-Dichloropropene	<0.21	0.21	0.016	mg/kg dry	1	"	"	"	"	
1,2,3-Trichlorobenzene	< 0.53	0.53	0.10	mg/kg dry	1	"	"	II .	"	
1,2,3-Trichloropropane	<0.21	0.21	0.032	mg/kg dry	1	"	"	II .	"	
1,2,4-Trichlorobenzene	<0.53	0.53	0.075	mg/kg dry	1	"	"	II .	"	
1,2,4-Trimethylbenzene	<0.21	0.21	0.019	mg/kg dry	1	"	"	II .	"	
1,2-Dibromo-3-chloropropane	<0.53	0.53	0.049	mg/kg dry	1	"	"	u u	"	
1,2-Dibromoethane (EDB)	<0.21	0.21	0.025	mg/kg dry	1	"	"	u u	"	
1,2-Dichlorobenzene	<0.21	0.21	0.014	mg/kg dry	1	"	"	u u	"	
1,2-Dichloroethane	<0.21	0.21	0.023	mg/kg dry	1	"	"	u u	"	
1,2-Dichloropropane	<0.21	0.21	0.022	mg/kg dry	1	"	"	u u	"	
1,3,5-Trimethylbenzene	<0.21	0.21	0.026	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.21	0.21	0.0095	mg/kg dry	1	"	"	· ·	"	
1,3-Dichloropropane	<0.21	0.21	0.016	mg/kg dry	1	"	"	· ·	"	
1,4-Dichlorobenzene	<0.21	0.21	0.017	mg/kg dry	1	"	"	"	"	
2,2-Dichloropropane	<0.21	0.21	0.055	mg/kg dry	1	"	"	"	"	
2-Butanone	<1.1	1.1	0.099	mg/kg dry	1	"	"	"	"	
2-Chlorotoluene	<0.21	0.21	0.021	mg/kg dry	1	"	"	"	"	
4-Chlorotoluene	<0.21	0.21	0.023	mg/kg dry	1	"	"	"		
Acetone	<1.1	1.1	0.13	mg/kg dry	1	"	"	"		
Allyl chloride	<0.21	0.21	0.026	mg/kg dry	1	"	"	"		
Benzene	<0.21	0.21	0.016	mg/kg dry	1	"	"	"		
Bromobenzene	<0.21	0.21	0.021	mg/kg dry	1	"	"	n	"	
Bromochloromethane	<0.21	0.21	0.024	mg/kg dry	1	"	"	n n	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_0-2 (1505280-06) Soil	Sampled: 11/24/15 11:	:00	Received:	11/25/15 9:30						
Bromodichloromethane	<0.21	0.21	0.020	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
Bromoform	<0.21	0.21	0.038	mg/kg dry	1	"	"	"	"	
Bromomethane	<0.21	0.21	0.032	mg/kg dry	1	"	"	"	"	
Carbon tetrachloride	<0.21	0.21	0.026	mg/kg dry	1	"	u u	u u	"	
Chlorobenzene	<0.21	0.21	0.015	mg/kg dry	1	"	II .	II .	II .	
Chloroethane	<0.21	0.21	0.032	mg/kg dry	1	"	II .	II .	"	
Chloroform	<0.21	0.21	0.033	mg/kg dry	1	"	II .	II .	II .	
Chloromethane	<0.21	0.21	0.029	mg/kg dry	1	"	"	"	"	
cis-1,2-Dichloroethene	<0.21	0.21	0.013	mg/kg dry	1	"	"	"	"	
cis-1,3-Dichloropropene	<0.21	0.21	0.026	mg/kg dry	1	"	II .	II .	"	
Dibromochloromethane	<0.21	0.21	0.026	mg/kg dry	1	"	n n	n .	"	
Dibromomethane	<0.21	0.21	0.026	mg/kg dry	1	"	"	"	"	
Dichlorodifluoromethane	<0.21	0.21	0.039	mg/kg dry	1	"	"	"	"	
Dichlorofluoromethane	<0.21	0.21	0.011	mg/kg dry	1	"	"	"	"	T5
Ethyl ether	<0.21	0.21	0.025	mg/kg dry	1	"	"	"	"	
Ethylbenzene	<0.21	0.21	0.022	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.53	0.53	0.084	mg/kg dry	1	"	"	"	"	
Isopropylbenzene	<0.21	0.21	0.032	mg/kg dry	1	"	"	"	"	
m,p-Xylene	<0.42	0.42	0.051	mg/kg dry	1	"	"	"	"	
Methyl isobutyl ketone	<0.21	0.21	0.045	mg/kg dry	1	"	"	"	"	
Methyl tert-butyl ether	<0.21	0.21	0.010	mg/kg dry	1	"	"	"	"	
Methylene chloride	<0.53	0.53	0.063	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.53	0.53	0.051	mg/kg dry	1	"	· ·	u u	"	
n-Butylbenzene	<0.21	0.21	0.017	mg/kg dry	1	"	· ·	u u	"	
n-Propylbenzene	<0.21	0.21	0.011	mg/kg dry	1	"	"	"	"	
o-Xylene	<0.21	0.21	0.018	mg/kg dry	1	"	"	"	"	
p-Isopropyltoluene	<0.21	0.21	0.012	mg/kg dry	1	"	· ·	u u	"	
sec-Butylbenzene	<0.21	0.21	0.023	mg/kg dry	1	"	"	"	"	
Styrene	<0.21	0.21	0.017	mg/kg dry	1	"	· ·	u u	"	
tert-Butylbenzene	<0.21	0.21	0.027	mg/kg dry	1	"	II .	II .	"	
Tetrachloroethene	<0.21	0.21	0.040	mg/kg dry	1	"	II .	II .	"	
Tetrahydrofuran	<1.1	1.1	0.12	mg/kg dry	1	"	II .	II .	"	T5
Toluene	<0.21	0.21	0.0072	mg/kg dry	1	"	"	"	"	
trans-1,2-Dichloroethene	<0.21	0.21	0.019	mg/kg dry	1	"	"	"	"	
trans-1,3-Dichloropropene	<0.21	0.21	0.021	mg/kg dry	1	"	II .	II .	"	
Trichloroethene	<0.21	0.21	0.019	mg/kg dry	1	"	"	u u	"	
Trichlorofluoromethane	<0.21	0.21	0.031	mg/kg dry	1	"	"	"	"	
Vinyl chloride	<0.21	0.21	0.022	mg/kg dry	1	"	"	"	"	
Surrogate: 4-Bromofluorobenzei	ne 88.7			80-124 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280 Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_0-2 (1505280-06) Soil	Sampled: 11/24/15 11	:00	Received:	11/25/15 9:30						
Surrogate: Dibromofluorometha	ane 95.6			77.1-123 %		B5L0233	12/01/15	12/01/15	EPA 8260B	
Surrogate: Toluene-d8	94.0			78.1-125 %		"	"	"	"	
B-4_2-4 (1505280-07) Soil	Sampled: 11/24/15 12	:00	Received:	11/25/15 9:30						
1,1,1,2-Tetrachloroethane	<0.21	0.21	0.021	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,1,1-Trichloroethane	<0.21	0.21	0.024	mg/kg dry	1	"	"	"	"	
1,1,2,2-Tetrachloroethane	<0.21	0.21	0.017	mg/kg dry	1	"	·	II .	"	
1,1,2-Trichloroethane	<0.21	0.21	0.015	mg/kg dry	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<0.21	0.21	0.021	mg/kg dry	1	"	"	"	"	T5
1,1-Dichloroethane	<0.21	0.21	0.010	mg/kg dry	1	"	"	"	"	
1,1-Dichloroethene	<0.21	0.21	0.014	mg/kg dry	1	"	"	"	"	
1,1-Dichloropropene	<0.21	0.21	0.016	mg/kg dry	1	"	"	"	"	
1,2,3-Trichlorobenzene	<0.53	0.53	0.10	mg/kg dry	1	"	"	"	"	
1,2,3-Trichloropropane	<0.21	0.21	0.032	mg/kg dry	1	"	"	"	"	
1,2,4-Trichlorobenzene	<0.53	0.53	0.076	mg/kg dry	1	"	· ·	II .	"	
1,2,4-Trimethylbenzene	<0.21	0.21	0.019	mg/kg dry	1	"	· ·	II .	"	
1,2-Dibromo-3-chloropropane	<0.53	0.53	0.049	mg/kg dry	1	"	"	"	"	
1,2-Dibromoethane (EDB)	<0.21	0.21	0.026	mg/kg dry	1	"	"	"	"	
1,2-Dichlorobenzene	<0.21	0.21	0.014	mg/kg dry	1	"	· ·	II .	"	
1,2-Dichloroethane	<0.21	0.21	0.023	mg/kg dry	1	"	· ·	II .	"	
1,2-Dichloropropane	<0.21	0.21	0.022	mg/kg dry	1	"	"	"	"	
1,3,5-Trimethylbenzene	<0.21	0.21	0.027	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.21	0.21	0.0096	mg/kg dry	1	"	"	"	"	
1,3-Dichloropropane	<0.21	0.21	0.016	mg/kg dry	1	"	"	II .	"	
1,4-Dichlorobenzene	<0.21	0.21	0.017	mg/kg dry	1	"	"	"	"	
2,2-Dichloropropane	<0.21	0.21	0.055	mg/kg dry	1	"	u u	II .	"	
2-Butanone	<1.1	1.1	0.10	mg/kg dry	1	"	· ·	II .	"	
2-Chlorotoluene	<0.21	0.21	0.021	mg/kg dry	1	"	"	"	"	
4-Chlorotoluene	<0.21	0.21	0.023	mg/kg dry	1	"	"	"	"	
Acetone	<1.1	1.1	0.13	mg/kg dry	1	"	"	"	"	
Allyl chloride	<0.21	0.21	0.027	mg/kg dry	1	"	"	"	"	
Benzene	<0.21	0.21	0.016	mg/kg dry	1	"	"	"	"	
Bromobenzene	<0.21	0.21	0.021	mg/kg dry	1	"	"	n .	"	
Bromochloromethane	<0.21	0.21	0.024	mg/kg dry	1	"	"	n .	"	
Bromodichloromethane	<0.21	0.21	0.020	mg/kg dry	1	"	"	n .	"	
Bromoform	<0.21	0.21	0.038	mg/kg dry	1	"	"	n .	"	
Bromomethane	<0.21	0.21	0.032	mg/kg dry	1	"	"	"	"	
Carbon tetrachloride	<0.21	0.21	0.027	mg/kg dry	1	"	"	"	"	
Chlorobenzene	<0.21	0.21	0.015	mg/kg dry	1	"	"	n n	"	
Chloroethane	<0.21	0.21	0.032	mg/kg dry	1	"	"	u u	"	
				· ·						



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4_2-4 (1505280-07) Soil	Sampled: 11/24/15 12:0	00	Received: 1	1/25/15 9:30						
Chloroform	<0.21	0.21	0.033	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
Chloromethane	<0.21	0.21	0.029	mg/kg dry	1	"	"	"	"	
cis-1,2-Dichloroethene	<0.21	0.21	0.013	mg/kg dry	1	"	"	"	"	
cis-1,3-Dichloropropene	<0.21	0.21	0.027	mg/kg dry	1		"	"	"	
Dibromochloromethane	<0.21	0.21	0.027	mg/kg dry	1	"	"	"	"	
Dibromomethane	<0.21	0.21	0.027	mg/kg dry	1	"	"	"	"	
Dichlorodifluoromethane	<0.21	0.21	0.039	mg/kg dry	1	"	"	"	"	
Dichlorofluoromethane	<0.21	0.21	0.011	mg/kg dry	1		"	"		T5
Ethyl ether	<0.21	0.21	0.026	mg/kg dry	1	"	"	"	"	
Ethylbenzene	<0.21	0.21	0.022	mg/kg dry	1	"	"	n n		
Hexachlorobutadiene	<0.53	0.53	0.084	mg/kg dry	1	"	"	"		
Isopropylbenzene	<0.21	0.21	0.032	mg/kg dry	1	"	"	"		
m,p-Xylene	<0.43	0.43	0.051	mg/kg dry	1	"	"	"	"	
Methyl isobutyl ketone	<0.21	0.21	0.046	mg/kg dry	1	"	"	"		
Methyl tert-butyl ether	<0.21	0.21	0.010	mg/kg dry	1	"	"	"	"	
Methylene chloride	<0.53	0.53	0.064	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.53	0.53	0.051	mg/kg dry	1	"	"	"	"	
n-Butylbenzene	<0.21	0.21	0.017	mg/kg dry	1	"	"	"		
n-Propylbenzene	<0.21	0.21	0.011	mg/kg dry	1	"	"	"	"	
o-Xylene	<0.21	0.21	0.018	mg/kg dry	1	"	"	"	"	
p-Isopropyltoluene	<0.21	0.21	0.012	mg/kg dry	1	"	"	"		
sec-Butylbenzene	<0.21	0.21	0.023	mg/kg dry	1	"	"	"		
Styrene	<0.21	0.21	0.017	mg/kg dry	1	"	"	"	"	
tert-Butylbenzene	<0.21	0.21	0.028	mg/kg dry	1	"	"	"	"	
Tetrachloroethene	<0.21	0.21	0.040	mg/kg dry	1		"	"		
Tetrahydrofuran	<1.1	1.1	0.12	mg/kg dry	1	"	"	"	"	T5
Toluene	<0.21	0.21	0.0072	mg/kg dry	1	"	"	"	"	
trans-1,2-Dichloroethene	<0.21	0.21	0.019	mg/kg dry	1	"	"	"	"	
trans-1,3-Dichloropropene	<0.21	0.21	0.021	mg/kg dry	1	"	"	"		
Trichloroethene	<0.21	0.21	0.019	mg/kg dry	1	"	"	"	"	
Trichlorofluoromethane	<0.21	0.21	0.031	mg/kg dry	1	"	"	"	"	
Vinyl chloride	<0.21	0.21	0.022	mg/kg dry	1	"	"	"	"	
Surrogate: 4-Bromofluorobenzer	ne 89.0			80-124 %		"	"	"	"	
Surrogate: Dibromofluoromethan	ne 99.1			77.1-123 %		"	"	"	"	
Surrogate: Toluene-d8	96.1			78.1-125 %		"	"	"	"	
B-4_8-10 (1505280-08) Soil	Sampled: 11/24/15 12	00	Received:	11/25/15 9:30			-			_
1,1,1,2-Tetrachloroethane	<0.24	0.24	0.024	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,1,1-Trichloroethane	<0.24	0.24	0.028	mg/kg dry	1	"	"	n .	· ·	
1,1,2,2-Tetrachloroethane	<0.24	0.24	0.019	mg/kg dry	1	"	"	n .	· ·	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280

Date Reported: 12/10/15

Analyte		Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4_8-10 (1505280-08) Soil	Sampled:	11/24/15 1	2:00	Received: 1	11/25/15 9:30)					
1,1,2-Trichloroethane		<0.24	0.24	0.017	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,1,2-Trichlorotrifluoroethane		<0.24	0.24	0.024	mg/kg dry	1	"		"	"	T5
1,1-Dichloroethane		<0.24	0.24	0.012	mg/kg dry	1	"		"	"	
1,1-Dichloroethene		<0.24	0.24	0.016	mg/kg dry	1	"	"	"	"	
1,1-Dichloropropene		<0.24	0.24	0.018	mg/kg dry	1	"	"	"	"	
1,2,3-Trichlorobenzene		<0.60	0.60	0.12	mg/kg dry	1	"	"	"	n .	
1,2,3-Trichloropropane		<0.24	0.24	0.036	mg/kg dry	1	"	"	"	"	
1,2,4-Trichlorobenzene		<0.60	0.60	0.086	mg/kg dry	1	"	"	"	"	
1,2,4-Trimethylbenzene		<0.24	0.24	0.022	mg/kg dry	1	"	"	m .	"	
1,2-Dibromo-3-chloropropane		<0.60	0.60	0.055	mg/kg dry	1	"	"	"	II .	
1,2-Dibromoethane (EDB)		<0.24	0.24	0.029	mg/kg dry	1	"	"	"	u u	
1,2-Dichlorobenzene		<0.24	0.24	0.016	mg/kg dry	1	"	"	"	u u	
1,2-Dichloroethane		<0.24	0.24	0.027	mg/kg dry	1	"	"	"	II .	
1,2-Dichloropropane		<0.24	0.24	0.025	mg/kg dry	1	"	"	"	u u	
1,3,5-Trimethylbenzene		<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	
,3-Dichlorobenzene		<0.24	0.24	0.011	mg/kg dry	1	"	"	"	n .	
,3-Dichloropropane		<0.24	0.24	0.018	mg/kg dry	1	"	"	"	n .	
,4-Dichlorobenzene		<0.24	0.24	0.019	mg/kg dry	1	"	"	"	"	
2,2-Dichloropropane		<0.24	0.24	0.063	mg/kg dry	1	"	"	"	"	
2-Butanone		<1.2	1.2	0.11	mg/kg dry	1	"	"	"	n .	
2-Chlorotoluene		<0.24	0.24	0.024	mg/kg dry	1	"	"	"	"	
1-Chlorotoluene		<0.24	0.24	0.027	mg/kg dry	1	"	"	"	"	
Acetone		<1.2	1.2	0.14	mg/kg dry	1	"	"	"	n .	
Allyl chloride		<0.24	0.24	0.030	mg/kg dry	1	"	"	"	n .	
Benzene		<0.24	0.24	0.018	mg/kg dry	1	"	"	"	"	
Bromobenzene		<0.24	0.24	0.024	mg/kg dry	1	"	"	"	"	
Bromochloromethane		<0.24	0.24	0.028	mg/kg dry	1	"	"	"	n .	
Bromodichloromethane		<0.24	0.24	0.023	mg/kg dry	1	"	"	"	n .	
Bromoform		<0.24	0.24	0.043	mg/kg dry	1	"	"	"	"	
Bromomethane		<0.24	0.24	0.036	mg/kg dry	1	"	"	"	"	
Carbon tetrachloride		<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	
Chlorobenzene		<0.24	0.24	0.017	mg/kg dry	1	"	"	"	"	
Chloroethane		<0.24	0.24	0.036	mg/kg dry	1	"	"	"	"	
Chloroform		<0.24	0.24	0.037	mg/kg dry	1	"	"	"	"	
Chloromethane		<0.24	0.24	0.033	mg/kg dry	1	"	"	"	"	
sis-1,2-Dichloroethene		<0.24	0.24	0.014	mg/kg dry	1	"	"	"	"	
sis-1,3-Dichloropropene		<0.24	0.24	0.030	mg/kg dry	1	"	•	"	"	
Dibromochloromethane		<0.24	0.24	0.030	mg/kg dry	1	"		"	"	
Dibromomethane		<0.24	0.24	0.030	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Work Order #: 1505280

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

. Andrea Nord Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4_8-10 (1505280-08) Soil	Sampled: 11/24/15 1	12:00	Received:	11/25/15 9:30	1					
Dichlorodifluoromethane	<0.24	0.24	0.045	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
Dichlorofluoromethane	<0.24	0.24	0.012	mg/kg dry	1	"	"	"	"	T5
Ethyl ether	<0.24	0.24	0.029	mg/kg dry	1	"	"	"	"	
Ethylbenzene	<0.24	0.24	0.025	mg/kg dry	1	"	"	"	u .	
Hexachlorobutadiene	<0.60	0.60	0.095	mg/kg dry	1	"	"	"	n .	
Isopropylbenzene	<0.24	0.24	0.036	mg/kg dry	1	"	n .	"	II .	
m,p-Xylene	<0.48	0.48	0.058	mg/kg dry	1	"	n .	"	II .	
Methyl isobutyl ketone	<0.24	0.24	0.052	mg/kg dry	1	"	"	"	"	
Methyl tert-butyl ether	<0.24	0.24	0.012	mg/kg dry	1	"	"	"	"	
Methylene chloride	<0.60	0.60	0.072	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.60	0.60	0.058	mg/kg dry	1	"	"	"	"	
n-Butylbenzene	<0.24	0.24	0.019	mg/kg dry	1	"	"	"	"	
n-Propylbenzene	<0.24	0.24	0.012	mg/kg dry	1	"	"	"	"	
o-Xylene	<0.24	0.24	0.020	mg/kg dry	1	"	"	"	"	
p-Isopropyltoluene	<0.24	0.24	0.013	mg/kg dry	1	"	"	"	"	
sec-Butylbenzene	<0.24	0.24	0.027	mg/kg dry	1	"	"	"	u .	
Styrene	<0.24	0.24	0.019	mg/kg dry	1	"	"	"	u .	
tert-Butylbenzene	<0.24	0.24	0.031	mg/kg dry	1	"	"	"	"	
Tetrachloroethene	<0.24	0.24	0.046	mg/kg dry	1	"	"	"	"	
Tetrahydrofuran	<1.2	1.2	0.13	mg/kg dry	1	"	"	"	u .	T5
Toluene	<0.24	0.24	0.0082	mg/kg dry	1	"	"	"	u .	
trans-1,2-Dichloroethene	<0.24	0.24	0.022	mg/kg dry	1	"	"	"	u .	
trans-1,3-Dichloropropene	<0.24	0.24	0.024	mg/kg dry	1	"	"	"	II .	
Trichloroethene	<0.24	0.24	0.022	mg/kg dry	1	"	"	"	II .	
Trichlorofluoromethane	<0.24	0.24	0.035	mg/kg dry	1	"	"	"	II .	
Vinyl chloride	<0.24	0.24	0.025	mg/kg dry	1	"	"	"	II .	
Surrogate: 4-Bromofluorobenzene				80-124 %		"	"	"	"	
Surrogate: Dibromofluoromethan				77.1-123 %		"	"	"	"	
Surrogate: Toluene-d8	95.1),45	Donahira di di	78.1-125 %		"	"	"	"	
B-5_0-2 (1505280-09) Soil	•			1/25/15 9:30		_				
1,1,1,2-Tetrachloroethane	<0.21	0.21	0.021	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
1,1,1-Trichloroethane	<0.21	0.21	0.024	mg/kg dry	1	"	"	"	II .	
1,1,2,2-Tetrachloroethane	<0.21	0.21	0.017	mg/kg dry	1	"	"	"	II .	
1,1,2-Trichloroethane	<0.21	0.21	0.015	mg/kg dry	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<0.21	0.21	0.021	mg/kg dry	1	"	"	"	"	T5
1,1-Dichloroethane	<0.21	0.21	0.010	mg/kg dry	1	"	"	"	II .	
1,1-Dichloroethene	<0.21	0.21	0.013	mg/kg dry	1	"	"	"	II .	
1,1-Dichloropropene	<0.21	0.21	0.016	mg/kg dry	1	"	"	"	"	
1,2,3-Trichlorobenzene	<0.52	0.52	0.10	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280 Date Reported: 12/10/15

B-5_0-2 (1505280-09) Soil 1,2,3-Trichloropropane 1,2,4-Trichlorobenzene	Sampled: 11/24/15 12:							Analyzed	Method	Notes
		45 F	Received:	11/25/15 9:30						
1,2,4-Trichlorobenzene	<0.21	0.21	0.031	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
	<0.52	0.52	0.074	mg/kg dry	1	"	"	"	"	
1,2,4-Trimethylbenzene	<0.21	0.21	0.019	mg/kg dry	1	"	"	"	II .	
1,2-Dibromo-3-chloropropane	<0.52	0.52	0.048	mg/kg dry	1	"	"	"	п	
1,2-Dibromoethane (EDB)	<0.21	0.21	0.025	mg/kg dry	1	"	"	"	"	
1,2-Dichlorobenzene	<0.21	0.21	0.013	mg/kg dry	1	"	"	"	"	
1,2-Dichloroethane	<0.21	0.21	0.023	mg/kg dry	1	"	"	"	"	
1,2-Dichloropropane	<0.21	0.21	0.022	mg/kg dry	1	"	"	"	"	
1,3,5-Trimethylbenzene	<0.21	0.21	0.026	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.21	0.21	0.0093	mg/kg dry	1	"	"	"	n .	
1,3-Dichloropropane	<0.21	0.21	0.016	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.21	0.21	0.017	mg/kg dry	1	"	"	"	u u	
2,2-Dichloropropane	<0.21	0.21	0.054	mg/kg dry	1	"	"	"	u u	
2-Butanone	<1.0	1.0	0.097	mg/kg dry	1	"	"	"	u u	
2-Chlorotoluene	<0.21	0.21	0.021	mg/kg dry	1	"	"	"	"	
4-Chlorotoluene	<0.21	0.21	0.023	mg/kg dry	1	"	"	"	u u	
Acetone	<1.0	1.0	0.12	mg/kg dry	1	"	"	"	u u	
Allyl chloride	<0.21	0.21	0.026	mg/kg dry	1	"	"	"	"	
Benzene	<0.21	0.21	0.016	mg/kg dry	1	"	"	"	u u	
Bromobenzene	<0.21	0.21	0.021	mg/kg dry	1	"	"	"	II .	
Bromochloromethane	<0.21	0.21	0.024	mg/kg dry	1	"	"	"	"	
Bromodichloromethane	<0.21	0.21	0.020	mg/kg dry	1	"	"	"	II .	
Bromoform	<0.21	0.21	0.037	mg/kg dry	1	"	"	"	u u	
Bromomethane	<0.21	0.21	0.031	mg/kg dry	1	"	"	II .	II .	
Carbon tetrachloride	<0.21	0.21	0.026	mg/kg dry	1	"	"	"	u u	
Chlorobenzene	<0.21	0.21	0.015	mg/kg dry	1	"	"	"	п	
Chloroethane	<0.21	0.21	0.031	mg/kg dry	1	"	"	II .	II .	
Chloroform	<0.21	0.21	0.032	mg/kg dry	1	"	"	II .	п	
Chloromethane	<0.21	0.21	0.028	mg/kg dry	1	"	"	II .	II .	
cis-1,2-Dichloroethene	<0.21	0.21	0.012	mg/kg dry	1	"	"	II .	II .	
cis-1,3-Dichloropropene	<0.21	0.21	0.026	mg/kg dry	1	"	"	II .	II .	
Dibromochloromethane	<0.21	0.21	0.026	mg/kg dry	1	"	"	"	u u	
Dibromomethane	<0.21	0.21	0.026	mg/kg dry	1	"	"	"	u u	
Dichlorodifluoromethane	<0.21	0.21	0.038	mg/kg dry	1	"	"	"	u u	
Dichlorofluoromethane	<0.21	0.21	0.010	mg/kg dry	1	"	"	"	u u	T5
Ethyl ether	<0.21	0.21	0.025	mg/kg dry	1	"	"	"	u u	
Ethylbenzene	<0.21	0.21	0.022	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.52	0.52	0.082	mg/kg dry	1	"	"	"	"	
Isopropylbenzene	<0.21	0.21	0.031	mg/kg dry	1	"	"	"	"	

Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-5_0-2 (1505280-09) Soil Sample	d: 11/24/15 12	2:45 R	eceived: 11	1/25/15 9:30						
m,p-Xylene	<0.41	0.41	0.050	mg/kg dry	1	B5L0233	12/01/15	12/01/15	EPA 8260B	
Methyl isobutyl ketone	<0.21	0.21	0.045	mg/kg dry	1	"	"	"	"	
Methyl tert-butyl ether	<0.21	0.21	0.010	mg/kg dry	1	"	"	"	"	
Methylene chloride	<0.52	0.52	0.062	mg/kg dry	1	"	"	II .	"	
Naphthalene	<0.52	0.52	0.050	mg/kg dry	1	n n	"	II .	II .	
n-Butylbenzene	<0.21	0.21	0.017	mg/kg dry	1	II .	"	II .	"	
n-Propylbenzene	<0.21	0.21	0.010	mg/kg dry	1	n n	"	II .	II .	
o-Xylene	<0.21	0.21	0.018	mg/kg dry	1	"	"	"	"	
p-Isopropyltoluene	<0.21	0.21	0.011	mg/kg dry	1	"	"	"	"	
sec-Butylbenzene	<0.21	0.21	0.023	mg/kg dry	1	II .	"	II .	"	
Styrene	<0.21	0.21	0.017	mg/kg dry	1	"	"	"	"	
tert-Butylbenzene	<0.21	0.21	0.027	mg/kg dry	1	"	"	"	"	
Tetrachloroethene	<0.21	0.21	0.039	mg/kg dry	1	"	"	"	"	
Tetrahydrofuran	<1.0	1.0	0.11	mg/kg dry	1	II .	"	II .	"	T5
Toluene	<0.21	0.21	0.0070	mg/kg dry	1	"	"	"	"	
trans-1,2-Dichloroethene	<0.21	0.21	0.019	mg/kg dry	1	"	"	"	"	
trans-1,3-Dichloropropene	<0.21	0.21	0.021	mg/kg dry	1	"	"	"	"	
Trichloroethene	<0.21	0.21	0.019	mg/kg dry	1	"	"	"	"	
Trichlorofluoromethane	<0.21	0.21	0.030	mg/kg dry	1	"	"	"	"	
Vinyl chloride	<0.21	0.21	0.022	mg/kg dry	1	"	"	"	"	
Surrogate: 4-Bromofluorobenzene	90.3			80-124 %		"	"	"	"	
Surrogate: Dibromofluoromethane	98.0			77.1-123 %		"	"	"	"	
Surrogate: Toluene-d8	95.7			78.1-125 %		"	"	"	"	
B-5_6-8 (1505280-10) Soil Sample	d: 11/24/15 12	2:45 R	eceived: 11	1/25/15 9:30						
1,1,1,2-Tetrachloroethane	<0.22	0.22	0.022	mg/kg dry	1	B5L0234	12/02/15	12/02/15	EPA 8260B	
1,1,1-Trichloroethane	<0.22	0.22	0.025	mg/kg dry	1	"	"	"	"	
1,1,2,2-Tetrachloroethane	<0.22	0.22	0.018	mg/kg dry	1	"	"	"	"	
1,1,2-Trichloroethane	<0.22	0.22	0.015	mg/kg dry	1	"	"	II .	"	
1,1,2-Trichlorotrifluoroethane	<0.22	0.22	0.022	mg/kg dry	1	"	"	II .	"	T5
1,1-Dichloroethane	<0.22	0.22	0.011	mg/kg dry	1	"	"	"	"	
1,1-Dichloroethene	<0.22	0.22	0.014	mg/kg dry	1	"	"	"	"	
1,1-Dichloropropene	<0.22	0.22	0.016	mg/kg dry	1	"	"	"	"	
1,2,3-Trichlorobenzene	< 0.55	0.55	0.11	mg/kg dry	1	"	"	"	"	
1,2,3-Trichloropropane	<0.22	0.22	0.033	mg/kg dry	1	II .	"	II .	"	
1,2,4-Trichlorobenzene	<0.55	0.55	0.078	mg/kg dry	1	"	"	"	"	
1,2,4-Trimethylbenzene	<0.22	0.22	0.020	mg/kg dry	1	II .	"	II .	"	
1,2-Dibromo-3-chloropropane	<0.55	0.55	0.051	mg/kg dry	1	II .	"	II .	"	
1,2-Dibromoethane (EDB)	<0.22	0.22	0.026	mg/kg dry	1	II .	"	II .	"	
1,2-Dichlorobenzene	<0.22	0.22	0.014	mg/kg dry	1	"	"	II .	"	



Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-5_6-8 (1505280-10) Soil	Sampled: 11/24/15 12	:45 R	eceived: 11	1/25/15 9:30						
1,2-Dichloroethane	<0.22	0.22	0.024	mg/kg dry	1	B5L0234	12/02/15	12/02/15	EPA 8260B	
1,2-Dichloropropane	<0.22	0.22	0.023	mg/kg dry	1	"	"	"	"	
1,3,5-Trimethylbenzene	<0.22	0.22	0.027	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.22	0.22	0.0099	mg/kg dry	1	"	"	"	"	
1,3-Dichloropropane	<0.22	0.22	0.016	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.22	0.22	0.018	mg/kg dry	1	"	"	"	"	
2,2-Dichloropropane	<0.22	0.22	0.057	mg/kg dry	1	"	"	"	"	
2-Butanone	<1.1	1.1	0.10	mg/kg dry	1	"	"	"	"	
2-Chlorotoluene	<0.22	0.22	0.022	mg/kg dry	1	"	"	"	"	
4-Chlorotoluene	<0.22	0.22	0.024	mg/kg dry	1	"	"	"	"	
Acetone	<1.1	1.1	0.13	mg/kg dry	1	"	"	"		
Allyl chloride	<0.22	0.22	0.027	mg/kg dry	1	"	"	"		
Benzene	<0.22	0.22	0.016	mg/kg dry	1	"	"	"		
Bromobenzene	<0.22	0.22	0.022	mg/kg dry	1	"	"	"	"	
Bromochloromethane	<0.22	0.22	0.025	mg/kg dry	1	"	"	"	"	
Bromodichloromethane	<0.22	0.22	0.021	mg/kg dry	1	"	"	"	"	
Bromoform	<0.22	0.22	0.040	mg/kg dry	1	"	"	"	"	
Bromomethane	<0.22	0.22	0.033	mg/kg dry	1	"	"	"	"	
Carbon tetrachloride	<0.22	0.22	0.027	mg/kg dry	1	"	"	"	"	
Chlorobenzene	<0.22	0.22	0.015	mg/kg dry	1	"	"	"	"	
Chloroethane	<0.22	0.22	0.033	mg/kg dry	1	"	"	"	"	
Chloroform	<0.22	0.22	0.034	mg/kg dry	1	"	"	"	"	
Chloromethane	<0.22	0.22	0.030	mg/kg dry	1	"	"	"	"	
cis-1,2-Dichloroethene	<0.22	0.22	0.013	mg/kg dry	1	"	"	"	"	
cis-1,3-Dichloropropene	<0.22	0.22	0.027	mg/kg dry	1	"	"	"	"	
Dibromochloromethane	<0.22	0.22	0.027	mg/kg dry	1	"	"	"	"	
Dibromomethane	<0.22	0.22	0.027	mg/kg dry	1	"	"	"		
Dichlorodifluoromethane	<0.22	0.22	0.041	mg/kg dry	1	"	"	"		
Dichlorofluoromethane	<0.22	0.22	0.011	mg/kg dry	1	"	"	"	"	T5
Ethyl ether	<0.22	0.22	0.026	mg/kg dry	1	"	"	"	"	
Ethylbenzene	<0.22	0.22	0.023	mg/kg dry	1	"	"	"	•	
Hexachlorobutadiene	<0.55	0.55	0.087	mg/kg dry	1	"	"	"	"	
Isopropylbenzene	<0.22	0.22	0.033	mg/kg dry	1	"	"	"	"	
m,p-Xylene	<0.44	0.44	0.053	mg/kg dry	1	"	"	"	"	
Methyl isobutyl ketone	<0.22	0.22	0.047	mg/kg dry	1	"	"	"	"	
Methyl tert-butyl ether	<0.22	0.22	0.011	mg/kg dry	1	"	"	"	"	
Methylene chloride	<0.55	0.55	0.066	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.55	0.55	0.053	mg/kg dry	1	"	"	"	"	
n-Butylbenzene	<0.22	0.22	0.018	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280

Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-5_6-8 (1505280-10) Soil Sample	d: 11/24/15 12	2:45 Re	eceived: 1	1/25/15 9:30						
n-Propylbenzene	<0.22	0.22	0.011	mg/kg dry	1	B5L0234	12/02/15	12/02/15	EPA 8260B	
o-Xylene	<0.22	0.22	0.019	mg/kg dry	1	"	"	"	"	
p-Isopropyltoluene	<0.22	0.22	0.012	mg/kg dry	1	u u	"	"	u .	
sec-Butylbenzene	<0.22	0.22	0.024	mg/kg dry	1	n n	"	"	u u	
Styrene	<0.22	0.22	0.018	mg/kg dry	1	п	n .	"	II .	
tert-Butylbenzene	<0.22	0.22	0.029	mg/kg dry	1	п	n .	"	II .	
Tetrachloroethene	<0.22	0.22	0.042	mg/kg dry	1	n n	"	"	u u	
Tetrahydrofuran	<1.1	1.1	0.12	mg/kg dry	1	п	n .	"	II .	T5
Toluene	<0.22	0.22	0.0075	mg/kg dry	1	II .	"	"	· ·	
trans-1,2-Dichloroethene	<0.22	0.22	0.020	mg/kg dry	1	п	n .	"	II .	
trans-1,3-Dichloropropene	<0.22	0.22	0.022	mg/kg dry	1	n n	"	"	u u	
Trichloroethene	<0.22	0.22	0.020	mg/kg dry	1	п	n .	"	II .	
Trichlorofluoromethane	<0.22	0.22	0.032	mg/kg dry	1	"	"	"	"	
Vinyl chloride	<0.22	0.22	0.023	mg/kg dry	1	II .	"	"	· ·	
Surrogate: 4-Bromofluorobenzene	91.4			80-124 %		"	"	"	"	
Surrogate: Dibromofluoromethane	98.4			77.1-123 %		"	"	"	"	
Surrogate: Toluene-d8	96.9			78.1-125 %		"	"	II .	II .	
B-6_0-2 (1505280-11) Soil Sample	d: 11/24/15 13	3:30 Re	eceived: 11	1/25/15 9:30						
1,1,1,2-Tetrachloroethane	<0.22	0.22	0.022	mg/kg dry	1	B5L0234	12/02/15	12/02/15	EPA 8260B	
1,1,1-Trichloroethane	<0.22	0.22	0.026	mg/kg dry	1	"	"	"	u u	
1,1,2,2-Tetrachloroethane	<0.22	0.22	0.018	mg/kg dry	1	"	"	"	u u	
1,1,2-Trichloroethane	<0.22	0.22	0.016	mg/kg dry	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<0.22	0.22	0.022	mg/kg dry	1	"	"	"	"	T5
1,1-Dichloroethane	<0.22	0.22	0.011	mg/kg dry	1	"	"	"	"	
1,1-Dichloroethene	<0.22	0.22	0.015	mg/kg dry	1	"	"	"	"	
1,1-Dichloropropene	<0.22	0.22	0.017	mg/kg dry	1	"	"	"	"	
1,2,3-Trichlorobenzene	<0.56	0.56	0.11	mg/kg dry	1	"	"	"	"	
1,2,3-Trichloropropane	<0.22	0.22	0.034	mg/kg dry	1	"	"	"	"	
1,2,4-Trichlorobenzene	<0.56	0.56	0.080	mg/kg dry	1	"	"	"	"	
1,2,4-Trimethylbenzene	<0.22	0.22	0.020	mg/kg dry	1	II .	"	"	· ·	
1,2-Dibromo-3-chloropropane	<0.56	0.56	0.052	mg/kg dry	1	II .	"	"	· ·	
1,2-Dibromoethane (EDB)	<0.22	0.22	0.027	mg/kg dry	1	II .	"	"	· ·	
1,2-Dichlorobenzene	<0.22	0.22	0.015	mg/kg dry	1	II .	"	"	· ·	
1,2-Dichloroethane	<0.22	0.22	0.025	mg/kg dry	1	"	"	"	u .	
1,2-Dichloropropane	<0.22	0.22	0.024	mg/kg dry	1	"	"	"	"	
1,3,5-Trimethylbenzene	<0.22	0.22	0.028	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.22	0.22	0.010	mg/kg dry	1	"	"	"	"	
1,3-Dichloropropane	<0.22	0.22	0.017	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280

Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-6_0-2 (1505280-11) Soil	Sampled: 11/24/15 13	:30	Received:	11/25/15 9:30						
2,2-Dichloropropane	<0.22	0.22	0.058	mg/kg dry	1	B5L0234	12/02/15	12/02/15	EPA 8260B	
2-Butanone	<1.1	1.1	0.11	mg/kg dry	1	"	"	"	"	
2-Chlorotoluene	<0.22	0.22	0.022	mg/kg dry	1	"	"	II .	"	
4-Chlorotoluene	<0.22	0.22	0.025	mg/kg dry	1	"	"	"	"	
Acetone	<1.1	1.1	0.13	mg/kg dry	1	"	"	"	"	
Allyl chloride	<0.22	0.22	0.028	mg/kg dry	1	"	"	"	"	
Benzene	<0.22	0.22	0.017	mg/kg dry	1	"	"	"	"	
Bromobenzene	<0.22	0.22	0.022	mg/kg dry	1	"	"	"	"	
Bromochloromethane	<0.22	0.22	0.026	mg/kg dry	1	"	"	"	"	
Bromodichloromethane	<0.22	0.22	0.021	mg/kg dry	1	"	"	"	"	
Bromoform	<0.22	0.22	0.040	mg/kg dry	1	"	"	"	"	
Bromomethane	<0.22	0.22	0.034	mg/kg dry	1	"	"	II .	"	
Carbon tetrachloride	<0.22	0.22	0.028	mg/kg dry	1	"	"	II .	"	
Chlorobenzene	<0.22	0.22	0.016	mg/kg dry	1	"	"	II .	"	
Chloroethane	<0.22	0.22	0.034	mg/kg dry	1	"	"	II .	"	
Chloroform	<0.22	0.22	0.035	mg/kg dry	1	"	"	II .	"	
Chloromethane	<0.22	0.22	0.030	mg/kg dry	1	"	"	II .	"	
cis-1,2-Dichloroethene	<0.22	0.22	0.013	mg/kg dry	1	"	"	II .	"	
cis-1,3-Dichloropropene	<0.22	0.22	0.028	mg/kg dry	1	"	"	"	"	
Dibromochloromethane	<0.22	0.22	0.028	mg/kg dry	1	"	"	"	"	
Dibromomethane	<0.22	0.22	0.028	mg/kg dry	1	"	"	"	"	
Dichlorodifluoromethane	<0.22	0.22	0.042	mg/kg dry	1	"	"	"	"	
Dichlorofluoromethane	<0.22	0.22	0.011	mg/kg dry	1	"	"	"	"	T5
Ethyl ether	<0.22	0.22	0.027	mg/kg dry	1	"	"	"	"	
Ethylbenzene	<0.22	0.22	0.024	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.56	0.56	0.089	mg/kg dry	1	"	"	"	"	
Isopropylbenzene	<0.22	0.22	0.034	mg/kg dry	1	"	"	"	"	
m,p-Xylene	<0.45	0.45	0.054	mg/kg dry	1	"	"	"	"	
Methyl isobutyl ketone	<0.22	0.22	0.048	mg/kg dry	1	"	"	"	"	
Methyl tert-butyl ether	<0.22	0.22	0.011	mg/kg dry	1	"	"	II .	•	
Methylene chloride	<0.56	0.56	0.067	mg/kg dry	1	"	"	"	"	
Naphthalene	<0.56	0.56	0.054	mg/kg dry	1	"	"	"	"	
n-Butylbenzene	<0.22	0.22	0.018	mg/kg dry	1	"	"	"	"	
n-Propylbenzene	<0.22	0.22	0.011	mg/kg dry	1	"	"	"	"	
o-Xylene	<0.22	0.22	0.019	mg/kg dry	1	"	"	"	"	
p-Isopropyltoluene	<0.22	0.22	0.012	mg/kg dry	1	"	"	"	"	
sec-Butylbenzene	<0.22	0.22	0.025	mg/kg dry	1	"	"	"	"	
Styrene	<0.22	0.22	0.018	mg/kg dry	1	"	"	"	"	
tert-Butylbenzene	<0.22	0.22	0.029	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-6_0-2 (1505280-11) Soil Sample	d: 11/24/15 13	:30 Re	eceived: 1	1/25/15 9:30						
Tetrachloroethene	<0.22	0.22	0.043	mg/kg dry	1	B5L0234	12/02/15	12/02/15	EPA 8260B	
Tetrahydrofuran	<1.1	1.1	0.12	mg/kg dry	1	"	"	"	"	T5
Toluene	<0.22	0.22	0.0076	mg/kg dry	1	u u	"	"	"	
trans-1,2-Dichloroethene	<0.22	0.22	0.020	mg/kg dry	1	n n	n .	m .	"	
trans-1,3-Dichloropropene	<0.22	0.22	0.022	mg/kg dry	1	"	"	"	"	
Trichloroethene	<0.22	0.22	0.020	mg/kg dry	1	"	"	"	"	
Trichlorofluoromethane	<0.22	0.22	0.033	mg/kg dry	1	"	"	"	"	
Vinyl chloride	<0.22	0.22	0.024	mg/kg dry	1	"	"	"	"	
Surrogate: 4-Bromofluorobenzene	87.0			80-124 %		"	"	"	"	
Surrogate: Dibromofluoromethane	96.3			77.1-123 %		"	"	"	"	
Surrogate: Toluene-d8	94.7			78.1-125 %		"	"	"	"	
B-6_6-8 (1505280-12) Soil Sample	ed: 11/24/15 13	3:30 Re	eceived: 1	1/25/15 9:30						
1,1,1,2-Tetrachloroethane	<0.25	0.25	0.025	mg/kg dry	1	B5L0234	12/02/15	12/02/15	EPA 8260B	
1,1,1-Trichloroethane	<0.25	0.25	0.029	mg/kg dry	1	"	"	"	"	
1,1,2,2-Tetrachloroethane	<0.25	0.25	0.020	mg/kg dry	1	"	"	"	"	
1,1,2-Trichloroethane	<0.25	0.25	0.018	mg/kg dry	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<0.25	0.25	0.025	mg/kg dry	1	"	"	"	"	T5
1,1-Dichloroethane	<0.25	0.25	0.012	mg/kg dry	1	"	"	"	"	
1,1-Dichloroethene	<0.25	0.25	0.016	mg/kg dry	1	"	"	"	"	
1,1-Dichloropropene	<0.25	0.25	0.019	mg/kg dry	1	"	"	"	"	
1,2,3-Trichlorobenzene	< 0.63	0.63	0.12	mg/kg dry	1	"	"	"	"	
1,2,3-Trichloropropane	<0.25	0.25	0.038	mg/kg dry	1	"	"	"	"	
1,2,4-Trichlorobenzene	<0.63	0.63	0.090	mg/kg dry	1	"	"	"	"	
1,2,4-Trimethylbenzene	<0.25	0.25	0.023	mg/kg dry	1	"	"	"	"	
1,2-Dibromo-3-chloropropane	<0.63	0.63	0.058	mg/kg dry	1	"	"	"	"	
1,2-Dibromoethane (EDB)	<0.25	0.25	0.030	mg/kg dry	1	"	"	"	"	
1,2-Dichlorobenzene	<0.25	0.25	0.016	mg/kg dry	1	"	"	"	"	
1,2-Dichloroethane	<0.25	0.25	0.028	mg/kg dry	1	"	"	"	"	
1,2-Dichloropropane	<0.25	0.25	0.027	mg/kg dry	1	"	"	"	"	
1,3,5-Trimethylbenzene	<0.25	0.25	0.032	mg/kg dry	1	"	"	"	"	
1,3-Dichlorobenzene	<0.25	0.25	0.011	mg/kg dry	1	"	"	"	"	
1,3-Dichloropropane	<0.25	0.25	0.019	mg/kg dry	1	"	"	"	"	
1,4-Dichlorobenzene	<0.25	0.25	0.020	mg/kg dry	1	"	"	"	"	
2,2-Dichloropropane	<0.25	0.25	0.066	mg/kg dry	1	II .	· ·	"	"	
2-Butanone	<1.3	1.3	0.12	mg/kg dry	1	"	"	"	"	
2-Chlorotoluene	<0.25	0.25	0.025	mg/kg dry	1	II .	· ·	"	"	
4-Chlorotoluene	<0.25	0.25	0.028	mg/kg dry	1	II .	· ·	"	"	
Acetone	<1.3	1.3	0.15	mg/kg dry	1	"	"	"	"	
Allyl chloride	<0.25	0.25	0.032	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-6_6-8 (1505280-12) Soil	Sampled: 11/24/15 13:	30	Received:	11/25/15 9:30						
Benzene	<0.25	0.25	0.019	mg/kg dry	1	B5L0234	12/02/15	12/02/15	EPA 8260B	
Bromobenzene	<0.25	0.25	0.025	mg/kg dry	1		"	"	"	
Bromochloromethane	<0.25	0.25	0.029	mg/kg dry	1	"	"	"	"	
Bromodichloromethane	<0.25	0.25	0.024	mg/kg dry	1	"	u u	II .	II .	
Bromoform	<0.25	0.25	0.046	mg/kg dry	1	"	· ·	n .	"	
Bromomethane	<0.25	0.25	0.038	mg/kg dry	1	"	"	"	"	
Carbon tetrachloride	<0.25	0.25	0.032	mg/kg dry	1	"	"	"	"	
Chlorobenzene	<0.25	0.25	0.018	mg/kg dry	1	"	"	"	"	
Chloroethane	<0.25	0.25	0.038	mg/kg dry	1	"	"	"	"	
Chloroform	<0.25	0.25	0.039	mg/kg dry	1	"	"	"	"	
Chloromethane	<0.25	0.25	0.034	mg/kg dry	1	"	"	"	"	
cis-1,2-Dichloroethene	<0.25	0.25	0.015	mg/kg dry	1	"	"	"	"	
cis-1,3-Dichloropropene	<0.25	0.25	0.032	mg/kg dry	1	"	"	"	"	
Dibromochloromethane	<0.25	0.25	0.032	mg/kg dry	1	"	"	"	"	
Dibromomethane	<0.25	0.25	0.032	mg/kg dry	1	"	"	"	"	
Dichlorodifluoromethane	<0.25	0.25	0.047	mg/kg dry	1	"	"	"	"	
Dichlorofluoromethane	<0.25	0.25	0.013	mg/kg dry	1	"	"	u u	"	T5
Ethyl ether	<0.25	0.25	0.030	mg/kg dry	1	"	"	"	"	
Ethylbenzene	<0.25	0.25	0.027	mg/kg dry	1	"	"	"	"	
Hexachlorobutadiene	<0.63	0.63	0.10	mg/kg dry	1	"	"	"	"	
Isopropylbenzene	<0.25	0.25	0.038	mg/kg dry	1	"	"	"	"	
m,p-Xylene	<0.51	0.51	0.061	mg/kg dry	1	"	"	u u	"	
Methyl isobutyl ketone	<0.25	0.25	0.054	mg/kg dry	1	II .	"	II .	"	
Methyl tert-butyl ether	<0.25	0.25	0.012	mg/kg dry	1	"	"	"	"	
Methylene chloride	<0.63	0.63	0.076	mg/kg dry	1	ıı	"	II .	"	
Naphthalene	<0.63	0.63	0.061	mg/kg dry	1	II .	· ·	II .	"	
n-Butylbenzene	<0.25	0.25	0.020	mg/kg dry	1	H .	"	n n	"	
n-Propylbenzene	<0.25	0.25	0.013	mg/kg dry	1	"	"	"	"	
o-Xylene	<0.25	0.25	0.022	mg/kg dry	1	H .	"	II .	"	
p-Isopropyltoluene	<0.25	0.25	0.014	mg/kg dry	1	"	"	"	"	
sec-Butylbenzene	<0.25	0.25	0.028	mg/kg dry	1	H .	"	II .	"	
Styrene	<0.25	0.25	0.020	mg/kg dry	1	II .	· ·	II .	"	
ert-Butylbenzene	<0.25	0.25	0.033	mg/kg dry	1	II .	· ·	II .	"	
Tetrachloroethene	<0.25	0.25	0.048	mg/kg dry	1	H .	"	II .	"	
Tetrahydrofuran	<1.3	1.3	0.14	mg/kg dry	1	H .	"	II .	"	T5
Toluene	<0.25	0.25	0.0086	mg/kg dry	1	II .	"	II .	"	
trans-1,2-Dichloroethene	<0.25	0.25	0.023	mg/kg dry	1	II .	"	II .	"	
trans-1,3-Dichloropropene	<0.25	0.25	0.025	mg/kg dry	1	"	"	"	"	
Trichloroethene	<0.25	0.25	0.023	mg/kg dry	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co.Project:345110104300 MarketPointe Drive, Suite 200Project Number:34511010Work Order #:1505280Minneapolis, MN 55435Project Manager:Ms. Andrea NordDate Reported:12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-6_6-8 (1505280-12) Soil Sampled	d: 11/24/15 13	:30 R	eceived: 1	1/25/15 9:30						
Trichlorofluoromethane	<0.25	0.25	0.037	mg/kg dry	1	B5L0234	12/02/15	12/02/15	EPA 8260B	
Vinyl chloride	<0.25	0.25	0.027	mg/kg dry	1	"	"	"	"	
Surrogate: 4-Bromofluorobenzene	88.9			80-124 %		"	"	"	"	
Surrogate: Dibromofluoromethane	98.7			77.1-123 %		"	"	"	"	
Surrogate: Toluene-d8	96.3			78.1-125 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Work Order #: 1505280
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/10/15

8015D DRO - Quality Control Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0301 - Sonication (Wisc DRO)											
Blank (B5L0301-BLK1)				ı	Prepared	l & Analyze	ed: 12/03/1	15			
Diesel Range Organics	< 8.0	8.0	1.7	mg/kg wet							
Surrogate: Triacontane (C-30)	17.2			mg/kg wet	16.0		108	70-130			
LCS (B5L0301-BS1)					Prepared	l & Analyze	ed: 12/03/1	15			
Diesel Range Organics	66.3	8.0	1.7	mg/kg wet	64.0		104	70-130			
Surrogate: Triacontane (C-30)	17.6			mg/kg wet	16.0		110	70-130			
LCS Dup (B5L0301-BSD1)					repared	l: 12/03/15	Analyzed	d: 12/04/15	;		
Diesel Range Organics	62.7	8.0	1.7	mg/kg wet	64.0		98.0	70-130	5.60	20	
Surrogate: Triacontane (C-30)	17.1			mg/kg wet	16.0		107	70-130			
Matrix Spike (B5L0301-MS1)	S	ource: 1	505280-	10	Prepared	l: 12/03/15	Analyzed	d: 12/04/15	;		
Diesel Range Organics	63.6	8.8	1.9	mg/kg dry	70.4	<8.8	90.3	70-130			
Surrogate: Triacontane (C-30)	17.4			mg/kg dry	17.6		98.7	70-130			
Matrix Spike Dup (B5L0301-MSD1)	S	ource: 1	505280-	·10 I	repared	l: 12/03/15	Analyzed	d: 12/04/15	j		
Diesel Range Organics	72.2	8.8	1.9	mg/kg dry	70.4	<8.8	102	70-130	12.7	30	
Surrogate: Triacontane (C-30)	19.2			mg/kg dry	17.6		109	70-130			



Fax: 651-642-1239

Barr Engineering Co.Project:345110104300 MarketPointe Drive, Suite 200Project Number:34511010Work Order #: 1505280Minneapolis, MN 55435Project Manager:Ms. Andrea NordDate Reported:12/10/15

8015D GRO - Quality Control Legend Technical Services, Inc.

					Spike	Source		%REC		%RPD	
Analyte	Result	RL	MDL	Units	Level	Result	%REC	Limits	%RPD	Limit	Notes
Batch B5L0123 - EPA 5035 Soil (Purg	ge and Trap))									
Blank (B5L0123-BLK1)					Prepared	ł & Analyz	ed: 12/01/	15			
Gasoline range organics	< 5.0	5.0	0.54	mg/kg wet							
Surrogate: 4-Fluorochlorobenzene	19.7			ug/L	20.0		98.5	80-150			
LCS (B5L0123-BS1)					Prepared	l & Analyz	ed: 12/01/	15			
Gasoline range organics	1000			ug/L	1000		100	80-120			
Surrogate: 4-Fluorochlorobenzene	21.4			ug/L	20.0		107	80-150			
LCS Dup (B5L0123-BSD1)					Prepared	l: 12/01/15	Analyzed	d: 12/02/15	;		
Gasoline range organics	1060			ug/L	1000		106	80-120	5.42	20	
Surrogate: 4-Fluorochlorobenzene	22.1			ug/L	20.0		110	80-150			
Duplicate (B5L0123-DUP1)	S	ource: 1	505280-	-05	Prepared	l: 12/01/15	Analyzed	d: 12/02/15	j		
Gasoline range organics	2.11	6.5	0.70	mg/kg dry		<6.5			NA	20	
Surrogate: 4-Fluorochlorobenzene	19.2			ug/L	20.0		96.0	80-150			
Matrix Spike (B5L0123-MS1)	S	ource: 1	505280-	-02	Prepared	l: 12/01/15	Analyzed	d: 12/02/15	;		
Gasoline range organics	986			ug/L	1000	42.6	94.3	70-130			
Surrogate: 4-Fluorochlorobenzene	21.4			ug/L	20.0		107	80-150			
Matrix Spike Dup (B5L0123-MSD1)	S	ource: 1	505280-	-02	Prepared	d: 12/01/15	Analyzed	d: 12/02/15	;	_	
Gasoline range organics	1000			ug/L	1000	42.6	95.9	70-130	1.59	20	
Surrogate: 4-Fluorochlorobenzene	21.5			ug/L	20.0		107	80-150			



Fax: 651-642-1239

Barr Engineering Co.Project:345110104300 MarketPointe Drive, Suite 200Project Number:34511010Work Order #:1505280Minneapolis, MN 55435Project Manager:Ms. Andrea NordDate Reported:12/10/15

TOTAL METALS ANALYSIS - Quality Control Legend Technical Services, Inc.

					Spike	Source		%REC		%RPD	
Analyte	Result	RL	MDL	Units	Level	Result	%REC	Limits	%RPD	Limit	Notes
Batch B5L0124 - EPA 3050B											
Blank (B5L0124-BLK1)				ı	Prepared:	12/01/15	Analyzed:	12/09/15			
Arsenic	< 0.50	0.50	0.10	mg/kg wet							
Barium	< 1.0	1.0	0.066	mg/kg wet							
Cadmium	< 0.25	0.25	0.0087	mg/kg wet							
Chromium	< 0.50	0.50	0.036	mg/kg wet							
Lead	< 1.0	1.0	0.062	mg/kg wet							
Mercury	< 0.50	0.50	0.23	mg/kg wet							
Selenium	< 1.0	1.0	0.29	mg/kg wet							
Silver	< 0.25	0.25	0.012	mg/kg wet							
LCS (B5L0124-BS1)					Prepared:	12/01/15	Analyzed:	12/09/15			
Arsenic	43.6	0.50	0.10	mg/kg wet	39.9		109	80-120			
Barium	43.1	1.0	0.066	mg/kg wet	39.9		108	80-120			
Cadmium	45.2	0.25	0.0087	mg/kg wet	39.9		113	80-120			
Chromium	44.4	0.50	0.036	mg/kg wet	39.9		111	80-120			
Lead	43.4	1.0	0.062	mg/kg wet	39.9		109	80-120			
Mercury	12.3	0.50	0.23	mg/kg wet	12.5		98.4	80-120			
Selenium	43.4	1.0	0.29	mg/kg wet	39.9		109	80-120			
Silver	4.28	0.25	0.012	mg/kg wet	3.99		107	80-120			
LCS Dup (B5L0124-BSD1)					Prepared:	12/01/15	Analyzed:	12/09/15			
Arsenic	43.1	0.50	0.10	mg/kg wet	39.9		108	80-120	1.27	20	
Barium	41.8	1.0	0.066	mg/kg wet	39.9		105	80-120	3.06	20	
Cadmium	45.7	0.25	0.0087	mg/kg wet	39.9		115	80-120	1.21	20	
Chromium	44.8	0.50	0.036	mg/kg wet	39.9		112	80-120	1.12	20	
Lead	43.4	1.0	0.062	mg/kg wet	39.9		109	80-120	0.00	20	
Mercury	11.8	0.50	0.23	mg/kg wet	12.5		94.0	80-120	4.57	20	
Selenium	44.2	1.0	0.29	mg/kg wet	39.9		111	80-120	1.94	20	
Silver	4.33	0.25	0.012	mg/kg wet	3.99		109	80-120	1.16	20	
Matrix Spike (B5L0124-MS1)	s	ource:	1505280-	0 1 l	Prepared:	12/01/15	Analyzed:	12/09/15			
Arsenic	58.0	0.68	0.14	mg/kg dry	53.5	4.07	101	75-125			
Barium	199	1.4	0.089	mg/kg dry	53.5	148	95.0	75-125			
Cadmium	53.7	0.34	0.012	mg/kg dry	53.5	< 0.34	100	75-125			
Chromium	71.8	0.68	0.049	mg/kg dry	53.5	15.4	105	75-125			
Lead	59.0	1.4	0.084	mg/kg dry	53.5	7.99	95.2	75-125			
Mercury	15.0	0.68	0.31	mg/kg dry	16.8	<0.68	89.2	75-125			
Selenium	53.0	1.4	0.39	mg/kg dry	53.5	<1.4	99.0	75-125			
Silver	5.23	0.34	0.016	mg/kg dry	5.35	<0.34	97.7	75-125			
Matrix Spike Dup (B5L0124-MSD1)	s	ource:	1505280-	01	Prepared:	12/01/15	Analyzed:	12/09/15			
Arsenic	53.3	0.68	0.14	mg/kg dry	53.3	4.07	92.4	75-125	8.39	20	
Barium	228	1.4	0.089	mg/kg dry	53.3	148	149	75-125	13.5	20	M1



Fax: 651-642-1239

Barr Engineering Co.Project:345110104300 MarketPointe Drive, Suite 200Project Number:34511010Work Order #: 1505280Minneapolis, MN 55435Project Manager:Ms. Andrea NordDate Reported:12/10/15

TOTAL METALS ANALYSIS - Quality Control Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0124 - EPA 3050B											
Matrix Spike Dup (B5L0124-MSD1)	S	ource:	1505280-	01	Prepared	I: 12/01/15	Analyzed	: 12/09/15			
Cadmium	50.5	0.34	0.012	mg/kg dry	53.3	< 0.34	94.6	75-125	6.12	20	
Chromium	70.2	0.68	0.049	mg/kg dry	53.3	15.4	103	75-125	2.22	20	
Lead	57.8	1.4	0.084	mg/kg dry	53.3	7.99	93.4	75-125	1.94	20	
Mercury	15.1	0.68	0.31	mg/kg dry	16.7	<0.68	90.4	75-125	0.999	20	
Selenium	50.0	1.4	0.39	mg/kg dry	53.3	<1.4	93.7	75-125	5.80	20	
Silver	4.90	0.34	0.016	mg/kg dry	5.33	<0.34	91.9	75-125	6.55	20	



Fax: 651-642-1239

Barr Engineering Co.Project:345110104300 MarketPointe Drive, Suite 200Project Number:34511010Work Order #:1505280Minneapolis, MN 55435Project Manager:Ms. Andrea NordDate Reported:12/10/15

PERCENT SOLIDS - Quality Control Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0306 - General Preparation											
Duplicate (B5L0306-DUP1)	S	ource:	1505280-0	7	Prepared	& Analyze	ed: 12/03/1	5			
% Solids	95.0			%		94.0			1.06	20	
Duplicate (B5L0306-DUP2)	S	ource:	1505293-0	3	Prepared	& Analyze	ed: 12/03/1	5			
% Solids	86.0			%		86.0			0.00	20	
Duplicate (B5L0306-DUP3)	s	ource:	1505328-0 ⁻	1	Prepared	& Analyze	ed: 12/03/1	5			
% Solids	79.0			%		80.0			1.26	20	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505280 Date Reported: 12/10/15

SVOC 8270D - Quality Control Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5K3002 - EPA 3545 ASE Ex											
Blank (B5K3002-BLK1)	ar aotron				Prepared	d & Analyz	ed: 11/30/1	5			
1,2,4-Trichlorobenzene	< 0.33	0.33	0.075	mg/kg wet	Горигос	a a many 2	ou. 11/00/1	•			
1,2-Dichlorobenzene	< 0.33	0.33		mg/kg wet							
1,2-Diphenylhydrazine as Azobenzene	< 0.33	0.33		mg/kg wet							
1,3-Dichlorobenzene	< 0.33	0.33	0.069	mg/kg wet							
1,4-Dichlorobenzene	< 0.33	0.33	0.068	mg/kg wet							
2,3,4,6-Tetrachlorophenol	< 0.67	0.67	0.19	mg/kg wet							
2,4,5-Trichlorophenol	< 0.67	0.67	0.071	mg/kg wet							
2,4,6-Trichlorophenol	< 0.67	0.67	0.16	mg/kg wet							
2,4-Dichlorophenol	< 0.67	0.67	0.15	mg/kg wet							
2,4-Dimethylphenol	< 0.67	0.67	0.13	mg/kg wet							
2,4-Dinitrophenol	< 0.67	0.67	0.071	mg/kg wet							
2,4-Dinitrotoluene	< 0.33	0.33	0.068	mg/kg wet							
2,6-Dichlorophenol	< 0.67	0.67	0.13	mg/kg wet							
2,6-Dinitrotoluene	< 0.33	0.33	0.077	mg/kg wet							
2-Chloronaphthalene	< 0.33	0.33	0.068	mg/kg wet							
2-Chlorophenol	< 0.67	0.67	0.15	mg/kg wet							
2-Methylnaphthalene	< 0.33	0.33	0.080	mg/kg wet							
2-Methylphenol	< 0.67	0.67	0.082	mg/kg wet							
2-Nitroaniline	< 0.33	0.33	0.069	mg/kg wet							
2-Nitrophenol	< 0.67	0.67	0.18	mg/kg wet							
3&4-Methylphenol	< 0.67	0.67	0.082	mg/kg wet							
3,3´-Dichlorobenzidine	< 1.6	1.6	0.45	mg/kg wet							
3-Nitroaniline	< 0.33	0.33	0.072	mg/kg wet							
4,6-Dinitro-2-methylphenol	< 0.67	0.67	0.11	mg/kg wet							
4-Bromophenyl phenyl ether	< 0.33	0.33	0.068	mg/kg wet							
4-Chloro-3-methylphenol	< 0.67	0.67	0.14	mg/kg wet							
4-Chloroaniline	< 0.67	0.67	0.067	mg/kg wet							
4-Chlorophenyl phenyl ether	< 0.33	0.33	0.068	mg/kg wet							
4-Nitroaniline	< 0.33	0.33	0.083	mg/kg wet							
4-Nitrophenol	< 0.67	0.67	0.17	mg/kg wet							
Acenaphthene	< 0.33	0.33	0.063	mg/kg wet							
Acenaphthylene	< 0.33	0.33	0.071	mg/kg wet							
Aniline	< 0.67	0.67	0.066	mg/kg wet							
Anthracene	< 0.33	0.33	0.069	mg/kg wet							
Benzidine	< 2.5	2.5	0.44	mg/kg wet							
Benzo(a)anthracene	< 0.33	0.33	0.065	mg/kg wet							
Benzo(a)pyrene	< 0.33	0.33	0.070	mg/kg wet							
Benzo(b)fluoranthene	< 0.33	0.33	0.059	mg/kg wet							
5 (1 %)			0 0 - 1								

0.071 mg/kg wet

< 0.33 0.33

Benzo(g,h,i)perylene



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Work Order #: 1505280
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/10/15

SVOC 8270D - Quality Control Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5K3002 - EPA 3545 ASE Extract	ion										
Blank (B5K3002-BLK1)				F	Prepared	l & Analyze	d: 11/30/1	5			
Benzo(k)fluoranthene	< 0.33	0.33	0.070	mg/kg wet							
Benzoic acid	< 0.33	0.33	0.064	mg/kg wet							
Benzyl alcohol	< 0.67	0.67	0.15	mg/kg wet							
Bis(2-chloroethoxy)methane	< 0.33	0.33	0.077	mg/kg wet							
Bis(2-chloroethyl)ether	< 0.33	0.33	0.069	mg/kg wet							
Bis(2-chloroisopropyl)ether	< 0.33	0.33	0.078	mg/kg wet							
Bis(2-ethylhexyl)phthalate	< 0.33	0.33	0.081	mg/kg wet							
Butyl benzyl phthalate	< 0.33	0.33	0.083	mg/kg wet							
Carbazole	< 0.33	0.33	0.076	mg/kg wet							
Chrysene	< 0.33	0.33	0.064	mg/kg wet							
Dibenz(a,h)anthracene	< 0.33	0.33	0.082	mg/kg wet							
Dibenzofuran	< 0.33	0.33	0.068	mg/kg wet							
Diethyl phthalate	< 0.33	0.33	0.063	mg/kg wet							
Dimethyl phthalate	< 0.33	0.33	0.069	mg/kg wet							
Di-n-butyl phthalate	< 0.33	0.33	0.079	mg/kg wet							
Di-n-octyl phthalate	< 0.33	0.33	0.10	mg/kg wet							
Fluoranthene	< 0.33	0.33	0.068	mg/kg wet							
Fluorene	< 0.33	0.33	0.065	mg/kg wet							
Hexachlorobenzene	< 0.33	0.33	0.062	mg/kg wet							
Hexachlorobutadiene	< 0.33	0.33	0.077	mg/kg wet							
Hexachlorocyclopentadiene	< 0.33	0.33	0.069	mg/kg wet							
Hexachloroethane	< 0.33	0.33	0.082	mg/kg wet							
Indeno (1,2,3-cd) pyrene	< 0.33	0.33	0.072	mg/kg wet							
Isophorone	< 0.33	0.33	0.076	mg/kg wet							
Naphthalene	< 0.33	0.33	0.071	mg/kg wet							
Nitrobenzene	< 0.33	0.33	0.080	mg/kg wet							
N-Nitrosodimethylamine	< 0.33	0.33	0.070	mg/kg wet							
N-Nitrosodi-n-propylamine	< 0.33	0.33	0.073	mg/kg wet							
N-Nitrosodiphenylamine	< 0.33	0.33	0.067	mg/kg wet							
Pentachlorophenol	< 0.67	0.67	0.19	mg/kg wet							
Phenanthrene	< 0.33	0.33	0.066	mg/kg wet							
Phenol	< 0.67	0.67	0.14	mg/kg wet							
Pyrene	< 0.33	0.33	0.059	mg/kg wet							
Surrogate: 2,4,6-Tribromophenol	4.91			mg/kg wet	6.67		73.7	53-107			
Surrogate: 2-Fluorobiphenyl	4.92			mg/kg wet	6.67		73.7	53.9-97.9			
Surrogate: 2-Fluorophenol	4.60			mg/kg wet	6.67		69.0	42.5-94.9			
Surrogate: Nitrobenzene-d5	4.52			mg/kg wet	6.67		67.7	48.9-100			
Surrogate: Phenol-d6	4.82			mg/kg wet	6.67		72.3	50.4-99.6			
Surrogate: Terphenyl-d14	4.11			mg/kg wet	6.67		61.6	51-99.6			



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Work Order #: 1505280
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/10/15

SVOC 8270D - Quality Control Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5K3002 - EPA 3545 ASE Extrac	tion					_ 				_ 	
LCS (B5K3002-BS1)				F	repared	I & Analyze	nd: 11/30/1	5			
1,2,4-Trichlorobenzene	2.39	0.33	0.075		•		71.7	50-100			
1,4-Dichlorobenzene	2.24	0.33	0.068				67.2	40-80			
2,4-Dinitrotoluene	2.69	0.33	0.068	mg/kg wet			80.6	50-90			
2-Chlorophenol	2.39	0.67	0.15	mg/kg wet	3.33		71.8	50-85			
4-Chloro-3-methylphenol	2.67	0.67	0.14	mg/kg wet	3.33		80.1	55-90			
4-Nitrophenol	3.07	0.67	0.17	mg/kg wet	3.33		92.2	45-100			
Anthracene	2.73	0.33	0.069	mg/kg wet	3.33		81.8	55-95			
Benzo(a)anthracene	2.79	0.33	0.065	mg/kg wet	3.33		83.8	55-100			
Benzo(a)pyrene	2.60	0.33	0.070	mg/kg wet	3.33		78.1	55-100			
Chrysene	2.89	0.33	0.064	mg/kg wet	3.33		86.7	55-100			
Fluoranthene	2.77	0.33	0.068	mg/kg wet	3.33		83.0	55-95			
Fluorene	2.68	0.33	0.065	mg/kg wet	3.33		80.3	55-95			
N-Nitrosodi-n-propylamine	2.51	0.33	0.073	mg/kg wet	3.33		75.4	50-90			
Pentachlorophenol	2.51	0.67	0.19	mg/kg wet	3.33		75.2	35-95			
Phenanthrene	2.71	0.33	0.066	mg/kg wet	3.33		81.4	55-95			
Phenol	2.52	0.67	0.14	mg/kg wet	3.33		75.5	50-85			
Surrogate: 2,4,6-Tribromophenol	5.60			mg/kg wet	6.67		84.0	53-107			
Surrogate: 2-Fluorobiphenyl	5.26			mg/kg wet	6.67		78.8	53.9-97.9			
Surrogate: 2-Fluorophenol	4.89			mg/kg wet	6.67		73.4	42.5-94.9			
Surrogate: Nitrobenzene-d5	4.82			mg/kg wet	6.67		72.3	48.9-100			
Surrogate: Phenol-d6	5.11			mg/kg wet	6.67		76.7	50.4-99.6			
Surrogate: Terphenyl-d14	3.85			mg/kg wet	6.67		57.8	51-99.6			
Matrix Spike (B5K3002-MS1)	s	ource:	1505201-	01	repared	I & Analyze	d: 11/30/1	5			
1,2,4-Trichlorobenzene	2.77	0.37	0.083	mg/kg dry	3.71	<0.37	74.5	35-100			
1,4-Dichlorobenzene	2.58	0.37	0.076	mg/kg dry	3.71	<0.37	69.5	30-85			
2,4-Dinitrotoluene	2.96	0.37	0.076	mg/kg dry	3.71	<0.37	79.7	45-95			
2-Chlorophenol	2.71	0.74	0.17	mg/kg dry	3.71	<0.74	73.1	35-100			
4-Chloro-3-methylphenol	2.91	0.74	0.16	mg/kg dry	3.71	<0.74	78.4	35-100			
4-Nitrophenol	3.11	0.74	0.19	mg/kg dry	3.71	<0.74	83.7	40-100			
Anthracene	3.11	0.37	0.077	mg/kg dry	3.71	<0.37	83.8	55-100			
Benzo(a)anthracene	2.98	0.37	0.072	mg/kg dry	3.71	<0.37	80.4	50-100			
Benzo(a)pyrene	2.87	0.37	0.078	mg/kg dry	3.71	<0.37	77.2	50-100			
Chrysene	3.29	0.37	0.071	mg/kg dry	3.71	<0.37	88.7	50-100			
Fluoranthene	2.90	0.37	0.076		3.71	<0.37	78.2	50-100			
Fluorene	2.99	0.37	0.072		3.71	<0.37	80.6	50-100			
N-Nitrosodi-n-propylamine	2.89	0.37	0.081		3.71	<0.37	77.7	35-100			
Pentachlorophenol	3.10	0.74	0.21	mg/kg dry	3.71	<0.74	83.5	30-100			
Phenanthrene	3.14	0.37	0.073	mg/kg dry	3.71	<0.37	84.6	55-100			
Phenol	2.82	0.74	0.16	mg/kg dry	3.71	<0.74	76.0	35-100			



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Work Order #: 1505280
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/10/15

SVOC 8270D - Quality Control Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5K3002 - EPA 3545 ASE Ext	raction										
Matrix Spike (B5K3002-MS1)	S	ource:	1505201-	01	Prepared	ł & Analyze	ed: 11/30/	15			
Surrogate: 2,4,6-Tribromophenol	5.92			mg/kg dry	7.42	•	79.8	53-107			
Surrogate: 2-Fluorobiphenyl	5.33			mg/kg dry	7.42		71.8	53.9-97.9			
Surrogate: 2-Fluorophenol	5.38			mg/kg dry	7.42		72.5	42.5-94.9			
Surrogate: Nitrobenzene-d5	5.31			mg/kg dry	7.42		71.5	48.9-100			
Surrogate: Phenol-d6	5.71			mg/kg dry	7.42		77.0	50.4-99.6			
Surrogate: Terphenyl-d14	4.13			mg/kg dry	7.42		55.6	51-99.6			
Matrix Spike Dup (B5K3002-MSD1)	S	ource:	1505201-	01	Prepared	l & Analyze	ed: 11/30/	15			
1,2,4-Trichlorobenzene	2.70	0.37	0.083	mg/kg dry	3.70	< 0.37	72.9	35-100	2.50	20	
1,4-Dichlorobenzene	2.53	0.37	0.076	mg/kg dry	3.70	< 0.37	68.3	30-85	2.02	20	
2,4-Dinitrotoluene	2.89	0.37	0.076	mg/kg dry	3.70	< 0.37	78.2	45-95	2.19	20	
2-Chlorophenol	2.65	0.74	0.17	mg/kg dry	3.70	< 0.74	71.6	35-100	2.39	20	
4-Chloro-3-methylphenol	2.83	0.74	0.16	mg/kg dry	3.70	< 0.74	76.5	35-100	2.78	20	
4-Nitrophenol	3.06	0.74	0.19	mg/kg dry	3.70	< 0.74	82.8	40-100	1.48	20	
Anthracene	3.07	0.37	0.077	mg/kg dry	3.70	< 0.37	83.0	55-100	1.31	20	
Benzo(a)anthracene	2.90	0.37	0.072	mg/kg dry	3.70	< 0.37	78.3	50-100	2.97	20	
Benzo(a)pyrene	2.81	0.37	0.078	mg/kg dry	3.70	< 0.37	75.9	50-100	2.03	20	
Chrysene	3.21	0.37	0.071	mg/kg dry	3.70	< 0.37	86.9	50-100	2.40	20	
Fluoranthene	2.85	0.37	0.076	mg/kg dry	3.70	< 0.37	77.1	50-100	1.77	20	
Fluorene	2.92	0.37	0.072	mg/kg dry	3.70	< 0.37	78.8	50-100	2.57	20	
N-Nitrosodi-n-propylamine	2.83	0.37	0.081	mg/kg dry	3.70	< 0.37	76.4	35-100	2.05	20	
Pentachlorophenol	3.00	0.74	0.21	mg/kg dry	3.70	<0.74	81.2	30-100	3.16	20	
Phenanthrene	3.07	0.37	0.073	mg/kg dry	3.70	< 0.37	83.1	55-100	2.10	20	
Phenol	2.75	0.74	0.16	mg/kg dry	3.70	<0.74	74.2	35-100	2.76	20	
Surrogate: 2,4,6-Tribromophenol	5.79			mg/kg dry	7.40		78.3	53-107			
Surrogate: 2-Fluorobiphenyl	5.25			mg/kg dry	7.40		71.0	53.9-97.9			
Surrogate: 2-Fluorophenol	5.31			mg/kg dry	7.40		71.8	42.5-94.9			
Surrogate: Nitrobenzene-d5	5.14			mg/kg dry	7.40		69.4	48.9-100			
Surrogate: Phenol-d6	5.60			mg/kg dry	7.40		75.7	50.4-99.6			
Surrogate: Terphenyl-d14	4.00			mg/kg dry	7.40		54.0	51-99.6			



Fax: 651-642-1239

Work Order #: 1505280

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
			IVIDL	Office	FEAGI	Nesull	/0NLU	LIIIIIIS	/0IXFD	LIIIII	140162
Batch B5L0233 - EPA 5035 Soil (F	rurge and Irap)			Dronore -	10 Anabr-	nd: 10/01/4	15			
Blank (B5L0233-BLK1) 1,1,1,2-Tetrachloroethane	. 0. 20	0.00	0.000		Prepared	l & Analyze	ea: 12/01/1	15			
1,1,1-Trichloroethane	< 0.20 < 0.20	0.20 0.20	0.020 0.023	mg/kg wet							
	< 0.20	0.20		mg/kg wet							
1,1,2,2-Tetrachloroethane 1,1,2-Trichloroethane	< 0.20	0.20		mg/kg wet mg/kg wet							
1,1,2-Trichlorottifluoroethane	< 0.20	0.20	0.020	mg/kg wet							
1,1-Dichloroethane	< 0.20	0.20		mg/kg wet							
1,1-Dichloroethene	< 0.20	0.20		mg/kg wet							
1,1-Dichloropropene	< 0.20	0.20		mg/kg wet							
1,2,3-Trichlorobenzene	< 0.50	0.50		mg/kg wet							
1,2,3-Trichloropropane	< 0.20	0.20	0.030	mg/kg wet							
1,2,4-Trichlorobenzene	< 0.50	0.50	0.030	mg/kg wet							
1,2,4-Trimethylbenzene	< 0.20	0.20	0.018	mg/kg wet							
1,2-Dibromo-3-chloropropane	< 0.50	0.50	0.046	mg/kg wet							
1,2-Dibromoethane (EDB)	< 0.20	0.20	0.024	mg/kg wet							
1,2-Dichlorobenzene	< 0.20	0.20		mg/kg wet							
1,2-Dichloroethane	< 0.20	0.20		mg/kg wet							
1,2-Dichloropropane	< 0.20	0.20	0.022	mg/kg wet							
1,3,5-Trimethylbenzene	< 0.20	0.20		mg/kg wet							
1,3-Dichlorobenzene	< 0.20	0.20		mg/kg wet							
1,3-Dichloropropane	< 0.20	0.20		mg/kg wet							
1,4-Dichlorobenzene	< 0.20	0.20		mg/kg wet							
2,2-Dichloropropane	< 0.20	0.20		mg/kg wet							
2-Butanone	< 1.0	1.0	0.094	mg/kg wet							
2-Chlorotoluene	< 0.20	0.20	0.020	mg/kg wet							
4-Chlorotoluene	< 0.20	0.20		mg/kg wet							
Acetone	< 1.0	1.0	0.12	mg/kg wet							
Allyl chloride	< 0.20	0.20		mg/kg wet							
Benzene	< 0.20	0.20		mg/kg wet							
Bromobenzene	< 0.20	0.20	0.020	mg/kg wet							
Bromochloromethane	< 0.20	0.20	0.023	mg/kg wet							
Bromodichloromethane	< 0.20	0.20	0.019	mg/kg wet							
Bromoform	< 0.20	0.20	0.036	mg/kg wet							
Bromomethane	< 0.20	0.20		mg/kg wet							
Carbon tetrachloride	< 0.20	0.20		mg/kg wet							
Chlorobenzene	< 0.20	0.20		mg/kg wet							
Chloroethane	< 0.20	0.20		mg/kg wet							
Chloroform	< 0.20	0.20		mg/kg wet							
Chloromethane	< 0.20	0.20		mg/kg wet							
cis-1,2-Dichloroethene	< 0.20	0.20		mg/kg wet							
•				0 0							



Fax: 651-642-1239

Barr Engineering Co.Project:345110104300 MarketPointe Drive, Suite 200Project Number:34511010Work Order #:1505280Minneapolis, MN 55435Project Manager:Ms. Andrea NordDate Reported:12/10/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0233 - EPA 5035 Soil (Pu	urge and Trap)				_					
Blank (B5L0233-BLK1)				1	Prepared	l & Analyze	ed: 12/01/1	15			
cis-1,3-Dichloropropene	< 0.20	0.20	0.025	mg/kg wet							
Dibromochloromethane	< 0.20	0.20	0.025	mg/kg wet							
Dibromomethane	< 0.20	0.20	0.025	mg/kg wet							
Dichlorodifluoromethane	< 0.20	0.20	0.037	mg/kg wet							
Dichlorofluoromethane	< 0.20	0.20	0.010	mg/kg wet							
Ethyl ether	< 0.20	0.20	0.024	mg/kg wet							
Ethylbenzene	< 0.20	0.20	0.021	mg/kg wet							
Hexachlorobutadiene	< 0.50	0.50	0.079	mg/kg wet							
Isopropylbenzene	< 0.20	0.20	0.030	mg/kg wet							
m,p-Xylene	< 0.40	0.40	0.048	mg/kg wet							
Methyl isobutyl ketone	< 0.20	0.20	0.043	mg/kg wet							
Methyl tert-butyl ether	< 0.20	0.20	0.0097	mg/kg wet							
Methylene chloride	< 0.50	0.50	0.060	mg/kg wet							
Naphthalene	< 0.50	0.50	0.048	mg/kg wet							
n-Butylbenzene	< 0.20	0.20	0.016	mg/kg wet							
n-Propylbenzene	< 0.20	0.20	0.010	mg/kg wet							
o-Xylene	< 0.20	0.20	0.017	mg/kg wet							
p-Isopropyltoluene	< 0.20	0.20	0.011	mg/kg wet							
sec-Butylbenzene	< 0.20	0.20	0.022	mg/kg wet							
Styrene	< 0.20	0.20	0.016	mg/kg wet							
tert-Butylbenzene	< 0.20	0.20	0.026	mg/kg wet							
Tetrachloroethene	< 0.20	0.20	0.038	mg/kg wet							
Tetrahydrofuran	< 1.0	1.0	0.11	mg/kg wet							
Toluene	< 0.20	0.20		mg/kg wet							
trans-1,2-Dichloroethene	< 0.20	0.20		mg/kg wet							
trans-1,3-Dichloropropene	< 0.20	0.20		mg/kg wet							
Trichloroethene	< 0.20	0.20	0.018	mg/kg wet							
Trichlorofluoromethane	< 0.20	0.20	0.029	mg/kg wet							
Vinyl chloride	< 0.20	0.20	0.021	mg/kg wet							
Surrogate: 4-Bromofluorobenzene	49.7			ug/L	56.0		88.8	80-124			
Surrogate: Dibromofluoromethane	54.7			ug/L	56.0		97.7	77.1-123			
Surrogate: Toluene-d8	54.5			ug/L	56.0		97.3	78.1-125			
LCS (B5L0233-BS1)				I	Prepared	l & Analyze	ed: 12/01/1	15			
1,1,2,2-Tetrachloroethane	50.7			ug/L	50.0		101	75-120			
1,1-Dichloroethane	48.7			ug/L	50.0		97.4	79.6-120			
1,1-Dichloroethene	49.2			ug/L	50.0		98.4	78.3-120			
1,3,5-Trimethylbenzene	47.8			ug/L	50.0		95.6	77-120			
1,4-Dichlorobenzene	46.0			ug/L	50.0		92.0	75-125			
2-Chlorotoluene	47.8			ug/L	50.0		95.6	75.9-120			



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Work Order #: 1505280
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0233 - EPA 5035 Soil (Pur	ge and Trap))									
LCS (B5L0233-BS1)					Prepared	l & Analyze	ed: 12/01/	15			
Benzene	49.6			ug/L	50.0	-	99.3	80-120			
Bromoform	51.6			ug/L	50.0		103	80-120			
Chlorobenzene	49.5			ug/L	50.0		99.1	80-120			
Chloroform	48.5			ug/L	50.0		97.0	80-120			
Ethylbenzene	49.6			ug/L	50.0		99.2	80-120			
n-Butylbenzene	48.1			ug/L	50.0		96.1	75-125			
n-Propylbenzene	48.0			ug/L	50.0		96.1	75-120			
Toluene	48.7			ug/L	50.0		97.5	80-120			
Trichloroethene	48.8			ug/L	50.0		97.6	80-120			
Vinyl chloride	46.4			ug/L	50.0		92.8	75-130			
Surrogate: 4-Bromofluorobenzene	51.5			ug/L	56.0		91.9	80-124			
Surrogate: Dibromofluoromethane	54.1			ug/L	56.0		96.7	77.1-123			
Surrogate: Toluene-d8	53.7			ug/L	56.0		95.8	78.1-125			
Matrix Spike (B5L0233-MS1)	S	ource: 1	505280-0)1	Prepared	l & Analyze	ed: 12/01/	15			
,1,2,2-Tetrachloroethane	49.7			ug/L	50.0	<	99.5	75-125			
,1-Dichloroethane	49.9			ug/L	50.0	<	99.9	78.7-123			
,1-Dichloroethene	49.5			ug/L	50.0	<	99.0	75.8-121			
,3,5-Trimethylbenzene	48.0			ug/L	50.0	<	96.1	75-120			
,4-Dichlorobenzene	45.9			ug/L	50.0	<	91.9	75-125			
2-Chlorotoluene	48.3			ug/L	50.0	<	96.7	75-120			
Benzene	50.0			ug/L	50.0	<	100	80-120			
Bromoform	50.6			ug/L	50.0	<	101	80-120			
Chlorobenzene	49.2			ug/L	50.0	<	98.3	80-120			
Chloroform	49.3			ug/L	50.0	<	98.6	80-120			
Ethylbenzene	49.5			ug/L	50.0	<	99.0	80-120			
n-Butylbenzene	47.5			ug/L	50.0	<	94.9	73.8-125			
n-Propylbenzene	48.8			ug/L	50.0	<	97.5	75-120			
Toluene	50.4			ug/L	50.0	<	101	80-120			
Trichloroethene	49.5			ug/L	50.0	<	99.1	80-120			
/inyl chloride	46.3			ug/L	50.0	<	92.6	74.8-130			
Surrogate: 4-Bromofluorobenzene	51.5			ug/L	56.0		92.1	80-124			
Surrogate: Dibromofluoromethane	55.5			ug/L	56.0		99.1	77.1-123			
Surrogate: Toluene-d8	53.9			ug/L	56.0		96.3	78.1-125			
Matrix Spike Dup (B5L0233-MSD1)	S	ource: 1	505280-0)1	Prepared	l & Analyze	ed: 12/01/	15			
1,1,2,2-Tetrachloroethane	50.8			ug/L	50.0	<	102	75-125	2.11	20	
I,1-Dichloroethane	50.2			ug/L	50.0	<	100	78.7-123	0.460	20	
1,1-Dichloroethene	48.8			ug/L	50.0	<	97.5	75.8-121	1.51	20	
1,3,5-Trimethylbenzene	49.0			ug/L	50.0	<	98.1	75-120	2.05	20	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Work Order #: 1505280 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/10/15

VOC 8260B - Quality Control Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0233 - EPA 5035 Soil (Pur	ge and Trap)									
Matrix Spike Dup (B5L0233-MSD1)	S	ource: 1	505280-0)1	Prepared	l & Analyze	ed: 12/01/	15			
1,4-Dichlorobenzene	46.0			ug/L	50.0	<	92.1	75-125	0.229	20	
2-Chlorotoluene	49.0			ug/L	50.0	<	98.0	75-120	1.38	20	
Benzene	49.7			ug/L	50.0	<	99.4	80-120	0.551	20	
Bromoform	49.6			ug/L	50.0	<	99.3	80-120	2.00	20	
Chlorobenzene	48.3			ug/L	50.0	<	96.6	80-120	1.74	20	
Chloroform	49.6			ug/L	50.0	<	99.2	80-120	0.598	20	
Ethylbenzene	49.0			ug/L	50.0	<	98.1	80-120	0.990	20	
n-Butylbenzene	49.1			ug/L	50.0	<	98.1	73.8-125	3.31	20	
n-Propylbenzene	49.6			ug/L	50.0	<	99.3	75-120	1.79	20	
Toluene	50.3			ug/L	50.0	<	101	80-120	0.284	20	
Trichloroethene	49.0			ug/L	50.0	<	98.0	80-120	1.11	20	
Vinyl chloride	44.9			ug/L	50.0	<	89.7	74.8-130	3.16	20	
Surrogate: 4-Bromofluorobenzene	52.1			ug/L	56.0		93.0	80-124			
Surrogate: Dibromofluoromethane	55.0			ug/L	56.0		98.2	77.1-123			
Surrogate: Toluene-d8	54.4			ug/L	56.0		97.2	78.1-125			

0.020 mg/kg wet

Batch B5L0234 - EPA 5035 Soil (Purge and Trap)

1,1,1,2-Tetrachloroethane

Blank (B5L0234-BLK1)	Prepared & Analyzed: 12/02/15

< 0.20 0.20

1,1,1-Trichloroethane	< 0.20	0.20	0.023 mg/kg wet
1,1,2,2-Tetrachloroethane	< 0.20	0.20	0.016 mg/kg wet
1,1,2-Trichloroethane	< 0.20	0.20	0.014 mg/kg wet
1,1,2-Trichlorotrifluoroethane	< 0.20	0.20	0.020 mg/kg wet
1,1-Dichloroethane	< 0.20	0.20	0.0097 mg/kg wet
1,1-Dichloroethene	< 0.20	0.20	0.013 mg/kg wet
1,1-Dichloropropene	< 0.20	0.20	0.015 mg/kg wet
1,2,3-Trichlorobenzene	< 0.50	0.50	0.097 mg/kg wet
1,2,3-Trichloropropane	< 0.20	0.20	0.030 mg/kg wet
1,2,4-Trichlorobenzene	< 0.50	0.50	0.071 mg/kg wet
1,2,4-Trimethylbenzene	< 0.20	0.20	0.018 mg/kg wet
1,2-Dibromo-3-chloropropane	< 0.50	0.50	0.046 mg/kg wet
1,2-Dibromoethane (EDB)	< 0.20	0.20	0.024 mg/kg wet
1,2-Dichlorobenzene	< 0.20	0.20	0.013 mg/kg wet
1,2-Dichloroethane	< 0.20	0.20	0.022 mg/kg wet
1,2-Dichloropropane	< 0.20	0.20	0.021 mg/kg wet
1,3,5-Trimethylbenzene	< 0.20	0.20	0.025 mg/kg wet
1,3-Dichlorobenzene	< 0.20	0.20	0.0090 mg/kg wet
1,3-Dichloropropane	< 0.20	0.20	0.015 mg/kg wet
1,4-Dichlorobenzene	< 0.20	0.20	0.016 mg/kg wet
2,2-Dichloropropane	< 0.20	0.20	0.052 mg/kg wet



Fax: 651-642-1139

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0234 - EPA 5035 Soil (Purge	and Trap)									
Blank (B5L0234-BLK1)					Prepared	d & Analyze	ed: 12/02/1	5			
2-Butanone	< 1.0	1.0	0.094	mg/kg wet							
2-Chlorotoluene	< 0.20	0.20	0.020	mg/kg wet							
4-Chlorotoluene	< 0.20	0.20	0.022	mg/kg wet							
Acetone	< 1.0	1.0	0.12	mg/kg wet							
Allyl chloride	< 0.20	0.20	0.025	mg/kg wet							
Benzene	< 0.20	0.20	0.015	mg/kg wet							
Bromobenzene	< 0.20	0.20	0.020	mg/kg wet							
Bromochloromethane	< 0.20	0.20	0.023	mg/kg wet							
Bromodichloromethane	< 0.20	0.20	0.019	mg/kg wet							
Bromoform	< 0.20	0.20	0.036	mg/kg wet							
Bromomethane	< 0.20	0.20	0.030	mg/kg wet							
Carbon tetrachloride	< 0.20	0.20	0.025	mg/kg wet							
Chlorobenzene	< 0.20	0.20	0.014	mg/kg wet							
Chloroethane	< 0.20	0.20	0.030	mg/kg wet							
Chloroform	< 0.20	0.20	0.031	mg/kg wet							
Chloromethane	< 0.20	0.20	0.027	mg/kg wet							
cis-1,2-Dichloroethene	< 0.20	0.20	0.012	mg/kg wet							
cis-1,3-Dichloropropene	< 0.20	0.20	0.025	mg/kg wet							
Dibromochloromethane	< 0.20	0.20	0.025	mg/kg wet							
Dibromomethane	< 0.20	0.20	0.025	mg/kg wet							
Dichlorodifluoromethane	< 0.20	0.20	0.037	mg/kg wet							
Dichlorofluoromethane	< 0.20	0.20	0.010	mg/kg wet							
Ethyl ether	< 0.20	0.20		mg/kg wet							
Ethylbenzene	< 0.20	0.20	0.021	mg/kg wet							
Hexachlorobutadiene	< 0.50	0.50	0.079	mg/kg wet							
Isopropylbenzene	< 0.20	0.20	0.030	mg/kg wet							
m,p-Xylene	< 0.40	0.40	0.048	mg/kg wet							
Methyl isobutyl ketone	< 0.20	0.20		mg/kg wet							
Methyl tert-butyl ether	< 0.20	0.20		mg/kg wet							
Methylene chloride	< 0.50	0.50		mg/kg wet							
Naphthalene	< 0.50	0.50		mg/kg wet							
n-Butylbenzene	< 0.20	0.20		mg/kg wet							
n-Propylbenzene	< 0.20	0.20		mg/kg wet							
o-Xylene	< 0.20	0.20		mg/kg wet							
p-Isopropyltoluene	< 0.20	0.20		mg/kg wet							
sec-Butylbenzene	< 0.20	0.20		mg/kg wet							
Styrene	< 0.20	0.20		mg/kg wet							
tert-Butylbenzene	< 0.20	0.20		mg/kg wet							
Tetrachloroethene	< 0.20	0.20	0.038	mg/kg wet							



Fax: 651-642-1239

Barr Engineering Co.Project:345110104300 MarketPointe Drive, Suite 200Project Number:34511010Work Order #: 1505280Minneapolis, MN 55435Project Manager:Ms. Andrea NordDate Reported:12/10/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0234 - EPA 5035 Soil (Pu	urge and Trap)									
Blank (B5L0234-BLK1)	• •				Prepared	I & Analyze	ed: 12/02/	15			
Tetrahydrofuran	< 1.0	1.0	0.11	mg/kg wet		,					
Toluene	< 0.20	0.20	0.0068	mg/kg wet							
trans-1,2-Dichloroethene	< 0.20	0.20	0.018	mg/kg wet							
trans-1,3-Dichloropropene	< 0.20	0.20	0.020	mg/kg wet							
Trichloroethene	< 0.20	0.20	0.018	mg/kg wet							
Trichlorofluoromethane	< 0.20	0.20	0.029	mg/kg wet							
Vinyl chloride	< 0.20	0.20	0.021	mg/kg wet							
Surrogate: 4-Bromofluorobenzene	50.9			ug/L	56.0		90.8	80-124			
Surrogate: Dibromofluoromethane	54.6			ug/L	56.0		97.4	77.1-123			
Surrogate: Toluene-d8	53.9			ug/L	56.0		96.3	78.1-125			
LCS (B5L0234-BS1)					Prepared	l & Analyze	ed: 12/02/	15			
1,1,2,2-Tetrachloroethane	51.3			ug/L	50.0	-	103	75-120			
1,1-Dichloroethane	49.0			ug/L	50.0		98.0	79.6-120			
1,1-Dichloroethene	48.9			ug/L	50.0		97.7	78.3-120			
1,3,5-Trimethylbenzene	48.4			ug/L	50.0		96.8	77-120			
1,4-Dichlorobenzene	45.8			ug/L	50.0		91.7	75-125			
2-Chlorotoluene	48.1			ug/L	50.0		96.3	75.9-120			
Benzene	48.7			ug/L	50.0		97.3	80-120			
Bromoform	50.4			ug/L	50.0		101	80-120			
Chlorobenzene	48.5			ug/L	50.0		96.9	80-120			
Chloroform	48.6			ug/L	50.0		97.2	80-120			
Ethylbenzene	48.9			ug/L	50.0		97.8	80-120			
n-Butylbenzene	48.2			ug/L	50.0		96.3	75-125			
n-Propylbenzene	49.1			ug/L	50.0		98.2	75-120			
Toluene	48.9			ug/L	50.0		97.8	80-120			
Trichloroethene	48.8			ug/L	50.0		97.6	80-120			
Vinyl chloride	46.0			ug/L	50.0		92.0	75-130			
Surrogate: 4-Bromofluorobenzene	52.0			ug/L	56.0		92.9	80-124			
Surrogate: Dibromofluoromethane	54.1			ug/L	56.0		96.5	77.1-123			
Surrogate: Toluene-d8	53.5			ug/L	56.0		95.5	78.1-125			
Matrix Spike (B5L0234-MS1)	S	ource:	1505280-	10	Prepared	l & Analyze	ed: 12/02/	15		_	-
1,1,2,2-Tetrachloroethane	49.7			ug/L	50.0	<	99.4	75-125			
1,1-Dichloroethane	51.3			ug/L	50.0	<	103	78.7-123			
1,1-Dichloroethene	49.4			ug/L	50.0	<	98.9	75.8-121			
1,3,5-Trimethylbenzene	48.8			ug/L	50.0	<	97.5	75-120			
1,4-Dichlorobenzene	46.0			ug/L	50.0	<	92.0	75-125			
2-Chlorotoluene	48.7			ug/L	50.0	<	97.3	75-120			
Benzene	49.9			ug/L	50.0	<	99.8	80-120			



Fax: 651-642-1239

Work Order #: 1505280

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

VOC 8260B - Quality Control

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0234 - EPA 5035 Soil (Purge a	and Trap)									
Matrix Spike (B5L0234-MS1)		ource: 1	505280-1	0	Prepared	l & Analyze	ed: 12/02/	15			
Bromoform	50.5			ug/L	50.0	<	101	80-120			
Chlorobenzene	48.9			ug/L	50.0	<	97.8	80-120			
Chloroform	50.4			ug/L	50.0	<	101	80-120			
Ethylbenzene	49.9			ug/L	50.0	<	99.8	80-120			
n-Butylbenzene	47.0			ug/L	50.0	<	94.1	73.8-125			
n-Propylbenzene	48.4			ug/L	50.0	<	96.8	75-120			
Toluene	49.9			ug/L	50.0	<	99.9	80-120			
Trichloroethene	49.9			ug/L	50.0	<	99.7	80-120			
Vinyl chloride	46.7			ug/L	50.0	<	93.4	74.8-130			
Surrogate: 4-Bromofluorobenzene	52.9			ug/L	56.0		94.5	80-124			
Surrogate: Dibromofluoromethane	55.2			ug/L	56.0		98.6	77.1-123			
Surrogate: Toluene-d8	54.6			ug/L	56.0		97.5	78.1-125			
Matrix Spike Dup (B5L0234-MSD1)	s	ource: 1	505280-1	0	Prepared	l & Analyze	ed: 12/02/	15			
1,1,2,2-Tetrachloroethane	49.8			ug/L	50.0	<	99.7	75-125	0.269	20	
1,1-Dichloroethane	51.3			ug/L	50.0	<	103	78.7-123	0.0807	20	
1,1-Dichloroethene	48.3			ug/L	50.0	<	96.7	75.8-121	2.25	20	
1,3,5-Trimethylbenzene	49.4			ug/L	50.0	<	98.8	75-120	1.28	20	
1,4-Dichlorobenzene	46.3			ug/L	50.0	<	92.6	75-125	0.628	20	
2-Chlorotoluene	48.7			ug/L	50.0	<	97.4	75-120	0.113	20	
Benzene	51.0			ug/L	50.0	<	102	80-120	2.23	20	
Bromoform	49.7			ug/L	50.0	<	99.3	80-120	1.68	20	
Chlorobenzene	48.7			ug/L	50.0	<	97.4	80-120	0.430	20	
Chloroform	50.4			ug/L	50.0	<	101	80-120	0.140	20	
Ethylbenzene	49.4			ug/L	50.0	<	98.9	80-120	0.947	20	
n-Butylbenzene	48.8			ug/L	50.0	<	97.6	73.8-125	3.71	20	
n-Propylbenzene	49.2			ug/L	50.0	<	98.3	75-120	1.52	20	
Toluene	51.4			ug/L	50.0	<	103	80-120	2.97	20	
Trichloroethene	51.0			ug/L	50.0	<	102	80-120	2.18	20	
Vinyl chloride	44.9			ug/L	50.0	<	89.8	74.8-130	3.95	20	
Surrogate: 4-Bromofluorobenzene	52.8			ug/L	56.0		94.2	80-124			
Surrogate: Dibromofluoromethane	55.2			ug/L	56.0		98.6	77.1-123			
Surrogate: Toluene-d8	55.7			ug/L	56.0		99.5	78.1-125			



Fax: 651-642-1239

Barr Engineering Co. 34511010 Project: 4300 MarketPointe Drive, Suite 200 Work Order #: 1505280 Project Number: 34511010 Minneapolis, MN 55435 Date Reported: 12/10/15 Project Manager: Ms. Andrea Nord

Notes and Definitions

T5 Laboratory not licensed for this parameter.

S-GC Surrogate recovery outside of control limits. The data was accepted based on valid recovery of the remaining surrogate(s).

M1 Matrix spike recovery was high, the associated blank spike recovery was acceptable.

Results in the diesel organics range are primarily due to overlap from a heavy oil range product. L1

< Less than value listed

dry Sample results reported on a dry weight basis

Not applicable. The %RPD is not calculated from values less than the reporting limit. NA

MDL Method Detection Limit; Equivalent to the method LOD (Limit of Detection)

RL Reporting Limit

RPD Relative Percent Difference

LCS Laboratory Control Spike = Blank Spike (BS) = Laboratory Fortified Blank (LFB)

MS Matrix Spike = Laboratory Fortified Matrix (LFM)



88 Empire Drive St Paul, MN 55103

Tel: 651-642-1150 Fax: 651-642-1239

3A	RR 4700 West 77th Minneapolis, M (952) 832-2600	Niveet IN 5543. I	5-4803		15	05280	0				Water	1	Soil		Project Mind	
rojec	Number: 3451	1010											6 92 0			
rojes	Numer Hrs Av	e Fl	ood	wal						200	1		me/GP o	Number Of Container	OC Connet:	dren
	e Origination State M [ij		(N H	1	70		Of Co	/V	112
)C	Number:					N:	0 1	150	52	CI) #1	ate (H unpres	A C	tared McOII), tared unpreser tempreserved) (ampreserved) a tplastic vial, n	mber	Sampled by:	11-
	Location	Start Depth	Stop Depth	Depth Unit (m/0, or in.)	Collection Date (mm/skl/yyyy)	Collection Time (hlumm)	Mate	a T	Ompt Comp	SVOC (III	Total Metals (HN) General (unpreser Diesel Range Ope	Nurring	VOCs (tared MeOH) GEO, Effect times that DRO (tared unpreserved) Adelais tempereserved) SVOCs (ampreserved) S Sorida (plantic vitil.)	Total Na	Sampled by: A	enl
	B-1	10	12	H	11/23/15	17:15	X		X				1111	4	STAT	0/
	B-1	16	18		_	17:15										02
	B-29	2	4		11/24/15	10.00									Ŋ	oz
V	B-29	4	ما			10:00							4-1/1			oy
	B-3	عا	8			11:00							i leng			us
	B-3	6	2			11:00							I printer			a
	B-4	2	ч		10	12 00							profession of			(2)
	B-4	8	1.0			12:00										O ₂
	13-5	6	2			1245			I						110	b.
0.	B-5	6	9	1		12:45						11	71777			I,
0001	non Parameter/Containe	er - Prese	_		Relinguished By	2		On Ice		Date 2+4/13*	Time	Receive	od by:		Dute	Time
-Se Fu	lante Organics = BTEX, Gi movilable Organics = PAH; B List, Herbicide/Pesticide/P	∟PCP, Dias CBs	dus, 827	1	Relinquished By:	1.0		On Ice	-	Date	Time	Receive	d by		Date (1)	Time 42s
7 - Ge 7 D 3 - N	meval = pH, Chlorde, Floor S, TS, Sulfan urisms = COD, TOC, Phen rogen, TKN	ride, Alkalu			Samples Shipped	Other	_						Number: 9.72 Pink - Lah Coordinator			



88 Empire Drive St Paul, MN 55103

Tel: 651-642-1150 Fax: 651-642-1239

Chain of		ody		Ť.	5052							1. 41/61.7	OF VIEW	of Con	tain	ers/	Pres	C-11-1	other.		_	cc)C	2.	1_2	
BARR 4700 West 77th Minneapolis, A (952) 832-2600	Street IN 5343	5-4803		13	505 F	37	2				П	Wa	T.	T	H	T	Т	So	il il	П	t					
	_								-	1				1	1			20.00	2						14 F	
Project Number: 34511						_	_	+			1		(1940)	1	1	1	,	ľ	1 P.		Bran	Peng	ect	1	100	0.1
Project Name: Ut= Art	F	und	wal	1				+	_	i i	NOS	1				7	(6000		anders.		ontar	QC	Contac	44	Arts	-
Sample Origination State N	(use two	n letter	postal si	ite abbreviation)				1		David	s (H	HNO	V.			OHO	PERMIT	OTHAI	F106.		Of C			//	010	ki ka
COC Number:					N	0	4	508	3	(I)	Metu	1	1	1		Sed N	on po	*preservent)	datte		iper	Sam	pled by	4	Mr.	
Location	Start Depth	Stop Depth	Depth Unit (m/n or in.)	Collection Date (mm/dd/yyy)	Collection Time (hh:mm)	Manage	itrix	ily span	pet of	SOC: (HCI) #	Patranoport	General Med	Diesel Renga Gribaics	1		VOCs Haned MacHyler SP	ORG (teced aspressived)	Matale 4se	Solids tplastic		Total Nun	Labe	oratory;	leg	dra lora Mk?	1
13-6			C+	11/24/15			χ	-	X						Ì	1	1		1	П	4	5	STA	T		/ 4
B-6			1	1		Į.		Į,									ļ				I				-	2)
temp blank	- N	A -							X																	
V.																I										
																Ī					I					
V.						П	Ī									Ī										
																Ī										
						П		П					П		ı	Ī					T					
X:						П		П	T			Ī	Ħ		Ī			ı	Ī		T					
4.								Ħ	T												T					
Common Parameter/Containe	r - Preser	vation l	Cey 1	telinquished By.	1	1	On K	lee?		Dute	T	Tim		Recei	red l	15	-	-			1		De	nte _	Tia	SE.
1 - Volatile Organics = BTEX, GR 2 - Semivolatile Organics = PAHs, Full Lin, Herbicide/Penicule/PO	PCP Dan	260 Full i inx, 8270	List 3	telinquished By:	7		-	ke?	named by	24//	51'	Tie		Recei	ed t	70	1	-					1//2	ite Tra	93	
 General = pH, Chloride, Fluors TDS, TS, Sulfaire Narman = CEID, TOC, Phena Narugan, TKN 	de, Alkalıı	ACMITANTE PAR	3	amples Shipped Stribution: White-	Other	1				-		Sam	-	Air B							77		Tarks	2 (4)	12	



Fax: 651-642-1239

Page 2

Bata File: \\lts-target\targetdata\chex\FJS5.[\151203.b\029.d


Date : 04-BEC-2015 00:41

Client 10:

Sample Info: 1508280-01

Instrument: FID5.i

Operator: yp



Page 2

Fax: 651-642-1239

Data File: \\lts-target\targetdata\chem\FID5.i\151203.b\021.d

Date : 03-DEC-2015 21:05


Client ID:

Sample Info: 1505280-02

Column phase;

Instrument: FID6.i

Operator: yp





Fax: 651-642-1239

Page 2

Data File: \\lts-target\targetdata\chem\FID5,i\151203.b\023.d

Date : 03-DEC-2015 21:59


Client ID:

Sample Info: 1505280-03

Column phase:

Instrument; FID5, i

Coerator: ye





Fax: 651-642-1239

Page 2

Data File: \\Its-target\tartotdata\chem\FID5.i\151203.b\025.d


Date : 03-060-2015 22:53

Client ID;

Sample Info: 1505290-04

Operator: 90

Column dismeter: 0.53 Column phase:



Instrument; FiDS, i



Fax: 651-642-1239

Page 2

Sata File: \\lts-target\targetdata\chem\FIB5.i\151203.b\027.d

Bate : 03-850-2015 23:47


Client ID:

Sample Info; 1505280-05

Column shase:

Instrument: FID5.i

Operator: up



Fax: 651-642-1239

Page 2

Data File: \\lts-target\targetdata\chem\FID5.i\151203.b\014.d


Date : 03-DEC-2015 17:56

Client ID:

Sample Info: 1505280-06

Instrument: F105.i

Operator: 50



Fax: 651-642-1239

Page 2

Data File: \\lts-target\targetdata\chem\FID5.i\151203.b\038.d

Bate : 04-0EC-2015 04:44


Client ID:

Sample Info: 1503280-07

Column phase:

Instrument: FID5.i

Operator: yp



Fax: 651-642-1239

Page 2

Data File: \\lts-torget\targetdata\chem\FIB5.i\151203.b\032.d


Date : 04-DEC-2015 02:02

Client ID:

Sample Info: 1505280-08

Instrument: FID5.i

Operator: yp



Fax: 651-642-1239

Page 2

Data File: \\lts-target\targetdata\chem\FID5.i\151203.b\019.d

Date : 03-DEC-2015 20:11


Client ID:

Sample Info: 1505280-09

Instrument: FIB5.i

Operator: yp

Column phase: Column diameter: 0.53





Fax: 651-642-1239

Page 2

Data File: \\lts-target\targetdata\chem\FID5.i\151203.b\034.d

Date : 04-DEC-2015 02;56


Client ID:

Sample Info: 1505290-10

Column phase:

instrument: FID5.i

Operator; yp





Fax: 651-642-1239

Page 2

Data File: \\lts-target\targetdata\chem\FID5.i\151203.b\017.d


Date : 03-DEC-2015 19:17

Client ID:

Sample Info: 1505280-11

instrument: FID5.i

Operator: up



Page 2

Fax: 651-642-1239

Data File: \\lts-target\targetdata\chem\FID5.i\151203.b\036.d

Date : 04-DEC-2015 03:50


Client ID:

Sample Info: 1505280-12

Column phase:

Instrument: FID6.i

Operator: yp





88 Empire Drive St Paul, MN 55103 Tel: 651-642-1150 Fax: 651-642-1239

December 08, 2015

Ms. Andrea Nord Barr Engineering Co. 4700 W 77th St Minneapolis, MN 55435

Work Order Number: 1505279

RE: 34511010

Enclosed are the results of analyses for samples received by the laboratory on 11/25/15. If you have any questions concerning this report, please feel free to contact me.

Results are not blank corrected unless noted within the report. Additionally, all QC results meet requirements unless noted.

All samples will be retained by Legend Technical Services, Inc., unless consumed in the analysis, at ambient conditions for 30 days from the date of this report and then discarded unless other arrangements are made. All samples were received in acceptable condition unless otherwise noted.

ND Accreditation #R-065

Prepared by, LEGEND TECHNICAL SERVICES, INC

Bach Pham
Client Manager II
bpham@legend-group.com



Fax: 651-642-1239

Work Order #: 1505279

Date Reported: 12/08/15

Barr Engineering Co. Project: 34511010
4700 W 77th St Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
B-1_10-20	1505279-01	Groundwater	11/24/15 15:00	11/25/15 09:30
B-3_8.6-18.6	1505279-02	Groundwater	11/24/15 15:45	11/25/15 09:30
Trip Blank	1505279-03	Water	11/24/15 00:00	11/25/15 09:30

Shipping Container Information

Default Cooler Temperature (°C): 2.4

Received on ice: Yes Received on melt water: No Temperature blank was present

Ambient: No

Received on ice pack: No Acceptable (IH/ISO only): No

Custody seals: No

Case Narrative:

The DRO chromatograms are attached for both samples.



Fax: 651-642-1139

Work Order #: 1505279

Date Reported: 12/08/15

Barr Engineering Co. Project: 34511010
4700 W 77th St Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

8015D DRO Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-20 (1505279-01) Groundwater	Sampled:	11/24/1	5 15:00	Received: 11	/25/15 9:3	0				
Diesel Range Organics	120	100	26	ug/L	1	B5L0106	12/01/15	12/01/15	EPA 8015D	
Surrogate: Triacontane (C-30)	81.4			70-130 %		"	"	"	"	
B-3_8.6-18.6 (1505279-02) Groundwate	r Sample	d: 11/2	4/15 15:45	Received:	11/25/15	9:30				
Diesel Range Organics	210	93	24	ug/L	1	B5L0106	12/01/15	12/01/15	EPA 8015D	L1
Surrogate: Triacontane (C-30)	93.3			70-130 %		"	"	"	"	



Fax: 651-642-1239

 Barr Engineering Co.
 Project:
 34511010

 4700 W 77th St
 Project Number:
 34511010
 Work Order #: 1505279

 Minneapolis, MN 55435
 Project Manager:
 Ms. Andrea Nord
 Date Reported: 12/08/15

8015D GRO Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-20 (1505279-01) Groundwater	Sampled:	11/24/1	5 15:00	Received: 11	/25/15 9:3	30				
Gasoline range organics	<100	100	16	ug/L	1	B5K2505	11/25/15	11/26/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	99.9			80-150 %		"	"	"	"	
B-3_8.6-18.6 (1505279-02) Groundwate	r Sample	d: 11/2	4/15 15:45	Received:	11/25/15	9:30				
Gasoline range organics	<100	100	16	ug/L	1	B5K2505	11/25/15	11/26/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	101			80-150 %		"	"	"	"	



Fax: 651-642-1239

 Barr Engineering Co.
 Project:
 34511010

 4700 W 77th St
 Project Number:
 34511010
 Work Order #: 1505279

 Minneapolis, MN 55435
 Project Manager:
 Ms. Andrea Nord
 Date Reported:
 12/08/15

DISSOLVED METAL ANALYSIS Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_8.6-18.6 (1505279-02) Groundwate	r Sampl	ed: 11/2	1/15 15:45	Received:	11/25/15	9:30				
Arsenic	<0.010	0.010	0.0026	mg/L	1	B5L0108	12/01/15	12/01/15	EPA 6010C (Dissolved)	
Barium	0.050	0.020	0.0022	mg/L	1	"	"	"	"	
Cadmium	<0.0010	0.0010	0.000059	mg/L	1	"	"	"	"	
Chromium	<0.010	0.010	0.0012	mg/L	1	"	"	"	"	
Lead	0.014	0.0050	0.0012	mg/L	1	"	"	"	"	
Mercury	<0.010	0.010	0.0023	mg/L	1	"	"	"	"	
Selenium	<0.030	0.030	0.0073	mg/L	1	"	"	"	"	
Silver	<0.0050	0.0050	0.00053	mg/L	1	"	"	"	"	

Fax: 651-642-1239

Work Order #: 1505279

Barr Engineering Co. Project: 34511010 4700 W 77th St Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Date Reported: 12/08/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-20 (1505279-01) Groundwater	Sampled:	11/24/1	5 15:00	Received: 1	11/25/15 9:3	30				
1,2,4-Trichlorobenzene	<9.3	9.3	0.50	ug/L	1	B5K3004	11/30/15	12/01/15	EPA 8270D	
1,2-Dichlorobenzene	<9.3	9.3	0.44	ug/L	1	"	"	"	"	
1,2-Diphenylhydrazine as Azobenzene	<9.3	9.3	0.30	ug/L	1	"	"	"	"	
1,3-Dichlorobenzene	<9.3	9.3	0.40	ug/L	1	"	"	"	"	
1,4-Dichlorobenzene	<9.3	9.3	0.30	ug/L	1	"	u u	II .	"	
2,3,4,6-Tetrachlorophenol	<9.3	9.3	0.69	ug/L	1	"	·	II .	"	
2,4,5-Trichlorophenol	<9.3	9.3	1.0	ug/L	1	"	"	"	"	
2,4,6-Trichlorophenol	<9.3	9.3	0.77	ug/L	1	"	n .	n	"	
2,4-Dichlorophenol	<9.3	9.3	0.73	ug/L	1	"	"	"	"	
2,4-Dimethylphenol	<9.3	9.3	0.93	ug/L	1	"	n .	n	"	
2,4-Dinitrophenol	<9.3	9.3	0.65	ug/L	1	"	·	II .	"	
2,4-Dinitrotoluene	<9.3	9.3	0.41	ug/L	1	"	"	n .	· ·	
2,6-Dichlorophenol	<9.3	9.3	0.87	ug/L	1	"	"	"	"	
2,6-Dinitrotoluene	<9.3	9.3	0.36	ug/L	1	"	"	n .	· ·	
2-Chloronaphthalene	<9.3	9.3	0.36	ug/L	1	"	"	"	"	
2-Chlorophenol	<9.3	9.3	1.1	ug/L	1	"	"	"	"	
2-Methylnaphthalene	<9.3	9.3	0.65	ug/L	1	"	"	"	"	
2-Methylphenol	<9.3	9.3	1.3	ug/L	1	"	"	"	"	
2-Nitroaniline	<9.3	9.3	0.78	ug/L	1	"	"	"	"	
2-Nitrophenol	<9.3	9.3	0.80	ug/L	1	"	"	"	"	
3&4-Methylphenol	<9.3	9.3	1.4	ug/L	1	"	"	"	"	
3,3´-Dichlorobenzidine	<23	23	9.3	ug/L	1	"	"	"	"	
3-Nitroaniline	<9.3	9.3	1.9	ug/L	1	"	"	"	"	
4,6-Dinitro-2-methylphenol	<9.3	9.3	0.93	ug/L	1	"	"	"	"	
4-Bromophenyl phenyl ether	<9.3	9.3	0.32	ug/L	1	"	"	"	"	
4-Chloro-3-methylphenol	<9.3	9.3	0.64	ug/L	1	"	"	"	"	
4-Chloroaniline	<9.3	9.3	2.1	ug/L	1	"	"	"	"	
4-Chlorophenyl phenyl ether	<9.3	9.3	0.42	ug/L	1	"	"	u u	"	
4-Nitroaniline	<9.3	9.3	1.1	ug/L	1	"	"	"	"	
4-Nitrophenol	<9.3	9.3	0.85	ug/L	1	"	"	u u	"	
Acenaphthene	<9.3	9.3	0.38	ug/L	1	II .	· ·	II .	"	
Acenaphthylene	<9.3	9.3	0.36	ug/L	1	"	"	u u	"	
Aniline	<9.3	9.3	1.2	ug/L	1	"	"	"	"	
Anthracene	<9.3	9.3	0.34	ug/L	1	"	"	"	"	
Benzidine	<93	93	7.7	ug/L	1	"	"	"	"	
Benzo(a)anthracene	<9.3	9.3	0.21	ug/L	1	"	"	"	"	
Benzo(a)pyrene	<9.3	9.3	0.32	ug/L	1	"	"	"	"	
Benzo(b)fluoranthene	<9.3	9.3	0.17	ug/L	1	"	"	"	"	
Benzo(g,h,i)perylene	<9.3	9.3	0.40	ug/L	1	"	·	II .	"	



Fax: 651-642-1239

Work Order #: 1505279

Date Reported: 12/08/15

Barr Engineering Co.Project:345110104700 W 77th StProject Number:34511010Minneapolis, MN 55435Project Manager:Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-20 (1505279-01) Groundwater	Sampled:	11/24/1	5 15:00	Received: 1	1/25/15 9:3	0				
Benzo(k)fluoranthene	<9.3	9.3	0.51	ug/L	1	B5K3004	11/30/15	12/01/15	EPA 8270D	
Benzoic acid	<9.3	9.3	1.7	ug/L	1	"	"	"	"	
Benzyl alcohol	<9.3	9.3	0.64	ug/L	1	"	u u	II .	"	
Bis(2-chloroethoxy)methane	<9.3	9.3	0.38	ug/L	1	"	"	"	"	
Bis(2-chloroethyl)ether	<9.3	9.3	0.55	ug/L	1	"	"	"	"	
Bis(2-chloroisopropyl)ether	<9.3	9.3	0.44	ug/L	1	"	"	"	"	
Bis(2-ethylhexyl)phthalate	9.8	9.3	0.72	ug/L	1	"	"	"	"	
Butyl benzyl phthalate	<9.3	9.3	0.63	ug/L	1	"	"	"	"	
Carbazole	<9.3	9.3	0.39	ug/L	1	"	"	"	"	
Chrysene	<9.3	9.3	0.32	ug/L	1	"	"	"	"	
Dibenz(a,h)anthracene	<9.3	9.3	0.29	ug/L	1	"	"	"	"	
Dibenzofuran	<9.3	9.3	0.72	ug/L	1	"	"	"	"	
Diethyl phthalate	<9.3	9.3	0.39	ug/L	1	"	"	"	"	
Dimethyl phthalate	<9.3	9.3	0.41	ug/L	1	"	"	"	"	
Di-n-butyl phthalate	<9.3	9.3	0.39	ug/L	1	"	"	"	"	
Di-n-octyl phthalate	<9.3	9.3	0.45	ug/L	1	"	"	"	"	
Fluoranthene	<9.3	9.3	0.34	ug/L	1	"	"	"	"	
Fluorene	<9.3	9.3	0.33	ug/L	1	"	"	"	"	
Hexachlorobenzene	<9.3	9.3	0.28	ug/L	1	"	"	"	"	
Hexachlorobutadiene	<9.3	9.3	0.35	ug/L	1	"	"	"	"	
Hexachlorocyclopentadiene	<9.3	9.3	0.49	ug/L	1	"	"	"	"	
Hexachloroethane	<9.3	9.3	0.57	ug/L	1	"	"	"	"	
Indeno (1,2,3-cd) pyrene	<9.3	9.3	0.35	ug/L	1	"	"	"	"	
Isophorone	<9.3	9.3	0.42	ug/L	1	"	"	"	"	
Naphthalene	<9.3	9.3	0.31	ug/L	1	"	"	"	"	
Nitrobenzene	<9.3	9.3	0.48	ug/L	1	"	"	"	"	
N-Nitrosodimethylamine	<9.3	9.3	0.32	ug/L	1	"	"	"	"	
N-Nitrosodi-n-propylamine	<9.3	9.3	0.44	ug/L	1	"	"	"	"	
N-Nitrosodiphenylamine	<9.3	9.3	0.50	ug/L	1	"	"	"	"	
Pentachlorophenol	<9.3	9.3	1.1	ug/L	1	"	"	"	"	
Phenanthrene	<9.3	9.3	0.26	ug/L	1	"	"	"	"	
Phenol	<9.3	9.3	1.1	ug/L	1	"	"	"	"	
Pyrene	<9.3	9.3	0.46	ug/L	1	"	"	"	"	
Surrogate: 2,4,6-Tribromophenol	67.3			30-122 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	75.7			39.2-104 %	;	"	"	"	"	
Surrogate: 2-Fluorophenol	41.6			30-80.1 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	70.9			51.2-103 %	•	"	"	"	"	
Surrogate: Phenol-d6	37.8 63.1			30-75.3 %		"	"	"	"	
Surrogate: Terphenyl-d14	63.1			30-116 %						

Fax: 651-642-1239

Work Order #: 1505279

Date Reported: 12/08/15

Barr Engineering Co. Project: 34511010
4700 W 77th St Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_8.6-18.6 (1505279-02) Groundwate	er Sample	ed: 11/2	1/15 15:45	Received:	11/25/15	9:30				
1,2,4-Trichlorobenzene	<10	10	0.53	ug/L	1	B5K3004	11/30/15	12/01/15	EPA 8270D	
1,2-Dichlorobenzene	<10	10	0.47	ug/L	1	"	"	II .	"	
1,2-Diphenylhydrazine as Azobenzene	<10	10	0.32	ug/L	1	"	"	"	"	
1,3-Dichlorobenzene	<10	10	0.43	ug/L	1	"	"	"	"	
1,4-Dichlorobenzene	<10	10	0.32	ug/L	1	"	"	"	"	
2,3,4,6-Tetrachlorophenol	<10	10	0.74	ug/L	1	"	"	"	"	
2,4,5-Trichlorophenol	<10	10	1.1	ug/L	1	"	"	"	"	
2,4,6-Trichlorophenol	<10	10	0.82	ug/L	1	"	"	"	"	
2,4-Dichlorophenol	<10	10	0.78	ug/L	1	"	"	"	"	
2,4-Dimethylphenol	<10	10	0.99	ug/L	1	"	"	II .	"	
2,4-Dinitrophenol	<10	10	0.70	ug/L	1	"	"	II .	"	
2,4-Dinitrotoluene	<10	10	0.44	ug/L	1	"	"	II .	"	
2,6-Dichlorophenol	<10	10	0.93	ug/L	1	"	"	II .	"	
2,6-Dinitrotoluene	<10	10	0.39	ug/L	1	"	"	II .	"	
2-Chloronaphthalene	<10	10	0.38	ug/L	1	"	"	II .	"	
2-Chlorophenol	<10	10	1.2	ug/L	1	"	"	II .	"	
2-Methylnaphthalene	<10	10	0.70	ug/L	1	"	"	II .	II .	
2-Methylphenol	<10	10	1.4	ug/L	1		"	"	"	
2-Nitroaniline	<10	10	0.83	ug/L	1	"	"	II .	"	
2-Nitrophenol	<10	10	0.86	ug/L	1	"	"	II .	"	
3&4-Methylphenol	<10	10	1.5	ug/L	1		"	"	"	
3,3´-Dichlorobenzidine	<25	25	9.9	ug/L	1		"	"	"	
3-Nitroaniline	<10	10	2.0	ug/L	1		"	"	"	
4,6-Dinitro-2-methylphenol	<10	10	1.0	ug/L	1		"	"	"	
4-Bromophenyl phenyl ether	<10	10	0.34	ug/L	1	"	"	"	"	
4-Chloro-3-methylphenol	<10	10	0.68	ug/L	1	"	"	"	"	
4-Chloroaniline	<10	10	2.3	ug/L	1	"	"	"	"	
4-Chlorophenyl phenyl ether	<10	10	0.45	ug/L	1	"	"	II .	"	
4-Nitroaniline	<10	10	1.2	ug/L	1	"	"	"	"	
4-Nitrophenol	<10	10	0.91	ug/L	1	"	"	"	"	
Acenaphthene	<10	10	0.41	ug/L	1	"	"	"	"	
Acenaphthylene	<10	10	0.38	ug/L	1	"	"	"	"	
Aniline	<10	10	1.3	ug/L	1	"	"	"	"	
Anthracene	<10	10	0.36	ug/L	1	"	"	"	"	
Benzidine	<100	100	8.2	ug/L	1	"	"	"	"	
Benzo(a)anthracene	<10	10	0.23	ug/L	1	"	"	"	"	
Benzo(a)pyrene	<10	10	0.34	ug/L	1	"	"	"	"	
Benzo(b)fluoranthene	<10	10	0.18	ug/L	1	"	"	п	m .	
Benzo(g,h,i)perylene	<10	10	0.43	ug/L	1		"			



Fax: 651-642-1239

Work Order #: 1505279

Date Reported: 12/08/15

Barr Engineering Co. 34511010 Project: 4700 W 77th St Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

SVOC 8270D

Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_8.6-18.6 (1505279-02) Groundwater	Sample	ed: 11/24	1/15 15:45	Received:	11/25/15	9:30				
Benzo(k)fluoranthene	<10	10	0.55	ug/L	1	B5K3004	11/30/15	12/01/15	EPA 8270D	
Benzoic acid	<10	10	1.8	ug/L	1	"	"	"	"	
Benzyl alcohol	<10	10	0.68	ug/L	1	n n	"	"	"	
Bis(2-chloroethoxy)methane	<10	10	0.41	ug/L	1	"	"	"	"	
Bis(2-chloroethyl)ether	<10	10	0.59	ug/L	1	"	"	"	"	
Bis(2-chloroisopropyl)ether	<10	10	0.47	ug/L	1	"	"	"	"	
Bis(2-ethylhexyl)phthalate	<10	10	0.77	ug/L	1	"	"	"	"	
Butyl benzyl phthalate	<10	10	0.67	ug/L	1	"	"	"	"	
Carbazole	<10	10	0.42	ug/L	1	"	"	II .	"	
Chrysene	<10	10	0.34	ug/L	1	"	"	"	"	
Dibenz(a,h)anthracene	<10	10	0.31	ug/L	1	"	"	"	"	
Dibenzofuran	<10	10	0.77	ug/L	1	"	"	"	"	
Diethyl phthalate	<10	10	0.42	ug/L	1	"	"	"	"	
Dimethyl phthalate	<10	10	0.44	ug/L	1	"	"	"	"	
Di-n-butyl phthalate	<10	10	0.42	ug/L	1	"	"	"	"	
Di-n-octyl phthalate	<10	10	0.48	ug/L	1	"	"	"	"	
Fluoranthene	<10	10	0.36	ug/L	1	"	"	"	"	
Fluorene	<10	10	0.35	ug/L	1	"	"	"	"	
Hexachlorobenzene	<10	10	0.30	ug/L	1	"	"	"	"	
Hexachlorobutadiene	<10	10	0.37	ug/L	1	"	"	"	"	
Hexachlorocyclopentadiene	<10	10	0.52	ug/L	1	"	"	"	"	
Hexachloroethane	<10	10	0.61	ug/L	1	"	"	"	"	
Indeno (1,2,3-cd) pyrene	<10	10	0.37	ug/L	1	"	"	"	"	
Isophorone	<10	10	0.45	ug/L	1	"	"	"	"	
Naphthalene	<10	10	0.33	ug/L	1	"	"	"	"	
Nitrobenzene	<10	10	0.51	ug/L	1	"	"	"	"	
N-Nitrosodimethylamine	<10	10	0.34	ug/L	1	"	"	"	"	
N-Nitrosodi-n-propylamine	<10	10	0.47	ug/L	1	"	"	"	"	
N-Nitrosodiphenylamine	<10	10	0.54	ug/L	1	"	"	"	"	
Pentachlorophenol	<10	10	1.2	ug/L	1	"	"	"	"	
Phenanthrene	<10	10	0.28	ug/L	1	"	"	"	"	
Phenol	<10	10	1.2	ug/L	1	"	"	"	"	
Pyrene	<10	10	0.49	ug/L	1	"	"	"	"	
Surrogate: 2,4,6-Tribromophenol	34.0			30-122 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	83.2			39.2-104 %		"	"	"	"	
Surrogate: 2-Fluorophenol	36.3			30-80.1 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	78.0			51.2-103 %		"	"	"	"	
Surrogate: Phenol-d6	41.5			30-75.3 %		"	"	"	"	
Surrogate: Terphenyl-d14	67.0			30-116 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4700 W 77th St Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505279 Date Reported: 12/08/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-20 (1505279-01) Groundwater	Sampled:	11/24/1	5 15:00	Received: 1	11/25/15 9:3	0				
1,1,1,2-Tetrachloroethane	<1.0	1.0	0.024	ug/L	1	B5L0232	11/25/15	11/25/15	EPA 8260B	
1,1,1-Trichloroethane	<1.0	1.0	0.069	ug/L	1	"	u u	II .	II .	
1,1,2,2-Tetrachloroethane	<1.0	1.0	0.051	ug/L	1	"	· ·	II .	"	
1,1,2-Trichloroethane	<1.0	1.0	0.10	ug/L	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<1.0	1.0	0.081	ug/L	1	"	"	"	"	T5
1,1-Dichloroethane	<1.0	1.0	0.050	ug/L	1	"	"	"	"	
1,1-Dichloroethene	<1.0	1.0	0.065	ug/L	1	"	"	"	"	
1,1-Dichloropropene	<1.0	1.0	0.15	ug/L	1	"	"	"	"	
1,2,3-Trichlorobenzene	<5.0	5.0	0.45	ug/L	1	"	"	"	"	
1,2,3-Trichloropropane	<2.5	2.5	0.056	ug/L	1	"	"	"	"	
1,2,4-Trichlorobenzene	<5.0	5.0	0.091	ug/L	1	"	"	"	"	
1,2,4-Trimethylbenzene	<1.0	1.0	0.054	ug/L	1	"	"	"	"	
1,2-Dibromo-3-chloropropane	<5.0	5.0	0.033	ug/L	1	"	"	"	"	
1,2-Dibromoethane (EDB)	<2.5	2.5	0.042	ug/L	1	"	"	"	"	
1,2-Dichlorobenzene	<1.0	1.0	0.052	ug/L	1	"	"	u u	"	
1,2-Dichloroethane	<1.0	1.0	0.064	ug/L	1	"	"	u u	"	
1,2-Dichloropropane	<1.0	1.0	0.034	ug/L	1	"	"	II .	"	
1,3,5-Trimethylbenzene	<1.0	1.0	0.046	ug/L	1	"	"	II .	"	
1,3-Dichlorobenzene	<1.0	1.0	0.068	ug/L	1	"	"	"	"	
1,3-Dichloropropane	<1.0	1.0	0.15	ug/L	1	"	"	"	"	
1,4-Dichlorobenzene	<1.0	1.0	0.047	ug/L	1	"	"	"	"	
2,2-Dichloropropane	<5.0	5.0	0.28	ug/L	1	"	"	"	"	
2-Butanone	<20	20	0.33	ug/L	1	"	"	"	"	
2-Chlorotoluene	<1.0	1.0	0.052	ug/L	1	"	"	"	"	
4-Chlorotoluene	<1.0	1.0	0.041	ug/L	1	"	"	"	"	
Acetone	<20	20	0.32	ug/L	1	"	"	"	"	
Allyl chloride	<5.0	5.0	0.078	ug/L	1	"	"	"	"	
Benzene	<1.0	1.0	0.034	ug/L	1	"	"	"	"	
Bromobenzene	<1.0	1.0	0.042	ug/L	1	"	"	"	"	
Bromochloromethane	<1.0	1.0	0.10	ug/L	1	"	"	"	"	
Bromodichloromethane	<1.0	1.0	0.042	ug/L	1	"	"	"	"	
Bromoform	<5.0	5.0	0.080	ug/L	1	"	"	"	"	
Bromomethane	<5.0	5.0	0.17	ug/L	1	"	"	"	"	
Carbon tetrachloride	<1.0	1.0	0.029	ug/L	1	"	"	"	"	
Chlorobenzene	<1.0	1.0	0.037	ug/L	1	"	"	"	"	
Chloroethane	<2.5	2.5	0.062	ug/L	1	"	"	"	"	
Chloroform	<1.0	1.0	0.056	ug/L	1	"	"	"	"	
Chloromethane	<2.5	2.5	0.062	ug/L	1	"	"	"	"	
cis-1,2-Dichloroethene	<1.0	1.0	0.097	ug/L	1	"	"	"	"	

Fax: 651-642-1239

Work Order #: 1505279

Date Reported: 12/08/15

Barr Engineering Co. Project: 34511010 4700 W 77th St Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-1_10-20 (1505279-01) Groundwater	Sampled:	11/24/1	5 15:00 H	Received: 11	/25/15 9:3	0				
cis-1,3-Dichloropropene	<1.0	1.0	0.041	ug/L	1	B5L0232	11/25/15	11/25/15	EPA 8260B	
Dibromochloromethane	<2.5	2.5	0.070	ug/L	1	"	"	"	"	
Dibromomethane	<2.5	2.5	0.088	ug/L	1	"	"	"	"	
Dichlorodifluoromethane	<5.0	5.0	0.14	ug/L	1	"	"	"	u .	
Dichlorofluoromethane	<1.0	1.0	0.059	ug/L	1	"	"	"	n .	T5
Ethyl ether	<5.0	5.0	0.091	ug/L	1	n .	II .	"	II .	
Ethylbenzene	<1.0	1.0	0.033	ug/L	1	n .	II .	"	II .	
Hexachlorobutadiene	<10	10	0.19	ug/L	1	n .	II .	"	II .	
Isopropylbenzene	<1.0	1.0	0.037	ug/L	1	"	"	"	"	
m,p-Xylene	<2.0	2.0	0.087	ug/L	1	"	u u	"	m .	
Methyl isobutyl ketone	<5.0	5.0	0.17	ug/L	1	"	"	"	"	
Methyl tert-butyl ether	<1.0	1.0	0.056	ug/L	1	"	"	"	"	
Methylene chloride	<5.0	5.0	0.10	ug/L	1	"	"	"	"	
Naphthalene	<5.0	5.0	0.032	ug/L	1	"	"	"	"	
n-Butylbenzene	<2.5	2.5	0.028	ug/L	1	"	"	"	"	
n-Propylbenzene	<1.0	1.0	0.040	ug/L	1	"	"	"	"	
o-Xylene	<1.0	1.0	0.053	ug/L	1	"	"	"	"	
p-Isopropyltoluene	<2.5	2.5	0.052	ug/L	1	"	"	"	"	
sec-Butylbenzene	<1.0	1.0	0.055	ug/L	1	"	"	"	"	
Styrene	<1.0	1.0	0.048	ug/L	1	"	"	"	u .	
tert-Butylbenzene	<1.0	1.0	0.028	ug/L	1	"	"	"	"	
Tetrachloroethene	<1.0	1.0	0.035	ug/L	1	"	"	"	"	
Tetrahydrofuran	<20	20	0.34	ug/L	1	"	"	"	u .	T5
Toluene	<1.0	1.0	0.064	ug/L	1	"	"	"	II .	
trans-1,2-Dichloroethene	<1.0	1.0	0.058	ug/L	1	"	"	"	II .	
trans-1,3-Dichloropropene	<1.0	1.0	0.067	ug/L	1	"	"	"	· ·	
Trichloroethene	<1.0	1.0	0.096	ug/L	1	"	"	"	II .	
Trichlorofluoromethane	<1.0	1.0	0.26	ug/L	1	"	"	"	II .	
Vinyl chloride	<1.0	1.0	0.046	ug/L	1	"	"	"	u .	
Surrogate: 4-Bromofluorobenzene	91.3			80-121 %		"	"	"	"	
Surrogate: Dibromofluoromethane	94.9			79.9-121 %		"	"	"	"	
Surrogate: Toluene-d8	94.0	M: 44/04	//E 4E-4F	80-120 %	11/25/45 1	")·30	"	"	"	
B-3_8.6-18.6 (1505279-02) Groundwate	•									
1,1,1,2-Tetrachloroethane	<1.0	1.0	0.024	ug/L	1	B5L0232	11/25/15	11/25/15	EPA 8260B	
1,1,1-Trichloroethane	<1.0	1.0	0.069	ug/L	1	"	"	"	II .	
1,1,2,2-Tetrachloroethane	<1.0	1.0	0.051	ug/L	1	"	"	"	II .	
1,1,2-Trichloroethane	<1.0	1.0	0.10	ug/L	1	"	"	"	II .	
1,1,2-Trichlorotrifluoroethane	<1.0	1.0	0.081	ug/L	1	"	"	"	"	T5
1,1-Dichloroethane	<1.0	1.0	0.050	ug/L	1	"	"	"	"	

Fax: 651-642-1239

Work Order #: 1505279

Date Reported: 12/08/15

Barr Engineering Co. Project: 34511010
4700 W 77th St Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_8.6-18.6 (1505279-02) Groundwate	r Sample	ed: 11/24	1/15 15:45	Received:	11/25/15	9:30				
1,1-Dichloroethene	<1.0	1.0	0.065	ug/L	1	B5L0232	11/25/15	11/25/15	EPA 8260B	
1,1-Dichloropropene	<1.0	1.0	0.15	ug/L	1	"	"	u u	"	
1,2,3-Trichlorobenzene	<5.0	5.0	0.45	ug/L	1	"	· ·	II .	"	
1,2,3-Trichloropropane	<2.5	2.5	0.056	ug/L	1	"	"	"	"	
1,2,4-Trichlorobenzene	<5.0	5.0	0.091	ug/L	1	"	"	"	"	
1,2,4-Trimethylbenzene	<1.0	1.0	0.054	ug/L	1	"	"	"	"	
1,2-Dibromo-3-chloropropane	<5.0	5.0	0.033	ug/L	1	"	"	"	"	
1,2-Dibromoethane (EDB)	<2.5	2.5	0.042	ug/L	1	"	"	"	"	
1,2-Dichlorobenzene	<1.0	1.0	0.052	ug/L	1	"	"	"	"	
1,2-Dichloroethane	<1.0	1.0	0.064	ug/L	1	"	· ·	II .	"	
1,2-Dichloropropane	<1.0	1.0	0.034	ug/L	1	"	"	n .	· ·	
1,3,5-Trimethylbenzene	<1.0	1.0	0.046	ug/L	1	"	n .	n	"	
1,3-Dichlorobenzene	<1.0	1.0	0.068	ug/L	1	"	"	n .	· ·	
1,3-Dichloropropane	<1.0	1.0	0.15	ug/L	1	"	"	u u	"	
1,4-Dichlorobenzene	<1.0	1.0	0.047	ug/L	1	"	"	u u	"	
2,2-Dichloropropane	<5.0	5.0	0.28	ug/L	1	"	"	u u	"	
2-Butanone	<20	20	0.33	ug/L	1	"	u u	II .	"	
2-Chlorotoluene	<1.0	1.0	0.052	ug/L	1		"	"	"	
4-Chlorotoluene	<1.0	1.0	0.041	ug/L	1	"	"	u u	"	
Acetone	<20	20	0.32	ug/L	1	"	u u	II .	"	
Allyl chloride	<5.0	5.0	0.078	ug/L	1		"	"	"	
Benzene	<1.0	1.0	0.034	ug/L	1	"	"	u u	"	
Bromobenzene	<1.0	1.0	0.042	ug/L	1	"	"	u u	"	
Bromochloromethane	<1.0	1.0	0.10	ug/L	1	"	"	u u	"	
Bromodichloromethane	<1.0	1.0	0.042	ug/L	1		"	"	"	
Bromoform	<5.0	5.0	0.080	ug/L	1	"	"	u u	"	
Bromomethane	<5.0	5.0	0.17	ug/L	1	"	"	u u	"	
Carbon tetrachloride	<1.0	1.0	0.029	ug/L	1	"	"	u u	"	
Chlorobenzene	<1.0	1.0	0.037	ug/L	1	"	"	u u	"	
Chloroethane	<2.5	2.5	0.062	ug/L	1	"	"	u u	"	
Chloroform	<1.0	1.0	0.056	ug/L	1	"	"	"	"	
Chloromethane	<2.5	2.5	0.062	ug/L	1	"	"	"	"	
cis-1,2-Dichloroethene	<1.0	1.0	0.097	ug/L	1	"	"	"	"	
cis-1,3-Dichloropropene	<1.0	1.0	0.041	ug/L	1	"	"	"	"	
Dibromochloromethane	<2.5	2.5	0.070	ug/L	1	"	"	"	"	
Dibromomethane	<2.5	2.5	0.088	ug/L	1	"	"	"	"	
Dichlorodifluoromethane	<5.0	5.0	0.14	ug/L	1	"	"	"		
Dichlorofluoromethane	<1.0	1.0	0.059	ug/L	1	"	"	"		T5
Ethyl ether	<5.0	5.0	0.091	ug/L	1		"	"	"	

Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4700 W 77th St Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505279
Date Reported: 12/08/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-3_8.6-18.6 (1505279-02) Groundwater	Sample	ed: 11/24/	15 15:45	Received:	11/25/15	9:30				
Ethylbenzene	<1.0	1.0	0.033	ug/L	1	B5L0232	11/25/15	11/25/15	EPA 8260B	
Hexachlorobutadiene	<10	10	0.19	ug/L	1	"	"	"	"	
Isopropylbenzene	<1.0	1.0	0.037	ug/L	1	"	"	"	"	
m,p-Xylene	<2.0	2.0	0.087	ug/L	1	"	"	u u	"	
Methyl isobutyl ketone	<5.0	5.0	0.17	ug/L	1	"	· ·	II .	"	
Methyl tert-butyl ether	<1.0	1.0	0.056	ug/L	1	"	· ·	II .	"	
Methylene chloride	<5.0	5.0	0.10	ug/L	1	"	"	u u	"	
Naphthalene	<5.0	5.0	0.032	ug/L	1	"	"	u u	"	
n-Butylbenzene	<2.5	2.5	0.028	ug/L	1	"	"	u u	"	
n-Propylbenzene	<1.0	1.0	0.040	ug/L	1	"	"	"	"	
o-Xylene	<1.0	1.0	0.053	ug/L	1	"	"	"	"	
p-Isopropyltoluene	<2.5	2.5	0.052	ug/L	1	"	"	"	"	
sec-Butylbenzene	<1.0	1.0	0.055	ug/L	1	"	"	"	"	
Styrene	<1.0	1.0	0.048	ug/L	1	"	"	"	"	
tert-Butylbenzene	<1.0	1.0	0.028	ug/L	1	"	"	"	"	
Tetrachloroethene	<1.0	1.0	0.035	ug/L	1	"	"	"	"	
Tetrahydrofuran	<20	20	0.34	ug/L	1	"	"	"	"	T5
Toluene	<1.0	1.0	0.064	ug/L	1	"	"	n n	"	
trans-1,2-Dichloroethene	<1.0	1.0	0.058	ug/L	1	"	"	"	"	
trans-1,3-Dichloropropene	<1.0	1.0	0.067	ug/L	1	"	"	"	"	
Trichloroethene	<1.0	1.0	0.096	ug/L	1	"	"	n n	"	
Trichlorofluoromethane	<1.0	1.0	0.26	ug/L	1	"	"	п	II .	
Vinyl chloride	<1.0	1.0	0.046	ug/L	1	"	"	n n	"	
Surrogate: 4-Bromofluorobenzene	92.9			80-121 %		"	"	"	"	
Surrogate: Dibromofluoromethane	97.3			79.9-121 %		"	"	"	"	
Surrogate: Toluene-d8	95.3			80-120 %		"	"	"	"	
Trip Blank (1505279-03) Water Sample	d: 11/24/1	15 00:00	Receive	d: 11/25/15	9:30					
1,1,1,2-Tetrachloroethane	<1.0	1.0	0.024	ug/L	1	B5L0232	11/25/15	11/25/15	EPA 8260B	
1,1,1-Trichloroethane	<1.0	1.0	0.069	ug/L	1	"	"	"	"	
1,1,2,2-Tetrachloroethane	<1.0	1.0	0.051	ug/L	1	"	"	"	"	
1,1,2-Trichloroethane	<1.0	1.0	0.10	ug/L	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<1.0	1.0	0.081	ug/L	1	"	"	"	"	T5
1,1-Dichloroethane	<1.0	1.0	0.050	ug/L	1	"	"	n .	"	
1,1-Dichloroethene	<1.0	1.0	0.065	ug/L	1	"	"	n n	"	
1,1-Dichloropropene	<1.0	1.0	0.15	ug/L	1	"	"	"	"	
1,2,3-Trichlorobenzene	<5.0	5.0	0.45	ug/L	1	"	"	"	"	
1,2,3-Trichloropropane	<2.5	2.5	0.056	ug/L	1	"	"	"	"	
1,2,4-Trichlorobenzene	<5.0	5.0	0.091	ug/L	1	"	"	"	"	
1,2,4-Trimethylbenzene	<1.0	1.0	0.054	ug/L	1	"	"	"	"	
•				J						

Fax: 651-642-1239

Work Order #: 1505279

Date Reported: 12/08/15

Barr Engineering Co. 34511010 Project: 4700 W 77th St Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
Trip Blank (1505279-03) Water	Sampled: 11/24/1	15 00:00	Receive	d: 11/25/15	9:30					
1,2-Dibromo-3-chloropropane	<5.0	5.0	0.033	ug/L	1	B5L0232	11/25/15	11/25/15	EPA 8260B	
1,2-Dibromoethane (EDB)	<2.5	2.5	0.042	ug/L	1	"	"	II .	"	
1,2-Dichlorobenzene	<1.0	1.0	0.052	ug/L	1	"	"	"	"	
1,2-Dichloroethane	<1.0	1.0	0.064	ug/L	1	"	"	"	"	
1,2-Dichloropropane	<1.0	1.0	0.034	ug/L	1	"	"	"	"	
1,3,5-Trimethylbenzene	<1.0	1.0	0.046	ug/L	1	"	"	"	"	
1,3-Dichlorobenzene	<1.0	1.0	0.068	ug/L	1	"	"	"	"	
1,3-Dichloropropane	<1.0	1.0	0.15	ug/L	1	"	"	"	"	
1,4-Dichlorobenzene	<1.0	1.0	0.047	ug/L	1	"	"	II .	"	
2,2-Dichloropropane	<5.0	5.0	0.28	ug/L	1	"	"	II .	"	
2-Butanone	<20	20	0.33	ug/L	1	"	"	II .	"	
2-Chlorotoluene	<1.0	1.0	0.052	ug/L	1	"	"	II .	"	
4-Chlorotoluene	<1.0	1.0	0.041	ug/L	1	"	"	II .	"	
Acetone	<20	20	0.32	ug/L	1		"	"	"	
Allyl chloride	<5.0	5.0	0.078	ug/L	1	"	"	II .	"	
Benzene	<1.0	1.0	0.034	ug/L	1	"	"	II .	"	
Bromobenzene	<1.0	1.0	0.042	ug/L	1	"	"	II .	"	
Bromochloromethane	<1.0	1.0	0.10	ug/L	1		"	"	"	
Bromodichloromethane	<1.0	1.0	0.042	ug/L	1	"	"	II .	"	
Bromoform	<5.0	5.0	0.080	ug/L	1	"	"	II .	"	
Bromomethane	<5.0	5.0	0.17	ug/L	1		"	"	"	
Carbon tetrachloride	<1.0	1.0	0.029	ug/L	1	"	"	II .	"	
Chlorobenzene	<1.0	1.0	0.037	ug/L	1	"	"	II .	"	
Chloroethane	<2.5	2.5	0.062	ug/L	1	"	"	II .	"	
Chloroform	<1.0	1.0	0.056	ug/L	1	"	"	II .	"	
Chloromethane	<2.5	2.5	0.062	ug/L	1	"	"	II .	"	
cis-1,2-Dichloroethene	<1.0	1.0	0.097	ug/L	1	"	"	II .	"	
cis-1,3-Dichloropropene	<1.0	1.0	0.041	ug/L	1	"	"	"	"	
Dibromochloromethane	<2.5	2.5	0.070	ug/L	1	"	"	II .	"	
Dibromomethane	<2.5	2.5	0.088	ug/L	1	"	"	II .	"	
Dichlorodifluoromethane	<5.0	5.0	0.14	ug/L	1	"	"	II .	"	
Dichlorofluoromethane	<1.0	1.0	0.059	ug/L	1	"	"	II .	"	T5
Ethyl ether	<5.0	5.0	0.091	ug/L	1	"	"	n n	"	
Ethylbenzene	<1.0	1.0	0.033	ug/L	1	"	"	"	"	
Hexachlorobutadiene	<10	10	0.19	ug/L	1	"	"	п	"	
Isopropylbenzene	<1.0	1.0	0.037	ug/L	1	"	"	п	"	
m,p-Xylene	<2.0	2.0	0.087	ug/L	1	"	"	"	"	
Methyl isobutyl ketone	<5.0	5.0	0.17	ug/L	1	"	"	"	"	
Methyl tert-butyl ether	<1.0	1.0	0.056	ug/L	1	"	"	"	"	
weary tert-butyr ether	<1.0	1.0	0.000	ug/L	ı					



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4700 W 77th St Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505279
Date Reported: 12/08/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
Trip Blank (1505279-03) Water	Sampled: 11/24/1	5 00:00	Receive	ed: 11/25/15	9:30					
Methylene chloride	<5.0	5.0	0.10	ug/L	1	B5L0232	11/25/15	11/25/15	EPA 8260B	
Naphthalene	<5.0	5.0	0.032	ug/L	1	"	"	"	"	
n-Butylbenzene	<2.5	2.5	0.028	ug/L	1	"	"	"	"	
n-Propylbenzene	<1.0	1.0	0.040	ug/L	1	"	"	"	"	
o-Xylene	<1.0	1.0	0.053	ug/L	1	"	"	"	"	
p-Isopropyltoluene	<2.5	2.5	0.052	ug/L	1	"	"	"	"	
sec-Butylbenzene	<1.0	1.0	0.055	ug/L	1	n n	"	"	· ·	
Styrene	<1.0	1.0	0.048	ug/L	1	n n	"	"	· ·	
tert-Butylbenzene	<1.0	1.0	0.028	ug/L	1	"	"	"	"	
Tetrachloroethene	<1.0	1.0	0.035	ug/L	1	n n	"	"	· ·	
Tetrahydrofuran	<20	20	0.34	ug/L	1	"	"	"	"	T5
Toluene	<1.0	1.0	0.064	ug/L	1	"	"	"	"	
trans-1,2-Dichloroethene	<1.0	1.0	0.058	ug/L	1	"	"	"	"	
trans-1,3-Dichloropropene	<1.0	1.0	0.067	ug/L	1	n n	"	"	· ·	
Trichloroethene	<1.0	1.0	0.096	ug/L	1	n n	"	"	· ·	
Trichlorofluoromethane	<1.0	1.0	0.26	ug/L	1	n n	"	"	· ·	
/inyl chloride	<1.0	1.0	0.046	ug/L	1	n n	"	"	· ·	
Surrogate: 4-Bromofluorobenzene	91.5			80-121 %		"	"	"	"	
Surrogate: Dibromofluoromethane	96.5			79.9-121 %		"	"	"	"	
Surrogate: Toluene-d8	95.9			80-120 %		"	"	"	"	



Fax: 651-642-1239

 Barr Engineering Co.
 Project:
 34511010

 4700 W 77th St
 Project Number:
 34511010
 Work Order #:
 1505279

 Minneapolis, MN 55435
 Project Manager:
 Ms. Andrea Nord
 Date Reported:
 12/08/15

8015D DRO - Quality Control Legend Technical Services, Inc.

					0 11	0		0/ DEO		0/ DDD	
Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0106 - EPA 3510C (Sep Fu	ınnel)										
Blank (B5L0106-BLK1)					Prepared	l & Analyze	ed: 12/01/	15			
Diesel Range Organics	< 100	100	26	ug/L							
Surrogate: Triacontane (C-30)	418			ug/L	400		104	70-130			
LCS (B5L0106-BS1)					Prepared	l & Analyze	ed: 12/01/	15			
Diesel Range Organics	1570	100	26	ug/L	1600		98.4	70-130			
Surrogate: Triacontane (C-30)	406			ug/L	400		101	70-130			
LCS Dup (B5L0106-BSD1)					Prepared	l: 12/01/15	Analyzed	d: 12/02/15			
Diesel Range Organics	1610	100	26	ug/L	1600		100	70-130	2.11	20	
Surrogate: Triacontane (C-30)	407			ug/L	400		102	70-130			



Fax: 651-642-1239

 Barr Engineering Co.
 Project:
 34511010

 4700 W 77th St
 Project Number:
 34511010
 Work Order #: 1505279

 Minneapolis, MN 55435
 Project Manager:
 Ms. Andrea Nord
 Date Reported: 12/08/15

8015D GRO - Quality Control Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5K2505 - EPA 5030 Water (Purge and Tra	ap)									
Blank (B5K2505-BLK1)					Prepared	: 11/25/15	Analyzed	l: 11/26/15			
Gasoline range organics	< 100	100	16	ug/L							
Surrogate: 4-Fluorochlorobenzene	20.0			ug/L	20.0		99.9	80-150			
LCS (B5K2505-BS1)					Prepared	: 11/25/15	Analyzed	l: 11/26/15			
Gasoline range organics	1010	100	16	ug/L	1000		101	80-120			
Surrogate: 4-Fluorochlorobenzene	21.6			ug/L	20.0		108	80-150			
LCS Dup (B5K2505-BSD1)					Prepared	: 11/25/15	Analyzed	l: 11/26/15			
Gasoline range organics	966	100	16	ug/L	1000		96.6	80-120	4.26	20	
Surrogate: 4-Fluorochlorobenzene	21.6			ug/L	20.0		108	80-150			



Fax: 651-642-1239

 Barr Engineering Co.
 Project:
 34511010

 4700 W 77th St
 Project Number:
 34511010
 Work Order #:
 1505279

 Minneapolis, MN 55435
 Project Manager:
 Ms. Andrea Nord
 Date Reported:
 12/08/15

DISSOLVED METAL ANALYSIS - Quality Control Legend Technical Services, Inc.

					0 "	_		0/5=0		0/000	
Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0108 - EPA 200.7/3005A D	igestion										
Blank (B5L0108-BLK1)					Prepared	& Analyze	ed: 12/01/1	15			
Arsenic	< 0.010	0.010	0.0026	mg/L							
Barium	< 0.020	0.020	0.0022	mg/L							
Cadmium	< 0.0010	0.0010	0.000059	mg/L							
Chromium	< 0.010	0.010	0.0012	mg/L							
Lead	< 0.0050	0.0050	0.0012	mg/L							
Mercury	< 0.010	0.010	0.0023	mg/L							
Selenium	< 0.030	0.030	0.0073	mg/L							
Silver	< 0.0050	0.0050	0.00053	mg/L							
LCS (B5L0108-BS1)					Prepared	& Analyze	ed: 12/01/1	15			
Arsenic	0.429	0.010	0.0026	mg/L	0.399		108	80-120			
Barium	0.428	0.020	0.0022	mg/L	0.399		107	80-120			
Cadmium	0.449	0.0010	0.000059	mg/L	0.399		113	80-120			
Chromium	0.450	0.010	0.0012	mg/L	0.399		113	80-120			
Lead	0.447	0.0050	0.0012	mg/L	0.399		112	80-120			
Mercury	0.248	0.010	0.0023	mg/L	0.250		99.4	80-120			
Selenium	0.436	0.030	0.0073	mg/L	0.399		109	80-120			
Silver	0.0417	0.0050	0.00053	mg/L	0.0399		105	80-120			
LCS Dup (B5L0108-BSD1)					Prepared	& Analyze	ed: 12/01/1	15			
Arsenic	0.428	0.010	0.0026	mg/L	0.399		107	80-120	0.140	20	
Barium	0.432	0.020	0.0022	mg/L	0.399		108	80-120	0.838	20	
Cadmium	0.449	0.0010	0.000059	mg/L	0.399		113	80-120	0.0223	20	
Chromium	0.449	0.010	0.0012	mg/L	0.399		113	80-120	0.267	20	
Lead	0.449	0.0050	0.0012	mg/L	0.399		113	80-120	0.558	20	
Mercury	0.246	0.010	0.0023	mg/L	0.250		98.2	80-120	1.17	20	
Selenium	0.436	0.030	0.0073	mg/L	0.399		109	80-120	0.0917	20	
Silver	0.0414	0.0050	0.00053	mg/L	0.0399		104	80-120	0.722	20	
Matrix Spike (B5L0108-MS1)	8	Source:	1505279-02	2	Prepared	& Analyze	ed: 12/01/1	15			
Arsenic	0.431	0.010	0.0026	mg/L	0.399	<0.010	108	75-125			
Barium	0.466	0.020	0.0022	mg/L	0.399	0.0504	104	75-125			
Cadmium	0.426	0.0010	0.000059	mg/L	0.399	<0.0010	107	75-125			
Chromium	0.440	0.010	0.0012	mg/L	0.399	<0.010	110	75-125			
Lead		0.0050	0.0012	mg/L	0.399	0.0144	106	75-125			
Mercury		0.010	0.0023	mg/L	0.250	<0.010	96.3	75-125			
Selenium	0.474	0.030	0.0073	mg/L	0.399	<0.030	115	75-125			
Silver	0.0431	0.0050	0.00053	mg/L	0.0399	<0.0050	108	75-125			
Matrix Spike Dup (B5L0108-MSD1)			1505279-02	2	•	& Analyze	ed: 12/01/1	15			
Arsenic	0.436	0.010	0.0026	mg/L	0.399	<0.010	109	75-125	1.18	20	
Barium	0.473	0.020	0.0022	mg/L	0.399	0.0504	106	75-125	1.51	20	



Fax: 651-642-1239

 Barr Engineering Co.
 Project:
 34511010

 4700 W 77th St
 Project Number:
 34511010
 Work Order #: 1505279

 Minneapolis, MN 55435
 Project Manager:
 Ms. Andrea Nord
 Date Reported: 12/08/15

DISSOLVED METAL ANALYSIS - Quality Control Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0108 - EPA 200.7/3005A D	igestion										
Matrix Spike Dup (B5L0108-MSD1)	8	ource:	1505279-02	2	Prepared	l & Analyze	ed: 12/01/	15			
Cadmium	0.432	0.0010	0.000059	mg/L	0.399	<0.0010	108	75-125	1.35	20	
Chromium	0.444	0.010	0.0012	mg/L	0.399	<0.010	111	75-125	1.06	20	
Lead	0.444	0.0050	0.0012	mg/L	0.399	0.0144	108	75-125	1.64	20	
Mercury	0.254	0.010	0.0023	mg/L	0.250	<0.010	98.8	75-125	2.43	200	
Selenium	0.478	0.030	0.0073	mg/L	0.399	<0.030	116	75-125	0.736	20	
Silver	0.0435	0.0050	0.00053	mg/L	0.0399	<0.0050	109	75-125	0.924	20	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4700 W 77th St Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505279 Date Reported: 12/08/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5K3004 - EPA 3510C (Sep Funne	el)										
Blank (B5K3004-BLK1)					Prepared	d: 11/30/15	Analyzed	: 12/01/15			
1,2,4-Trichlorobenzene	< 10	10	0.53	ug/L			-				
1,2-Dichlorobenzene	< 10	10	0.47	ug/L							
1,2-Diphenylhydrazine as Azobenzene	< 10	10	0.32	ug/L							
1,3-Dichlorobenzene	< 10	10	0.43	ug/L							
1,4-Dichlorobenzene	< 10	10	0.32	ug/L							
2,3,4,6-Tetrachlorophenol	< 10	10	0.74	ug/L							
2,4,5-Trichlorophenol	< 10	10	1.1	ug/L							
2,4,6-Trichlorophenol	< 10	10	0.82	ug/L							
2,4-Dichlorophenol	< 10	10	0.78	ug/L							
2,4-Dimethylphenol	< 10	10	0.99	ug/L							
2,4-Dinitrophenol	< 10	10	0.70	ug/L							
2,4-Dinitrotoluene	< 10	10	0.44	ug/L							
2,6-Dichlorophenol	< 10	10	0.93	ug/L							
2,6-Dinitrotoluene	< 10	10	0.39	ug/L							
2-Chloronaphthalene	< 10	10	0.38	ug/L							
2-Chlorophenol	< 10	10	1.2	ug/L							
2-Methylnaphthalene	< 10	10	0.70	ug/L							
2-Methylphenol	< 10	10	1.4	ug/L							
2-Nitroaniline	< 10	10	0.83	ug/L							
2-Nitrophenol	< 10	10	0.86	ug/L							
3&4-Methylphenol	< 10	10	1.5	ug/L							
3,3´-Dichlorobenzidine	< 25	25	9.9	ug/L							
3-Nitroaniline	< 10	10	2.0	ug/L							
4,6-Dinitro-2-methylphenol	< 10	10	1.0	ug/L							
4-Bromophenyl phenyl ether	< 10	10	0.34	ug/L							
4-Chloro-3-methylphenol	< 10	10	0.68	ug/L							
4-Chloroaniline	< 10	10	2.3	ug/L							
4-Chlorophenyl phenyl ether	< 10	10	0.45	ug/L							
4-Nitroaniline	< 10	10	1.2	ug/L							
4-Nitrophenol	< 10	10	0.91	ug/L							
Acenaphthene	< 10	10	0.41	ug/L							
Acenaphthylene	< 10	10	0.38	ug/L							
Aniline	< 10	10	1.3	ug/L							
Anthracene	< 10	10	0.36	ug/L							
Benzidine	< 100	100	8.2	ug/L							
Benzo(a)anthracene	< 10	10	0.23	ug/L							
Benzo(a)pyrene	< 10	10	0.34	ug/L							
Benzo(b)fluoranthene	< 10	10	0.18	ug/L							
Benzo(g,h,i)perylene	< 10	10	0.43	ug/L							



Fax: 651-642-1239

 Barr Engineering Co.
 Project:
 34511010

 4700 W 77th St
 Project Number:
 34511010
 Work Order #: 1505279

 Minneapolis, MN 55435
 Project Manager:
 Ms. Andrea Nord
 Date Reported: 12/08/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5K3004 - EPA 3510C (Sep Funn	el)										
Blank (B5K3004-BLK1)					Prepared	l: 11/30/15	Analyzed	: 12/01/15			
Benzo(k)fluoranthene	< 10	10	0.55	ug/L	·						
Benzoic acid	< 10	10	1.8	ug/L							
Benzyl alcohol	< 10	10	0.68	ug/L							
Bis(2-chloroethoxy)methane	< 10	10	0.41	ug/L							
Bis(2-chloroethyl)ether	< 10	10	0.59	ug/L							
Bis(2-chloroisopropyl)ether	< 10	10	0.47	ug/L							
Bis(2-ethylhexyl)phthalate	< 10	10	0.77	ug/L							
Butyl benzyl phthalate	< 10	10	0.67	ug/L							
Carbazole	< 10	10	0.42	ug/L							
Chrysene	< 10	10	0.34	ug/L							
Dibenz(a,h)anthracene	< 10	10	0.31	ug/L							
Dibenzofuran	< 10	10	0.77	ug/L							
Diethyl phthalate	< 10	10	0.42	ug/L							
Dimethyl phthalate	< 10	10	0.44	ug/L							
Di-n-butyl phthalate	< 10	10	0.42	ug/L							
Di-n-octyl phthalate	< 10	10	0.48	ug/L							
Fluoranthene	< 10	10	0.36	ug/L							
Fluorene	< 10	10	0.35	ug/L							
Hexachlorobenzene	< 10	10	0.30	ug/L							
Hexachlorobutadiene	< 10	10	0.37	ug/L							
Hexachlorocyclopentadiene	< 10	10	0.52	ug/L							
Hexachloroethane	< 10	10	0.61	ug/L							
Indeno (1,2,3-cd) pyrene	< 10	10	0.37	ug/L							
Isophorone	< 10	10	0.45	ug/L							
Naphthalene	< 10	10	0.33	ug/L							
Nitrobenzene	< 10	10	0.51	ug/L							
N-Nitrosodimethylamine	< 10	10	0.34	ug/L							
N-Nitrosodi-n-propylamine	< 10	10	0.47	ug/L							
N-Nitrosodiphenylamine	< 10	10	0.54	ug/L							
Pentachlorophenol	< 10	10	1.2	ug/L							
Phenanthrene	< 10	10	0.28	ug/L							
Phenol	< 10	10	1.2	ug/L							
Pyrene	< 10	10	0.49	ug/L							
Surrogate: 2,4,6-Tribromophenol	87.4			ug/L	100		87.4	30-122			
Surrogate: 2-Fluorobiphenyl	85.3			ug/L	100		85.3	39.2-104			
Surrogate: 2-Fluorophenol	61.6			ug/L	100		61.6	30-80.1			
Surrogate: Nitrobenzene-d5	79.5			ug/L	100		79.5	51.2-103			
Surrogate: Phenol-d6	56.1			ug/L	100		56.1	30-75.3			
Surrogate: Terphenyl-d14	89.3			ug/L	100		89.3	30-116			



Fax: 651-642-1239

Work Order #: 1505279

Date Reported: 12/08/15

Barr Engineering Co. Project: 34511010
4700 W 77th St Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Anglista	Deside	ום	MD	-غاما ا	Spike	Source	0/ DEC	%REC	0/ DDD	%RPD	Note -
Analyte	Result	RL	MDL	Units	Level	Result	%REC	Limits	%RPD	Limit	Notes
Batch B5K3004 - EPA 3510C (Sep Fun	nnel)										
LCS (B5K3004-BS1)					Prepared	l: 11/30/15	Analyzed	l: 12/03/15			
1,2,4-Trichlorobenzene	39.4	10	0.53	ug/L	50.0		78.7	38-100			
1,4-Dichlorobenzene	37.7	10	0.32	ug/L	50.0		75.4	30-90			
2,4-Dinitrotoluene	43.9	10	0.44	ug/L	50.0		87.9	57-100			
2-Chlorophenol	37.9	10	1.2	ug/L	50.0		75.7	45-95			
4-Chloro-3-methylphenol	43.2	10	0.68	ug/L	50.0		86.5	52-100			
4-Nitrophenol	37.7	10	0.91	ug/L	50.0		75.4	30-100			
Anthracene	45.0	10	0.36	ug/L	50.0		89.9	60-100			
Benzo(a)anthracene	47.8	10	0.23	ug/L	50.0		95.7	64-100			
Benzo(a)pyrene	49.8	10	0.34	ug/L	50.0		99.5	60-100			
Chrysene	50.0	10	0.34	ug/L	50.0		100	60-100			
Fluoranthene	44.9	10	0.36	ug/L	50.0		89.8	63-100			
Fluorene	45.0	10	0.35	ug/L	50.0		90.0	59-100			
N-Nitrosodi-n-propylamine	43.5	10	0.47	ug/L	50.0		86.9	55-100			
Pentachlorophenol	46.1	10	1.2	ug/L	50.0		92.2	45-107			
Phenanthrene	45.3	10	0.28	ug/L	50.0		90.5	62-100			
Phenol	30.0	10	1.2	ug/L	50.0		59.9	30-80			
Surrogate: 2,4,6-Tribromophenol	69.0			ug/L	100		69.0	30-122			
Surrogate: 2-Fluorobiphenyl	64.5			ug/L	100		64.5	39.2-104			
Surrogate: 2-Fluorophenol	46.7			ug/L	100		46.7	30-80.1			
Surrogate: Nitrobenzene-d5	64.3			ug/L	100		64.3	51.2-103			
Surrogate: Phenol-d6	46.8			ug/L	100		46.8	30-75.3			
Surrogate: Terphenyl-d14	62.7	_		ug/L	100		62.7	30-116			
Matrix Spike (B5K3004-MS1)	So	ource:	1505301-0	1	Prepared	l: 11/30/15	Analyzed	1: 12/01/15			
1,2,4-Trichlorobenzene	38.9	10	0.53	ug/L	50.0	<10	77.9	30-100			
1,4-Dichlorobenzene	36.9	10	0.32	ug/L	50.0	<10	73.7	30-90			
2,4-Dinitrotoluene	48.2	10	0.44	ug/L	50.0	<10	96.4	30-110			
2-Chlorophenol	36.5	10	1.2	ug/L	50.0	<10	73.0	30-100			
4-Chloro-3-methylphenol	43.9	10	0.68	ug/L	50.0	<10	87.8	30-113			
4-Nitrophenol	43.1	10	0.91	ug/L	50.0	<10	86.1	30-112			
Anthracene	47.6	10	0.36	ug/L	50.0	<10	91.5	30-119			
Benzo(a)anthracene	50.7	10	0.23	ug/L	50.0	<10	101	30-122			
Benzo(a)pyrene	49.4	10	0.34	ug/L	50.0	<10	98.7	30-118			
Chrysene	50.4	10	0.34	ug/L	50.0	<10	101	30-125			
Fluoranthene	55.7	10	0.36	ug/L	50.0	<10	103	30-119			
Fluorene	53.6	10	0.35	ug/L	50.0	<10	92.1	30-107			
N-Nitrosodi-n-propylamine	42.7	10	0.47	ug/L	50.0	<10	85.3	37-100			
Pentachlorophenol	43.6	10	1.2	ug/L	50.0	<10	87.2	30-130			
Phenanthrene	52.5	10	0.28	ug/L	50.0	<10	93.4	30-117			
Phenol	26.7	10	1.2	ug/L	50.0	<10	51.0	30-80			
	_5.1	. •			22.0	•					



Fax: 651-642-1239

Work Order #: 1505279

Date Reported: 12/08/15

Barr Engineering Co. Project: 34511010
4700 W 77th St Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5K3004 - EPA 3510C (Sep Fi	unnel)										
Matrix Spike (B5K3004-MS1)	S	ource:	1505301-0)1	Prepared	: 11/30/15	Analyzed	: 12/01/15			
Surrogate: 2,4,6-Tribromophenol	98.1			ug/L	100		98.1	30-122			
Surrogate: 2-Fluorobiphenyl	85.8			ug/L	100		85.8	39.2-104			
Surrogate: 2-Fluorophenol	57.0			ug/L	100		57.0	30-80.1			
Surrogate: Nitrobenzene-d5	79.8			ug/L	100		79.8	51.2-103			
Surrogate: Phenol-d6	50.6			ug/L	100		50.6	30-75.3			
Surrogate: Terphenyl-d14	76.1			ug/L	100		76.1	30-116			
Matrix Spike Dup (B5K3004-MSD1)	s	ource:	505301-0)1	Prepared	: 11/30/15	Analyzed	: 12/01/15			
1,2,4-Trichlorobenzene	37.7	10	0.53	ug/L	50.5	<10	74.6	30-100	3.30	20	
1,4-Dichlorobenzene	35.2	10	0.32	ug/L	50.5	<10	69.7	30-90	4.58	20	
2,4-Dinitrotoluene	45.7	10	0.44	ug/L	50.5	<10	90.4	30-110	5.43	20	
2-Chlorophenol	36.2	10	1.2	ug/L	50.5	<10	71.7	30-100	0.748	20	
4-Chloro-3-methylphenol	43.8	10	0.68	ug/L	50.5	<10	86.6	30-113	0.348	20	
4-Nitrophenol	44.4	10	0.91	ug/L	50.5	<10	87.9	30-112	2.97	34.3	
Anthracene	46.0	10	0.36	ug/L	50.5	<10	87.3	30-119	3.54	20	
Benzo(a)anthracene	48.7	10	0.23	ug/L	50.5	<10	96.4	30-122	4.16	20	
Benzo(a)pyrene	48.3	10	0.34	ug/L	50.5	<10	95.7	30-118	2.10	20	
Chrysene	48.6	10	0.34	ug/L	50.5	<10	96.2	30-125	3.71	20	
Fluoranthene	53.3	10	0.36	ug/L	50.5	<10	97.1	30-119	4.44	20	
Fluorene	52.0	10	0.35	ug/L	50.5	<10	88.1	30-107	2.92	20	
N-Nitrosodi-n-propylamine	41.4	10	0.47	ug/L	50.5	<10	82.0	37-100	2.94	20	
Pentachlorophenol	41.7	10	1.2	ug/L	50.5	<10	82.6	30-130	4.45	20	
Phenanthrene	50.4	10	0.28	ug/L	50.5	<10	88.2	30-117	4.24	20	
Phenol	28.4	10	1.2	ug/L	50.5	<10	53.7	30-80	5.93	31.9	
Surrogate: 2,4,6-Tribromophenol	92.3			ug/L	101		91.4	30-122			
Surrogate: 2-Fluorobiphenyl	84.2			ug/L	101		83.3	39.2-104			
Surrogate: 2-Fluorophenol	58.2			ug/L	101		57.6	30-80.1			
Surrogate: Nitrobenzene-d5	77.6			ug/L	101		76.8	51.2-103			
Surrogate: Phenol-d6	54.2			ug/L	101		53.6	30-75.3			
Surrogate: Terphenyl-d14	78.9			ug/L	101		78.1	30-116			



Fax: 651-642-1239

Work Order #: 1505279

Date Reported: 12/08/15

Barr Engineering Co. Project: 34511010 4700 W 77th St Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0232 - EPA 5030 Water ((Purge and Tra	p)									
Blank (B5L0232-BLK1)					Prepared	l & Analyze	ed: 11/25/1	5			
1,1,1,2-Tetrachloroethane	< 1.0	1.0	0.024	ug/L							
1,1,1-Trichloroethane	< 1.0	1.0	0.069	ug/L							
1,1,2,2-Tetrachloroethane	< 1.0	1.0	0.051	ug/L							
1,1,2-Trichloroethane	< 1.0	1.0	0.10	ug/L							
1,1,2-Trichlorotrifluoroethane	< 1.0	1.0	0.081	ug/L							
1,1-Dichloroethane	< 1.0	1.0	0.050	ug/L							
1,1-Dichloroethene	< 1.0	1.0	0.065	ug/L							
1,1-Dichloropropene	< 1.0	1.0	0.15	ug/L							
1,2,3-Trichlorobenzene	< 5.0	5.0	0.45	ug/L							
1,2,3-Trichloropropane	< 2.5	2.5	0.056	ug/L							
1,2,4-Trichlorobenzene	< 5.0	5.0	0.091	ug/L							
1,2,4-Trimethylbenzene	< 1.0	1.0	0.054	ug/L							
1,2-Dibromo-3-chloropropane	< 5.0	5.0	0.033	ug/L							
1,2-Dibromoethane (EDB)	< 2.5	2.5	0.042	ug/L							
1,2-Dichlorobenzene	< 1.0	1.0	0.052	ug/L							
1,2-Dichloroethane	< 1.0	1.0	0.064	ug/L							
1,2-Dichloropropane	< 1.0	1.0	0.034	ug/L							
1,3,5-Trimethylbenzene	< 1.0	1.0	0.046	ug/L							
1,3-Dichlorobenzene	< 1.0	1.0	0.068	ug/L							
1,3-Dichloropropane	< 1.0	1.0	0.15	ug/L							
1,4-Dichlorobenzene	< 1.0	1.0	0.047	ug/L							
2,2-Dichloropropane	< 5.0	5.0	0.28	ug/L							
2-Butanone	< 20	20	0.33	ug/L							
2-Chlorotoluene	< 1.0	1.0	0.052	ug/L							
4-Chlorotoluene	< 1.0	1.0	0.041	ug/L							
Acetone	< 20	20	0.32	ug/L							
Allyl chloride	< 5.0	5.0	0.078	ug/L							
Benzene	< 1.0	1.0	0.034	ug/L							
Bromobenzene	< 1.0	1.0	0.042	ug/L							
Bromochloromethane	< 1.0	1.0	0.10	ug/L							
Bromodichloromethane	< 1.0	1.0	0.042	ug/L							
Bromoform	< 5.0	5.0	0.080	ug/L							
Bromomethane	< 5.0	5.0	0.17	ug/L							
Carbon tetrachloride	< 1.0	1.0	0.029	ug/L							
Chlorobenzene	< 1.0	1.0	0.037	ug/L							
Chloroethane	< 2.5	2.5	0.062	ug/L							
Chloroform	< 1.0	1.0	0.056	ug/L							
Chloromethane	< 2.5	2.5	0.062	ug/L							
cis-1,2-Dichloroethene	< 1.0	1.0	0.097	ug/L							



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4700 W 77th St Project Number: 34511010 Work Order #: 1505279 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/08/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0232 - EPA 5030 Water (Purg	e and Tra	p)									
Blank (B5L0232-BLK1)					Prepared	ł & Analyze	d: 11/25/1	5			
cis-1,3-Dichloropropene	< 1.0	1.0	0.041	ug/L	-	•					
Dibromochloromethane	< 2.5	2.5	0.070	ug/L							
Dibromomethane	< 2.5	2.5	0.088	ug/L							
Dichlorodifluoromethane	< 5.0	5.0	0.14	ug/L							
Dichlorofluoromethane	< 1.0	1.0	0.059	ug/L							
Ethyl ether	< 5.0	5.0	0.091	ug/L							
Ethylbenzene	< 1.0	1.0	0.033	ug/L							
Hexachlorobutadiene	< 10	10	0.19	ug/L							
Isopropylbenzene	< 1.0	1.0	0.037	ug/L							
m,p-Xylene	< 2.0	2.0	0.087	ug/L							
Methyl isobutyl ketone	< 5.0	5.0	0.17	ug/L							
Methyl tert-butyl ether	< 1.0	1.0	0.056	ug/L							
Methylene chloride	< 5.0	5.0	0.10	ug/L							
Naphthalene	< 5.0	5.0	0.032	ug/L							
n-Butylbenzene	< 2.5	2.5	0.028	ug/L							
n-Propylbenzene	< 1.0	1.0	0.040	ug/L							
o-Xylene	< 1.0	1.0	0.053	ug/L							
p-Isopropyltoluene	< 2.5	2.5	0.052	ug/L							
sec-Butylbenzene	< 1.0	1.0	0.055	ug/L							
Styrene	< 1.0	1.0	0.048	ug/L							
tert-Butylbenzene	< 1.0	1.0	0.028	ug/L							
Tetrachloroethene	< 1.0	1.0	0.035	ug/L							
Tetrahydrofuran	< 20	20	0.34	ug/L							
Toluene	< 1.0	1.0	0.064	ug/L							
trans-1,2-Dichloroethene	< 1.0	1.0	0.058	ug/L							
trans-1,3-Dichloropropene	< 1.0	1.0	0.067	ug/L							
Trichloroethene	< 1.0	1.0	0.096	ug/L							
Trichlorofluoromethane	< 1.0	1.0	0.26	ug/L							
Vinyl chloride	< 1.0	1.0	0.046	ug/L							
Surrogate: 4-Bromofluorobenzene	51.3			ug/L	56.0		91.6	80-121			
Surrogate: Dibromofluoromethane	54.6			ug/L	56.0		97.5	79.9-121			
Surrogate: Toluene-d8	54.0			ug/L	56.0		96.3	80-120			
LCS (B5L0232-BS1)	_	_	_	_	Prepared	l & Analyze	ed: 11/25/1	5	_		
1,1,2,2-Tetrachloroethane	53.6	1.0	0.051	ug/L	50.0		107	80-121			
1,1-Dichloroethane	51.3	1.0	0.050	ug/L	50.0		103	80-125			
1,1-Dichloroethene	48.6	1.0	0.065	ug/L	50.0		97.1	80-125			
1,3,5-Trimethylbenzene	50.2	1.0	0.046	ug/L	50.0		100	75.4-125			
1,4-Dichlorobenzene	48.6	1.0	0.047	ug/L	50.0		97.2	75-125			
2-Chlorotoluene	50.0	1.0	0.052	ug/L	50.0		100	75.4-125			



Fax: 651-642-1239

 Barr Engineering Co.
 Project:
 34511010

 4700 W 77th St
 Project Number:
 34511010
 Work Order #: 1505279

 Minneapolis, MN 55435
 Project Manager:
 Ms. Andrea Nord
 Date Reported: 12/08/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0232 - EPA 5030 Water (Purge a				0.1110		rtoouit	701.120		, (i ti D		110100
LCS (B5L0232-BS1)	u 11a	P)			Prenared	l & Analyze	d· 11/25/	15			
Benzene	50.1	1.0	0.034	ug/L	50.0	i & Allaly26	100	80-120			
Bromoform	49.9	5.0	0.034	ug/L ug/L	50.0		99.8	80-120			
Chlorobenzene	48.6	1.0	0.037	ug/L ug/L	50.0		97.3	80-120			
Chloroform	50.4	1.0	0.056	ug/L ug/L	50.0		101	80-123			
Ethylbenzene	48.3	1.0	0.033	ug/L	50.0		96.5	80-120			
n-Butylbenzene	50.1	2.5	0.033	ug/L ug/L	50.0		100	75-125			
n-Propylbenzene	50.1	1.0	0.028	ug/L ug/L	50.0		101	75.8-125			
Toluene	50.3	1.0	0.040	ug/L ug/L	50.0		100	80-120			
Trichloroethene	49.6	1.0	0.096	ug/L ug/L	50.0		99.2	80-120			
Vinyl chloride	45.0	1.0	0.046	ug/L	50.0		90.1	75-130			
•	52.4	1.0	0.040	_	56.0		93.6	80-121			
Surrogate: 4-Bromofluorobenzene Surrogate: Dibromofluoromethane	53.2			ug/L ug/l	56.0 56.0		93.0 95.0	79.9-121			
Surrogate: Dibromonuorometnane Surrogate: Toluene-d8	53.2 53.8			ug/L ug/L	56.0 56.0		95.0 96.1	79.9-121 80-120			
			1505070.0			I O A l					
Matrix Spike (B5L0232-MS1)			1505279-0		•	l & Analyze					
1,1,2,2-Tetrachloroethane	56.6	1.0	0.051	ug/L	50.0	<1.0	113	76.8-125			
1,1-Dichloroethane	53.1	1.0	0.050	ug/L	50.0	<1.0	106	80-125			
1,1-Dichloroethene	50.7	1.0	0.065	ug/L	50.0	<1.0	101	80-125 75-125			
1,3,5-Trimethylbenzene	51.7 40.0	1.0	0.046	ug/L	50.0	<1.0	103				
1,4-Dichlorobenzene	49.9 51.6	1.0	0.047	ug/L	50.0	<1.0	99.8	75-125 75-125			
2-Chlorotoluene	51.6	1.0 1.0	0.052	ug/L	50.0	<1.0	103	75-125 80 120			
Benzene Bromoform	53.3 53.9	5.0	0.034 0.080	ug/L	50.0 50.0	<1.0 <5.0	107 108	80-120 80-120			
				ug/L							
Chlorobenzene Chloroform	51.5 52.8	1.0 1.0	0.037 0.056	ug/L	50.0 50.0	<1.0 <1.0	103 106	80-120 79.8-125			
Ethylbenzene	52.6 51.4	1.0	0.033	ug/L ug/L	50.0	<1.0 <1.0	103	79.6-125 80-120			
n-Butylbenzene	51.4 51.2	2.5	0.033	ug/L ug/L	50.0	<1.0 <2.5	103	75-130			
n-Propylbenzene	52.2	2.5 1.0	0.028	ug/L ug/L	50.0	<2.5 <1.0	104	75-130 75-125			
Toluene	52.2 52.7	1.0	0.040	_	50.0	<1.0 <1.0	104	75-125 80-120			
Trichloroethene	52.7 52.5	1.0	0.064	ug/L ug/L	50.0	<1.0 <1.0	105	80-120			
Vinyl chloride	52.5 47.6	1.0	0.096	ug/L ug/L	50.0	<1.0 <1.0	95.2	75-130			
•		1.0	0.040			\1.0					
Surrogate: 4-Bromofluorobenzene	54.7			ug/L	56.0		97.8	80-121			
Surrogate: Dibromofluoromethane	53.8			ug/L	56.0		96.1	79.9-121			
Surrogate: Toluene-d8	54.0			ug/L	56.0		96.4	80-120			
Matrix Spike Dup (B5L0232-MSD1)			1505279-0			l & Analyze			0.4.10	00	
1,1,2,2-Tetrachloroethane	56.7	1.0	0.051	ug/L	50.0	<1.0	113	76.8-125	0.146	20	
1,1-Dichloroethane	52.3	1.0	0.050	ug/L	50.0	<1.0	105	80-125	1.60	20	
1,1-Dichloroethene	49.4	1.0	0.065	ug/L	50.0	<1.0	98.9	80-125	2.44	20	
1,3,5-Trimethylbenzene	51.5	1.0	0.046	ug/L	50.0	<1.0	103	75-125	0.527	20	



Fax: 651-642-1239

 Barr Engineering Co.
 Project:
 34511010

 4700 W 77th St
 Project Number:
 34511010
 Work Order #: 1505279

 Minneapolis, MN 55435
 Project Manager:
 Ms. Andrea Nord
 Date Reported: 12/08/15

		5.			Spike	Source		%REC		%RPD	
Analyte	Result	RL	MDL	Units	Level	Result	%REC	Limits	%RPD	Limit	Notes
Batch B5L0232 - EPA 5030 Water (Pt	urge and Tra	p)									
Matrix Spike Dup (B5L0232-MSD1)	S	ource:	1505279-0	1	Prepared	ł & Analyze	ed: 11/25/	15			
1,4-Dichlorobenzene	48.8	1.0	0.047	ug/L	50.0	<1.0	97.5	75-125	2.35	20	
2-Chlorotoluene	51.0	1.0	0.052	ug/L	50.0	<1.0	102	75-125	1.20	20	
Benzene	51.5	1.0	0.034	ug/L	50.0	<1.0	103	80-120	3.37	20	
Bromoform	51.6	5.0	0.080	ug/L	50.0	<5.0	103	80-120	4.34	20	
Chlorobenzene	49.4	1.0	0.037	ug/L	50.0	<1.0	98.7	80-120	4.17	20	
Chloroform	51.4	1.0	0.056	ug/L	50.0	<1.0	103	79.8-125	2.73	20	
Ethylbenzene	49.2	1.0	0.033	ug/L	50.0	<1.0	98.4	80-120	4.41	20	
n-Butylbenzene	50.1	2.5	0.028	ug/L	50.0	<2.5	100	75-130	2.11	20	
n-Propylbenzene	52.3	1.0	0.040	ug/L	50.0	<1.0	105	75-125	0.132	20	
Toluene	51.5	1.0	0.064	ug/L	50.0	<1.0	103	80-120	2.36	20	
Trichloroethene	51.9	1.0	0.096	ug/L	50.0	<1.0	104	80-120	1.16	20	
Vinyl chloride	44.8	1.0	0.046	ug/L	50.0	<1.0	89.5	75-130	6.12	20	
Surrogate: 4-Bromofluorobenzene	53.3			ug/L	56.0		95.1	80-121			
Surrogate: Dibromofluoromethane	55.1			ug/L	56.0		98.4	79.9-121			
Surrogate: Toluene-d8	54.6			ug/L	56.0		97.6	80-120			



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4700 W 77th St Project Number: 34511010 Work Order #: 1505279 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/08/15

Notes and Definitions

T5	l abaratanı nat	liaanaad far	this parameter.

Results in the diesel organics range are primarily due to overlap from a heavy oil range product. L1

Less than value listed <

dry Sample results reported on a dry weight basis

Not applicable. The %RPD is not calculated from values less than the reporting limit. NA

MDL Method Detection Limit; Equivalent to the method LOD (Limit of Detection)

RLReporting Limit

RPD Relative Percent Difference

LCS Laboratory Control Spike = Blank Spike (BS) = Laboratory Fortified Blank (LFB)

MS Matrix Spike = Laboratory Fortified Matrix (LFM)



88 Empire Drive St Paul, MN 55103

Tel: 651-642-1150 Fax: 651-642-1239

Chain of	Cust	ody		1505279						N	mbe	r of Con	tumers/Preservative	4	coc	of _ /		
ARR Minneapolis, 1	IN 5543	5-4803			1505	1	17			H	-	W	ter	-	5oil	+	112402	ACRES TATE
(952) 832-260)	_						-	_				4				Project Manager: MA	rdy B
oject Number: 345	lioit	1						ij.										1
rijest Name: UHZ A			idi	rall							3		(HC)		()	tuise	Project QC Contact:	dre
mple Origination State 💩 [1		1	(HNC	170	Organics	š	CORP. #1 d McOnt. reserved rved) #2 rved) #2	Com	Λ	ford
OC Number:					N	0	4	508	4	-	totate	THE		(77)	EEX transd McOH) #2 areal augressive fungereserved (augresserved) #2	Number Of Contains	Sampled by: A	UKL
	Taxes -		Depth	Collection	Collection		trix		pe	1361	ced &	-	Range	18	O. BEEN transition of transiti	Nomb		1
Location	Start Depth	Stop Depth	Unit (m/ft/ or in/j	Date (mm/dd/yyyy)	Time (lihumn)	Water	Seat	Chate		VOCE (BCI) 🕸	Dissalved Aptain (HNO s)	total Mensi - 4HMO.1	Diexes	3,2,1	VDCs. (tarest MeOB) are ORO. BTRX transf MeOB) are DRO. (tarest corpreserved) Scenali (unpreserved) SVOCs. (unpreserved) are	Total	Sampled by: A	yend
B-1	10	20	Ŧŧ	11/24/15	1500	χ		X		3	1		H	3		ien.	STAT	
B-3	84	18 4	4+	h	1545	K		X		3	t i		1	3		9		
temp bkn)	- N	A						-11	X							1		
HCL brank	(2)	A -	_				H	-	1							1		
		791201																
							Ì		Ť		T	I				T		
									İ	Ħ	T	İ						7
							t		t	l	t	T		Ħ		t		
B.													H			H	17	
mmon Parameter/Containe	r - Preser	vation I	Cey I	telinquished By:	K			loo?		Dute		Ti		Receiv	ed by:		Date	Time
Volatile Organics = BTEX, GB Semisolatile Organics = PAHs, Full Ltst. Herbicide/Pentride/Po	PCP Dion			tolinquished By:	17		-	lce?	11/	Date	11.5	-	ne ne	Roceiv	calling L		1/2C/1	7mc 933
Genwal = pH. Chlorule, Fluor TDS, TS, Sulfate Nutrients = COD, TOC, Phens	de, Alkalin		5	amples Shipped 1	Ac Air F		l'i	/ 1	ni E	apres	· [San	pler	Air Bi	Number:		10.570	150

Fax: 651-642-1239

Page 2

Data File; \\lts-target\targetdata\chem\FIB5.i\151201.b\013.d

Date : 01-DEC-2015 15:23


Client ID:

Sample Info: 1505279-01

Instrument: F106,i

Operator: gp

Column diameter: 0,53





Fax: 651-642-1239

Page 2

Bata File; \\lts-target\targetdata\chem\FID5.i\151201.b\017.d

Date : 01-0EC-2015 17:11

Client ID:


Sample Info: 1505279-02

Column phase:

Instrument: FID5.i

Operator: yp

Column diameter: 0.53





88 Empire Drive St Paul, MN 55103 Tel: 651-642-1150 Fax: 651-642-1239

December 10, 2015

Ms. Andrea Nord Barr Engineering Co. 4300 MarketPointe Drive, Suite 200 Minneapolis, MN 55435

Work Order Number: 1505312

RE: 34511010

Enclosed are the results of analyses for samples received by the laboratory on 12/01/15. If you have any questions concerning this report, please feel free to contact me.

Results are not blank corrected unless noted within the report. Additionally, all QC results meet requirements unless noted.

All samples will be retained by Legend Technical Services, Inc., unless consumed in the analysis, at ambient conditions for 30 days from the date of this report and then discarded unless other arrangements are made. All samples were received in acceptable condition unless otherwise noted.

ND Accreditation #R-065

Prepared by, LEGEND TECHNICAL SERVICES, INC

Bach Pham Client Manager II

bpham@legend-group.com



Fax: 651-642-1239

Barr Engineering Co.Project:345110104300 MarketPointe Drive, Suite 200Project Number:34511010Work Order #: 1505312Minneapolis, MN 55435Project Manager:Ms. Andrea NordDate Reported:12/10/15

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
B-4	1505312-01	Water	11/25/15 07:40	12/01/15 08:00
B-D	1505312-02	Water	11/25/15 08:10	12/01/15 08:00
B-2a	1505312-03	Water	11/25/15 08:40	12/01/15 08:00
Trip Blank	1505312-04	Water	11/25/15 00:00	12/01/15 08:00

Shipping Container Information

Default Cooler Temperature (°C): 3.7

Received on ice: Yes Temperature blank was present Received on ice pack: No Received on melt water: No Ambient: No Acceptable (IH/ISO only): No

Custody seals: No

Case Narrative:

An LCS/LCSD was prepared and analyzed for the 8270 batch B5L0201 instead of the method specified LCS/MS/MSD. Insufficient sample was received to meet method QC requirements.

Recovery for the 8270 surrogate phenol-d6 was below laboratory acceptance limits in sample B-2a. All surrogates were within acceptance limits in the batch B5L0201 method blank, LCS, and LCSD.

The DRO chromatograms are attached for all samples.



Fax: 651-642-1139

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312
Date Reported: 12/10/15

8015D DRO Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4 (1505312-01) Water Sampled: 1	1/25/15 07:40	Rec	eived: 12/0	1/15 8:00						
Diesel Range Organics	110	100	26	ug/L	1	B5L0202	12/02/15	12/02/15	EPA 8015D	
Surrogate: Triacontane (C-30)	93.4			70-130 %		"	"	"	"	
B-D (1505312-02) Water Sampled: 1	1/25/15 08:10	Rec	eived: 12/0	1/15 8:00						
Diesel Range Organics	190	100	26	ug/L	1	B5L0202	12/02/15	12/02/15	EPA 8015D	
Surrogate: Triacontane (C-30)	99.7			70-130 %		"	"	"	"	
B-2a (1505312-03) Water Sampled:	11/25/15 08:4	0 Re	ceived: 12/	01/15 8:00						
Diesel Range Organics	130	100	26	ug/L	1	B5L0202	12/02/15	12/02/15	EPA 8015D	
Surrogate: Triacontane (C-30)	84.3			70-130 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Work Order #: 1505312 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/10/15

8015D GRO Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4 (1505312-01) Water Sampled: 11	/25/15 07:40	Rec	eived: 12/0	1/15 8:00						
Gasoline range organics	<100	100	16	ug/L	1	B5L0228	12/02/15	12/03/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	131			80-150 %		"	"	"	"	
B-D (1505312-02) Water Sampled: 11	/25/15 08:10	Rec	eived: 12/0	1/15 8:00						
Gasoline range organics	<100	100	16	ug/L	1	B5L0228	12/02/15	12/02/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	103			80-150 %		"	"	"	"	
B-2a (1505312-03) Water Sampled: 1	1/25/15 08:4	0 Re	ceived: 12/	01/15 8:00						
Gasoline range organics	<100	100	16	ug/L	1	B5L0228	12/02/15	12/02/15	EPA 8015D	
Surrogate: 4-Fluorochlorobenzene	103			80-150 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312
Date Reported: 12/10/15

DISSOLVED METAL ANALYSIS Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4 (1505312-01) Water	Sampled: 11/25/15 07:4	0 Rece	eived: 12/01	/15 8:00						
Arsenic	<0.010	0.010	0.0026	mg/L	1	B5L0127	12/01/15	12/03/15	EPA 6010C (Dissolved)	
Barium	0.15	0.020	0.0022	mg/L	1	"	"	"	"	
Cadmium	<0.0010	0.0010	0.000059	mg/L	1	"	"	"	"	
Chromium	<0.010	0.010	0.0012	mg/L	1	"	"	"	"	
Lead	<0.0050	0.0050	0.0012	mg/L	1	"	"	u u	"	
Mercury	<0.010	0.010	0.0023	mg/L	1	"	"	u u	"	
Selenium	<0.030	0.030	0.0073	mg/L	1	"	"	u u	"	
Silver	<0.0050	0.0050	0.00053	mg/L	1	"	"	"	"	
B-D (1505312-02) Water	Sampled: 11/25/15 08:	I0 Rec	eived: 12/01	/15 8:00						
Arsenic	<0.010	0.010	0.0026	mg/L	1	B5L0127	12/01/15	12/03/15	EPA 6010C (Dissolved)	
Barium	0.097	0.020	0.0022	mg/L	1	"	II .	u u	"	
Cadmium	<0.0010	0.0010	0.000059	mg/L	1	"	II .	II .	"	
Chromium	<0.010	0.010	0.0012	mg/L	1	"	II .	II .	"	
Lead	0.0068	0.0050	0.0012	mg/L	1	"	"	u u	"	
Mercury	<0.010	0.010	0.0023	mg/L	1	"	"	u u	"	
Selenium	<0.030	0.030	0.0073	mg/L	1	"	II .	u u	"	
Silver	<0.0050	0.0050	0.00053	mg/L	1	"	II .	II .	II .	
B-2a (1505312-03) Water	r Sampled: 11/25/15 08:	40 Re	ceived: 12/0	1/15 8:00						
Arsenic	<0.010	0.010	0.0026	mg/L	1	B5L0127	12/01/15	12/03/15	EPA 6010C (Dissolved)	
Barium	0.087	0.020	0.0022	mg/L	1	"	II .	II .	"	
Cadmium	<0.0010	0.0010	0.000059	mg/L	1	"	"	"	"	
Chromium	<0.010	0.010	0.0012	mg/L	1	"	"	"	"	
Lead	0.012	0.0050	0.0012	mg/L	1	"	II .	"	"	
Mercury	<0.010	0.010	0.0023	mg/L	1	"	"	"	"	
Selenium	<0.030	0.030	0.0073	mg/L	1	"	"	"	"	
Silver	<0.0050	0.0050	0.00053	mg/L	1	"	II .	II .	"	

Fax: 651-642-1239

Work Order #: 1505312

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4 (1505312-01) Water Sampled: 1	1/25/15 07:40	Rece	ived: 12/01	1/15 8:00						
1,2,4-Trichlorobenzene	<10	10	0.53	ug/L	1	B5L0201	12/02/15	12/03/15	EPA 8270D	
1,2-Dichlorobenzene	<10	10	0.47	ug/L	1	"	"	"	"	
1,2-Diphenylhydrazine as Azobenzene	<10	10	0.32	ug/L	1	"	"	II .	"	
1,3-Dichlorobenzene	<10	10	0.43	ug/L	1	"	"	"	"	
1,4-Dichlorobenzene	<10	10	0.32	ug/L	1	"	"	"	"	
2,3,4,6-Tetrachlorophenol	<10	10	0.74	ug/L	1	"	"	"	"	
2,4,5-Trichlorophenol	<10	10	1.1	ug/L	1	"	II .	II .	"	
2,4,6-Trichlorophenol	<10	10	0.82	ug/L	1	"	"	"	"	
2,4-Dichlorophenol	<10	10	0.78	ug/L	1	"	"	"	"	
2,4-Dimethylphenol	<10	10	0.99	ug/L	1	"	II .	II .	"	
2,4-Dinitrophenol	<10	10	0.70	ug/L	1	"	"	"	"	
2,4-Dinitrotoluene	<10	10	0.44	ug/L	1	"	"	"	"	
2,6-Dichlorophenol	<10	10	0.93	ug/L	1	"	II .	II .	"	
2,6-Dinitrotoluene	<10	10	0.39	ug/L	1	"	"	u u	"	
2-Chloronaphthalene	<10	10	0.38	ug/L	1	"	"	II .	"	
2-Chlorophenol	<10	10	1.2	ug/L	1	"	II .	II .	"	
2-Methylnaphthalene	<10	10	0.70	ug/L	1	"	II .	II .	"	
2-Methylphenol	<10	10	1.4	ug/L	1	"	"	II .	"	
2-Nitroaniline	<10	10	0.83	ug/L	1	"	II .	II .	"	
2-Nitrophenol	<10	10	0.86	ug/L	1	"	"	"	"	
3&4-Methylphenol	<10	10	1.5	ug/L	1	"	"	"	"	
3,3´-Dichlorobenzidine	<25	25	9.9	ug/L	1	"	"	"	"	
3-Nitroaniline	<10	10	2.0	ug/L	1	"	"	"	"	
4,6-Dinitro-2-methylphenol	<10	10	1.0	ug/L	1	"	"	"	•	
4-Bromophenyl phenyl ether	<10	10	0.34	ug/L	1	"	"	"	"	
4-Chloro-3-methylphenol	<10	10	0.68	ug/L	1	"	"	"	"	
4-Chloroaniline	<10	10	2.3	ug/L	1	"	"	"	"	
4-Chlorophenyl phenyl ether	<10	10	0.45	ug/L	1	"	"	"	•	
4-Nitroaniline	<10	10	1.2	ug/L	1	"	"	"	"	
4-Nitrophenol	<10	10	0.91	ug/L	1	"	"	"	"	
Acenaphthene	<10	10	0.41	ug/L	1	"	"	"	"	
Acenaphthylene	<10	10	0.38	ug/L	1	"	n .	n .	"	
Aniline	<10	10	1.3	ug/L	1	"	n .	n .	"	
Anthracene	<10	10	0.36	ug/L	1	"	n .	n .	"	
Benzidine	<100	100	8.2	ug/L	1	"	n .	n .	"	
Benzo(a)anthracene	<10	10	0.23	ug/L	1	"	n .	n .	"	
Benzo(a)pyrene	<10	10	0.34	ug/L	1	"	n .	n .	"	
Benzo(b)fluoranthene	<10	10	0.18	ug/L	1	"	n .	n .	"	
Benzo(g,h,i)perylene	<10	10	0.43	ug/L	1	"	n .	n .	"	



Fax: 651-642-1239

Work Order #: 1505312

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Ms. Andrea Nord Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4 (1505312-01) Water	Sampled: 11/25/15 07:40	Rec	eived: 12/0	1/15 8:00						
Benzo(k)fluoranthene	<10	10	0.55	ug/L	1	B5L0201	12/02/15	12/03/15	EPA 8270D	
Benzoic acid	<10	10	1.8	ug/L	1	"	"	II .	"	
Benzyl alcohol	<10	10	0.68	ug/L	1	"	"	II .	"	
Bis(2-chloroethoxy)methane	<10	10	0.41	ug/L	1	"	"	II .	"	
Bis(2-chloroethyl)ether	<10	10	0.59	ug/L	1	"	"	II .	"	
Bis(2-chloroisopropyl)ether	<10	10	0.47	ug/L	1	"	"	II .	"	
Bis(2-ethylhexyl)phthalate	<10	10	0.77	ug/L	1	"	"	"	"	
Butyl benzyl phthalate	<10	10	0.67	ug/L	1	"	"	"	"	
Carbazole	<10	10	0.42	ug/L	1	"	"	"	"	
Chrysene	<10	10	0.34	ug/L	1	"	"	"	"	
Dibenz(a,h)anthracene	<10	10	0.31	ug/L	1	"	"	"	"	
Dibenzofuran	<10	10	0.77	ug/L	1	"	"	"	"	
Diethyl phthalate	<10	10	0.42	ug/L	1	"	"	"	"	
Dimethyl phthalate	<10	10	0.44	ug/L	1	"	"	"		
Di-n-butyl phthalate	<10	10	0.42	ug/L	1	"	"	"		
Di-n-octyl phthalate	<10	10	0.48	ug/L	1	"	"	"		
Fluoranthene	<10	10	0.36	ug/L	1	"	"	"		
Fluorene	<10	10	0.35	ug/L	1	"	"	"		
Hexachlorobenzene	<10	10	0.30	ug/L	1	"	"	"		
Hexachlorobutadiene	<10	10	0.37	ug/L	1	"	"	"		
Hexachlorocyclopentadiene	<10	10	0.52	ug/L	1	"	"	"	"	
Hexachloroethane	<10	10	0.61	ug/L	1	"	"	"		
Indeno (1,2,3-cd) pyrene	<10	10	0.37	ug/L	1	"	"	"		
Isophorone	<10	10	0.45	ug/L	1	"	"	"		
Naphthalene	<10	10	0.33	ug/L	1	"	"	"	"	
Nitrobenzene	<10	10	0.51	ug/L	1	"	"	"		
N-Nitrosodimethylamine	<10	10	0.34	ug/L	1	"	"	"		
N-Nitrosodi-n-propylamine	<10	10	0.47	ug/L	1	"	"	"		
N-Nitrosodiphenylamine	<10	10	0.54	ug/L	1	"	"	"	"	
Pentachlorophenol	<10	10	1.2	ug/L	1	"	"	"	"	
Phenanthrene	<10	10	0.28	ug/L	1	"	"			
Phenol	<10	10	1.2	ug/L	1	"	"	"	"	
Pyrene	<10	10	0.49	ug/L	1	"	"	"	"	
Surrogate: 2,4,6-Tribromophe				30-122 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	78.1			39.2-104 %		"	"	"	"	
Surrogate: 2-Fluorophenol	48.1			30-80.1 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	76.1			51.2-103 %		"	"	"	"	
Surrogate: Phenol-d6	44.3			30-75.3 %		"	"	"	"	
Surrogate: Terphenyl-d14	82.4			30-116 %		"	"	"	"	

Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-D (1505312-02) Water Sampled:	11/25/15 08:1	0 Rece	ived: 12/01/	′15 8:00						
1,2,4-Trichlorobenzene	<9.4	9.4	0.50	ug/L	1	B5L0201	12/02/15	12/03/15	EPA 8270D	
,2-Dichlorobenzene	<9.4	9.4	0.44	ug/L	1	"	"	"	"	
,2-Diphenylhydrazine as Azobenzene	<9.4	9.4	0.30	ug/L	1	"	"	"	"	
,3-Dichlorobenzene	<9.4	9.4	0.41	ug/L	1	"	"	"	"	
1,4-Dichlorobenzene	<9.4	9.4	0.30	ug/L	1	"	"	"	"	
2,3,4,6-Tetrachlorophenol	<9.4	9.4	0.70	ug/L	1	"	"	"	"	
2,4,5-Trichlorophenol	<9.4	9.4	1.0	ug/L	1	"	"	"	"	
2,4,6-Trichlorophenol	<9.4	9.4	0.77	ug/L	1	"	"	"	"	
2,4-Dichlorophenol	<9.4	9.4	0.74	ug/L	1	"	"	"	"	
2,4-Dimethylphenol	<9.4	9.4	0.93	ug/L	1	"	"	"	"	
2,4-Dinitrophenol	<9.4	9.4	0.66	ug/L	1	"	"	"	"	
2,4-Dinitrotoluene	<9.4	9.4	0.42	ug/L	1	"	"	"	"	
2,6-Dichlorophenol	<9.4	9.4	0.88	ug/L	1	"	"	"	"	
2,6-Dinitrotoluene	<9.4	9.4	0.37	ug/L	1	"	"	"	"	
2-Chloronaphthalene	<9.4	9.4	0.36	ug/L	1	"	"	"	"	
2-Chlorophenol	<9.4	9.4	1.1	ug/L	1	"	"	"	"	
2-Methylnaphthalene	<9.4	9.4	0.66	ug/L	1	"	"	"	"	
2-Methylphenol	<9.4	9.4	1.3	ug/L	1	"	"	"	"	
2-Nitroaniline	<9.4	9.4	0.78	ug/L	1	"	"	"	"	
2-Nitrophenol	<9.4	9.4	0.81	ug/L	1	"	"	"	"	
8&4-Methylphenol	<9.4	9.4	1.4	ug/L	1	"	"	"	"	
3,3'-Dichlorobenzidine	<24	24	9.3	ug/L	1	"	"	"	"	
3-Nitroaniline	<9.4	9.4	1.9	ug/L	1	"	"	"	"	
4,6-Dinitro-2-methylphenol	<9.4	9.4	0.94	ug/L	1	"	"	"	"	
1-Bromophenyl phenyl ether	<9.4	9.4	0.32	ug/L	1	"	"	"	"	
1-Chloro-3-methylphenol	<9.4	9.4	0.64	ug/L	1	"	"	"	"	
1-Chloroaniline	<9.4	9.4	2.2	ug/L	1	"	"	"	"	
1-Chlorophenyl phenyl ether	<9.4	9.4	0.42	ug/L	1	"	"	"	"	
1-Nitroaniline	<9.4	9.4	1.1	ug/L	1	"	"	"	"	
1-Nitrophenol	<9.4	9.4	0.86	ug/L	1	"	"	"	"	
Acenaphthene	<9.4	9.4	0.39	ug/L	1	"			"	
Acenaphthylene	<9.4	9.4	0.36	ug/L	1	"			"	
Aniline	<9.4	9.4	1.2	ug/L	1	"			"	
Anthracene	<9.4	9.4	0.34	ug/L	1	"			"	
Benzidine	<94	94	7.7	ug/L	1	"	"	"	"	
Benzo(a)anthracene	<9.4	9.4	0.22	ug/L	1	"	"	"	"	
Benzo(a)pyrene	<9.4	9.4	0.32	ug/L	1	"	"	"		
Benzo(b)fluoranthene	<9.4	9.4	0.32	ug/L ug/L	1	"	"	"		
Benzo(g,h,i)perylene	<9.4 <9.4	9.4	0.17	ug/L ug/L	1		_	_		



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-D (1505312-02) Water	Sampled: 11/25/15 08:1	0 Rec	eived: 12/01	/15 8:00						
Benzo(k)fluoranthene	<9.4	9.4	0.52	ug/L	1	B5L0201	12/02/15	12/03/15	EPA 8270D	
Benzoic acid	<9.4	9.4	1.7	ug/L	1	"	"	"	"	
Benzyl alcohol	<9.4	9.4	0.64	ug/L	1	"	"	"	"	
Bis(2-chloroethoxy)methane	<9.4	9.4	0.39	ug/L	1	"	n n	n n	"	
Bis(2-chloroethyl)ether	<9.4	9.4	0.56	ug/L	1	"	"	"	"	
Bis(2-chloroisopropyl)ether	<9.4	9.4	0.44	ug/L	1	"	II .	II .	"	
Bis(2-ethylhexyl)phthalate	<9.4	9.4	0.73	ug/L	1	"	u u	u u	"	
Butyl benzyl phthalate	<9.4	9.4	0.63	ug/L	1	"	II .	II .	"	
Carbazole	<9.4	9.4	0.40	ug/L	1	"	n n	n n	"	
Chrysene	<9.4	9.4	0.32	ug/L	1	"	"	"	"	
Dibenz(a,h)anthracene	<9.4	9.4	0.29	ug/L	1	"	"	"	"	
Dibenzofuran	<9.4	9.4	0.73	ug/L	1	"	"	"	"	
Diethyl phthalate	<9.4	9.4	0.40	ug/L	1	"	n n	n n	"	
Dimethyl phthalate	<9.4	9.4	0.42	ug/L	1	"	"	"	"	
Di-n-butyl phthalate	<9.4	9.4	0.40	ug/L	1	"	"	"	"	
Di-n-octyl phthalate	<9.4	9.4	0.45	ug/L	1	"	"	"	"	
Fluoranthene	<9.4	9.4	0.34	ug/L	1	"	"	"	"	
Fluorene	<9.4	9.4	0.33	ug/L	1	"	"	"	"	
Hexachlorobenzene	<9.4	9.4	0.28	ug/L	1	"	"	"	"	
Hexachlorobutadiene	<9.4	9.4	0.35	ug/L	1	"	"	"	"	
Hexachlorocyclopentadiene	<9.4	9.4	0.49	ug/L	1	"	"	"	"	
Hexachloroethane	<9.4	9.4	0.58	ug/L	1	"	"	"	"	
Indeno (1,2,3-cd) pyrene	<9.4	9.4	0.35	ug/L	1	"	"	"	"	
Isophorone	<9.4	9.4	0.42	ug/L	1	"	"	"	"	
Naphthalene	<9.4	9.4	0.31	ug/L	1	"	"	"	"	
Nitrobenzene	<9.4	9.4	0.48	ug/L	1	"	"	"	"	
N-Nitrosodimethylamine	<9.4	9.4	0.32	ug/L	1	"	"	"	"	
N-Nitrosodi-n-propylamine	<9.4	9.4	0.44	ug/L	1	"	"	"	"	
N-Nitrosodiphenylamine	<9.4	9.4	0.51	ug/L	1	"	"	"		
Pentachlorophenol	<9.4	9.4	1.1	ug/L	1	"	"	"	"	
Phenanthrene	<9.4	9.4	0.26	ug/L	1	"	"	"	"	
Phenol	<9.4	9.4	1.1	ug/L	1	"	"	"		
Pyrene	<9.4	9.4	0.46	ug/L	1	"	"	"	"	
。 Surrogate: 2,4,6-Tribromophe				30-122 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	65.5			39.2-104 %		"	"	"	"	
Surrogate: 2-Fluorophenol	36.4			30-80.1 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	68.1		,	51.2-103 %		"	"	"	"	
Surrogate: Phenol-d6	34.3			30-75.3 %		"	"	"	"	
Surrogate: Terphenyl-d14	52.2			30-116 %		"	"	"	"	

Fax: 651-642-1239

Work Order #: 1505312

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

B-2a (1505312-03) Water Sampled:			MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
•	11/25/15 08:4	40 Re	ceived: 12/0	1/15 8:00						
1,2,4-Trichlorobenzene	<9.3	9.3	0.50	ug/L	1	B5L0201	12/02/15	12/03/15	EPA 8270D	
1,2-Dichlorobenzene	<9.3	9.3	0.44	ug/L	1	"	"	"	"	
1,2-Diphenylhydrazine as Azobenzene	<9.3	9.3	0.30	ug/L	1	"	"	"	"	
1,3-Dichlorobenzene	<9.3	9.3	0.40	ug/L	1	"	"	"	"	
1,4-Dichlorobenzene	<9.3	9.3	0.30	ug/L	1	"	"	"	"	
2,3,4,6-Tetrachlorophenol	<9.3	9.3	0.69	ug/L	1	"	"	"	"	
2,4,5-Trichlorophenol	<9.3	9.3	1.0	ug/L	1	"	"	"	"	
2,4,6-Trichlorophenol	<9.3	9.3	0.77	ug/L	1	"	"	"	"	
2,4-Dichlorophenol	<9.3	9.3	0.73	ug/L	1	"	"	"	"	
2,4-Dimethylphenol	<9.3	9.3	0.93	ug/L	1	"	"	"	"	
2,4-Dinitrophenol	<9.3	9.3	0.65	ug/L	1	"	"	"	"	
2,4-Dinitrotoluene	<9.3	9.3	0.41	ug/L	1	"	"	"	"	
2,6-Dichlorophenol	<9.3	9.3	0.87	ug/L	1	"	"	"	"	
2,6-Dinitrotoluene	<9.3	9.3	0.36	ug/L	1	"	"	"	"	
2-Chloronaphthalene	<9.3	9.3	0.36	ug/L	1	"	"	"	"	
2-Chlorophenol	<9.3	9.3	1.1	ug/L	1	"	"	"	"	
2-Methylnaphthalene	<9.3	9.3	0.65	ug/L	1	"	"	"	"	
2-Methylphenol	<9.3	9.3	1.3	ug/L	1	"	"	"	"	
2-Nitroaniline	<9.3	9.3	0.78	ug/L	1	"	"	"	"	
2-Nitrophenol	<9.3	9.3	0.80	ug/L	1	"	"	"	"	
3&4-Methylphenol	<9.3	9.3	1.4	ug/L	1	"	"	"	"	
3,3´-Dichlorobenzidine	<23	23	9.3	ug/L	1	"	"	"	"	
3-Nitroaniline	<9.3	9.3	1.9	ug/L	1	"	"	"	"	
4,6-Dinitro-2-methylphenol	<9.3	9.3	0.93	ug/L	1	"	"	"	"	
4-Bromophenyl phenyl ether	<9.3	9.3	0.32	ug/L	1	"	"	"	"	
4-Chloro-3-methylphenol	<9.3	9.3	0.64	ug/L	1	"	"	"	"	
4-Chloroaniline	<9.3	9.3	2.1	ug/L	1	"	"	"	"	
4-Chlorophenyl phenyl ether	<9.3	9.3	0.42	ug/L	1	"	"	"	"	
4-Nitroaniline	<9.3	9.3	1.1	ug/L	1	"	"	"	"	
4-Nitrophenol	<9.3	9.3	0.85	ug/L	1	"	"	"	"	
Acenaphthene	<9.3	9.3	0.38	ug/L	1	"	"	"	"	
Acenaphthylene	<9.3	9.3	0.36	ug/L	1	"	"	"	"	
Aniline	<9.3	9.3	1.2	ug/L	1	"	"	"	"	
Anthracene	<9.3	9.3	0.34	ug/L	1	"	"	"	"	
Benzidine	<93	93	7.7	ug/L	1	"	"	"	"	
Benzo(a)anthracene	<9.3	9.3	0.21	ug/L	1	"	"	"	"	
Benzo(a)pyrene	<9.3	9.3	0.32	ug/L	1	"	· ·	"	"	
Benzo(b)fluoranthene	<9.3	9.3	0.17	ug/L	1	"	· ·	"	"	
Benzo(g,h,i)perylene	<9.3	9.3	0.40	ug/L	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-2a (1505312-03) Water	Sampled: 11/25/15 08:4	0 R	eceived: 12/0	1/15 8:00						
Benzo(k)fluoranthene	<9.3	9.3	0.51	ug/L	1	B5L0201	12/02/15	12/03/15	EPA 8270D	
Benzoic acid	<9.3	9.3	1.7	ug/L	1	"	"	"	"	
Benzyl alcohol	<9.3	9.3	0.64	ug/L	1	"	"	"	"	
Bis(2-chloroethoxy)methane	<9.3	9.3	0.38	ug/L	1	"	"	"	"	
Bis(2-chloroethyl)ether	<9.3	9.3	0.55	ug/L	1	"	"	"	"	
Bis(2-chloroisopropyl)ether	<9.3	9.3	0.44	ug/L	1	"	"	"	"	
Bis(2-ethylhexyl)phthalate	<9.3	9.3	0.72	ug/L	1	"	"	"	"	
Butyl benzyl phthalate	<9.3	9.3	0.63	ug/L	1	"	"	"	"	
Carbazole	<9.3	9.3	0.39	ug/L	1	"	"	"	"	
Chrysene	<9.3	9.3	0.32	ug/L	1	"	"	"	"	
Dibenz(a,h)anthracene	<9.3	9.3	0.29	ug/L	1	"	"	"	"	
Dibenzofuran	<9.3	9.3	0.72	ug/L	1	"	"	"	"	
Diethyl phthalate	<9.3	9.3	0.39	ug/L	1	"	"	"	"	
Dimethyl phthalate	<9.3	9.3	0.41	ug/L	1	"	"	"	"	
Di-n-butyl phthalate	<9.3	9.3	0.39	ug/L	1	"	"	"	"	
Di-n-octyl phthalate	<9.3	9.3	0.45	ug/L	1	"	"	"	"	
Fluoranthene	<9.3	9.3	0.34	ug/L	1	"	"	"	"	
Fluorene	<9.3	9.3	0.33	ug/L	1	"	"	"	"	
Hexachlorobenzene	<9.3	9.3	0.28	ug/L	1	"	"	"	"	
Hexachlorobutadiene	<9.3	9.3	0.35	ug/L	1	"	"	"	"	
Hexachlorocyclopentadiene	<9.3	9.3	0.49	ug/L	1	"	"	"	"	
Hexachloroethane	<9.3	9.3	0.57	ug/L	1	"	"	"	"	
Indeno (1,2,3-cd) pyrene	<9.3	9.3	0.35	ug/L	1	"	"	"	"	
Isophorone	<9.3	9.3	0.42	ug/L	1	"	"	"	"	
Naphthalene	<9.3	9.3	0.31	ug/L	1	"	"	"	"	
Nitrobenzene	<9.3	9.3	0.48	ug/L	1	"	"	"	"	
N-Nitrosodimethylamine	<9.3	9.3	0.32	ug/L	1	"	"	"	"	
N-Nitrosodi-n-propylamine	<9.3	9.3	0.44	ug/L	1	"	"	"	"	
N-Nitrosodiphenylamine	<9.3	9.3	0.50	ug/L	1	"	"	"	"	
Pentachlorophenol	<9.3	9.3	1.1	ug/L	1	"	"	"	"	
Phenanthrene	<9.3	9.3	0.26	ug/L	1	"	"	"	"	
Phenol	<9.3	9.3	1.1	ug/L	1	"	"	"	"	
Pyrene	<9.3	9.3	0.46	ug/L	1	"	"	"	"	
Surrogate: 2,4,6-Tribromophen	nol 33.5			30-122 %		"	"	"	"	
Surrogate: 2-Fluorobiphenyl	55.6			39.2-104 %		"	"	"	"	
Surrogate: 2-Fluorophenol	30.8			30-80.1 %		"	"	"	"	
Surrogate: Nitrobenzene-d5	62.3			51.2-103 %		"	"	" "	"	0.55
Surrogate: Phenol-d6 Surrogate: Terphenyl-d14	29.0 43.2			30-75.3 %		"	"	"	"	S-GC
зинодате. тегрпенут-ит4	43.2			30-116 %		-				



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4 (1505312-01) Water	Sampled: 11/25/15 07:40	Rec	eived: 12/01	1/15 8:00						
1,1,1,2-Tetrachloroethane	<1.0	1.0	0.024	ug/L	1	B5L0814	12/04/15	12/04/15	EPA 8260B	
1,1,1-Trichloroethane	<1.0	1.0	0.069	ug/L	1	"	"	"	"	
1,1,2,2-Tetrachloroethane	<1.0	1.0	0.051	ug/L	1	"	"	"	"	
1,1,2-Trichloroethane	<1.0	1.0	0.10	ug/L	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<1.0	1.0	0.081	ug/L	1	"	"	"	"	T5
1,1-Dichloroethane	<1.0	1.0	0.050	ug/L	1	"	"	"	"	
1,1-Dichloroethene	<1.0	1.0	0.065	ug/L	1	"	"	"	"	
1,1-Dichloropropene	<1.0	1.0	0.15	ug/L	1	"	"	"	"	
1,2,3-Trichlorobenzene	<5.0	5.0	0.45	ug/L	1	"	"	"	"	
1,2,3-Trichloropropane	<2.5	2.5	0.056	ug/L	1	"	"	"	"	
1,2,4-Trichlorobenzene	<5.0	5.0	0.091	ug/L	1	"	"	"	"	
1,2,4-Trimethylbenzene	<1.0	1.0	0.054	ug/L	1	"	"	"	"	
1,2-Dibromo-3-chloropropane	<5.0	5.0	0.033	ug/L	1	"	"	"	"	
1,2-Dibromoethane (EDB)	<2.5	2.5	0.042	ug/L	1	"	"	"	"	
1,2-Dichlorobenzene	<1.0	1.0	0.052	ug/L	1	"	"	"	"	
1,2-Dichloroethane	<1.0	1.0	0.064	ug/L	1	"	"	"	"	
1,2-Dichloropropane	<1.0	1.0	0.034	ug/L	1	"	"	"	"	
1,3,5-Trimethylbenzene	<1.0	1.0	0.046	ug/L	1	"	"	"	"	
1,3-Dichlorobenzene	<1.0	1.0	0.068	ug/L	1	"	"	"	"	
1,3-Dichloropropane	<1.0	1.0	0.15	ug/L	1	"	"	"	"	
1,4-Dichlorobenzene	<1.0	1.0	0.047	ug/L	1	"	"	"	"	
2,2-Dichloropropane	<5.0	5.0	0.28	ug/L	1	"	"	"	"	
2-Butanone	<20	20	0.33	ug/L	1	"	"	"	"	
2-Chlorotoluene	<1.0	1.0	0.052	ug/L	1	"	"	"	"	
4-Chlorotoluene	<1.0	1.0	0.041	ug/L	1	"	"	"	"	
Acetone	<20	20	0.32	ug/L	1	"	"	"	"	
Allyl chloride	<5.0	5.0	0.078	ug/L	1	"	"	"	"	
Benzene	<1.0	1.0	0.034	ug/L	1	"	"	"	"	
Bromobenzene	<1.0	1.0	0.042	ug/L	1	"	"	"	"	
Bromochloromethane	<1.0	1.0	0.10	ug/L	1	"	"	"	"	
Bromodichloromethane	<1.0	1.0	0.042	ug/L	1	"	"	"	"	
Bromoform	<5.0	5.0	0.080	ug/L	1	"	"	"	"	
Bromomethane	<5.0	5.0	0.17	ug/L	1	"	"	"	"	
Carbon tetrachloride	<1.0	1.0	0.029	ug/L	1	"	"	"	"	
Chlorobenzene	<1.0	1.0	0.037	ug/L	1	"	"	"	"	
Chloroethane	<2.5	2.5	0.062	ug/L	1	"	"	"	"	
Chloroform	<1.0	1.0	0.056	ug/L	1	"	"	"	"	
Chloromethane	<2.5	2.5	0.062	ug/L	1	"	"	"	"	
cis-1,2-Dichloroethene	<1.0	1.0	0.097	ug/L	1		"	"	"	

Fax: 651-642-1239

Work Order #: 1505312

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Ager: Ms. Andrea Nord Date Reported: 12/10/15 VOC 8260B

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-4 (1505312-01) Water S	Sampled: 11/25/15 07:40	Rec	eived: 12/0	1/15 8:00		_	_			_
cis-1,3-Dichloropropene	<1.0	1.0	0.041	ug/L	1	B5L0814	12/04/15	12/04/15	EPA 8260B	
Dibromochloromethane	<2.5	2.5	0.070	ug/L	1	"	"	"	п	
Dibromomethane	<2.5	2.5	0.088	ug/L	1	"	"	"	п	
Dichlorodifluoromethane	<5.0	5.0	0.14	ug/L	1	"	"	"	п	
Dichlorofluoromethane	<1.0	1.0	0.059	ug/L	1	"	"	"	п	T5
Ethyl ether	<5.0	5.0	0.091	ug/L	1	"	"	"	п	
Ethylbenzene	<1.0	1.0	0.033	ug/L	1	"	"	"	п	
Hexachlorobutadiene	<10	10	0.19	ug/L	1	"	"	"	п	
Isopropylbenzene	<1.0	1.0	0.037	ug/L	1	"	ıı .	"	п	
m,p-Xylene	<2.0	2.0	0.087	ug/L	1	"	"	"	п	
Methyl isobutyl ketone	<5.0	5.0	0.17	ug/L	1	"	"	"	п	
Methyl tert-butyl ether	<1.0	1.0	0.056	ug/L	1	"	II .	"	п	
Methylene chloride	<5.0	5.0	0.10	ug/L	1	"	ıı .	"	п	
Naphthalene	<5.0	5.0	0.032	ug/L	1	"	"	"	п	
n-Butylbenzene	<2.5	2.5	0.028	ug/L	1	"	ıı .	"	п	
n-Propylbenzene	<1.0	1.0	0.040	ug/L	1	"	"	n .	II .	
o-Xylene	<1.0	1.0	0.053	ug/L	1	"	"	"	"	
p-Isopropyltoluene	<2.5	2.5	0.052	ug/L	1	"	"	"	п	
sec-Butylbenzene	<1.0	1.0	0.055	ug/L	1	"	"	n .	II .	
Styrene	<1.0	1.0	0.048	ug/L	1	"	"	n .	II .	
tert-Butylbenzene	<1.0	1.0	0.028	ug/L	1	"	ıı .	"	п	
Tetrachloroethene	<1.0	1.0	0.035	ug/L	1	"	"	n .	II .	
Tetrahydrofuran	<20	20	0.34	ug/L	1	"	ıı .	"	п	T5
Toluene	<1.0	1.0	0.064	ug/L	1	"	"	"	"	
trans-1,2-Dichloroethene	<1.0	1.0	0.058	ug/L	1	"	"	"	п	
trans-1,3-Dichloropropene	<1.0	1.0	0.067	ug/L	1	"	"	n .	II .	
Trichloroethene	<1.0	1.0	0.096	ug/L	1	"	ıı .	"	п	
Trichlorofluoromethane	<1.0	1.0	0.26	ug/L	1	"	"	"	"	
Vinyl chloride	<1.0	1.0	0.046	ug/L	1	"	"	n .	II .	
Surrogate: 4-Bromofluorobenze	ene 88.0			80-121 %		"	"	"	"	
Surrogate: Dibromofluorometha	ane 93.8			79.9-121 %		"	"	"	"	
Surrogate: Toluene-d8	93.1			80-120 %		"	"	"	"	
B-D (1505312-02) Water	Sampled: 11/25/15 08:10	Red	ceived: 12/0	1/15 8:00						
1,1,1,2-Tetrachloroethane	<1.0	1.0	0.024	ug/L	1	B5L0814	12/04/15	12/04/15	EPA 8260B	
1,1,1-Trichloroethane	<1.0	1.0	0.069	ug/L	1	"	"	"	"	
1,1,2,2-Tetrachloroethane	<1.0	1.0	0.051	ug/L	1	"	"	"	u u	
1,1,2-Trichloroethane	<1.0	1.0	0.10	ug/L	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<1.0	1.0	0.081	ug/L	1	"	"	n .	II .	T5
1,1-Dichloroethane	<1.0	1.0	0.050	ug/L	1	"	"	"	"	

Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-D (1505312-02) Water	Sampled: 11/25/15 08:1	0 Rec	eived: 12/0	1/15 8:00						
1,1-Dichloroethene	<1.0	1.0	0.065	ug/L	1	B5L0814	12/04/15	12/04/15	EPA 8260B	
1,1-Dichloropropene	<1.0	1.0	0.15	ug/L	1	"	"	"	"	
1,2,3-Trichlorobenzene	<5.0	5.0	0.45	ug/L	1		"	"	"	
1,2,3-Trichloropropane	<2.5	2.5	0.056	ug/L	1	"	"	"	"	
,2,4-Trichlorobenzene	<5.0	5.0	0.091	ug/L	1	"	u u	"	II .	
,2,4-Trimethylbenzene	<1.0	1.0	0.054	ug/L	1	"	· ·	"	II .	
,2-Dibromo-3-chloropropane	<5.0	5.0	0.033	ug/L	1		"	"	"	
,2-Dibromoethane (EDB)	<2.5	2.5	0.042	ug/L	1	"	u u	"	II .	
1,2-Dichlorobenzene	<1.0	1.0	0.052	ug/L	1	"	u u	"	II .	
,2-Dichloroethane	<1.0	1.0	0.064	ug/L	1	"	"	"	"	
,2-Dichloropropane	<1.0	1.0	0.034	ug/L	1	"	"	"	"	
1,3,5-Trimethylbenzene	<1.0	1.0	0.046	ug/L	1	"	n .	"	"	
1,3-Dichlorobenzene	<1.0	1.0	0.068	ug/L	1	"	"	"	"	
,3-Dichloropropane	<1.0	1.0	0.15	ug/L	1	"	· ·	"	II .	
,4-Dichlorobenzene	<1.0	1.0	0.047	ug/L	1	"	· ·	"	II .	
2,2-Dichloropropane	<5.0	5.0	0.28	ug/L	1	"	"	"	"	
-Butanone	<20	20	0.33	ug/L	1	"	"	"	"	
2-Chlorotoluene	<1.0	1.0	0.052	ug/L	1	"	· ·	"	II .	
-Chlorotoluene	<1.0	1.0	0.041	ug/L	1	"	· ·	"	II .	
Acetone	<20	20	0.32	ug/L	1	"	"	"	"	
Allyl chloride	<5.0	5.0	0.078	ug/L	1	"	· ·	"	II .	
Benzene	<1.0	1.0	0.034	ug/L	1	"	"	"	"	
Bromobenzene	<1.0	1.0	0.042	ug/L	1	"	"	"	"	
Bromochloromethane	<1.0	1.0	0.10	ug/L	1	"	"	"	"	
Bromodichloromethane	<1.0	1.0	0.042	ug/L	1	"	"	"	"	
Bromoform	<5.0	5.0	0.080	ug/L	1	"	"	"	"	
Bromomethane	<5.0	5.0	0.17	ug/L	1	"	"	"	"	
Carbon tetrachloride	<1.0	1.0	0.029	ug/L	1	"	"	"	"	
Chlorobenzene	<1.0	1.0	0.037	ug/L	1	"	"	"	"	
Chloroethane	<2.5	2.5	0.062	ug/L	1	"	"	"	"	
Chloroform	<1.0	1.0	0.056	ug/L	1	"	"	"	"	
Chloromethane	<2.5	2.5	0.062	ug/L	1	"	"	"	"	
is-1,2-Dichloroethene	<1.0	1.0	0.097	ug/L	1	"	"	"	"	
is-1,3-Dichloropropene	<1.0	1.0	0.041	ug/L	1	"	"	"	"	
Dibromochloromethane	<2.5	2.5	0.070	ug/L	1	"	"	"	"	
Dibromomethane	<2.5	2.5	0.088	ug/L	1	"	"	"	"	
Dichlorodifluoromethane	<5.0	5.0	0.14	ug/L	1	"	"	"	"	
Dichlorofluoromethane	<1.0	1.0	0.059	ug/L	1	"	"	"	"	T5
Ethyl ether	<5.0	5.0	0.091	ug/L	1	"	"	"	"	

Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312 Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-D (1505312-02) Water Sample	d: 11/25/15 08:1	0 Rec	eived: 12/0	1/15 8:00						
Ethylbenzene	<1.0	1.0	0.033	ug/L	1	B5L0814	12/04/15	12/04/15	EPA 8260B	
Hexachlorobutadiene	<10	10	0.19	ug/L	1	"	"	"	"	
Isopropylbenzene	<1.0	1.0	0.037	ug/L	1	"	"	"	"	
m,p-Xylene	<2.0	2.0	0.087	ug/L	1	"	"	"	"	
Methyl isobutyl ketone	<5.0	5.0	0.17	ug/L	1	"	u u	u u	II .	
Methyl tert-butyl ether	<1.0	1.0	0.056	ug/L	1	"	· ·	u u	"	
Methylene chloride	<5.0	5.0	0.10	ug/L	1	"	"	"	"	
Naphthalene	<5.0	5.0	0.032	ug/L	1	"	· ·	u u	"	
n-Butylbenzene	<2.5	2.5	0.028	ug/L	1	"	"	"	"	
n-Propylbenzene	<1.0	1.0	0.040	ug/L	1	"	· ·	u u	"	
o-Xylene	<1.0	1.0	0.053	ug/L	1	n n	"	"	"	
p-lsopropyltoluene	<2.5	2.5	0.052	ug/L	1	"	· ·	u u	"	
sec-Butylbenzene	<1.0	1.0	0.055	ug/L	1	"	"	"	"	
Styrene	<1.0	1.0	0.048	ug/L	1	"	"	"	"	
tert-Butylbenzene	<1.0	1.0	0.028	ug/L	1	"	"	"	"	
Tetrachloroethene	<1.0	1.0	0.035	ug/L	1	"	"	"	"	
Tetrahydrofuran	<20	20	0.34	ug/L	1	"	"	"	"	T5
Toluene	1.0	1.0	0.064	ug/L	1	"	"	"	"	
trans-1,2-Dichloroethene	<1.0	1.0	0.058	ug/L	1	"	"	"	"	
trans-1,3-Dichloropropene	<1.0	1.0	0.067	ug/L	1	"	"	"	"	
Trichloroethene	<1.0	1.0	0.096	ug/L	1	"	"	"	"	
Trichlorofluoromethane	<1.0	1.0	0.26	ug/L	1	"	"	"	"	
Vinyl chloride	<1.0	1.0	0.046	ug/L	1	"	"	"	"	
Surrogate: 4-Bromofluorobenzene	89.0			80-121 %		"	"	"	"	
Surrogate: Dibromofluoromethane	91.0			79.9-121 %		"	"	"	"	
Surrogate: Toluene-d8	92.4			80-120 %		"	"	"	"	
B-2a (1505312-03) Water Sample	ed: 11/25/15 08:	lo Re	ceived: 12/0	01/15 8:00						
1,1,1,2-Tetrachloroethane	<1.0	1.0	0.024	ug/L	1	B5L0814	12/04/15	12/04/15	EPA 8260B	
1,1,1-Trichloroethane	<1.0	1.0	0.069	ug/L	1	"	"	"	"	
1,1,2,2-Tetrachloroethane	<1.0	1.0	0.051	ug/L	1	"	"	"	"	
1,1,2-Trichloroethane	<1.0	1.0	0.10	ug/L	1	"	"	"	"	
1,1,2-Trichlorotrifluoroethane	<1.0	1.0	0.081	ug/L	1	"	"	"	"	T5
1,1-Dichloroethane	<1.0	1.0	0.050	ug/L	1	"	"	"	"	
1,1-Dichloroethene	<1.0	1.0	0.065	ug/L	1	II .	· ·	"	"	
1,1-Dichloropropene	<1.0	1.0	0.15	ug/L	1	II .	· ·	"	"	
1,2,3-Trichlorobenzene	<5.0	5.0	0.45	ug/L	1	II .	· ·	"	"	
1,2,3-Trichloropropane	<2.5	2.5	0.056	ug/L	1	"	"	"	"	
1,2,4-Trichlorobenzene	<5.0	5.0	0.091	ug/L	1	"	"	"	"	
1,2,4-Trimethylbenzene	<1.0	1.0	0.054	ug/L	1	"	"	"	"	



Fax: 651-642-1239

Work Order #: 1505312

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
B-2a (1505312-03) Water	Sampled: 11/25/15 08:4	0 R	Received: 12/0	1/15 8:00						
1,2-Dibromo-3-chloropropane	<5.0	5.0	0.033	ug/L	1	B5L0814	12/04/15	12/04/15	EPA 8260B	
1,2-Dibromoethane (EDB)	<2.5	2.5	0.042	ug/L	1	"	"	u u	"	
1,2-Dichlorobenzene	<1.0	1.0	0.052	ug/L	1	"	"	II .	"	
1,2-Dichloroethane	<1.0	1.0	0.064	ug/L	1	"	"	"	"	
1,2-Dichloropropane	<1.0	1.0	0.034	ug/L	1	"	"	"	"	
1,3,5-Trimethylbenzene	<1.0	1.0	0.046	ug/L	1	"	"	"	"	
1,3-Dichlorobenzene	<1.0	1.0	0.068	ug/L	1	"	"	"	"	
1,3-Dichloropropane	<1.0	1.0	0.15	ug/L	1	"	"	"	"	
1,4-Dichlorobenzene	<1.0	1.0	0.047	ug/L	1	"	"	"	"	
2,2-Dichloropropane	<5.0	5.0	0.28	ug/L	1	"	"	"	"	
2-Butanone	<20	20	0.33	ug/L	1	"	"	"	"	
2-Chlorotoluene	<1.0	1.0	0.052	ug/L	1	"	"	"	"	
4-Chlorotoluene	<1.0	1.0	0.041	ug/L	1	"	"	"	"	
Acetone	<20	20	0.32	ug/L	1	"	"	"	"	
Allyl chloride	<5.0	5.0	0.078	ug/L	1	"	"	II .	"	
Benzene	<1.0	1.0	0.034	ug/L	1	"	"	"	"	
Bromobenzene	<1.0	1.0	0.042	ug/L	1	"	"	"	"	
Bromochloromethane	<1.0	1.0	0.10	ug/L	1	"	"	II .	"	
Bromodichloromethane	<1.0	1.0	0.042	ug/L	1	"	"	"	"	
Bromoform	<5.0	5.0	0.080	ug/L	1	"	"	"	"	
Bromomethane	<5.0	5.0	0.17	ug/L	1	"	"	II .	"	
Carbon tetrachloride	<1.0	1.0	0.029	ug/L	1	"	"	"	"	
Chlorobenzene	<1.0	1.0	0.037	ug/L	1	"	"	"	"	
Chloroethane	<2.5	2.5	0.062	ug/L	1	"	"	"	"	
Chloroform	<1.0	1.0	0.056	ug/L	1	"	"	"	"	
Chloromethane	<2.5	2.5	0.062	ug/L	1	"	"	"	"	
cis-1,2-Dichloroethene	<1.0	1.0	0.097	ug/L	1	"	"	"	"	
cis-1,3-Dichloropropene	<1.0	1.0	0.041	ug/L	1	"	"	"	"	
Dibromochloromethane	<2.5	2.5	0.070	ug/L	1	"	"	"	"	
Dibromomethane	<2.5	2.5	0.088	ug/L	1	"	"	"	"	
Dichlorodifluoromethane	<5.0	5.0	0.14	ug/L	1	"	"	"	"	
Dichlorofluoromethane	<1.0	1.0	0.059	ug/L	1	"	"	II .	"	T5
Ethyl ether	<5.0	5.0	0.091	ug/L	1	"	"	"	"	
Ethylbenzene	<1.0	1.0	0.033	ug/L	1	"	"	"	"	
Hexachlorobutadiene	<10	10	0.19	ug/L	1	"	"	"	"	
Isopropylbenzene	<1.0	1.0	0.037	ug/L	1	"	"	"	"	
m,p-Xylene	<2.0	2.0	0.087	ug/L	1	"	"	n .	"	
Methyl isobutyl ketone	<5.0	5.0	0.17	ug/L	1	"	"	n .	"	
Methyl tert-butyl ether	<1.0	1.0	0.056	ug/L	1	"	"	n .	"	

Fax: 651-642-1239

Work Order #:

Date Reported: 12/10/15

1505312

Barr Engineering Co. 34511010 Project: 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

VOC 8260B Legend Technical Services, Inc.

Analyte RL Units Dilution Prepared Method Notes Result Batch Analyzed B-2a (1505312-03) Water Sampled: 11/25/15 08:40 Received: 12/01/15 8:00 Methylene chloride <5.0 5.0 0.10 ug/L 1 B5L0814 12/04/15 12/04/15 **EPA 8260B** Naphthalene <5.0 5.0 0.032 ug/L 1 2.5 0.028 n-Butylbenzene <2.5 ug/L 1 <10 1.0 0.040 ug/L 1 n-Propylbenzene <1.0 1.0 0.053 ug/L 1 o-Xylene 2.5 p-Isopropyltoluene <2.5 0.052 ug/L 1 sec-Butylbenzene <1.0 1.0 0.055 ug/L <1.0 1.0 0.048 ug/L 1 Styrene tert-Butylbenzene <1.0 1.0 0.028 ug/L 1 1.0 1 Tetrachloroethene <1.0 0.035 ug/L 20 ug/L 1 T5 Tetrahydrofuran <20 0.34 1.0 ug/L 1 Toluene 1.1 0.064 trans-1,2-Dichloroethene <1.0 1.0 0.058 ug/L 1 trans-1,3-Dichloropropene <1.0 1.0 0.067 ug/L 1 Trichloroethene 1.0 0.096 ug/L 1 <1.0 Trichlorofluoromethane <1.0 1.0 0.26 ug/L 1 Vinyl chloride <1.0 1.0 0.046 ug/L Surrogate: 4-Bromofluorobenzene 89 1 80-121 % Surrogate: Dibromofluoromethane 93.3 79.9-121 % Surrogate: Toluene-d8 94.2 80-120 % Trip Blank (1505312-04) Water Sampled: 11/25/15 00:00 Received: 12/01/15 8:00 1,1,1,2-Tetrachloroethane <1.0 1.0 0.024 ug/L 1 B5L0814 12/04/15 12/04/15 EPA 8260B 1.0 1,1,1-Trichloroethane <1.0 0.069 ug/L 1 <1.0 1.0 0.051 ug/L 1 1,1,2,2-Tetrachloroethane 1 1 2-Trichloroethane <10 1.0 0.10 ug/L 1 1,1,2-Trichlorotrifluoroethane <1.0 1.0 0.081 ug/L 1 T5 1,1-Dichloroethane <1.0 1.0 0.050 ug/L 1 1,1-Dichloroethene <1.0 1.0 0.065 ug/L 1,1-Dichloropropene <1.0 1.0 0.15 ug/L 1 1,2,3-Trichlorobenzene <5.0 5.0 0.45 ug/L 1 2.5 0.056 ug/L 1,2,3-Trichloropropane <25 1 <5.0 5.0 ug/L 1 1,2,4-Trichlorobenzene 0.091 1,2,4-Trimethylbenzene <1.0 1.0 0.054 ug/L 1 <5.0 5.0 0.033 ug/L 1 1,2-Dibromo-3-chloropropane 1,2-Dibromoethane (EDB) <2.5 2.5 0.042 ug/L 1 1.0 0.052 ug/L 1 1,2-Dichlorobenzene <1.0 1,2-Dichloroethane <1.0 1.0 0.064 ug/L 1 1,2-Dichloropropane <1.0 1.0 0.034 ug/L 1 1,3,5-Trimethylbenzene <1.0 1.0 0.046 1 ug/L



Fax: 651-642-1239

Work Order #: 1505312

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
Trip Blank (1505312-04) Water	Sampled: 11/25/1	5 00:00	Received	d: 12/01/15	8:00					
1,3-Dichlorobenzene	<1.0	1.0	0.068	ug/L	1	B5L0814	12/04/15	12/04/15	EPA 8260B	
1,3-Dichloropropane	<1.0	1.0	0.15	ug/L	1	"	"	"	"	
1,4-Dichlorobenzene	<1.0	1.0	0.047	ug/L	1	"	"	n	"	
2,2-Dichloropropane	<5.0	5.0	0.28	ug/L	1	"	"	"	"	
2-Butanone	<20	20	0.33	ug/L	1	"	"	"	"	
2-Chlorotoluene	<1.0	1.0	0.052	ug/L	1	"	"	"	"	
4-Chlorotoluene	<1.0	1.0	0.041	ug/L	1	"	"	"	"	
Acetone	<20	20	0.32	ug/L	1	"	"	"	"	
Allyl chloride	<5.0	5.0	0.078	ug/L	1	"	"	"	"	
Benzene	<1.0	1.0	0.034	ug/L	1	"	"	"	"	
Bromobenzene	<1.0	1.0	0.042	ug/L	1	"	"	"	"	
Bromochloromethane	<1.0	1.0	0.10	ug/L	1	"	"	"	"	
Bromodichloromethane	<1.0	1.0	0.042	ug/L	1	"	"	u u	"	
Bromoform	<5.0	5.0	0.080	ug/L	1	"	"	"	"	
Bromomethane	<5.0	5.0	0.17	ug/L	1	"	"	u u	"	
Carbon tetrachloride	<1.0	1.0	0.029	ug/L	1	"	"	u u	"	
Chlorobenzene	<1.0	1.0	0.037	ug/L	1	"	"	"	"	
Chloroethane	<2.5	2.5	0.062	ug/L	1	"	"	"	"	
Chloroform	<1.0	1.0	0.056	ug/L	1	"	· ·	II .	"	
Chloromethane	<2.5	2.5	0.062	ug/L	1	"	· ·	II .	"	
cis-1,2-Dichloroethene	<1.0	1.0	0.097	ug/L	1	"	· ·	II .	"	
cis-1,3-Dichloropropene	<1.0	1.0	0.041	ug/L	1	"	"	II .	"	
Dibromochloromethane	<2.5	2.5	0.070	ug/L	1	"	"	"	"	
Dibromomethane	<2.5	2.5	0.088	ug/L	1	"	"	"	"	
Dichlorodifluoromethane	<5.0	5.0	0.14	ug/L	1	"	"	II .	"	
Dichlorofluoromethane	<1.0	1.0	0.059	ug/L	1	"	"	"	"	T5
Ethyl ether	<5.0	5.0	0.091	ug/L	1	"	"	"	"	
Ethylbenzene	<1.0	1.0	0.033	ug/L	1	"	"	"	"	
Hexachlorobutadiene	<10	10	0.19	ug/L	1	"	"	II .	"	
Isopropylbenzene	<1.0	1.0	0.037	ug/L	1	"	"	"	"	
m,p-Xylene	<2.0	2.0	0.087	ug/L	1	"	"	"	"	
Methyl isobutyl ketone	<5.0	5.0	0.17	ug/L	1	"	"	"	"	
Methyl tert-butyl ether	<1.0	1.0	0.056	ug/L	1	"	"	"	"	
Methylene chloride	<5.0	5.0	0.10	ug/L	1	"	"	"	"	
Naphthalene	<5.0	5.0	0.032	ug/L	1	"	"	"	"	
n-Butylbenzene	<2.5	2.5	0.028	ug/L	1	"	"	"	"	
n-Propylbenzene	<1.0	1.0	0.040	ug/L	1	"	"	II .	"	
o-Xylene	<1.0	1.0	0.053	ug/L	1	"	"	"	"	
p-Isopropyltoluene	<2.5	2.5	0.052	ug/L	1	"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
Trip Blank (1505312-04) Water	Sampled: 11/25/1	5 00:00	Receive	d: 12/01/15	8:00					
sec-Butylbenzene	<1.0	1.0	0.055	ug/L	1	B5L0814	12/04/15	12/04/15	EPA 8260B	
Styrene	<1.0	1.0	0.048	ug/L	1	"	"	"	"	
tert-Butylbenzene	<1.0	1.0	0.028	ug/L	1	"	"	"	"	
Tetrachloroethene	<1.0	1.0	0.035	ug/L	1	"	"	"	"	
Tetrahydrofuran	<20	20	0.34	ug/L	1	"	"	"	"	T5
Toluene	<1.0	1.0	0.064	ug/L	1	"	"	"	"	
trans-1,2-Dichloroethene	<1.0	1.0	0.058	ug/L	1	"	"	II .	"	
trans-1,3-Dichloropropene	<1.0	1.0	0.067	ug/L	1	"	"	II .	"	
Trichloroethene	<1.0	1.0	0.096	ug/L	1	"	"	II .	"	
Trichlorofluoromethane	<1.0	1.0	0.26	ug/L	1	"	"	u u	"	
Vinyl chloride	<1.0	1.0	0.046	ug/L	1	"	"	"	"	
Surrogate: 4-Bromofluorobenzene	87.8			80-121 %		"	"	"	"	
Surrogate: Dibromofluoromethane	92.3			79.9-121 %		"	"	"	"	
Surrogate: Toluene-d8	94.1			80-120 %		"	"	"	"	



Fax: 651-642-1239

Barr Engineering Co.Project:345110104300 MarketPointe Drive, Suite 200Project Number:34511010Work Order #:1505312Minneapolis, MN 55435Project Manager:Ms. Andrea NordDate Reported:12/10/15

8015D DRO - Quality Control Legend Technical Services, Inc.

	.	Б.	MDI		Spike	Source	0/050	%REC	0/ 000	%RPD	N1 /
Analyte	Result	RL	MDL	Units	Level	Result	%REC	Limits	%RPD	Limit	Notes
Batch B5L0202 - EPA 3510C (Sep Funne	el)										
Blank (B5L0202-BLK1)					Prepared	& Analyze	ed: 12/02/	15			
Diesel Range Organics	< 100	100	26	ug/L							
Surrogate: Triacontane (C-30)	402			ug/L	400		100	70-130			
LCS (B5L0202-BS1)					Prepared	& Analyze	ed: 12/02/	15			
Diesel Range Organics	1580	100	26	ug/L	1600		98.7	70-130			
Surrogate: Triacontane (C-30)	412			ug/L	400		103	70-130			
LCS Dup (B5L0202-BSD1)					Prepared	& Analyze	ed: 12/02/	15			
Diesel Range Organics	1580	100	26	ug/L	1600		98.8	70-130	0.0833	20	
Surrogate: Triacontane (C-30)	413			ug/L	400		103	70-130			
Matrix Spike (B5L0202-MS1)	S	ource: 1	505312-0	O1 Prepared & Analyzed: 12/02/15							
Diesel Range Organics	1750	100	26	ug/L	1630	109	101	70-130			
Surrogate: Triacontane (C-30)	420			ug/L	408		103	70-130			



Fax: 651-642-1239

Barr Engineering Co.Project:345110104300 MarketPointe Drive, Suite 200Project Number:34511010Work Order #:1505312Minneapolis, MN 55435Project Manager:Ms. Andrea NordDate Reported:12/10/15

8015D GRO - Quality Control Legend Technical Services, Inc.

Analys	Danill	ы	MDI	11-21-	Spike	Source	0/DE0	%REC	0/ DDD	%RPD	Nietee
Analyte	Result	RL	MDL	Units	Level	Result	%REC	Limits	%RPD	Limit	Notes
Batch B5L0228 - EPA 5030 Water (Pur	ge and Tra	p)									
Blank (B5L0228-BLK1)					Prepared	l & Analyze	ed: 12/02/1	15			
Gasoline range organics	< 100	100	16	ug/L							
Surrogate: 4-Fluorochlorobenzene	20.4			ug/L	20.0		102	80-150			
LCS (B5L0228-BS1)					Prepared	l & Analyze	ed: 12/02/1	15			
Gasoline range organics	1050	100	16	ug/L	1000		105	80-120			
Surrogate: 4-Fluorochlorobenzene	22.2			ug/L	20.0		111	80-150			
LCS Dup (B5L0228-BSD1)					Prepared	l: 12/02/15	Analyzed	l: 12/03/15			
Gasoline range organics	1060	100	16	ug/L	1000		106	80-120	0.885	20	
Surrogate: 4-Fluorochlorobenzene	22.7			ug/L	20.0		114	80-150			
Duplicate (B5L0228-DUP1)	S	ource: 1	1505329-0	1	Prepared	l: 12/02/15	Analyzed	l: 12/03/15			
Gasoline range organics	44.8	100	16	ug/L		<100			NA	20	
Surrogate: 4-Fluorochlorobenzene	20.5			ug/L	20.0		102	80-150			
Matrix Spike (B5L0228-MS1)	S	ource: 1	1505312-0	1	Prepared	l: 12/02/15	Analyzed	l: 12/03/15	1		
Gasoline range organics	1020	100	16	ug/L	1000	<100	97.6	70-130			
Surrogate: 4-Fluorochlorobenzene	22.1			ug/L	20.0		111	80-150			
Matrix Spike Dup (B5L0228-MSD1)	S	ource: 1	1505312-0	1	Prepared	l: 12/02/15	Analyzed	l: 12/03/15	;		
Gasoline range organics	1020	100	16	ug/L	1000	<100	96.9	70-130	0.606	20	
Surrogate: 4-Fluorochlorobenzene	22.5			ug/L	20.0		113	80-150			



Fax: 651-642-1239

Barr Engineering Co.Project:345110104300 MarketPointe Drive, Suite 200Project Number:34511010Work Order #:1505312Minneapolis, MN 55435Project Manager:Ms. Andrea NordDate Reported:12/10/15

DISSOLVED METAL ANALYSIS - Quality Control Legend Technical Services, Inc.

					Snika	Source		%REC		%RPD	
Analyte	Result	RL	MDL	Units	Spike Level	Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0127 - EPA 200.7/3005A Dig	gestion							_			
Blank (B5L0127-BLK1)					Prepared	: 12/01/15	Analyzed	l: 12/03/15			
Arsenic	< 0.010	0.010	0.0026	mg/L							
Barium	< 0.020	0.020	0.0022	mg/L							
Cadmium	< 0.0010	0.0010	0.000059	mg/L							
Chromium	< 0.010	0.010	0.0012	mg/L							
Lead	< 0.0050	0.0050	0.0012	mg/L							
Mercury	< 0.010	0.010	0.0023	mg/L							
Selenium	< 0.030	0.030	0.0073	mg/L							
Silver	< 0.0050	0.0050	0.00053	mg/L							
LCS (B5L0127-BS1)					Prepared	: 12/01/15	Analyzed	l: 12/03/15			
Arsenic	0.410	0.010	0.0026	mg/L	0.399		103	80-120			
Barium	0.422	0.020	0.0022	mg/L	0.399		106	80-120			
Cadmium	0.434	0.0010	0.000059	mg/L	0.399		109	80-120			
Chromium	0.420	0.010	0.0012	mg/L	0.399		105	80-120			
Lead	0.422	0.0050	0.0012	mg/L	0.399		106	80-120			
Mercury	0.237	0.010	0.0023	mg/L	0.250		94.8	80-120			
Selenium	0.420	0.030	0.0073	mg/L	0.399		105	80-120			
Silver	0.0398	0.0050	0.00053	mg/L	0.0399		99.7	80-120			
LCS Dup (B5L0127-BSD1)					Prepared	: 12/01/15	Analyzed	l: 12/03/15			
Arsenic	0.402	0.010	0.0026	mg/L	0.399		101	80-120	1.97	20	
Barium	0.419	0.020	0.0022	mg/L	0.399		105	80-120	0.713	20	
Cadmium	0.432	0.0010	0.000059	mg/L	0.399		108	80-120	0.462	20	
Chromium	0.418	0.010	0.0012	mg/L	0.399		105	80-120	0.477	20	
Lead	0.428	0.0050	0.0012	mg/L	0.399		107	80-120	1.41	20	
Mercury	0.251	0.010	0.0023	mg/L	0.250		100	80-120	5.74	20	
Selenium	0.421	0.030	0.0073	mg/L	0.399		106	80-120	0.238	20	
Silver	0.0392	0.0050	0.00053	mg/L	0.0399		98.2	80-120	1.52	20	
Matrix Spike (B5L0127-MS1)	8		1505312-0 ⁻	I	Prepared	: 12/01/15	Analyzed	l: 12/03/15			
Arsenic	0.403	0.010	0.0026	mg/L	0.399	<0.010	101	75-125			
Barium	0.563	0.020	0.0022	mg/L	0.399	0.151	103	75-125			
Cadmium	0.425	0.0010	0.000059	mg/L	0.399	<0.0010	107	75-125			
Chromium	0.426	0.010	0.0012	mg/L	0.399	<0.010	106	75-125			
Lead		0.0050	0.0012	mg/L	0.399	<0.0050	104	75-125			
Mercury		0.010	0.0023	mg/L	0.250	<0.010	82.0	75-125			
Selenium	0.426	0.030	0.0073	mg/L	0.399	<0.030	107	75-125			
Silver	0.0390	0.0050	0.00053	mg/L	0.0399	<0.0050	97.7	75-125			
Matrix Spike Dup (B5L0127-MSD1)			1505312-0 ⁻	I			Analyzed	l: 12/03/15			
Arsenic	0.393	0.010	0.0026	mg/L	0.399	<0.010	98.5	75-125	2.51	20	
Barium	0.560	0.020	0.0022	mg/L	0.399	0.151	103	75-125	0.534	20	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Work Order #: 1505312
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/10/15

DISSOLVED METAL ANALYSIS - Quality Control Legend Technical Services, Inc.

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0127 - EPA 200.7/3005A D	gestion										
Matrix Spike Dup (B5L0127-MSD1)	8	Source:	1505312-0 ⁻	l	Prepared	: 12/01/15	Analyzed	d: 12/03/15	;		
Cadmium	0.422	0.0010	0.000059	mg/L	0.399	<0.0010	106	75-125	0.708	20	
Chromium	0.424	0.010	0.0012	mg/L	0.399	<0.010	105	75-125	0.471	20	
Lead	0.421	0.0050	0.0012	mg/L	0.399	< 0.0050	105	75-125	0.955	20	
Mercury	0.194	0.010	0.0023	mg/L	0.250	<0.010	77.6	75-125	5.51	200	
Selenium	0.431	0.030	0.0073	mg/L	0.399	< 0.030	108	75-125	1.17	20	
Silver	0.0384	0.0050	0.00053	mg/L	0.0399	<0.0050	96.2	75-125	1.55	20	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312 Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0201 - EPA 3510C (Sep Fun	nel)										
Blank (B5L0201-BLK1)					Prepared	l: 12/02/15	Analyzed	: 12/03/15			
1,2,4-Trichlorobenzene	< 10	10	0.53	ug/L	-		•				
1,2-Dichlorobenzene	< 10	10	0.47	ug/L							
1,2-Diphenylhydrazine as Azobenzene	< 10	10	0.32	ug/L							
1,3-Dichlorobenzene	< 10	10	0.43	ug/L							
1,4-Dichlorobenzene	< 10	10	0.32	ug/L							
2,3,4,6-Tetrachlorophenol	< 10	10	0.74	ug/L							
2,4,5-Trichlorophenol	< 10	10	1.1	ug/L							
2,4,6-Trichlorophenol	< 10	10	0.82	ug/L							
2,4-Dichlorophenol	< 10	10	0.78	ug/L							
2,4-Dimethylphenol	< 10	10	0.99	ug/L							
2,4-Dinitrophenol	< 10	10	0.70	ug/L							
2,4-Dinitrotoluene	< 10	10	0.44	ug/L							
2,6-Dichlorophenol	< 10	10	0.93	ug/L							
2,6-Dinitrotoluene	< 10	10	0.39	ug/L							
2-Chloronaphthalene	< 10	10	0.38	ug/L							
2-Chlorophenol	< 10	10	1.2	ug/L							
2-Methylnaphthalene	< 10	10	0.70	ug/L							
2-Methylphenol	< 10	10	1.4	ug/L							
2-Nitroaniline	< 10	10	0.83	ug/L							
2-Nitrophenol	< 10	10	0.86	ug/L							
3&4-Methylphenol	< 10	10	1.5	ug/L							
3,3´-Dichlorobenzidine	< 25	25	9.9	ug/L							
3-Nitroaniline	< 10	10	2.0	ug/L							
4,6-Dinitro-2-methylphenol	< 10	10	1.0	ug/L							
4-Bromophenyl phenyl ether	< 10	10	0.34	ug/L							
4-Chloro-3-methylphenol	< 10	10	0.68	ug/L							
4-Chloroaniline	< 10	10	2.3	ug/L							
4-Chlorophenyl phenyl ether	< 10	10	0.45	ug/L							
4-Nitroaniline	< 10	10	1.2	ug/L							
4-Nitrophenol	< 10	10	0.91	ug/L							
Acenaphthene	< 10	10	0.41	ug/L							
Acenaphthylene	< 10	10	0.38	ug/L							
Aniline	< 10	10	1.3	ug/L							
Anthracene	< 10	10	0.36	ug/L							
Benzidine	< 100	100	8.2	ug/L							
Benzo(a)anthracene	< 10	10	0.23	ug/L							
Benzo(a)pyrene	< 10	10	0.34	ug/L							
Benzo(b)fluoranthene	< 10	10	0.18	ug/L							
Benzo(g,h,i)perylene	< 10	10	0.43	ug/L							
				-							



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0201 - EPA 3510C (Sep Funr											
Blank (B5L0201-BLK1)	101,				Prenared	· 12/02/15	Analyzed	I: 12/03/15			
Benzo(k)fluoranthene	< 10	10	0.55	ug/L	ricparcu	. 12/02/13	Analyzou	1. 12/03/13			
Benzoic acid	< 10	10	1.8	ug/L							
Benzyl alcohol	< 10	10	0.68	ug/L							
Bis(2-chloroethoxy)methane	< 10	10	0.41	ug/L							
Bis(2-chloroethyl)ether	< 10	10	0.59	ug/L							
Bis(2-chloroisopropyl)ether	< 10	10	0.47	ug/L							
Bis(2-ethylhexyl)phthalate	< 10	10	0.77	ug/L							
Butyl benzyl phthalate	< 10	10	0.67	ug/L							
Carbazole	< 10	10	0.42	ug/L							
Chrysene	< 10	10	0.34	ug/L							
Dibenz(a,h)anthracene	< 10	10	0.31	ug/L							
Dibenzofuran	< 10	10	0.77	ug/L							
Diethyl phthalate	< 10	10	0.42	ug/L							
Dimethyl phthalate	< 10	10	0.44	ug/L							
Di-n-butyl phthalate	< 10	10	0.42	ug/L							
Di-n-octyl phthalate	< 10	10	0.48	ug/L							
Fluoranthene	< 10	10	0.36	ug/L							
Fluorene	< 10	10	0.35	ug/L							
Hexachlorobenzene	< 10	10	0.30	ug/L							
Hexachlorobutadiene	< 10	10	0.37	ug/L							
Hexachlorocyclopentadiene	< 10	10	0.52	ug/L							
Hexachloroethane	< 10	10	0.61	ug/L							
Indeno (1,2,3-cd) pyrene	< 10	10	0.37	ug/L							
Isophorone	< 10	10	0.45	ug/L							
Naphthalene	< 10	10	0.33	ug/L							
Nitrobenzene	< 10	10	0.51	ug/L							
N-Nitrosodimethylamine	< 10	10	0.34	ug/L							
N-Nitrosodi-n-propylamine	< 10	10	0.47	ug/L							
N-Nitrosodiphenylamine	< 10	10	0.54	ug/L							
Pentachlorophenol	< 10	10	1.2	ug/L							
Phenanthrene	< 10	10	0.28	ug/L							
Phenol	< 10	10	1.2	ug/L							
Pyrene	< 10	10	0.49	ug/L							
Surrogate: 2,4,6-Tribromophenol	86.4			ug/L	100		86.4	30-122			
Surrogate: 2-Fluorobiphenyl	87.2			ug/L	100		87.2	39.2-104			
Surrogate: 2-Fluorophenol	61.9			ug/L	100		61.9	30-80.1			
Surrogate: Nitrobenzene-d5	81.2			ug/L	100		81.2	51.2-103			
Surrogate: Phenol-d6	55.9			ug/L	100		55.9	30-75.3			
Surrogate: Terphenyl-d14	102			ug/L	100		102	30-116			



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312 Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0201 - EPA 3510C (Sep	Funnel)	_									
LCS (B5L0201-BS1)					Prepared	l: 12/02/15	Analyzed	l: 12/03/15			
1,2,4-Trichlorobenzene	37.4	10	0.53	ug/L	50.0		74.7	38-100			
1,4-Dichlorobenzene	35.1	10	0.32	ug/L	50.0		70.2	30-90			
2,4-Dinitrotoluene	42.9	10	0.44	ug/L	50.0		85.7	57-100			
2-Chlorophenol	36.3	10	1.2	ug/L	50.0		72.6	45-95			
4-Chloro-3-methylphenol	41.5	10	0.68	ug/L	50.0		83.0	52-100			
4-Nitrophenol	39.5	10	0.91	ug/L	50.0		78.9	30-100			
Anthracene	42.7	10	0.36	ug/L	50.0		85.5	60-100			
Benzo(a)anthracene	43.5	10	0.23	ug/L	50.0		87.0	64-100			
Benzo(a)pyrene	40.5	10	0.34	ug/L	50.0		81.0	60-100			
Chrysene	45.0	10	0.34	ug/L	50.0		90.1	60-100			
Fluoranthene	43.7	10	0.36	ug/L	50.0		87.3	63-100			
Fluorene	41.9	10	0.35	ug/L	50.0		83.8	59-100			
N-Nitrosodi-n-propylamine	41.2	10	0.47	ug/L	50.0		82.3	55-100			
Pentachlorophenol	38.8	10	1.2	ug/L	50.0		77.5	45-107			
Phenanthrene	42.4	10	0.28	ug/L	50.0		84.7	62-100			
Phenol	26.9	10	1.2	ug/L	50.0		53.8	30-80			
Surrogate: 2,4,6-Tribromophenol	86.6			ug/L	100		86.6	30-122			
Surrogate: 2-Fluorobiphenyl	82.6			ug/L	100		82.6	39.2-104			
Surrogate: 2-Fluorophenol	58.7			ug/L	100		58.7	30-80.1			
Surrogate: Nitrobenzene-d5	77.9			ug/L	100		77.9	51.2-103			
Surrogate: Phenol-d6	54.2			ug/L	100		54.2	30-75.3			
Surrogate: Terphenyl-d14	89.7			ug/L	100		89.7	30-116			
LCS Dup (B5L0201-BSD1)					Prepared	l: 12/02/15	Analyzed	d: 12/03/15			Q9, QM-10
1,2,4-Trichlorobenzene	36.6	10	0.53	ug/L	50.0		73.2	38-100	2.09	20	
1,4-Dichlorobenzene	35.5	10	0.32	ug/L	50.0		71.1	30-90	1.25	20	
2,4-Dinitrotoluene	40.7	10	0.44	ug/L	50.0		81.4	57-100	5.18	20	
2-Chlorophenol	35.8	10	1.2	ug/L	50.0		71.5	45-95	1.43	20	
4-Chloro-3-methylphenol	39.3	10	0.68	ug/L	50.0		78.7	52-100	5.33	20	
4-Nitrophenol	38.0	10	0.91	ug/L	50.0		76.0	30-100	3.85	20	
Anthracene	39.8	10	0.36	ug/L	50.0		79.6	60-100	7.08	20	
Benzo(a)anthracene	41.7	10	0.23	ug/L	50.0		83.5	64-100	4.11	20	
Benzo(a)pyrene	38.9	10	0.34	ug/L	50.0		77.7	60-100	4.18	20	
Chrysene	43.1	10	0.34	ug/L	50.0		86.1	60-100	4.49	20	
Fluoranthene	41.6	10	0.36	ug/L	50.0		83.2	63-100	4.88	20	
Fluorene	40.0	10	0.35	ug/L	50.0		80.0	59-100	4.68	20	
N-Nitrosodi-n-propylamine	40.3	10	0.47	ug/L	50.0		80.5	55-100	2.21	20	
Pentachlorophenol	35.9	10	1.2	ug/L	50.0		71.9	45-107	7.57	20	
Phenanthrene	40.3	10	0.28	ug/L	50.0		80.5	62-100	5.10	20	
Phenol	26.0	10	1.2	ug/L	50.0		52.1	30-80	3.29	20	



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010 Work Order #: 1505312
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0201 - EPA 3510C (Se	p Funnel)										
LCS Dup (B5L0201-BSD1)					Prepared:	12/02/15	Analyzed	: 12/03/15			Q9, QM-10
Surrogate: 2,4,6-Tribromophenol	80.4			ug/L	100		80.4	30-122			
Surrogate: 2-Fluorobiphenyl	78.0			ug/L	100		78.0	39.2-104			
Surrogate: 2-Fluorophenol	57.8			ug/L	100		57.8	30-80.1			
Surrogate: Nitrobenzene-d5	76.1			ug/L	100		76.1	51.2-103			
Surrogate: Phenol-d6	51.6			ug/L	100		51.6	30-75.3			
Surrogate: Terphenyl-d14	80.2			ug/L	100		80.2	30-116			



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
			IVIDL	Ullits	FEAGI	Nesull	/0NLU	LIIIIII	/0IXF IJ	LIIIIII	140162
Batch B5L0814 - EPA 5030 Water (Pu Blank (B5L0814-BLK1)	irge and ira	h)			Prenareo	ł & Analyze	ad: 12/04/1	15			
1,1,1,2-Tetrachloroethane	< 1.0	1.0	0.024	ug/L	Перагес	i & Allalyze	5u. 12/04/	3			
1,1,1-Trichloroethane	< 1.0	1.0	0.069	ug/L							
1,1,2,2-Tetrachloroethane	< 1.0	1.0	0.051	ug/L							
1,1,2-Trichloroethane	< 1.0	1.0	0.10	ug/L							
1,1,2-Trichlorotrifluoroethane	< 1.0	1.0	0.081	ug/L							
1,1-Dichloroethane	< 1.0	1.0	0.050	ug/L							
1,1-Dichloroethene	< 1.0	1.0	0.065	ug/L							
1,1-Dichloropropene	< 1.0	1.0	0.15	ug/L							
1,2,3-Trichlorobenzene	< 5.0	5.0	0.45	ug/L							
1,2,3-Trichloropropane	< 2.5	2.5	0.056	ug/L							
1,2,4-Trichlorobenzene	< 5.0	5.0	0.091	ug/L							
1,2,4-Trimethylbenzene	< 1.0	1.0	0.054	ug/L							
1,2-Dibromo-3-chloropropane	< 5.0	5.0	0.033	ug/L							
1,2-Dibromoethane (EDB)	< 2.5	2.5	0.042	ug/L							
1,2-Dichlorobenzene	< 1.0	1.0	0.052	ug/L							
1,2-Dichloroethane	< 1.0	1.0	0.064	ug/L							
1,2-Dichloropropane	< 1.0	1.0	0.034	ug/L							
1,3,5-Trimethylbenzene	< 1.0	1.0	0.046	ug/L							
1,3-Dichlorobenzene	< 1.0	1.0	0.068	ug/L							
1,3-Dichloropropane	< 1.0	1.0	0.15	ug/L							
1,4-Dichlorobenzene	< 1.0	1.0	0.047	ug/L							
2,2-Dichloropropane	< 5.0	5.0	0.28	ug/L							
2-Butanone	< 20	20	0.33	ug/L							
2-Chlorotoluene	< 1.0	1.0	0.052	ug/L							
4-Chlorotoluene	< 1.0	1.0	0.041	ug/L							
Acetone	< 20	20	0.32	ug/L							
Allyl chloride	< 5.0	5.0	0.078	ug/L							
Benzene	< 1.0	1.0	0.034	ug/L							
Bromobenzene	< 1.0	1.0	0.042	ug/L							
Bromochloromethane	< 1.0	1.0	0.10	ug/L							
Bromodichloromethane	< 1.0	1.0	0.042	ug/L							
Bromoform	< 5.0	5.0	0.080	ug/L							
Bromomethane	< 5.0	5.0	0.17	ug/L							
Carbon tetrachloride	< 1.0	1.0	0.029	ug/L							
Chlorobenzene	< 1.0	1.0	0.037	ug/L							
Chloroethane	< 2.5	2.5	0.062	ug/L							
Chloroform	< 1.0	1.0	0.056	ug/L							
Chloromethane	< 2.5	2.5	0.062	ug/L							
cis-1,2-Dichloroethene	< 1.0	1.0	0.097	ug/L							



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0814 - EPA 5030 Water (Purge and Tra	ıp)									
Blank (B5L0814-BLK1)					Prepared	l & Analyze	ed: 12/04/	15			
cis-1,3-Dichloropropene	< 1.0	1.0	0.041	ug/L							
Dibromochloromethane	< 2.5	2.5	0.070	ug/L							
Dibromomethane	< 2.5	2.5	0.088	ug/L							
Dichlorodifluoromethane	< 5.0	5.0	0.14	ug/L							
Dichlorofluoromethane	< 1.0	1.0	0.059	ug/L							
Ethyl ether	< 5.0	5.0	0.091	ug/L							
Ethylbenzene	< 1.0	1.0	0.033	ug/L							
Hexachlorobutadiene	< 10	10	0.19	ug/L							
Isopropylbenzene	< 1.0	1.0	0.037	ug/L							
m,p-Xylene	< 2.0	2.0	0.087	ug/L							
Methyl isobutyl ketone	< 5.0	5.0	0.17	ug/L							
Methyl tert-butyl ether	< 1.0	1.0	0.056	ug/L							
Methylene chloride	< 5.0	5.0	0.10	ug/L							
Naphthalene	< 5.0	5.0	0.032	ug/L							
n-Butylbenzene	< 2.5	2.5	0.028	ug/L							
n-Propylbenzene	< 1.0	1.0	0.040	ug/L							
o-Xylene	< 1.0	1.0	0.053	ug/L							
p-Isopropyltoluene	< 2.5	2.5	0.052	ug/L							
sec-Butylbenzene	< 1.0	1.0	0.055	ug/L							
Styrene	< 1.0	1.0	0.048	ug/L							
tert-Butylbenzene	< 1.0	1.0	0.028	ug/L							
Tetrachloroethene	< 1.0	1.0	0.035	ug/L							
Tetrahydrofuran	< 20	20	0.34	ug/L							
Toluene	< 1.0	1.0	0.064	ug/L							
trans-1,2-Dichloroethene	< 1.0	1.0	0.058	ug/L							
trans-1,3-Dichloropropene	< 1.0	1.0	0.067	ug/L							
Trichloroethene	< 1.0	1.0	0.096	ug/L							
Trichlorofluoromethane	< 1.0	1.0	0.26	ug/L							
Vinyl chloride	< 1.0	1.0	0.046	ug/L							
Surrogate: 4-Bromofluorobenzene	49.2			ug/L	56.0		87.9	80-121			
Surrogate: Dibromofluoromethane	52.1			ug/L	56.0		93.0	79.9-121			
Surrogate: Toluene-d8	51.6			ug/L	56.0		92.1	80-120			
LCS (B5L0814-BS1)					Prepared	l & Analyze	ed: 12/04/	15			
1,1,2,2-Tetrachloroethane	52.7	1.0	0.051	ug/L	50.0		105	80-121			
1,1-Dichloroethane	49.8	1.0	0.050	ug/L	50.0		99.6	80-125			
1,1-Dichloroethene	46.6	1.0	0.065	ug/L	50.0		93.2	80-125			
1,3,5-Trimethylbenzene	47.7	1.0	0.046	ug/L	50.0		95.4	75.4-125			
1,4-Dichlorobenzene	46.8	1.0	0.047	ug/L	50.0		93.6	75-125			
2-Chlorotoluene	48.5	1.0	0.052	ug/L	50.0		97.1	75.4-125			



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

Work Order #: 1505312
Date Reported: 12/10/15

Analyte	Result	RL	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	%RPD	%RPD Limit	Notes
Batch B5L0814 - EPA 5030 Water (Purg			IVIDE	Cilito		result	701 KEO	Liiillo	/01 NI D	Little	140103
· · · · · · · · · · · · · · · · · · ·	e anu 11a	ν)			Dranarad	l & Analyze	ad: 12/04/:	15			
LCS (B5L0814-BS1) Benzene	50.4	1.0	0.034	ug/L	50.0	i & AllalyZe	101 101	80-120			
Bromoform	49.6	5.0	0.034	ug/L ug/L	50.0		99.2	80-120			
Chlorobenzene	48.8	1.0	0.080	ug/L ug/L	50.0		97.6	80-120			
Chloroform	46.7	1.0	0.056	ug/L	50.0		93.3	80-123			
Ethylbenzene	48.2	1.0	0.033	ug/L	50.0		96.4	80-120			
n-Butylbenzene	49.0	2.5	0.028	ug/L	50.0		98.1	75-125			
n-Propylbenzene	49.9	1.0	0.040	ug/L	50.0		99.9	75.8-125			
Toluene	50.3	1.0	0.064	ug/L	50.0		101	80-120			
Trichloroethene	47.6	1.0	0.096	ug/L	50.0		95.3	80-120			
Vinyl chloride	42.6	1.0	0.046	ug/L	50.0		85.1	75-130			
Surrogate: 4-Bromofluorobenzene	52.7	***		ug/L	56.0		94.2	80-121			
Surrogate: 4-Bromofluoromethane	52.7 52.7			ug/L ug/L	56.0		94.2 94.1	79.9-121			
Surrogate: Toluene-d8	54.2			ug/L ug/L	56.0		96.7	80-120			
Matrix Spike (B5L0814-MS1)		Olirca:	1505312-0			l & Analyze					
1,1,2,2-Tetrachloroethane	53.4	1.0	0.051	ug/L	50.0	<1.0	107	76.8-125			
1,1-Dichloroethane	51.0	1.0	0.050	ug/L	50.0	<1.0	107	80-125			
1,1-Dichloroethene	48.9	1.0	0.065	ug/L	50.0	<1.0	97.7	80-125			
1,3,5-Trimethylbenzene	47.9	1.0	0.046	ug/L	50.0	<1.0	95.9	75-125			
1,4-Dichlorobenzene	46.7	1.0	0.047	ug/L	50.0	<1.0	93.4	75-125			
2-Chlorotoluene	48.1	1.0	0.052	ug/L	50.0	<1.0	96.2	75-125			
Benzene	51.4	1.0	0.034	ug/L	50.0	<1.0	103	80-120			
Bromoform	51.3	5.0	0.080	ug/L	50.0	<5.0	103	80-120			
Chlorobenzene	48.6	1.0	0.037	ug/L	50.0	<1.0	97.2	80-120			
Chloroform	48.6	1.0	0.056	ug/L	50.0	<1.0	97.1	79.8-125			
Ethylbenzene	49.0	1.0	0.033	ug/L	50.0	<1.0	97.9	80-120			
n-Butylbenzene	46.8	2.5	0.028	ug/L	50.0	<2.5	93.5	75-130			
n-Propylbenzene	49.0	1.0	0.040	ug/L	50.0	<1.0	98.1	75-125			
Toluene	50.8	1.0	0.064	ug/L	50.0	<1.0	102	80-120			
Trichloroethene	48.4	1.0	0.096	ug/L	50.0	<1.0	96.8	80-120			
Vinyl chloride	42.5	1.0	0.046	ug/L	50.0	<1.0	85.1	75-130			
Surrogate: 4-Bromofluorobenzene	53.0			ug/L	56.0		94.6	80-121			
Surrogate: Dibromofluoromethane	52.6			ug/L	56.0		93.9	79.9-121			
Surrogate: Toluene-d8	53.1			ug/L	56.0		94.8	80-120			
Matrix Spike Dup (B5L0814-MSD1)	S	ource:	1505312-0)1	Prepared	l & Analyze	ed: 12/04/	15			
1,1,2,2-Tetrachloroethane	53.0	1.0	0.051	ug/L	50.0	<1.0	106	76.8-125	0.858	20	
1,1-Dichloroethane	52.4	1.0	0.050	ug/L	50.0	<1.0	105	80-125	2.62	20	
1,1-Dichloroethene	48.9	1.0	0.065	ug/L	50.0	<1.0	97.8	80-125	0.0344	20	
1,3,5-Trimethylbenzene	47.6	1.0	0.046	ug/L	50.0	<1.0	95.2	75-125	0.733	20	



Fax: 651-642-1239

Work Order #: 1505312

Date Reported: 12/10/15

Barr Engineering Co. Project: 34511010
4300 MarketPointe Drive, Suite 200 Project Number: 34511010
Minneapolis, MN 55435 Project Manager: Ms. Andrea Nord

					Spike	Source		%REC	0/555	%RPD	
Analyte	Result	RL	MDL	Units	Level	Result	%REC	Limits	%RPD	Limit	Notes
Batch B5L0814 - EPA 5030 Water (Pt	urge and Tra	p)									
Matrix Spike Dup (B5L0814-MSD1)	S	ource:	1505312-0	1	Prepared	ł & Analyze	ed: 12/04/	15			
1,4-Dichlorobenzene	47.0	1.0	0.047	ug/L	50.0	<1.0	94.1	75-125	0.713	20	
2-Chlorotoluene	49.0	1.0	0.052	ug/L	50.0	<1.0	97.9	75-125	1.76	20	
Benzene	51.2	1.0	0.034	ug/L	50.0	<1.0	102	80-120	0.450	20	
Bromoform	51.4	5.0	0.080	ug/L	50.0	<5.0	103	80-120	0.0680	20	
Chlorobenzene	49.1	1.0	0.037	ug/L	50.0	<1.0	98.3	80-120	1.16	20	
Chloroform	49.3	1.0	0.056	ug/L	50.0	<1.0	98.6	79.8-125	1.48	20	
Ethylbenzene	48.8	1.0	0.033	ug/L	50.0	<1.0	97.6	80-120	0.287	20	
n-Butylbenzene	48.8	2.5	0.028	ug/L	50.0	<2.5	97.6	75-130	4.20	20	
n-Propylbenzene	48.7	1.0	0.040	ug/L	50.0	<1.0	97.4	75-125	0.756	20	
Toluene	51.8	1.0	0.064	ug/L	50.0	<1.0	104	80-120	2.00	20	
Trichloroethene	49.4	1.0	0.096	ug/L	50.0	<1.0	98.8	80-120	2.04	20	
Vinyl chloride	42.4	1.0	0.046	ug/L	50.0	<1.0	84.8	75-130	0.305	20	
Surrogate: 4-Bromofluorobenzene	53.2			ug/L	56.0		95.0	80-121			
Surrogate: Dibromofluoromethane	53.0			ug/L	56.0		94.6	79.9-121			
Surrogate: Toluene-d8	53.9			ug/L	56.0		96.2	80-120			



Fax: 651-642-1239

Barr Engineering Co. Project: 34511010 4300 MarketPointe Drive, Suite 200 Work Order #: 1505312 Project Number: 34511010 Minneapolis, MN 55435 Date Reported: 12/10/15 Project Manager: Ms. Andrea Nord

Notes and Definitions

T5 Laboratory not licensed for this parameter.

S-GC Surrogate recovery outside of control limits. The data was accepted based on valid recovery of the remaining surrogate(s).

QM-10 LCS/LCSD were analyzed in place of MS/MSD.

Q9 Insufficient sample received to meet method QC requirements.

< Less than value listed

dry Sample results reported on a dry weight basis

NA Not applicable. The %RPD is not calculated from values less than the reporting limit.

MDL Method Detection Limit; Equivalent to the method LOD (Limit of Detection)

RL Reporting Limit

RPD Relative Percent Difference

LCS Laboratory Control Spike = Blank Spike (BS) = Laboratory Fortified Blank (LFB)

Matrix Spike = Laboratory Fortified Matrix (LFM) MS



88 Empire Drive St Paul, MN 55103

Tel: 651-642-1150 Fax: 651-642-1239

Project Number: 34511010 Project Number: 42 Ave Floodweld Sample Origination State AlD (use two letter postal state abbrevia) COC Number: Location State AlD (use two letter postal state abbrevia) COC Number: Location State AlD (use two letter postal state abbrevia) COC Number: Location State AlD (use two letter postal state abbrevia) COC Number: Location State AlD (use two letter postal state abbrevia) COC Number: Location State AlD (use two letter postal state abbrevia) Location State AlD (use two letter postal state abbrevia) COC Number: Location State AlD (use two letter postal state abbrevia)	Nº 45065	VOCs (HCl) #1 SVOCs (Unpreserved) #2 SVOCs (Unpreserved) #2 Strokes Metals (HNO ₃) Strat Ministry (HNO ₃) Strat Ministry (HNO ₃)	is OfCI)	ONLAST ONLAST INCC) IMP INDER ONTAINERS	Project Manager: And Co.
Project Number: 34511010 Project Number: 42 Ave Floodwall Sample Origination State Al D. (use two letter postal state abbrevia COC Number: Location Start Stop Unit Original B-4 Depth Depth origin.)		t served #2 served #2 served #2 served #3	E 25-	ONLAS ONLAS Nace) Ince)	11
Project Name: 42 Ave Floodwall Sample Origination State MD (use two letter postal state abbrevia COC Number: Location Start Stop Unit Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original Original O	Nº 45065	t (NO 3) as (NO 3) as (NO 3) as (NO 3) as (NO 3)	E 25-	ONL MI ONL MI INCO INCO INDICE: I	11
Sample Origination State M.D. (use two letter postal state abbrevia COC Number: Start Stop Unit (m./h. Orie.) Collect Date (nm/daty)	Nº 45065	de (HNO3)	E 25-	DOM;#1	OC Compet. Thy Me
COC Number: Location Start Stop Depth Unit (m./h. or in.)	Nº 45065	The can	主用	1 April 1981 1981 1982 1983 1983 1983 1983 1983 1983 1983 1983	Project OC Contact: And Contact Nord Sampled by: AMX Laboratory Legend
Location Start Depth Unit Unit Ontice (num/dily)	Nº 45065 on Collection Matrix Type		HILL OF THE CL	McOH) red Mei upresed served; vist,	
B-4 Depth Depth or in.) (num/dat/)	on Collection Matrix Type	5 Comment	T. T.	red to red to ampres ampres ampres ampres	Sampled by: / [4] K
	Time Hand	VOCs (H SVOCs (H SVOCs (Drandver Breat Mr	Secondary Or Christoler Comments (1135)	VOCs (tured McON), #1 GRO, HTEN (tured MsON), #1 DRO (tared unpreserved) Metals (appreserved), #2 NVOCs (unpreserved), #2 NVOCs (unpreserved), #2 NVOCs (unpreserved), #2 NVOCs (unpreserved), #2	Liboratory Legend
		X311	2 3	19	Standard TAT
2 B-b F+ 1	08 11 X X	311	1 3	19	
B-2a H +	08:41 X X	311	1 3	9	<u>\$1</u> ,
temp blank MA	——————————————————————————————————————	X		1	
HIL blank NIA	——	y .			
		_	$\downarrow\downarrow$		
10,				1	-
Common Parameter Container - Preservation Key Relinquished	i By: On too?	Date Tin		d try:	Date Time
l - Volatile Gegarnes = BTEX, GRQ TFH, \$260 Fall List 2 - Sevanolatile Organics = PAIIs, PCR Dianos, \$270 Full List, Herbicide/Pesneide/PCBs	Will J	Date Tin	man,	d tw	Date Time
3 - General = pH. Chloride, Fluoride Albalinity, TS5, TDS TS, Sulfair 4 - Nutrients = COD, TOC, Phenols, Aranumia Natiogen, TKN	pped VIA: Air Freight LiFederal		- Di		1711

Fax: 651-642-1239

Page 2

Data File: \\Its-target\targetdata\chem\FID5.i\151202.b\005.d

Date : 02-DEC-2015 15:48


Client ID:

Sample Info: 1505312-01

Instrument: FIR5.i

Operator: 5P

Column diameter: 0.53



Fax: 651-642-1239

Page 2

Data File: \\lts-target\targetdata\chem\FID5.i\151202.b\G10.d

Date : 02-DEC-2015 18:03


Client ID:

Sample Info: 1505312-02

Instrument: FID5.i

Operator: yp

Column diameter: 0.53



Fax: 651-642-1239

Page 2

Data File: \\lts-target\targetdata\chem\F1D5.i\151202.6\C07.d

Date : 02-DEC-2015 16:42

Client ID:

Sample Info: 1505312-03

Instrument: FID5.i

Operator: yp

Column diameter: 0.53

